

# D-PLCA Comment #47 Blocking Detection Of Own Transmitted Beacons



---

A Leading Provider of Smart, Connected and Secure Embedded Control Solutions



SMART | CONNECTED | SECURE

**Tim Baggett**

IEEE 802.3da Interim May 2025

# Introduction


- **D-PLCA enables nodes may self elect as the coordinator, if allowed, when no BEACONS are heard**
  - Allows for plug-and-play self-configuration
  - Allows for a new coordinator to “step in” if the original coordinator fails
- **When the D-PLCA coordinator hears a BEACON on the line, it will automatically re-configure as a Follower with a non-zero local\_nodeID by selecting an unused Transmit Opportunity**

# Problem

- **As identified by David Law during the January 2025 Interim meeting (Draft 2.0 comment #333), Clause 147 and 188 PHYs are defined to loop back from the transmit MII path to the receive MII path.**
  - When `coordinator_role_allowed` is TRUE, the D-PLCA node may become a coordinator and begin transmitting BEACONS
  - Transmitted BEACONS are looped back to MII setting `rx_cmd = BEACON` causing the coordinator to switch out of coordinator mode and into follower node.

# D2.1 Comment #333 Resolution


- **Resolution for D2.1 from the January Interim**
  - When a beacon is transmitted (tx\_cmd=BEACON), exit COORDINATOR for LOOPBACK.
  - Return to COORDINATOR state when reception of our own beacon is finished (rx\_cmd≠BEACON) ... and no collision or carrier sense



(Only the relevant portion of the D-PLCA Control State Diagram (Figure 148-8) shown)

IEEE 802.3da May 2025 Interim - New Orleans

# Timing of tx\_cmd and rx\_cmd




- Given the delay constraints in Clauses 147 and 188, the timing of rx\_cmd and CRS from tx\_cmd may vary significantly.
- At the slow end of the constraints, the current algorithm to block loopback reception of transmitted BEACONS will not work.
  - Carrier sense goes away before the BEACON is decoded and placed on the MII prematurely moving from LOOPBACK back into COORDINATOR
  - The BEACON is then decoded and on the MII (rx\_cmd=BEACON) causing incorrect transition from COORDINATOR to LEARNING

# Proposed solution


- **Use two loopback states:**

- The current loopback state is renamed LOOPBACK\_TX
  - Entered when a BEACON is being transmitted (tx\_cmd=BEACON)
- The new, second loopback state is LOOPBACK\_RX
  - Entered when the loopback BEACON is being detected (rx\_cmd=BEACON)
  - Exited to COORDINATOR when the loopback BEACON is no longer detected (rx\_cmd≠BEACON)



(Only the relevant portion of the D-PLCA Control State Diagram (Figure 148-8) shown)

# Proposed solution - timing




- Once command to transmit a BEACON starts, enter the LOOPBACK\_TX state
- Remain in LOOPBACK\_TX until the loopback BEACON is detected
- Enter and remain in the LOOPBACK\_RX state until end of loopback BEACON detection
- Once end of the loopback BEACON detection has ended, return to the COORDINATOR state

# Editing Instructions - 1

- 148.4.7.5 (P79 L22) Update Fig 148-8 D-PLCA Control State Diagram

(Only the COORDINATOR state and new/changed states are shown. All other portions have been cropped for brevity.)



# Editing Instructions - 2

- 148.4.7.2 (P76 L9) Delete COL from D-PLCA variables
- 148.4.7.2 (P76 L18) Remove CRS from D-PLCA variables

## 148.4.7.2 D-PLCA variables

~~COL~~

~~The MII signal COL (see 22.2.2.12).  
Values: TRUE or FALSE~~

coordinator\_role\_allowed

This variable controls whether the local node is allowed to take the coordinator role (local\_nodeID = 0) during the D-PLCA node assignment procedure. This variable maps on the aDPLCACoordinatorRoleAllowed attribute in 30.16.1.1.10.  
Values: TRUE or FALSE

~~CRS~~

~~The MII signal CRS (see 22.2.2.11).  
Values: TRUE or FALSE~~

dplca\_aging

This variable controls the state of the D-PLCA aging state diagram.  
Values: ON or OFF

7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24

# Thank You

# Questions?