

Cl 180 SC 180.9.5 P447 L1 # 1 [REDACTED]
 El-Chayeb, Ahmad Keysight Technologies (ahmad.el-chayeb@keysight.c
 Comment Type **TR** Comment Status **X**
 Current definition for TDECQ points to clause 121.8.5.1 where TDECQ is calculated at a pre-FEC target SER. This definition is not a very good indicator of link performance
SuggestedRemedy
 Re-define TDECQ and extend it to CER (codeword error ratio) to have better correlation with link performance. CER TDECQ definition need to be technically and economically feasible. A subsequent presentation will be provided at a later ad-hoc meeting.
 Proposed Response Response Status **O**

Cl 185 SC 185.8.16 P571 L18 # 2 [REDACTED]
 Stassar, Peter Huawei
 Comment Type **TR** Comment Status **X**
 The wording for the definition of Receiver Sensitivity is right from the intent but not sufficiently precise. "lowest average receiver input power at TP3 with no link impairments" is not right. Power is independent of impairments. Also applies to 187.8.17
SuggestedRemedy
 Change "Receiver sensitivity is an optional parameter defined as the lowest average receiver input power at TP3 with no link impairments at which the block error ratio requirement in 185.2 is met." to "Receiver sensitivity is an optional parameter defined as the lowest average receiver input power at TP3 with at which the block error ratio requirement in 185.2 is met. This does not have to be met in the presence of impairments from the link, which are addressed separately in the allocation for penalties in Table 185-7."
 Proposed Response Response Status **O**

Cl 30 SC 30.5.1.1.2 P62 L30 # 3 [REDACTED]
 Marris, Arthur Cadence Design Systems
 Comment Type **T** Comment Status **X**
 The description of 200GBASE-DR1-2 should include mention of the inner FEC requirement to distinguish it from the 200GBASE-DR1 description
SuggestedRemedy
 Change "200GBASE-R PCS/PMA over single-mode fiber PMD" to "200GBASE-R PCS/PMA with type 200GBASE-R Inner FEC"
 Make similar changes to 400GBASE-DR2-2, 800GBASE-DR4-2, and 1.6TBASE-DR8-2)
 Change "800GBASE-R PCS/PMA over single-mode fiber PMD" to "800GBASE-R PCS/PMA with type 800GBASE-LR1 Inner FEC over single-mode fiber PMD"
 Proposed Response Response Status **O**

Cl 45 SC 45.2.1.168a P95 L6 # 4 [REDACTED]
 Marris, Arthur Cadence Design Systems
 Comment Type **E** Comment Status **X**
 Typo "PRBS" should be "PRBS31"
SuggestedRemedy
 Change "The assignment of bits in the PRBS seed value lane 0 register" to "The assignment of bits in the PMA/PMD PRBS31 seed value lane 0 register"
 Also change "The assignment of bits in the PMA/PMD training pattern lanes 1 through 7 registers" to "The assignment of bits in the PMA/PMD PRBS31 seed value lanes 1 through 7 registers" on lines 6 and 7 of page 95
 Proposed Response Response Status **O**

Cl 45 SC 45.2.1.60c P82 L4 # 5 [REDACTED]
 Marris, Arthur Cadence Design Systems
 Comment Type **E** Comment Status **X**
 Typo, missing "2"
SuggestedRemedy
 Change "45.2.1.60c 800G PMA/PMD extended ability register (Register 1.74)" to "45.2.1.60c 800G PMA/PMD extended ability 2 register (Register 1.74)"
 Proposed Response Response Status **O**

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

CI 45 SC 45.2.1.168b P96 L3 # 6

Marris, Arthur Cadence Design Systems

Comment Type E Comment Status X

Typo, missing word "interface"

SuggestedRemedy

Change "The assignment of bits in the PMA/PMD training status register" to "The assignment of bits in the PMA/PMD interface training status register"

Proposed Response Response Status O

CI 45 SC 45.2.1.258 P109 L3 # 7

Marris, Arthur Cadence Design Systems

Comment Type E Comment Status X

Correct table name

SuggestedRemedy

Change "Table 45-212g—PMA/PMD status 1 register bit definitions" to "Table 45-212g—Inner FEC status 1 register bit definitions"

Proposed Response Response Status O

CI 116 SC 116.3.2 P156 L48 # 8

Marris, Arthur Cadence Design Systems

Comment Type E Comment Status X

Strikethrough and underlining not correct on line 48

SuggestedRemedy

Correct underlining and strike throughs to indicate change from "in Figure 116-2 and Figure 116-3," to "in Figure 116-2 through Figure 116-3a". That is strikethrough "and Figure 116-3" and underline "through Figure 116-3a"

Proposed Response Response Status O

CI 176 SC 176.7.4.2 P317 L16 # 9

Marris, Arthur Cadence Design Systems

Comment Type TR Comment Status X

The PRB31Q pattern needs decoding before being sent to the PRBS31 checker, not after it has been sent to the checker.

SuggestedRemedy

Change the word "followed" to "preceded" in "The PRBS31Q test pattern checking is provided by the PRBS31 checker (see 176.7.4.1), followed by inverse precoding (if enabled), and inverse Gray mapping in the PAM4 decoder (see 176.4.3.5)." Also consider using similar wording in 177.6.2.2

Proposed Response Response Status O

CI 45 SC 45.2.1.269 P115 L45 # 10

Marris, Arthur Cadence Design Systems

Comment Type E Comment Status X

Change "lower" to "bottom" to match Annex 178B nomenclature

SuggestedRemedy

Change "lower AUI" to "bottom AUI" in two places

Proposed Response Response Status O

CI 185A SC 185A.2.3 P862 L15 # 11

Pfiele, Joerg Keysight Technologies

Comment Type T Comment Status X

Digital signal processing steps should be described in more details in order to ensure consistency of ETCC results, e.g. block-wise processing with a specified block length.

SuggestedRemedy

Add to the description a text similar to OIF-400ZR-03.0, Appendix C, footnote 11: "The processing is done block wise with block size N = 1000. It is possible to group multiple blocks for some of the processing steps. The processing steps should perform only the tasks mentioned in the description. Processing steps can be consolidated and changed in order but not perform any additional signal processing with the purpose of compensating for signal distortions resulting for example from CD, PMD, skews, crosstalk, etc."

Proposed Response Response Status O

Cl 185A SC 185A.2.3.5 P863 L12 # 12
 Pfieffe, Joerg Keysight Technologies
 Comment Type T Comment Status X
 Reference equalizer comprises two steps, which do not necessarily need to be combined.
 SuggestedRemedy
 Add a separate block for the polarization demultiplexing. Or add a comment stating that polarization demultiplexing may also be performed as a separate processing block.
 Proposed Response Response Status O

Cl 185A SC 185A.2.3.5 P863 L12 # 13
 Pfieffe, Joerg Keysight Technologies
 Comment Type T Comment Status X
 Reference equalizer misses to specify the number of taps.
 SuggestedRemedy
 Add a specified number of taps to the description. For example: "... with an adaptive 45 tap (TBC) T-spaced feed-forward equalizer ..."
 Proposed Response Response Status O

Cl 185A SC 185A.2.4 P863 L28 # 14
 Pfieffe, Joerg Keysight Technologies
 Comment Type T Comment Status X
 Effective number of bits (ENOB) specification needs further details to be meaningful. There is a standard, which defines ENOB and how to measure it: IEEE Standard 1241-2023. This standard requires that the "amplitude and frequency at which the measurement was made shall be specified.". Therefore, it is also needed to specify the amplitude of the sine wave, which may also be translated to a percentage of the full-scale of the ADC, and the frequency.
 SuggestedRemedy
 Add a citation to IEEE Standard 1241-2023, Section 9.4.
 Add the sine wave amplitude and frequency information for which the specified value shall be achieved.
 Propose to specify the amplitude as 90% of the full-scale of the ADC and the frequency as at least 10 evenly spaced values between DC and the 3-dB bandwidth (according to Table 185A-1). The final ENOB number is then the average of these points.
 Proposed Response Response Status O

Cl 180 SC 180.7.3 P441 L42 # 15
 Johnson, John Broadcom
 Comment Type TR Comment Status X
 The allocation for MPI and DGD penalties of 0.1 dB is too small. It should be increased to 0.1 dB for MPI and 0.2 dB for DGD per johnson_3dj_01-2505.
 SuggestedRemedy
 In Table 180-9, make the following changes:
 1. Change Allocation for penalties (for max TDECQ) from 3.5 dB to 3.7 dB
 2. Change Power budget (for max TDECQ) from 6.5 dB to 6.7 dB
 3. Change footnote (b) to read: "...This channel insertion loss may be reduced by up to 0.5 dB depending on ..."
 4. Change footnote (c) to read: "...includes an allocation of 0.1 dB for MPI and 0.2 dB for DGD penalties. For cases with a channel insertion loss less than 3 dB, as shown in Table 180-12, the allocation for penalties should be "6.7 – channel insertion loss".
 Supporting editorial instructions are provided in johnson_3dj_01_2507
 Proposed Response Response Status O

Cl 180 SC 180.7.1 P438 L33 # 16
 Johnson, John Broadcom
 Comment Type TR Comment Status X
 The minimum TX launch power and OMA must be increased by 0.2dB to account for the changes in MPI+DGD penalty allocation in Table 180-9.
 SuggestedRemedy
 In Table 180-7, make the following changes:
 1. Change Average launch power, each lane (min) from -3.3 dBm to -3.1 dBm.
 2. Change Outer Optical Modulation Amplitude (OMA_{outer}), each lane (min) from -0.3 dBm to -0.1 dBm, and from -1.2 + max(TECQ,TDECQ) to -1 + max(TECQ,TDECQ).
 3. Change footnote (b) to read: "An average launch power of -3.1 dBm corresponds to an OMA of -0.1 dBm with an infinite extinction ratio."
 Supporting editorial instructions are provided in johnson_3dj_01_2507
 Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 180 SC 180.7.1 P439 L28 # 17

Johnson, John Broadcom

Comment Type **TR** Comment Status **X**

Figure 180-3 must be updated to correspond to the 0.2 dB increase in OMAouter(min) in Table 180-7.

SuggestedRemedy

Update the OMAouter(min) curve in Figure 180-3 to correspond to the updated values -0.1 dBm and -1 + max(TECQ,TDECQ), with editorial license.

Supporting editorial instructions are provided in johnson_3dj_01_2507

Proposed Response Response Status

Cl 180 SC 180.7.2 P440 L17 # 18

Johnson, John Broadcom

Comment Type **TR** Comment Status **X**

The minimum RX receive power must be increased by 0.2dB to account for the changes in MPI+DGD penalty allocation in Table 180-9.

SuggestedRemedy

In Table 180-8, change Average receive power, each lane (min) from -6.3 dBm to -6.1 dBm.

Supporting editorial instructions are provided in johnson_3dj_01_2507

Proposed Response Response Status

Cl 180 SC 180.7.3 P442 L6 # 19

Johnson, John Broadcom

Comment Type **TR** Comment Status **X**

Figure 180-5 must be updated to correspond to the 0.2 dB increase in TX OMAouter in Table 180-7.

SuggestedRemedy

Update the Transmitter OMAouter(min) curve in Figure 180-5 to correspond to the updated values in Table 180-7, with editorial license.

Supporting editorial instructions are provided in johnson_3dj_01_2507

Proposed Response Response Status

Cl 180 SC 180.8.2 P444 L10 # 20

Johnson, John Broadcom

Comment Type **TR** Comment Status **X**

Update the maximum channel insertion loss Table 180-12 per the updated MPI penalties given in consensus presentation johnson_3dj_01_2505.

SuggestedRemedy

Replace the values of maximum channel insertion loss in Table 180-12 with the new values included in supporting editorial presentation, johnson_3dj_01_2507, slide 7.

Proposed Response Response Status

Cl 181 SC 181.7.3 P465 L32 # 21

Johnson, John Broadcom

Comment Type **TR** Comment Status **X**

The allocation for MPI and DGD penalties of 0.5 dB is too small. It should be increased to 0.4 dB for MPI and 0.2 dB for DGD per consensus presentation johnson_3dj_01_2505.

SuggestedRemedy

In Table 181-7, make the following changes:

1. Change Allocation for penalties (for max TDECQ) from 3.9 dB to 4 dB
2. Change Power budget (max TDECQ) from 7.4 dB to 7.5 dB
3. Replace footnotes b, c and d with new footnotes b and c following the form of Table 180-9, with changes appropriate to CL 181, as given in johnson_3dj_01_2507, slide 6.

Supporting editorial instructions are provided in johnson_3dj_01_2507

Proposed Response Response Status

IE P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

CI 181 SC 181.7.1 P462 L16 # 22

Johnson, John Broadcom

Comment Type TR Comment Status X

The minimum TX launch power and OMA must be increased by 0.1dB to account for the changes in MPI+DGD penalty allocation in Table 181-7.

SuggestedRemedy

In Table 181-5, make the following changes:

1. Change Average launch power, each lane (min) from -2.2 dBm to -2.1 dBm.
2. Change Outer Optical Modulation Amplitude (OMAAouter), each lane (min) from 0.8 dBm to 0.9 dBm, and from -0.1 + max(TECQ,TDECQ) to 0 + max(TECQ,TDECQ).
3. Change footnote (b) to read: "An average launch power of -2.1 dBm corresponds to an OMA of 0.9 dBm with an infinite extinction ratio."

Supporting editorial instructions are provided in johnson_3dj_01_2507

Proposed Response Response Status O

CI 181 SC 181.7.1 P463 L4 # 23

Johnson, John Broadcom

Comment Type TR Comment Status X

Figure 181-3 must be updated to correspond to the 0.1 dB increase in OMAouter(min) in Table 181-5.

SuggestedRemedy

Update the OMAouter(min) curve in Figure 181-3 to correspond to the updated values 0.9 dBm and 0 + max(TECQ,TDECQ), with editorial license.

Supporting editorial instructions are provided in johnson_3dj_01_2507

Proposed Response Response Status O

CI 181 SC 181.7.2 P464 L18 # 24

Johnson, John Broadcom

Comment Type TR Comment Status X

The minimum RX receive power must be increased by 0.1 dB to account for the changes in MPI+DGD penalty allocation in Table 181-7.

SuggestedRemedy

In Table 181-6, change Average receive power, each lane (min) from -5.7 dBm to -5.6 dBm.

Supporting editorial instructions are provided in johnson_3dj_01_2507

Proposed Response Response Status O

CI 181 SC 181.7.3 P466 L6 # 25

Johnson, John Broadcom

Comment Type TR Comment Status X

Figure 181-5 must be updated to correspond to the 0.1 dB increase in TX OMAouter in Table 181-5.

SuggestedRemedy

Update the Transmitter OMAouter(min) curve in Figure 181-5 to correspond to the updated values in Table 181-5, with editorial license.

Supporting editorial instructions are provided in johnson_3dj_01_2507

Proposed Response Response Status O

Cl 181 SC 181.8.2 P467 L48 # 26

Johnson, John Broadcom

Comment Type TR Comment Status X

CL 181.8.2 should be rewritten to mirror the subclause structure and text in CL 180.8.2, with editorial license, including a table of maximum channel insertion loss versus the number of discrete reflections, as discussed in consensus presentation johnson_3dj_01_2505.

SuggestedRemedy

Make the following changes to CL 181.8.2:

1. Re-write CL 181.8.2 using the structure and text in CL 180.8.2, with editorial license.
2. Delete old Table 181-10, Maximum value of each discrete reflectance.
3. Insert new Table 181-xx, Maximum channel insertion loss versus number of discrete reflectances, with the values given in johnson_3dj_01_2507, slide 11.

Supporting editorial instructions are provided in johnson_3dj_01_2507

Proposed Response Response Status O

Cl 181 SC 181.8 P467 L4 # 27

Johnson, John Broadcom

Comment Type TR Comment Status X

Channel insertion loss (max) in Table 181-8 should point to new Table 181-xx.

SuggestedRemedy

In Table 181-8,

1. Replace Channel insertion loss(max) value 3.5dB with "See Table 181-xx".
2. Add text in CL 181.8 similar to CL 180.8: "The maximum value of channel insertion loss is dependent on the number and maximum value of the discrete reflectances within the channel as given in Table 181-xx. Discrete reflectances below -55 dB may be ignored when determining the supported channel insertion loss." with editorial license.

Supporting editorial instructions are provided in johnson_3dj_01_2507

Proposed Response Response Status O

Cl 182 SC 182.7.3 P491 L30 # 28

Johnson, John Broadcom

Comment Type TR Comment Status X

The allocation for MPI and DGD penalties of 0.4 dB is too large. It should be reduced to 0.1 dB for MPI and 0.2 dB for DGD per consensus presentation johnson_3dj_01_2505.

SuggestedRemedy

In Table 182-9, make the following changes:

1. Change Allocation for penalties (for max TDECQ) from 3.8 dB to 3.7 dB
2. Change Power budget (max TDECQ) from 7.8 dB to 7.7 dB
3. Replace footnotes b, c and d with new footnotes b and c following the form of Table 180-9, with changes appropriate to CL 182, as given in johnson_3dj_01_2507, slide 14.

Supporting editorial instructions are provided in johnson_3dj_01_2507

Proposed Response Response Status O

Cl 182 SC 182.7.1 P488 L45 # 29

Johnson, John Broadcom

Comment Type TR Comment Status X

For TX commonality, the minimum TX launch power and OMA must be increased by 0.2dB to align DRn-2 TX launch power with the new values for 500m DRn TX in Table 180-7 as discussed in consensus presentation johnson_3dj_01_2505.

SuggestedRemedy

In Table 182-7, make the following changes:

1. Change Average launch power, each lane (min) from -3.3 dBm to -3.1 dBm.
2. Change Outer Optical Modulation Amplitude (OMA_{outer}), each lane (min) from -0.3 dBm to -0.1 dBm, and from -1.2 + max(TECQ,TDECQ) to -1 + max(TECQ,TDECQ).
3. Change footnote (b) to read: "An average launch power of -3.1 dBm corresponds to an OMA of -0.1 dBm with an infinite extinction ratio."

Supporting editorial instructions are provided in johnson_3dj_01_2507

Proposed Response Response Status O

Cl 182 SC 182.7.1 P489 L36 # 30
 Johnson, John Broadcom
 Comment Type TR Comment Status X
 Figure 182-3 must be updated to correspond to the 0.2 dB increase in OMAouter(min) in Table 182-7.
SuggestedRemedy
 Update the OMAouter(min) curve in Figure 182-3 to correspond to the updated values -0.1 dBm and $1 + \max(\text{TECQ}, \text{TDECQ})$, with editorial license.
 Supporting editorial instructions are provided in johnson_3dj_01_2507
 Proposed Response Response Status

Cl 182 SC 182.7.2 P491 L3 # 32
 Johnson, John Broadcom
 Comment Type TR Comment Status X
 Figure 182-4 must be updated to correspond to the 0.3 dB increases in OMAouter in Table 182-8.
SuggestedRemedy
 Update the Receiver sensitivity (OMAouter) curve in Figure 182-4 to correspond to the updated values in Table 182-4, with editorial license.
 Supporting editorial instructions are provided in johnson_3dj_01_2507
 Proposed Response Response Status

Cl 182 SC 182.7.2 P490 L20 # 31
 Johnson, John Broadcom
 Comment Type TR Comment Status X
 The minimum RX receive power must be increased by 0.2 dB (RX power) and 0.3 dB (RX sensitivity) to account for the changes in MPI+DGD penalty allocation in Table 182-9, as discussed in consensus presentation johnson_3dj_01_2505.
SuggestedRemedy
 In Table 182-8, make the following changes:
 1. Change Average receive power, each lane (min) from -7.3 dBm to -7.1 dBm.
 2. Change Receiver sensitivity (OMAouter), each lane (max) from -4.7 dBm to -4.4 dBm, and from $-5.6 + \text{TECQ}$ to $-5.3 + \text{TECQ}$.
 3. Change Stressed receiver sensitivity (OMAouter), each lane (max) from -2.2 dBm to -1.9 dBm.
 Supporting editorial instructions are provided in johnson_3dj_01_2507
 Proposed Response Response Status

Cl 182 SC 182.7.3 P492 L3 # 33
 Johnson, John Broadcom
 Comment Type TR Comment Status X
 Figure 182-5 must be updated to correspond to the changes in OMAouter in Tables 182-7 and 182-8.
SuggestedRemedy
 Update the Transmitter OMAouter(min) and Receiver OMAouter(max) curves in Figure 182-5 to correspond to the updated values in Table 182-7 and Table 182-8, with editorial license.
 Supporting editorial instructions are provided in johnson_3dj_01_2507
 Proposed Response Response Status

CL 182 SC 182.8.2 P493 L49 # 34

Johnson, John Broadcom

Comment Type TR Comment Status X

CL 182.8.2 should be rewritten to mirror the subclause structure and text in CL 180.8.2, with editorial license, including a table of maximum channel insertion loss versus the number of discrete reflections, as discussed in consensus presentation johnson_3dj_01_2505.

SuggestedRemedy

Make the following changes to CL 182.8.2:

1. Re-write CL 182.8.2 using the structure and text in CL 180.8.2, with editorial license.
2. Delete old Table 182-12, maximum value of each discrete reflectance.
3. Insert new Table 182-xx, Maximum channel insertion loss versus number of discrete reflectances, with the values given in johnson_3dj_01_2507, slide 15.

Supporting editorial instructions are provided in johnson_3dj_01_2507

Proposed Response Response Status

CL 182 SC 182.8 P492 L47 # 35

Johnson, John Broadcom

Comment Type TR Comment Status X

Channel insertion loss (max) in Table 182-10 should point to new Table 182-xx.

SuggestedRemedy

In Table 182-10,

1. Replace Channel insertion loss(max) value 4 dB with "See Table 182-xx".
2. Add text in CL 182.8 similar to text in CL 180.8: "The maximum value of channel insertion loss is dependent on the number and maximum value of the discrete reflectances within the channel as given in Table 182-xx. Discrete reflectances below -55 dB may be ignored when determining the supported channel insertion loss." with editorial license.

Supporting editorial instructions are provided in johnson_3dj_01_2507

Proposed Response Response Status

CL 174A SC 174A.4 P678 L3 # 36

Salvekar, Atul Cadence Design Systems

Comment Type TR Comment Status X

Uncorrelated is iid for Gaussian Distributions. However, I believe this not to be the case generally. I believe the correct term to put is in independent and identically distributed (iid) with a Binomial Distribution.

SuggestedRemedy

Change "If the errors at the input of the RS-FEC are uncorrelated"

to

"If the errors at the input of the RS-FEC are iid with a Binomial Distribution"

Change other places in 174A with editorial discretion.

Proposed Response Response Status

CL 175 SC 175.2.4.10 P272 L13 # 37

Salvekar, Atul Cadence Design Systems

Comment Type ER Comment Status X

Put in Generator Polynomial

SuggestedRemedy

Change "X⁵⁸ scrambler" to "G(x) = 1 + x³⁹ + x⁵⁸"

Proposed Response Response Status

CI 174A SC 174A.8.1.5 P682 L26 # 38

Liu, Cathy Broadcom Inc.

Comment Type T Comment Status X

The assumption of the equation 174A-6 of BER=1/2 of PAM4 symbol error ratio SER is not always true. When pre-coding is applied, or inner hamming decoding is applied, the assumption will not hold which results in the error mask is higher.

SuggestedRemedy

Either we ignore the special cases with pre-coding or inner code decoding, but add a note to clarify the assumption. Or we can apply two cases to the equation 174A-6 as following:
 RSSER = $1 - (1 - 2BER)^5$ for no precoding and inner code decoding; and $RSSER = 1 - (1 - BER)^5$ for precoding or inner code decoding.

Proposed Response Response Status O

CI 176C SC 176C.2 P720 L5 # 39

Liu, Cathy Broadcom Inc.

Comment Type E Comment Status X

The BER_added is defined as 2.841×10^{-4} . It is three-bit decimal. Other places in the document are two-bit decimal.

SuggestedRemedy

Change to 2.84×10^{-4}

Proposed Response Response Status O

CI 176C SC 176C.3 P721 L15 # 40

Liu, Cathy Broadcom Inc.

Comment Type T Comment Status X

The figure 176C-2 has one mated connector illustrated as the C2C channel. The C2C channel could have no connector or up to one connector. The figure might misleading the readers to "must have one connector" for the C2C interconnect.

SuggestedRemedy

Add a note to clarify that the connector is optional.

Proposed Response Response Status O

CI 176D SC 176D.2 P741 L5 # 41

Liu, Cathy Broadcom Inc.

Comment Type E Comment Status X

The BER_added is defined as 2.681×10^{-4} . It is three-bit decimal. Other places in the document are two-bit decimal.

SuggestedRemedy

Change to 2.68×10^{-4}

Proposed Response Response Status O

CI 73A SC 73A.1a P657 L6 # 42

Lusted, Kent Synopsys

Comment Type TR Comment Status X

There are now three CR host loss classes for 200 Gb/s per lane PHYs: HL, HN, HH. For interoperability, a host needs to know the host loss class of the partner to determine if the two host end points can support the inserted cable assemble. The local CR host knows a priori of its host class. The local host also can access the cable assemble class via management means such as CMIS contents inside the plug end. However, the partner's host class remains elusive.

Contribution planned for July session.

SuggestedRemedy

Define two new bits in the Extended FEC and Technology Ability Message code link codeword in location D42:43 as "CR Host Class for 200 Gb/s per lane PHYs". Abbreviated EH0:1

D42	D43	Class
0	0	Host Nominal HN
0	1	Host Loss HL
1	0	Host High HH
1	1	Reserved

change the second paragraphs as follows:

"Extended Technology Ability bits EA0:EA27 map to bits D16:D41 (U0:U25), CR Host Class for 200 Gb/s per lane PHYS D42:D43 (U26:U27) and Extended FEC capability bits EF0:EF3 map to bits D44:D47 (U28:31). Reserved fields are sent as zero and ignored on receive."

Update Table 73A-1a appropriately.

Proposed Response Response Status O

Cl 179B SC 179B.1 P823 L19 # 43

Mellitz, Richard

Samtec

Comment Type TR Comment Status X

Referring to the words "using the equation": The Insertion loss equation uses a complicated set of coefficient powers (eq 179B-3, 4, and 5) which do not appear to be tied to the physics of the test fixture design nor to compliance testing. Measurements of IL at a particular frequency had been demonstrated wander considerably. A fitted insertion loss wanders considerably less.

SuggestedRemedy

Replace line:

"The reference insertion loss of the mated test fixtures is 9.75 dB at 53.125 GHz using Equation (179B-5)"

With:

"The reference fitted insertion loss of the mated test fixtures is 9.75 dB at 53.125 GHz."

This resolution is tied to the comment suggesting the removal of sections 17B.2.1, 179B.3.1, 179B.4.1

In other sections and appendixes, the fit loss at Nyquist shall be used for budgeting test setups.

Proposed Response Response Status

Cl 179B SC 179B.2 P823 L27 # 44

Mellitz, Richard

Samtec

Comment Type TR Comment Status X

The Insertion loss equation uses a complicated set of coefficient powers (eq 179B-1) which do not appear to be tied to the physics of the test fixture design nor to compliance testing

SuggestedRemedy

Replace:

"The TP2 or TP3 test fixture (also known as Host Compliance Board) is required for measuring the transmitter and receiver specifications at TP2 and TP3. The TP2 and TP3 test points are illustrated in Figure 179-2."

with:

The TP2 or TP3 test fixture (also known as Host Compliance Board) is required for measuring the transmitter and receiver specifications at TP2 and TP3. The TP2 and TP3 test points have a normalized signal power between 0.46 and 0.52 V². The fit insertion loss is 3.8 dB.

The normalized signal power (P_{signal}) is calculated according to ### (slide 7 in mellitz_3dj_03_2505") with fb = 106.25 GHz, Tt = 6 ps, and fr = 0.55 × fb over the range fmin = 0.05 GHz to fmax = 67 GHz.

Remove section: 179B.2.1

Proposed Response Response Status

Cl 179B SC 179B.3 P823 L27 # 45

Mellitz, Richard

Samtec

Comment Type TR Comment Status X

The Insertion loss equation uses a complicated set of coefficient powers (eq 179B-2) which do not appear to be tied to the physics of the test fixture design nor to compliance testing.

SuggestedRemedy

Replace:

The cable assembly test fixture (also known as Module Compliance Board) is required for measuring the cable assembly specifications in 179.11 at TP1 and TP4. The TP1 and TP4 test points are illustrated in Figure 179-2.

With:

The TP1 or TP4 test fixture (also known as Host Compliance Board) is required for measuring the transmitter and receiver specifications at TP2 and TP3. The TP2 and TP3 test points have a normalized signal power between 0.41 and 0.47 V². The fit loss is 5.95 dB.

The normalized signal power (P_{signal}) is calculated according to ### (slide 7 in mellitz_3dj_03_2505") with fb = 106.25 GHz, Tt = 6 ps, and fr = 0.55 × fb over the range fmin = 0.05 GHz to fmax = 67 GHz.

Remove section: 179B.3.1

Proposed Response Response Status

CI 179B SC 179B.4 P825 L3 # 46

Mellitz, Richard

Samtec

Comment Type TR Comment Status X

The Insertion loss specification uses a complicated reference line (eq 179B-3, 4, and 5) which does not appear to be tied to the physics of the test fixture design nor to compliance testing measurements. The reason for the 1.5 power term is not defined. The equation was developed as an average of measurements (kocsis_3dj_adhoc_01_250206). The normalized signal power is expected to track performance better than the specified frequency masks and reference lines

SuggestedRemedy

Replace:

“The TP2 or TP3 test fixture and the cable assembly test fixture are specified in a mated state illustrated in Figure 92–18. The mated test fixtures specifications are given below.”

With:

The TP2 or TP3 test fixture and the cable assembly test fixture has a normalized signal power (P_{signal}) of the Insertion loss shall be between 0.31 and $0.34 V^2$. The normalized signal power (P_{signal}) is calculated according to ### (slide 7 in mellitz_3dj_03_2505”) with $f_b = 106.25 \text{ GHz}$, $T_t = 6 \text{ ps}$, and $f_r = 0.55 \times f_b$ over the range $f_{\text{min}} = 0.05 \text{ GHz}$ to $f_{\text{max}} = 67 \text{ GHz}$.

Remove section: 179B.3.1 to line 1 on page 825.

Keep the following lines:

The FOM_ILD and is calculated according to 93A.4 with $f_b = 106.25 \text{ GHz}$, $T_t = 6 \text{ ps}$, and $f_r = 0.55 \times f_b$. The fitted insertion loss and insertion loss deviation are computed over the range $f_{\text{min}} = 0.05 \text{ GHz}$ to $f_{\text{max}} = 67 \text{ GHz}$. FOM_ILD shall be less than or equal to 0.15 dB.

Proposed Response Response Status O

CI 179B SC 179B.4.6 P830 L23 # 47

Mellitz, Richard

Samtec

Comment Type TR Comment Status X

“Total integrated crosstalk noise voltage” and “MDFEXT integrated crosstalk noise voltage” is system use case dependent. Aft is not relevant. See “mellitz_3dj_03_2505”

SuggestedRemedy

Remove “Total integrated crosstalk noise voltage” lines (24)

Add section describing slide 7 on in “mellitz_3dj_03_2505” for SNR_MDFEXT.

Replace:

MDFEXT integrated crosstalk noise voltage (max)

with:

SNR_MDFEXT (min) of 40 dB

(slide 10 in mellitz_3dj_03_2505”)

Proposed Response Response Status O

CI 178 SC 178.9.2.6 P364 L53 # 48

Mellitz, Richard

Samtec

Comment Type TR Comment Status X

SNDR(meas) replaced V_{peak}^2 with P_{signal} . SCMR should be aligned with SNDR(meas) (eq 179-9)

SuggestedRemedy

SNDR(meas) replaced V_{peak}^2 with P_{signal} . SCMR should be aligned with SNDR(meas) (eq 179-9)

Replace equation 178-1 with

$SCMR = 10 \cdot \log_{10}(P_{\text{signal}} / VCM_{\text{FB}}^2)$

In P365 line 4

Replace:

V_{peak} is defined in 179.9.4.1.2

With

P_{signal} is defined in equation 179-8

Proposed Response Response Status O

CI 178 SC 178.10 P370 L44 # 49

Mellitz, Richard

Samtec

Comment Type TR Comment Status X

Channel intrapair skew has not been considered for interoperability. Although a channel skew would be included in s-parameters passed to COM, the effect of skew on interoperability has not been specified. Channel common mode includes skew and other imbalance interoperable effects.

SuggestedRemedy

add line to Table 178–11—Channel characteristics summary

Channel Signal to common mode ratio (SCMR_CH) min 20 dB

Add section based on slides 12 and 14

[https://www.ieee802.org/3/dj/public/adhoc/electrical/23_1207/mellitz_3dj_elec_01_231207.p](https://www.ieee802.org/3/dj/public/adhoc/electrical/23_1207/mellitz_3dj_elec_01_231207.pdf)

df

replacing V_{peak}^2 with σ_{tn}^2 from equation 179.15 with $c(n)=1$ (no TxFFE)

i.e. $SCMR_{\text{CH}} = 10 \cdot \log_{10}(\sigma_{\text{ts}}^2 / VCM_{\text{CH}}^2)$

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

CI 179 SC 179.11 P412 L38 # 50

Mellitz, Richard Samtec

Comment Type TR Comment Status X

Channel intrapair skew has not been considered for interoperability. Although a channel skew would be included in s-parameters passed to COM, the effect of skew on interoperability has not been specified. Channel common mode includes skew and other imbalance interoperable effects.

SuggestedRemedy

add line to Table 179-13—Cable assembly characteristics summary
Channel Signal to common mode ratio (SCMR_CH) min 20 dB
Add section based on slides 12 and 14
https://www.ieee802.org/3/dj/public/adhoc/electrical/23_1207/mellitz_3dj_elec_01_231207.pdf
replacing V_{peak}^2 with σ_{tn}^2 from equation 179.15 with $c(n)=1$ (no TxFFE)
i.e. $SCMR_{CH} = 10 \cdot \log_{10}(\sigma_{ts}^2 / VCM_{CH}^2)$

Proposed Response Response Status O

CI 180A SC 180A P850 L4 # 51

D'Ambrosia, John Futurewei, U.S. Subsidiary of Huawei

Comment Type ER Comment Status X

The title of the Annex is incorrect. This annex only addresses MDIs for the DR family of optics.

SuggestedRemedy

Change title to "MDIs for 200GBASE-DR1, 400GBASE-DR2, 800GBASE-DR4, 1.6TBASE-DR8, 200GBASE-DR1-2, 400GBASE-DR2-2, 800GBASE-DR4-2, and 1.6TBASE-DR8-2"

Proposed Response Response Status O

CI 178B SC 178B.3 P786 L33 # 52

D'Ambrosia, John Futurewei, U.S. Subsidiary of Huawei

Comment Type E Comment Status X

Given the introduction of inter-sublayer link training to the Ethernet world, it would be helpful if the term inter-sublayer link (ISL) was displayed graphically for the reader.

SuggestedRemedy

Implement figure on Page 3 of
https://www.ieee802.org/3/dj/public/adhoc/electrical/25_0605/dambrosia_3dj_elec_02_250605.pdf with editorial license

Proposed Response Response Status O

CI 116 SC 116.2.9 P155 L155 # 53

D'Ambrosia, John Futurewei, U.S. Subsidiary of Huawei

Comment Type TR Comment Status X

This subclause mistakenly notes ILT for PHY types solely based on what the PMD can do. A PHY may also support ILT if using 200Gb/s based AUIs or the physical layer can support ILT if an extender based on a 200 Gb/s AUI is used. The same is also true for 169.2.10, and 174.2.12

SuggestedRemedy

Implement language on Page 6 of
https://www.ieee802.org/3/dj/public/adhoc/electrical/25_0605/dambrosia_3dj_elec_02_250605.pdf with editorial license for each of the subclauses noted.

Proposed Response Response Status O

CI 178B SC 178B.5.2 P789 L2 # 54

Jones, Chad Cisco Systems, Inc.

Comment Type E Comment Status X

Use of the word guarantee, in two places. This will likely be flagged during MEC. Staff review will likely recommend this replaced with "helps ensure".

SuggestedRemedy

change "guarantees" to "helps ensure" in two places on lines 2 and 3.

Proposed Response Response Status O

CI 178B SC 178B.14.2.1 P804 L15 # 55

Jones, Chad Cisco Systems, Inc.

Comment Type E Comment Status X

Use of the work avoid. This will likely be flagged during MEC. Staff review would likely recommend to replace with "help reduce".

SuggestedRemedy

change "avoid" to "help reduce".

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 73 SC 73.4.1 P129 L26 # 56
 Jones, Chad Cisco Systems, Inc.
 Comment Type E Comment Status X
 Use of "may".
 SuggestedRemedy
 replace "may be" with "are".
 Proposed Response Response Status O

Cl 169 SC 169.2.9 P190 L25 # 57
 Jones, Chad Cisco Systems, Inc.
 Comment Type E Comment Status X
 Use of "may".
 SuggestedRemedy
 change "may optionally support" to "optionally supports"
 Proposed Response Response Status O

Cl 174 SC 174.2.11 P250 L26 # 58
 Jones, Chad Cisco Systems, Inc.
 Comment Type E Comment Status X
 Use of "may".
 SuggestedRemedy
 change "may optionally support" to "optionally supports"
 Proposed Response Response Status O

Cl 178 SC 178.9.2.1.2 P363 L45 # 59
 Mellitz, Richard Samtec
 Comment Type TR Comment Status X
 ERL impedance should be aligned to Rd and 179B.
 SuggestedRemedy
 Add line:
 The reference differential impedance for the test fixture ERL computation shall be 92.5 ohms.
 Proposed Response Response Status O

Cl 179 SC 179.9.4.7 P403 L23 # 60
 Mellitz, Richard Samtec
 Comment Type TR Comment Status X
 ERL impedance should be aligned to Rd and 179B.
 SuggestedRemedy
 Add line:
 The reference differential impedance for the test fixture ERL computation shall be 92.5 ohms.
 Proposed Response Response Status O

Cl 179 SC 179.11.3 P412 L11 # 61
 Mellitz, Richard Samtec
 Comment Type TR Comment Status X
 ERL impedance should be aligned to Rd and 179B.
 SuggestedRemedy
 Add line:
 The reference differential impedance for the test fixture ERL computation shall be 92.5 ohms.
 Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

CI 176C SC 176C.6.3.5 P726 L38 # 62

Mellitz, Richard Samtec

Comment Type TR Comment Status X

ERL impedance should be aligned to Rd and 179B.

SuggestedRemedy

Add line:
The reference differential impedance for the test fixture ERL computation shall be 92.5 ohms.

Proposed Response Response Status O

CI 178 SC 178.9.1 P361 L43 # 63

Mellitz, Richard Samtec

Comment Type TR Comment Status X

The reference impedance for measurement should align with the test fixture reference.

SuggestedRemedy

Change line to:

The reference impedance for differential specifications is 92.5 ohms. The reference impedance for common-mode specifications is 23.125 ohms.

Proposed Response Response Status O

CI 179 SC 179.9.3 P393 L40 # 64

Mellitz, Richard Samtec

Comment Type TR Comment Status X

The reference impedance for measurement should align with the test fixture reference.

SuggestedRemedy

Change line to:

The reference impedance for differential specifications is 92.5 ohms. The reference impedance for common-mode specifications is 23.125 ohms.

Proposed Response Response Status O

CI 179 SC 179.11.1 P412 L47 # 65

Mellitz, Richard Samtec

Comment Type TR Comment Status X

The reference impedance for measurement should align with the test fixture reference.

SuggestedRemedy

Change line to:

The reference impedance for differential specifications is 92.5 ohms. The reference impedance for common-mode specifications is 23.125 ohms.

Proposed Response Response Status O

CI 176C SC 176C.6.2 P723 L18 # 66

Mellitz, Richard Samtec

Comment Type TR Comment Status X

The reference impedance for measurement should align with the test fixture reference.

SuggestedRemedy

Change line to:

The reference impedance for differential specifications is 92.5 ohms. The reference impedance for common-mode specifications is 23.125 ohms.

Proposed Response Response Status O

CI 119 SC 119.2.4.1 P174 L52 # 67

Bruckman, Leon Nvidia

Comment Type ER Comment Status X

Missing dot

SuggestedRemedy

Add a dot at the end of the phrase (after "payload")

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 119 SC 119.3.1 P177 L20 # 68
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 Bin counters are defined for 1 to 15 errors, no bin for 0 errors. In 45.2.1.264 the PMA test block error bin counters are defined for 0 to 15.
SuggestedRemedy
 Define the FEC codeword error bin counters to be 0 to 15 errors
 Proposed Response Response Status

Cl 175 SC 175.2.5.3 P273 L50 # 71
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 There may be undetected errors
SuggestedRemedy
 Change: "errors that were not corrected"
 to: "errors that were detected but not corrected"
 Proposed Response Response Status

Cl 175 SC 175.1.3 P261 L10 # 69
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 "FEC degrade detection and signaling" is an optional function (see 175.3), no need to list it here. It is not listed in similar sections in 802.3df (88GBASE-R PCS) or the base standard (200G/400GBASE-R PCS)
SuggestedRemedy
 Either delete the bullet: FEC degrade detection and signaling
 Or add: (optional) to the end of the text for this bullet
 Proposed Response Response Status

Cl 175 SC 175.2.6.2.2 P276 L20 # 72
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 The behavior of hi_ser is specified in 175.2.5.3. No need to detail it in the variables definitions.
SuggestedRemedy
 Change the definition of hi_ser to: "Boolean variable that is set to true if hi_ser is asserted (see 172.2.5.3). Otherwise, this variable is set to false."
 Proposed Response Response Status

Cl 175 SC 175.2.1 P263 L10 # 70
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 PMA is also a sublayer, and inner FEC shall be capitalized
SuggestedRemedy
 Change: "PMA or inner FEC sublayer" to: "PMA or Inner FEC sublayers"
 And in line 13 change: "inner FEC" to "Inner FEC"
 Proposed Response Response Status

Cl 175 SC 175.2.6.2.4 P277 L17 # 73
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 The text of the definition of this counter is different from the one in 119.2.6.2.4
SuggestedRemedy
 Change the definition of amp_counter to: "This counter counts the interval of 32768 FEC codewords containing normal alignment marker payload sequences."
 Proposed Response Response Status

Cl 176 SC 176.1.4 P290 L35 # 74
 Bruckman, Leon Nvidia
 Comment Type TR Comment Status X
 Not all functions are required in all cases described in this clause, but specific restrictions are only indicated for: Delay alternating PCSLs by two RS-FEC codewords
 SuggestedRemedy
 If this is a list of general function that are not necessarily needed in all cases then delete: "for 200GBASE-R and 400GBASE-R PMAs".
 If it is a full list with restrictions then indicate for which cases each function is used according to the relevant sections.
 Proposed Response Response Status O

Cl 176 SC 176.1.5 P291 L23 # 75
 Bruckman, Leon Nvidia
 Comment Type TR Comment Status X
 In tables 176-1 and 176-2 no need for a foot note to limit the xAUI-m to a single value.
 SuggestedRemedy
 In tables 176-1 and 176-2 change: xAUI-m instances that are tagged with the footnote "a" to 1.6TAUI-16 and remove footnote
 Proposed Response Response Status O

Cl 176 SC 176.2 P292 L51 # 76
 Bruckman, Leon Nvidia
 Comment Type TR Comment Status X
 Inconsistent naming with the paragraphs above. See similar paragraph in section 176.3 (page 294 line 8)
 SuggestedRemedy
 Change: "from the sublayer above the PMA" to: "from the client sublayer"
 Proposed Response Response Status O

Cl 176 SC 176.3 P294 L12 # 77
 Bruckman, Leon Nvidia
 Comment Type TR Comment Status X
 It is not clear which SIGNAL_OK is being considered. In the similar paragraph of section 176.2 the description is more detailed.
 SuggestedRemedy
 Change: "the received SIGNAL_OK value."
 to: "the received SIGNAL_OK parameter from the sublayer above the PMA (PMA:IS_SIGNAL.request(SIGNAL_OK))."
 Proposed Response Response Status O

Cl 176 SC 176.4.1 P296 L8 # 78
 Bruckman, Leon Nvidia
 Comment Type TR Comment Status X
 Missing arrowhead
 SuggestedRemedy
 Add the arrowhead to the input to the PAM4 decode process
 Proposed Response Response Status O

Cl 176 SC 176.4.2.3.1 P298 L3 # 79
 Bruckman, Leon Nvidia
 Comment Type TR Comment Status X
 The same information is provided in the text and in the equations below
 SuggestedRemedy
 Delete: "For the 200GBASE-R 8:1 PMA, it equals $N \times 272$ RS-FEC symbols, and for the 400GBASE-R 16:2 PMA, it equals $N \times 136$ RS-FEC symbols, where N is an integer."
 After the bullets add this text: "where N is an integer."
 Proposed Response Response Status O

Cl 176 SC 176.4.3.2 P305 L16 # 80
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 In the receive function there are processes not steps
 SuggestedRemedy
 Change: "to the next steps" to: "to the next steps processes"
 Proposed Response Response Status

Cl 176 SC 176.7.2 P316 L28 # 81
 Bruckman, Leon Nvidia
 Comment Type **ER** Comment Status **X**
 Missing word
 SuggestedRemedy
 Change: "When local loopback mode enabled" to: "When local loopback mode is enabled"
 Proposed Response Response Status

Cl 177 SC 177.1.3 P326 L7 # 82
 Bruckman, Leon Nvidia
 Comment Type **E** Comment Status **X**
 The convolutional interleaver is "a convolutional interleaver"
 SuggestedRemedy
 Change: "using the convolutional interleaver" to: "using a convolutional interleaver"
 Proposed Response Response Status

Cl 177 SC 177.2 P328 L21 # 83
 Bruckman, Leon Nvidia
 Comment Type **ER** Comment Status **X**
 Different language used in adjacent paragraphs. In the first paragraph: ", the tx_symbol parameters are undefined." and in the next paragraph: "the corresponding rx_symbol parameters on all lanes are unspecified."
 SuggestedRemedy
 Use similar language in both paragraphs.
 Make same change in the two last paragraphs of 177.3
 Proposed Response Response Status

Cl 177 SC 177.4.2 P331 L30 # 84
 Bruckman, Leon Nvidia
 Comment Type **E** Comment Status **X**
 Missing word
 SuggestedRemedy
 Change: "The data from deskewed PMA lane" to: "The data from a deskewed PMA lane"
 Proposed Response Response Status

Cl 177 SC 177.4.7.3 P336 L4 # 85
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 The bit pair interleaving function for the pad field is not described.
 SuggestedRemedy
 Add section describing the bit-pair interleaving function shown in figure 177-8. Something in the lines of: "After Inner FEC encoding, the eight pad flows of Inner FEC codewords shall be multiplexed together as described in 177.4.6".
 Also refer to comment against the figures in Clause 177 vs the ones in Annex 177A regarding the pad insertion function location.
 Proposed Response Response Status

Cl 177 SC 177.5.2 P337 L9 # 86
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 The pad field is not used to frame the data stream in the state diagram shown in Figure 177-10.
SuggestedRemedy
 Change: "The eight codewords inserted as pad (see 177.4.7) are used to frame the data stream and are then removed before the received data is processed further."
 To: "The eight codewords inserted as pad (see 177.4.7) are then identified and removed before the received data is processed further."
 Proposed Response Response Status

Cl 177 SC 177.5.5 P339 L11 # 87
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 There is no mention regarding when are the 8 parity bits removed
SuggestedRemedy
 Add to the end of the section: "Parity bits are then removed from each Inner FEC codeword"
 Proposed Response Response Status

Cl 177 SC 177.5.8 P339 L26 # 88
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 The convolutional interleaver function is not trivial. Needs a more detailed description
SuggestedRemedy
 Add a figure that describes the convolutional deinterleaver (refer to 184.5.8)
 Proposed Response Response Status

Cl 177 SC 177.6.1.1 P339 L44 # 89
 Bruckman, Leon Nvidia
 Comment Type **ER** Comment Status **X**
 Missing "the"
SuggestedRemedy
 Change: "is processed by Inner FEC sublayer" to: "is processed by the Inner FEC sublayer"
 Proposed Response Response Status

Cl 177 SC 177.6.2.3 P340 L41 # 90
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 This checker is not shown in Figure 177-2.
SuggestedRemedy
 Add the PRBS31 encoded by Inner FEC test pattern checker location in Figure 177-2.
 Proposed Response Response Status

Cl 178 SC 178.1 P357 L1 # 91
 Bruckman, Leon Nvidia
 Comment Type **ER** Comment Status **X**
 Table 178-4 footnotes are in the next page
SuggestedRemedy
 Make sure the footnotes of Table 178-4 are in the same page with their correspondent table.
 Proposed Response Response Status

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

CI 178 SC 178.8.1 P360 L24 # 92
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 The ILT function and SIGNAL_OK handling is missing. In the optical PMDs appears in the block diagram figures
 SuggestedRemedy
 In Figure 178-2 add the ILT function above the PMD transmit and receive functions. Show the SIGNAL_OK as an input to the ILT function at the left side and as an output to the ILT function in the right side (refer for example to Figure 180-2)
 Apply also to Figure 179-2.
 Proposed Response Response Status **O**

CI 183 SC 183.1 P505 L48 # 93
 Bruckman, Leon Nvidia
 Comment Type **ER** Comment Status **X**
 Wrong singular in note c
 SuggestedRemedy
 In note c change: "If one or two 800GAUI-n is implemented"
 To: "If one or two 800GAUI-n are implemented"
 Proposed Response Response Status **O**

CI 184 SC 184.5.8 P544 L12 # 94
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 This section describes the deinterleaver, not the interleaver
 SuggestedRemedy
 Change: "the convolutional interleaver process" to: "the convolutional deinterleaver process"
 Proposed Response Response Status **O**

CI 185 SC 185.1 P556 L45 # 95
 Bruckman, Leon Nvidia
 Comment Type **ER** Comment Status **X**
 Wrong singular in note c
 SuggestedRemedy
 In note c change: "If one or two 800GAUI-n is implemented"
 To: "If one or two 800GAUI-n are implemented"
 Proposed Response Response Status **O**

CI 185 SC 185.6 P563 L51 # 96
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 An 800GBASE-LR1 PMD that supports 10Km is obviously complaint sinc ethis is the requirement
 SuggestedRemedy
 Change: "could operate over 10 km would meet the operating range requirement of 2 m to 10 km"
 To: "could operate over 12 km would meet the operating range requirement of 2 m to 10 km"
 Proposed Response Response Status **O**

CI 186 SC 186.2.3.3 P584 L24 # 97
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 In Figure 186-4 it is hard to identify the 5 bits of pad
 SuggestedRemedy
 In Figure 186-4 label the 5 bits of pad in the payload area
 Proposed Response Response Status **O**

Cl 186 SC 186.2.3.3 P584 L47 # 98
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 The contents of the 5 bits of pad during test are ambiguous. Are these bits removed or do they carry test data ? This is defined later on in section 186.2.3.12, but better have it clear from the beginning
 SuggestedRemedy
 Change: "there is no 5-bit pad following the OH field"
 To: "the 5-bit pad following the OH field carry test data"
 Proposed Response Response Status **O**

Cl 186 SC 186.2.3.5.9 P589 L2 # 99
 Bruckman, Leon Nvidia
 Comment Type **ER** Comment Status **X**
 Text in this paragraph can be improved
 SuggestedRemedy
 Change: "the test pattern is generated using the clock for the 800GBASE-ER1 tributary frame"
 To "the test pattern is generated using the same clock as the one used to generate the 800GBASE-ER1 tributary frame"
 Proposed Response Response Status **O**

Cl 186 SC 186.2.3.5.10 P589 L10 # 100
 Bruckman, Leon Nvidia
 Comment Type **ER** Comment Status **X**
 Missing "the"
 SuggestedRemedy
 Change: "by 800GBASE-ER1 FEC" to "by the 800GBASE-ER1 FEC"
 Proposed Response Response Status **O**

Cl 186 SC 186.2.4.6.1 P595 L40 # 101
 Bruckman, Leon Nvidia
 Comment Type **ER** Comment Status **X**
 Strange character
 SuggestedRemedy
 Change: "multiOframe" to "multi-frame"
 Proposed Response Response Status **O**

Cl 186 SC 186.2.4.9.3 P597 L32 # 102
 Bruckman, Leon Nvidia
 Comment Type **ER** Comment Status **X**
 Inconsistent language
 SuggestedRemedy
 Change: "If the alignment marker location feature is supported (FEC_alignment_marker_location_ability is set to 1) and is enabled by the FEC control variable FEC_alignment_marker_location_enable (set to 1),"
 To: "If the alignment marker location feature is supported (FEC_alignment_marker_location_ability is set to 1) and is enabled (FEC control variable FEC_alignment_marker_location_enable is set to 1),"
 Proposed Response Response Status **O**

Cl 187 SC 187.5.1 P634 L31 # 103
 Bruckman, Leon Nvidia
 Comment Type **ER** Comment Status **X**
 Text can be improved to be consistent with other similar PMD clauses
 SuggestedRemedy
 Change: "A block diagram for the transmit/receive paths is shown in Figure 187-3 and a block diagram of the PMD is shown in Figure 187-4." to "Thetransmit/receive paths block diagram is shown in Figure 187-3 and the PMD block diagram is shown in Figure 187-4."
 Proposed Response Response Status **O**

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 187 SC 187.6 P637 L54 # 104
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 An 800GBASE-ER1 PMD that supports 40Km is obviously complaint sinc ethis is the requirement
 SuggestedRemedy
 Change: "could operate over 40 km would meet the operating range requirement of 2 m to 40 km"
 To: "could operate over 45 km would meet the operating range requirement of 2 m to 40 km"
 Proposed Response Response Status **O**

Cl 174A SC 174A.3 P677 L44 # 105
 Bruckman, Leon Nvidia
 Comment Type **ER** Comment Status **X**
 The note regarding FLR is repeated several times
 SuggestedRemedy
 Remove the notes regarding the FLR not being normative for any sublayer. Add a general sentence at the end of 74A.2 with the note's text.
 Proposed Response Response Status **O**

Cl 174A SC 174A.5 P678 L10 # 106
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 A figure will make this much more clear
 SuggestedRemedy
 Add a figure to show the link in 174A.5, 174A.6 and 174A.7
 Proposed Response Response Status **O**

Cl 174A SC 174A.8.1.3 P681 L18 # 107
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 In Hm(i)(k) it is not clear what m represents.
 SuggestedRemedy
 Define "m"
 Proposed Response Response Status **O**

Cl 174A SC 174A.9 P683 L17 # 108
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 This section is not about 200GBASE-LR1
 SuggestedRemedy
 Change: "200GBASE-LR1" to "800GBASE-LR1"
 Proposed Response Response Status **O**

Cl 176C SC 176C.6.3.1 P724 L35 # 109
 Bruckman, Leon Nvidia
 Comment Type **TR** Comment Status **X**
 There is no Type E defined in Annex 178B
 SuggestedRemedy
 Change: "Type E"
 to: "Type E1"
 Proposed Response Response Status **O**

CI 177A SC 177A P765 L46 # 110

Bruckman, Leon Nvidia

Comment Type TR Comment Status X

Figure 177A-1 shows the pad insertion in a different position than Figure 177-2

SuggestedRemedy

Make the figures consistent.
Either move the pad insertion in Figure 177-2 to be before the Inner FEC encoder, or move it in Figure 177A-1 to be after the 8:1 PAM4 interleaver block

Proposed Response Response Status O

CI 178B SC 178B.8 P797 L20 # 111

Bruckman, Leon Nvidia

Comment Type TR Comment Status X

The ILT bit is not used anyway in Annex 178B.

SuggestedRemedy

Change bit 14 in the status field in Tables 178B-4 and 178B-5 to "Reserved"

Proposed Response Response Status O

CI 178B SC 178B.3 P786 L36 # 112

Mascitto, Marco Nokia

Comment Type E Comment Status X

The ISL should be defined as the link between two adjacent sublayers and excludes the sublayers themselves. ISLs can be between two adjacent sublayers in the same Physical layer implementation (e.g., connecting PMAs in a single PHY) or between adjacent sublayers in two autonomous systems (e.g., connecting the two PHY PMDs via a medium).

SuggestedRemedy

Replace "The ISL may be an xAUI-n between a pair of PMA sublayers within the same Physical Layer implementation or a pair of PMDs and the medium between"

with

"The ISL may be an xAUI-n between a pair of PMA sublayers within the same PHY. The ISL may be an MDI between a pair of PMD sublayers, each of which is instantiated in separate PHYs".

Proposed Response Response Status O

CI 178B SC 178B.3 P786 L41 # 113

Mascitto, Marco Nokia

Comment Type E Comment Status X

The second sentence might be too short and risks causing confusion.

SuggestedRemedy

Replace "For a PMD this term is equivalent to link partner"

with

"In the case where the ISL is an MDI between two PMDs, this term is equivalent to link partner".

Proposed Response Response Status O

CI 178B SC 178B.4 P786 L52 # 114

Mascitto, Marco Nokia

Comment Type E Comment Status X

It is unclear if "former" and "latter" refer to "one or two instantiated interfaces" or to "PMD or AUI components" in the next statements. Suggest removing text to improve clarity.

SuggestedRemedy

Delete "[...] specifically PMD or AUI components" from sentence.

Proposed Response Response Status O

CI 178B SC 178B.3 P786 L38 # 115

Mascitto, Marco Nokia

Comment Type E Comment Status X

Add single and multi-ISL definition here to help with 178B.5.

SuggestedRemedy

Add: "A single-ISL path comprises exactly two sublayers connected by a single ISL. A multi-ISL path comprises three or more sublayers connected in series by ISLs".

Proposed Response Response Status O

CI 178B SC 178B.5 P787 L39 # 116

Mascitto, Marco

Nokia

Comment Type E Comment Status X

Improve clarity.

SuggestedRemedy

Replace: "ILT enables independent ISL training in a multi-ISL path that includes AUI components and PMDs. It also supports operation over paths that include ISLs that do not implement ILT".

With

"ILT supports independent training of ISLs in a multi-ISL path. ILT also operates over paths that include ISLs that do not support ILT".

Proposed Response Response Status O

CI 178B SC 178B.5.1 P788 L13 # 117

Mascitto, Marco

Nokia

Comment Type E Comment Status X

Improve clarity.

SuggestedRemedy

Replace "Local variables are sent to the peer interface via the training frames. Remote variables are received from the peer interface"

with

"Peer interfaces send local variables and receive remote variables via the training frames".

Proposed Response Response Status O

CI 178B SC 178B.5.1 P788 L16 # 118

Mascitto, Marco

Nokia

Comment Type E Comment Status X

In this subclause, I assume we are describing the interface behavior of Inter-sublayer Links (ISLs) and not the behavior of the overall ILT path from PCS to PCS (or XS to XS). If this assumption is correct, use of the term "device" is confusing.

SuggestedRemedy

Replace the word "device" with "sublayer".

Proposed Response Response Status O

CI 178B SC 178B.5.3 P789 L47 # 119

Mascitto, Marco

Nokia

Comment Type E Comment Status X

Subclause 178B.3 defines Path as the series of all ISLs between the two PCSs (or XSs), so use of "PCS to PCS path" or "main path" may cause confusion (as it suggests something different). I was thinking about suggesting a rename of "Path" to "ILT Path" to emphasize the end-to-end scope. Not sure if that is any better.

SuggestedRemedy

Replace "PCS to PCS path" and "main path" with "path".

Proposed Response Response Status O

CI 178B SC 178B.8.5 P799 L1 # 120

Mascitto, Marco

Nokia

Comment Type E Comment Status X

Consistently use "1" for boolean true and "0" for boolean false.

SuggestedRemedy

Replace "[...] and is not set to one" with "and is not set to 1".

Proposed Response Response Status O

CI 178B SC 178B.10 P799 L50 # 121
 Mascitto, Marco Nokia
 Comment Type T Comment Status X
 If this note is making reference to an ISL that can be administratively disabled by system management, this should not be allowed. See my comment regarding page 804, line 18.
 SuggestedRemedy
 Do not allow management control of ILT for ISLs required to support it.
 Proposed Response Response Status O

CI 178B SC 178B.3 P786 L25 # 124
 Mascitto, Marco Nokia
 Comment Type E Comment Status X
 You define terms in this subclause but named the subclause "Conventions". Why not be consistent with 802.3-2022 and rename it "Definitions"?
 SuggestedRemedy
 Rename subclause "Definitions".
 Proposed Response Response Status O

CI 178B SC 178B.13 P802 L47 # 122
 Mascitto, Marco Nokia
 Comment Type E Comment Status X
 Consistently use "1" for boolean true and "0" for boolean false.
 SuggestedRemedy
 Replace "[...] transmitted training frames is set to one" with "transmitted training frames is set to 1".
 Proposed Response Response Status O

CI 178B SC 178B.14.2.1 P804 L15 # 125
 Mascitto, Marco Nokia
 Comment Type E Comment Status X
 Could be clearer.
 SuggestedRemedy
 Replace NOTE with the following text, "There is no specified time limit for ILT to complete. ILT should be restarted if there is an indication of an unrecoverable fault or a livelock situation. The definition of unrecoverable fault is beyond the scope of this annex".
 Proposed Response Response Status O

CI 178B SC 178B.14.2.1 P803 L46 # 123
 Mascitto, Marco Nokia
 Comment Type E Comment Status X
 This is not very clear. I would suggest adding the definition of "adjacent service interface" in subclause 178B.3.
 SuggestedRemedy
 I would suggest adding the definition of "adjacent service interface" to subclause 178B.3 and referencing a diagram, like the one on Slide 3 of "Making Sense out of ILT" (J. D'Ambrosia, M. Brown, 802.3dj Joint Ad hoc Mtg - 05 Jun 2025).
 Adjacent service interface
 The service interface adjoining a PMD or AUI component to a PMA.
 Proposed Response Response Status O

CI 178B SC 178B.14.2.1 P804 L18 # 126
 Mascitto, Marco Nokia
 Comment Type T Comment Status X
 It is my understanding that ILT is mandatory for all ISLs that make use of one or more 200 Gb/s lanes. These links will come up (i.e., tx_mode = data) IFF ILT completes successfully. I cannot envision a use case where ILT would be administratively disabled by system management (but do see the need to mr_restart, of course). Having the ability to disable ILT on these ISLs opens the door to operator misconfiguration, confusion during deployments, and reduces the plug-n-play value of 802.3 interfaces. It gets even more complicated if we consider the case of the multi-ISL path.
 SuggestedRemedy
 Do not allow management control of ILT for ISLs required to support it.
 Proposed Response Response Status O

CI 178B SC 178B.14.2.1 P804 L27 # 127
 Mascitto, Marco Nokia
 Comment Type E Comment Status X
 Clarify "device".
 SuggestedRemedy
 Replace "Boolean variable that controls the resetting of the device" with "Boolean variable that controls the global resetting of the ILT per-interface state machines".
 Proposed Response Response Status O

CI 178B SC 178B.14.3 P805 L51 # 128
 Mascitto, Marco Nokia
 Comment Type E Comment Status X
 Missing "state machines".
 SuggestedRemedy
 Replace "An AUI component or PMD implements one instance of each of the Training control and the Training frame lock, and their associated variables[...]" with "An AUI component or PMD implements one instance of each of the Training control and the Training frame lock state machines, and their associated variables[...]."
 Proposed Response Response Status O

CI 178B SC 178B.14.3 P806 L1 # 129
 Mascitto, Marco Nokia
 Comment Type E Comment Status X
 Replace instances of "state diagram" with "state machine".
 SuggestedRemedy
 Replace "E1 interfaces also implement one instance of the Coefficient update state diagram and its associated variables and functions independently for each of the n physical lanes. For O1 interfaces, this diagram and its associated variables and functions are not used" with "E1 interfaces also implement one instance of the Coefficient update state machine and its associated variables and functions independently for each of the n physical lanes. For O1 interfaces, this state machine and its associated variables and functions are not used".
 Proposed Response Response Status O

CI 178B SC 178B.14.3.5 P809 L26 # 130
 Mascitto, Marco Nokia
 Comment Type E Comment Status X
 These state diagrams inherit the variables, functions, and timers previously defined in 178B.14.2. There should be a statement to that effect.
 SuggestedRemedy
 Replace the first sentence with, "The training control state diagram (Figure 178B-8) defines the operation of ILT for AUI components and PMDs, and makes use of the per-interface state diagram definitions (178B.14.2) and per-lane state diagram definitions (178B.14.3)".
 Proposed Response Response Status O

CI 178B SC 178B.16.1 P815 L7 # 131
 Mascitto, Marco Nokia
 Comment Type E Comment Status X
 Include complete title of annex. Forgot "optical".
 SuggestedRemedy
 Replace first sentence with, "The supplier of a protocol implementation that is claimed to conform to Annex 178B, Inter-sublayer link training for electrical and optical interfaces, shall complete the following protocol implementation conformance statement (PICS) proforma".
 Proposed Response Response Status O

CI 178B SC 178B.16.2.2 P815 L36 # 132
 Mascitto, Marco Nokia
 Comment Type E Comment Status X
 Include complete title of annex. Forgot "optical".
 SuggestedRemedy
 Replace with "IEEE Std 802.3dj-202x, Annex 178B, Inter-sublayer link training for electrical and optical interfaces".
 Proposed Response Response Status O

CI 178B SC 178B.16.3 P816 L18 # 133
 Mascitto, Marco Nokia
 Comment Type E Comment Status X
 Syntax error.
 SuggestedRemedy
 Replace "O<1>" with "O.1" per C21. Apply change to IL7 through IL10, and IL12 through IL16.
 Proposed Response Response Status O

CI 180 SC 180.8.3 P444 L47 # 134
 Parsons, Earl CommScope
 Comment Type T Comment Status X
 The phrase "option to connect to a single fiber MDI" is incorrect since there are two fibers in that MDI.
 SuggestedRemedy
 Change "For 200GBASE-DR1, besides the option to connect to a single fiber MDI, there are two additional specified MDI optical receptacles, a single-row 12-fiber interface and a single-row 16 fiber interface."
 to
 "For 200GBASE-DR1, besides the option to connect to an MDI with two fibers, there are two additional specified MDI optical receptacles, a single-row 12-fiber interface and a single-row 16 fiber interface."
 Proposed Response Response Status O

CI 182 SC 182.8.3 P494 L52 # 135
 Parsons, Earl CommScope
 Comment Type T Comment Status X
 The phrase "option to connect to a single fiber MDI" is incorrect since there are two fibers in that MDI.
 SuggestedRemedy
 Change "For 200GBASE-DR1, besides the option to connect to a single fiber MDI, there are two additional specified MDI optical receptacles, a single-row 12-fiber interface and a single-row 16 fiber interface."
 to
 "For 200GBASE-DR1, besides the option to connect to an MDI with two fibers, there are two additional specified MDI optical receptacles, a single-row 12-fiber interface and a single-row 16 fiber interface."
 Proposed Response Response Status O

CI 179B SC 179B.4.1 P825 L11 # 136
 Noujeim, Leesa Google
 Comment Type TR Comment Status X
 Spread between Idd_MTFmin and Idd_MTFmax curves is too large
 SuggestedRemedy
 shift the min curve down and the max curve up, especially in 40-60GHz region
 Proposed Response Response Status O

CI 174A SC 174A.8.1.5 P682 L23 # 137
 Noujeim, Leesa Google
 Comment Type T Comment Status X
 Eqn 174A.5 is derived from randomly distributed error probabilities (at the specified BER) and so makes no allowance for burstiness of errors; this results in unreasonably tight mask limits especially for the higher bins.
 SuggestedRemedy
 Adjust the mask to increase the allowed ratio in bins 8-15, and reduce in bins ~1-4 accordingly
 Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 179 SC 179.11 P412 L29 # 138
 Noujeim, Leesa Google
 Comment Type **TR** Comment Status **X**
 Iddmin is unreasonably high.
 SuggestedRemedy
 Change 16dB to 13dB
 Proposed Response Response Status **O**

Cl 176D SC 176D.6.6 P747 L35 # 141
 Hidaka, Yasuo Credo Semiconductor, Inc.
 Comment Type **T** Comment Status **X**
 Module input specification should refer to TP1, not TP1a.
 SuggestedRemedy
 Change TP1a to TP1 in the caption of Table 176D-5.
 Proposed Response Response Status **O**

Cl 179 SC 179.11.3 P413 L8 # 139
 Noujeim, Leesa Google
 Comment Type **T** Comment Status **X**
 ERL calculation shouldn't de-embed to just before mating interface; this language was inherited from adjustment of HCB, but doesn't apply to CATF in the same way. CA ERL should include the connector and launch but this would be removed with the definition of Tfx currently in the draft
 SuggestedRemedy
 Reword to remove reference to the mating interface discontinuity; Tfx should include the RF test connector only.
 Proposed Response Response Status **O**

Cl 176D SC 176D.8.2 P752 L29 # 142
 Hidaka, Yasuo Credo Semiconductor, Inc.
 Comment Type **T** Comment Status **X**
 ERL definition in 93A.5 needs a parameter M that is not defined in Table 176D-8, because M is not used in COM definition in Annex 178A.
 SuggestedRemedy
 Add M to Annex 178A in the same way as Annex 93A and to all related tables that refer Annex 178A.
 Proposed Response Response Status **O**

Cl 176D SC 176D.7.2 P749 L51 # 140
 Hidaka, Yasuo Credo Semiconductor, Inc.
 Comment Type **T** Comment Status **X**
 tau^(h) value of 5.97x10⁽⁻³⁾ in Table 176D-6 seems a typo of 5.79x10⁽⁻³⁾. It is 5.79x10⁽⁻³⁾ in Table 179-16 and lim_3dj_01a_2409, slide 2.
 SuggestedRemedy
 Change 5.97x10⁽⁻³⁾ to 5.79x10⁽⁻³⁾.
 Proposed Response Response Status **O**

Cl 181 SC 181.7.3 P465 L45 # 143
 Lambert, Angela Corning
 Comment Type **E** Comment Status **X**
 Cabled fiber attenuation and fiber attenuation are different. As noted at the footnote of other link power budget tables (i.e. Table 180-9 on p. 441 and Table 182-9 on p. 491) and in the respective Optical fiber and cable characteristics tables (in this case, Table 181-9 on page 467), this should be "Cabled optical fiber attenuation"
 SuggestedRemedy
 Change "fiber attenuation" to "cabled optical fiber attenuation"
 Proposed Response Response Status **O**

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

CI 183 SC 183.7.3 P515 L44 # 144
 Lambert, Angela Corning
 Comment Type E Comment Status X
 Cabled fiber attenuation and fiber attenuation are different. As noted at the footnote of other link power budget tables (i.e. Table 180-9 on p. 441 and Table 182-9 on p. 491) and in the respective Optical fiber and cable characteristics tables (in this case, Table 183-10 on page 518), this should be "Cabled optical fiber attenuation"
 SuggestedRemedy
 Change "fiber attenuation" to "cabled optical fiber attenuation"
 Proposed Response Response Status O

CI 1 SC 1.3 P53 L54 # 145
 Huber, Thomas Nokia
 Comment Type E Comment Status X
 This footnote indicates where to find SFP-DD224, QSFP224, and QSFP-DD1600 specifications, but the normative reference associated with this footnote is "QSFP-DD/QSFPDD-800/QSFP-DD1600 Hardware Specification for QSFP Double Density 8x Pluggable Transceivers", which makes no mention of SFP224 or QSFP224, and following the URL in the footnote does not take the reader to a site with documents that have information about SFP-DD224 or QSFP224 formats (nor does the normatively referenced document have that information).
 SuggestedRemedy
 Align the footnote with the referenced document by replacing "SFP-DD224, QSP224" with "QSFP-DD, QSFP-DD800"
 Proposed Response Response Status O

CI 30 SC 30.3.2.1.2 P61 L11 # 146
 Huber, Thomas Nokia
 Comment Type TR Comment Status X
 There is no longer an 800GBASE-ER1 PCS; ER1 and ER1-20 PHYs use the 800GBASE-R PCS.
 SuggestedRemedy
 Delete the instruction and text to insert 800GBASE-ER1 after 400GBASE-R
 Proposed Response Response Status O

CI 30 SC 30.3.2.1.3 P61 L31 # 147
 Huber, Thomas Nokia
 Comment Type TR Comment Status X
 There is no longer an 800GBASE-ER1 PCS; ER1 and ER1-20 PHYs use the 800GBASE-R PCS.
 SuggestedRemedy
 Delete the instruction and text to insert 800GBASE-ER1 after 400GBASE-R
 Proposed Response Response Status O

CI 30 SC 30.5.1.1.2 P62 L27 # 148
 Huber, Thomas Nokia
 Comment Type E Comment Status X
 200GBASE-DR1-2 should be inserted before 200GBASE-DR4 and after 200GBASE-DR1 rather than after 200GBASE-ER4
 SuggestedRemedy
 Delete the editing instruction that is related to the insertion of 200GBASE-DR1-2. Modify the previous editing instruction to say "Insert the following new entries... before the esntry for 200GBASE-DR4, and remove the space so 200GBASE-DR1 and 200GBASE-DR1-2 are both inserted by the same instruction.
 Proposed Response Response Status O

CI 30 SC 30.5.1.1.2 P63 L36 # 149
 Huber, Thomas Nokia
 Comment Type TR Comment Status X
 There is no longer an 800GBASE-ER1 PCS; the ER1 and ER-20 PHYs use the 800GBASE-R PCS. However they do have a unique PMA from other 800GBASE-R PHYs.
 SuggestedRemedy
 Change the description of 800GBASE-ER1 and 800GBASE-ER1-20 so they begin with "800GBASE-R PCS and 800GBASE-ER1 PMA over single-mode fiber PMD with a reach..."
 Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

CI 30 SC 30.5.1.1.2 P63 L47 # 150

Huber, Thomas

Nokia

Comment Type E Comment Status X

An instruction to insert before 800GBASE-KR8 is the same thing as an instruction to insert after 800GBASE-DR8-2, since they are currently adjacent to each other (and no other task force is adding 800G PHYs). This instruction can be combined with the previous one.

SuggestedRemedy

Delete the editing instruction "Insert the following new entry into the "APPROPRIATE SYNTAX" section of 30.5.1.1.2 before the entry for 800GBASE-KR8 (inserted by IEEE Std 802.3df-2024)", and remove the space so that the text for 800GBASE-KR4 is part of the prior instruction.

Proposed Response Response Status O

CI 30 SC 30.13.1.1 P65 L16 # 151

Huber, Thomas

Nokia

Comment Type T Comment Status X

The same mgmt registers/attributes are used for ER1 FEC as are used for Inner FEC, but the text here doesn't mention ER1 FEC.

SuggestedRemedy

Change "If a Clause 45 MDIO Interface to PMA/PMD, Inner Fec, WIS, ..." to "If a Clause 45 MDIO Interface to PMA/PMD, Inner FEC or ER1 FEC, WIS, ..."

Change the second bullet from "For Inner FEC:..." to "For Inner FEC or ER1 FEC:..."

Make the same changes to 30.13.1.2 through 30.13.1.12

Proposed Response Response Status O

CI 45 SC 45.2.1 P71 L48 # 152

Huber, Thomas

Nokia

Comment Type T Comment Status X

The TimeSync Inner FEC transmit and receive registers are also used for ER1 FEC.

SuggestedRemedy

Change "Time Sync inner FEC ..." to "TimeSync inner FEC or ER1 FEC...."

Proposed Response Response Status O

CI 45 SC 45.2.1 P72 L27 # 153

Huber, Thomas

Nokia

Comment Type T Comment Status X

Registers 1.2412 through 1.2423 are used for ER1 FEC as well as Inner FEC.

SuggestedRemedy

Change the "Inner FEC ..." to "Inner FEC or ER1 FEC ..." for each set of registers in the range.

Proposed Response Response Status O

CI 45 SC 45.2.1.10 P77 L32 # 154

Huber, Thomas

Nokia

Comment Type T Comment Status X

The text of table 45-14 (not currently included in the document) should be updated to refer to the newly added additional extended ability registers for 200G and 400G PHYs

SuggestedRemedy

Bring in clause 45.2.1.10 and Table 45-14. Update description for a one value for bit 1.11.13 from:

"1 = PMA/PMD has 200G/400G extended abilities listed in register 1.23 or register 1.24"

to:
"1 = PMA/PMD has 200G/400G extended abilities listed in register 1.23 (200G) or registers 1.24 and 1.75 (400G)"

Proposed Response Response Status O

CI 45 SC 45.2.1.23 P79 L24 # 155

Huber, Thomas

Nokia

Comment Type T Comment Status X

The description for bit 1.25.1 should also identify the abilities in register 1.74.

SuggestedRemedy

Change "... and has the abilities listed in register 1.73" to "... and has the abilities listed in registers 1.73 and 1.74"

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

CI 45 SC 45.2.1.23 P79 L35 # 156

Huber, Thomas

Nokia

Comment Type E Comment Status X

The editing instruction to insert 45.2.1.23.aa should note that 45.2.1.23.a was inserted by 802.3df-2024

SuggestedRemedy

Change to say "Insert 45.2.1.23.aa before 45.2.1.23.a (as inserted by IEEE Std 802.3df-2024) as follows:"

Proposed Response Response Status O

CI 45 SC 45.2.1.60e.3 P84 L16 # 157

Huber, Thomas

Nokia

Comment Type ER Comment Status X

This subclauses concerns 1.6TBASE-DR8, but the text refers to 1.6TBASE-DR2.

SuggestedRemedy

Change both instances of "1.6TBASE-DR2" in the text to "1.6TBASE-DR8".

Proposed Response Response Status O

CI 45 SC 45.2.1.175 P97 L44 # 158

Huber, Thomas

Nokia

Comment Type E Comment Status X

The 'inner FEC' TimeSync registers are also used for ER1 FEC

SuggestedRemedy

Change "... PMA/PMD and inner FEC..." to "...PMA/PMD, inner FEC, and ER1 FEC..."

In table 45-139, change "inner FEC" to "inner FEC or ER1 FEC" in the Name and Description columns of rows 1.1800.7 through 1.1800.4

Proposed Response Response Status O

CI 45 SC 45.2.1.177a P99 L5 # 159

Huber, Thomas

Nokia

Comment Type T Comment Status X

The 'inner FEC' TimeSync registers are also used for ER1 FEC

SuggestedRemedy

Change the title to "TimeSync FEC sublayer transmit path delay (Registers 1.1813 through 1.1818)"

Add a new first sentence to the first paragraph: "The TimeSync FEC sublayer transmit path data delay registers are used with Inner FEC sublayers and the ER1 FEC sublayer."

Change the rest of the existing text and table to replace 'inner FEC' with 'FEC sublayer'.

Make similar changes to 45.2.1.177b.

Proposed Response Response Status O

CI 45 SC 45.2.3.8 P119 L23 # 160

Huber, Thomas

Nokia

Comment Type E Comment Status X

Per the style guide, when inserting new subclauses before the first existing subclause, the nomenclature is 'X.Y.Z.a' rather than 'X.Y.Za'

SuggestedRemedy

Change the editing instruction to say "Insert 45.2.3.8.a and 45.2.3.8.b before 45.2.3.8.1"

Proposed Response Response Status O

CI 73 SC 73.4.2 P130 L13 # 161

Huber, Thomas

Nokia

Comment Type E Comment Status X

"An Auto-Negotiation able device shall recognize..." is awkward wording.

SuggestedRemedy

Change to "A device capable of Auto-Negotiation shall recognize..."

Proposed Response Response Status O

Cl 116 SC 116.1.4 P149 L34 # 162

Huber, Thomas

Nokia

Comment Type **TR** Comment Status **X**

The clause numbers in Table 116-3a are incorrect and the columns are not in the right order. Auto-Negotiation is clause 73 rather than 116, and should be the left-most column. (the text was correct in the table inserted by 802.3ck, so the errors were introduced here in 802.3dj)

SuggestedRemedy

Change 116 to 73, and swap the order of the first two columns so 73 comes first.

Proposed Response Response Status **O**

Cl 116 SC 116.2.9 P155 L42 # 163

Huber, Thomas

Nokia

Comment Type **T** Comment Status **X**

While it is clear what "DATA mode" is intended to mean here in the context of ILT, that term has specific meaning for 1000BASE-T PHYs that differs from what is intended here (see 1.4.278) Annex 178B.5 indicates that in the context of ILT, "data mode" means the variable tx_mode has the value 'data', which is associated with being in the PATH_UP state per figure 178B-8. As such, it would be more clear if the text in 116.2.9 referred to the PATH_UP state.

SuggestedRemedy

Change "coordinate the transition to DATA mode." to "coordinate the transition to the PATH_UP state (see Figure 178B-8)."

Proposed Response Response Status **O**

Cl 116 SC 116.2.9 P155 L45 # 164

Huber, Thomas

Nokia

Comment Type **T** Comment Status **X**

ILT is supported by any PHY that uses a 200GAUI-1 or 400GAUI-2. What's listed here are PMDs that support ILT.

SuggestedRemedy

If the intent is to list the PMDs that support ILT, change 'PHY' to 'PMD'. If the intent was to indicate PHYs that can support ILT, replace the sentence that introduces the dashed list with "ILT is supported by any 200GBASE-R PHY that uses a 200GAUI-1. any 400GBASE-R PHY that uses a 400GAUI-2, or any PHY that uses one of the following PMD types:"

Proposed Response Response Status **O**

Cl 116 SC 116.3.3.1 P161 L4 # 165

Huber, Thomas

Nokia

Comment Type **ER** Comment Status **X**

The text regarding the values of the SIGNAL_OK parameter is not sufficiently clear in a number of aspects. As the first paragraph states, IN_PROGRESS and READY are only supported if ILT is supported. The paragraphs about the OK and FAIL values refer to "if the service interface supports the values IN_PROGRESS and READY", which is needlessly complex wording; the condition is more succinctly expressed as "if ILT is supported", rather than if the states that ILT uses are supported. Further, since the meanings of OK and FAIL are different depending on whether ILT is used, instead of saying 'here are four values of SIGNAL_OK', and embedding in those definitions the details of whether ILT is used or not, it would be more clear to say 'SIGNAL_OK has these values if ILT is used, and these values if ILT is not used'.

SuggestedRemedy

Replace the second through fifth paragraphs with this text (text spills beyond the bottom of the cell):

If ILT is not used:

A value of OK indicates that communication with the next lower sublayer is established (but does not guarantee that valid data is being presented to the next higher sublayer).

A value of FAIL indicates that the sublayer has not established communication to the next lower sublayer, and data is not being presented to the next higher sublayer (the rx_symbol parameters are undefined).

If ILT is used:

A value of OK indicates that valid data is being presented by the sublayer to the next higher sublayer in the rx_symbol parameters.

A value of READY indicates that communication is established with the next lower sublayer, but communication with the peer interface is not fully established yet. The rx_symbol parameters presented to the next higher sublayer do not represent traffic data and might be invalid. Management intervention is not required.

A value of IN_PROGRESS indicates that the sublayer is establishing communication with the next lower sublayer. Data is not being presented by the sublayer to the next higher sublayer (the rx_symbol parameters are unspecified). Management intervention is not required.

A value of FAIL indicates that an attempt to communicate with the next lower sublayer has failed. Data is not being presented to the next higher sublayer (rx_symbol parameters are unspecified)

Proposed Response Response Status **O**

Cl 169 SC 169.2.10 P190 L41 # 166

Huber, Thomas

Nokia

Comment Type E Comment Status X

While it is clear what "DATA mode" is intended to mean here in the context of ILT, that term has specific meaning for 1000BASE-T PHYs that differs from what is intended here (see 1.4.278) Annex 178B.5 indicates that in the context of ILT, "data mode" means the variable tx_mode has the value 'data', which is associated with being in the PATH_UP state per figure 178B-8. As such, it would be more clear if the text in 169.2.10 referred to the PATH_UP state.

SuggestedRemedy

Change "coordinate the transition to DATA mode." to "coordinate the transition to the PATH_UP state (see Figure 178B-8)."

Proposed Response Response Status O

Cl 169 SC 169.2.10 P190 L43 # 167

Huber, Thomas

Nokia

Comment Type T Comment Status X

ILT is in principle supported by any 800GBASE-R PHY that uses a 200G/lane AUI. The dashed list here is the PMDs that can support ILT.

SuggestedRemedy

If the intent is to list the PMDs that support ILT, change 'PHY' to 'PMD'. If the intent was to indicate PHYs that can support ILT, replace the sentence that introduces the dashed list with "ILT is supported by any 800GBASE-R PHY that uses an 800GAUI-4 or one of the following PMD types:"

Proposed Response Response Status O

Cl 169 SC 169.3.2 P191 L17 # 168

Huber, Thomas

Nokia

Comment Type E Comment Status X

While the ER1 FEC is an example of a segmented FEC, that term isn't being used elsewhere in the text, so probably better to call it the ER1 FEC here.

SuggestedRemedy

Change "Segmented FEC" to "ER1 FEC":

Proposed Response Response Status O

Cl 169 SC 169.5 P198 L14 # 169

Huber, Thomas

Nokia

Comment Type T Comment Status X

In Figures 169-4 and 169-5, it needs to be more clear that "Inner FEC" can also be the ER1 FEC.

SuggestedRemedy

Replace "Inner FEC" in both figures with "Inner FEC or ER1 FEC".

Proposed Response Response Status O

Cl 169 SC 169.8 P201 L48 # 170

Huber, Thomas

Nokia

Comment Type T Comment Status X

Subclause 169.8 (PICS summary) needs to be updated to refer to new PMD clauses added by 802.3dj.

SuggestedRemedy

Bring in clause 169.8

Add this editing instruction:

Change the first paragraph of subclause 169.8 (as added by IEEE Std 802.3df-2024) as follows

Copy in the first paragraph of the existing 169.8, and change "Clause 170 through Clause 173" to "Clause 170 through Clause 173 or Clause 176 through Clause 187:"

Proposed Response Response Status O

Cl 172 SC 172.2.5.2 P242 L9 # 171

Huber, Thomas

Nokia

Comment Type T Comment Status X

The text here was modified from "PMA service interface lanes" to "service interface lanes", since the sublayer below the PCS may be a FEC or a PMA. But just saying "service interface lanes" is not sufficiently clear that it is the service interface from the next lower layer.

SuggestedRemedy

Change the first sentence to read:

"The PCS lanes might be received in any order from the service interface below the PCS."

Proposed Response Response Status O

Cl 172 SC 172.6 P242 L36 # 172
 Huber, Thomas Nokia
 Comment Type E Comment Status X
 The PMDs for which AN is mandatory are already explained in the tables in clause 169, so there is no need to repeat all of them here. At the same time, it is maybe useful to at least note that the requirements apply to CRn and KRn PMDs.
SuggestedRemedy
 Replace "800GBASE-CR8, 800GBASE-CR4, 800GBASE-KR8, or 800GBASE-KR4 PMD" with "800GBASE-CRn or 800GBASE-KRn PMD"
 Proposed Response Response Status O

Cl 172 SC 172.7.4.7 P243 L17 # 173
 Huber, Thomas Nokia
 Comment Type E Comment Status X
 Easier to say CRn/KRn rather than enumerate all the CRn and KRn PMDs in the PICS
SuggestedRemedy
 Replace "800GBASE-CR8, 800GBASE-CR4, 800GBASE-KR8, or 800GBASE-KR4 PMD" with "800GBASE-CRn or 800GBASE-KRn PMD"
 Proposed Response Response Status O

Cl 173 SC 173.4.2 P244 L46 # 174
 Huber, Thomas Nokia
 Comment Type T Comment Status X
 If a conversion from BM to SM PMA is needed, the 8:32 PMA could also connect to a 32:4 PMA (e.g., an 800GBASE-LR4 module that has an 800GAUI-8 host-side interface would need to do this since the optical interface requires the clause 177 inner FEC - so the stack would be 800GBASE-R PCS, 32:8 PMA, [800GAUI-8], 8:32 PMA, 32:4 PMA, 800GBASE-R Inner FEC, 800GBASE-LR4 PMD).
SuggestedRemedy
 Add "32:4 SM-PMA, " after PHY 800GXS.
 Proposed Response Response Status O

Cl 173 SC 173.4.2 P245 L36 # 175
 Huber, Thomas Nokia
 Comment Type T Comment Status X
 Figure 173-3 is missing the possibility that a 32:4 PMA could be connected. Also, the explanatory notes b and c seem unnecessary. It should be quite obvious to any reader that 'inst' is PHY_XS when the sublayer below the PMA is a PHY 800GXS and FEC when it is a FEC sublayer (or PMA when it is a PMA).
SuggestedRemedy
 At the bottom of the figure, just under the 32 output lanes and 32 input lanes, add "or 32:4 PMA" after PHY 800GXS, and in the explanation of "inst", add "or PMA" after PHY_XS. Delete notes b and c and the references to them in the explanation of 'inst'.
 Proposed Response Response Status O

Cl 174 SC 174.1.4 P248 L30 # 176
 Huber, Thomas Nokia
 Comment Type T Comment Status X
 Table 174-3 is missing clause 73 Auto-Negotiation
SuggestedRemedy
 Add a column for Clause 73 Auto-Negotiation and indicate it as Mandatory for both 1.6TBASE-KR8 and 1.6TBASE-CR8.
 Proposed Response Response Status O

Cl 174 SC 174.2.12 P250 L42 # 177
 Huber, Thomas Nokia
 Comment Type T Comment Status X
 While it is clear what "DATA mode" is intended to mean here in the context of ILT, that term has specific meaning for 1000BASE-T PHYs that differs from what is intended here (see 1.4.278) Annex 178B.5 indicates that in the context of ILT, "data mode" means the variable tx_mode has the value 'data', which is associated with being in the PATH_UP state per figure 178B-8. As such, it would be more clear if the text in 174.2.12 referred to the PATH_UP state.
SuggestedRemedy
 Change "coordinate the transition to DATA mode." to "coordinate the transition to the PATH_UP state (see Figure 178B-8)."
 Proposed Response Response Status O

Cl 174 SC 174.6 P259 L34 # 178
 Huber, Thomas Nokia
 Comment Type T Comment Status X
 Clause 182 is also relevant to 1.6TBASE-R.
SuggestedRemedy
 Change "Clause 175 through Clause 180" to "Clause 175 through Clause 180 or Clause 182"
 Proposed Response Response Status O

Cl 176 SC 176.4.2.4 P298 L37 # 179
 Huber, Thomas Nokia
 Comment Type E Comment Status X
 In the second paragraph, the phrases that start with "which employ..." are not necessary to understand the sentence (they are additional explanatory information), so they should be separated by commas both before and after the phrases.
SuggestedRemedy
 Add a comma after 800GBASE-R 32:4 PMAs and after 1.6TBASE-R 16:8 PMA, so it reads as follows:
 This delay function is used by the 200GBASE-R 8:1, 400GBASE-R 16:2, and 800GBASE-R 32:4 PMAs, which employ symbol-pair multiplexing, but not by the 1.6TBASE-R 16:8 PMA, which employs symbol-quartet multiplexing.
 Proposed Response Response Status O

Cl 176 SC 176.4.2.4.2 P300 L29 # 180
 Huber, Thomas Nokia
 Comment Type E Comment Status X
 The first sentence has a list of two items separated with a comma rather than 'and'.
SuggestedRemedy
 Change the sentence to read: This delay is performed for the 200GBASE-R 8:1 and 400GBASE-R 16:2 PMAs.
 Proposed Response Response Status O

Cl 176 SC 176.7.1.2 P316 L11 # 181
 Huber, Thomas Nokia
 Comment Type T Comment Status X
 If the precoder is configured either based on ILT (as in the penultimate paragraph) or is "set as required by the implementation" (as in the last paragraph), what is the purpose of having the set of "precoder_{tx|rx}_{in|out}_enable_i" variables to enable and disable it for each lane/direction? It doesn't sound like the user has any need to control these settings.
SuggestedRemedy
 Either remove the variables entirely, or treat them as status variables that report the configuration if there is some value in the user knowing what the configuration is Or, if the intent in the case that ILT is not being used is that the user needs to figure out whether to enable the precoder on a per-lane basis, make that more clear.
 Proposed Response Response Status O

Cl 177 SC 177.2 P328 L14 # 182
 Huber, Thomas Nokia
 Comment Type E Comment Status X
 It would be better to not list the specific PMDs here and create a potential need to regularly update this text if new PHYs are added that use this inner FEC.
SuggestedRemedy
 Replace "The number of parallel streams, n, is 1 for 200GBASE-DR1-2, 2 for 400GBASE-DR2-2, 4 for 800GBASE-DR4-2, 800GBASE-FR4, and 800GBASE-LR4, and 8 for 1.6TBASE-DR8-2."
 with
 "The number of parallel streams, n, is 1 for 200GBASE-R PHYs, 2 for 400GBASE-R PHYs, 4 for 800GBASE-R PHYs, and 8 for 1.6TBASE-R PHYs."
 Proposed Response Response Status O

CI 177 SC 177.3 P328 L45 # 183
 Huber, Thomas Nokia
 Comment Type T Comment Status X
 Clause 182 is not the only PMD that is used with this inner FEC, so the service interface below the Inner FEC is not limited to the PMD service interface in 182.3. It could also be the interface in 183.3. Rather than enumerating all the clauses (which would create a potential need to regularly update the clause), a more generic statement can be used.
SuggestedRemedy
 Change "the PMD service interface defined in 182.3" to "the PMD service interface for the PHY".
 Proposed Response Response Status O

CI 177 SC 177.4.2 P331 L29 # 184
 Huber, Thomas Nokia
 Comment Type E Comment Status X
 Awkward grammer in "The data from deskwed PMA lane is fed..."
SuggestedRemedy
 Change to "Data from the deskwed PMA lane is fed..."
 Proposed Response Response Status O

CI 177 SC 177.4.7 P334 L37 # 185
 Huber, Thomas Nokia
 Comment Type T Comment Status X
 Figure 177-7 is a bit confusing. The 1024-bit pad is the equivalent number of bits as "8x Inner FEC codewords", but of course is not that, it's padding bits as described by the text and subclauses under the figure. More generatly, the use of "8x" in the figure is not appropriate, as there is no multiplication going on. In the text under the horizontal brace (8704 Inner FEC codewords), the intent is that there are 1088 blocks of 8 Inner FEC codewords (a total of 8704 codewords), but this could easily be misinterpreted by a careless reader as 8704 blocks of 8 Inner FEC codewords It would also be helpful to explicitly indicate 1088 blocks, as that would more clearly relate back to the text about the 1088/1089 ratio.
SuggestedRemedy
 In the pad blocks, replace "8x Inner FEC codewords" with "1024 bits". In the other blocks, change "8x" to "8". In the text under the brace, add another line that says "(1088 blocks of 8 inner FEC codewords)".
 Proposed Response Response Status O

CI 177 SC 177.4.8.2 P336 L15 # 186
 Huber, Thomas Nokia
 Comment Type T Comment Status X
 If the precoder is configured either based on ILT or is "set as required by the implementation", what is the purpose of having the set of "precoder_{tx|rx}_{in|out}_enable_i" variables to enable and disable it for each lane/direction? It doesn't sound like the user has any need to control these settings.
SuggestedRemedy
 Either remove the variables entirely, or treat them as status variables that report the configuration if there is some value in the user knowing what the configuration is Or, if the intent in the case that ILT is not being used is that the user needs to figure out whether to enable the precoder, make that more clear.
 Proposed Response Response Status O

CI 177 SC 177.5.1 P336 L36 # 187
 Huber, Thomas Nokia
 Comment Type E Comment Status X
 The last sentence is a comma splice.
SuggestedRemedy
 Change to read: "The hard-decision PAM4 decoding function.... in Figure 177.2. The soft-decision PAM4 decoding..."
 Proposed Response Response Status O

CI 177 SC 177.5.2 P337 L20 # 188
 Huber, Thomas Nokia
 Comment Type E Comment Status X
 "128b-bit blocks" has a stray b
SuggestedRemedy
 Change to "128-bit blocs"
 Proposed Response Response Status O

Cl 177 SC 177.6.1.4 P340 L10 # 189

Huber, Thomas

Nokia

Comment Type T Comment Status X

Isn't this subclause just a natural consequence of subclause 177.6.1.2? I.e., if there is a PRBS 31 generator at the input to the PAM4 encoder, it stands to reason that there can be a PRBS31Q pattern at the output of the PAM4 encoder; that is not a unique test pattern, it's the natural result of enabling the PRBS31 generator.

SuggestedRemedy

Delete this subclause. Or if there is some value in noting that this pattern exists, rather than saying the inner FEC shall include it, just state that enabling the PRBS31 generator (see 177.6.1.2) produces a PRBS31Q pattern at the output of the PAM4 encoder.

Proposed Response Response Status O

Cl 178 SC 178.8.9 P361 L26 # 190

Huber, Thomas

Nokia

Comment Type T Comment Status X

While it is clear what "DATA mode" is intended to mean here in the context of ILT, that term has specific meaning for 1000BASE-T PHYs that differs from what is intended here (see 1.4.278) Annex 178B.5 indicates that in the context of ILT, "data mode" means the variable tx_mode has the value 'data', which is associated with being in the PATH_UP state per figure 178B-8. As such, it would be more clear if the text in 178.8.9 referred to the PATH_UP state.

SuggestedRemedy

Change "coordinate the transition to DATA mode." to "coordinate the transition to the PATH_UP state (see Figure 178B-8)."

Proposed Response Response Status O

Cl 179 SC 179.8.2 P391 L31 # 191

Huber, Thomas

Nokia

Comment Type T Comment Status X

While it is clear what "DATA mode" is intended to mean here in the context of ILT, that term has specific meaning for 1000BASE-T PHYs that differs from what is intended here (see 1.4.278) Annex 178B.5 indicates that in the context of ILT, "data mode" means the variable tx_mode has the value 'data', which is associated with being in the PATH_UP state per figure 178B-8. As such, it would be more clear if the text in 179.8.2 referred to the PATH_UP state.

SuggestedRemedy

Change "When operating in DATA mode, ..." to "When operating in the PATH_UP state (see Figure 178B-8),..."

Proposed Response Response Status O

Cl 179 SC 179.8.9 P393 L6 # 192

Huber, Thomas

Nokia

Comment Type T Comment Status X

While it is clear what "DATA mode" is intended to mean here in the context of ILT, that term has specific meaning for 1000BASE-T PHYs that differs from what is intended here (see 1.4.278) Annex 178B.5 indicates that in the context of ILT, "data mode" means the variable tx_mode has the value 'data', which is associated with being in the PATH_UP state per figure 178B-8. As such, it would be more clear if the text in 179.8.9 referred to the PATH_UP state.

SuggestedRemedy

Change "coordinate the transition to DATA mode." to "coordinate the transition to the PATH_UP state (see Figure 178B-8)."

Proposed Response Response Status O

Cl 180 SC 180.5.12 P437 L28 # 193

Huber, Thomas

Nokia

Comment Type T Comment Status X

While it is clear what "DATA mode" is intended to mean here in the context of ILT, that term has specific meaning for 1000BASE-T PHYs that differs from what is intended here (see 1.4.278) Annex 178B.5 indicates that in the context of ILT, "data mode" means the variable tx_mode has the value 'data', which is associated with being in the PATH_UP state per figure 178B-8. As such, it would be more clear if the text in 180.5.12 referred to the PATH_UP state.

SuggestedRemedy

Change "coordinate the transition to DATA mode." to "coordinate the transition to the PATH_UP state (see Figure 178B-8)."

Proposed Response Response Status

Cl 180 SC 180.8.3 P444 L47 # 194

Huber, Thomas

Nokia

Comment Type T Comment Status X

DR MDIs use pairs of fibers

SuggestedRemedy

Change "...besides the option to connect to a single fiber MDI, ..." to "...besides the option to connect to a single fiber-pair MDI, ..."

Proposed Response Response Status

Cl 181 SC 181.5.12 P460 L24 # 195

Huber, Thomas

Nokia

Comment Type T Comment Status X

While it is clear what "DATA mode" is intended to mean here in the context of ILT, that term has specific meaning for 1000BASE-T PHYs that differs from what is intended here (see 1.4.278) Annex 178B.5 indicates that in the context of ILT, "data mode" means the variable tx_mode has the value 'data', which is associated with being in the PATH_UP state per figure 178B-8. As such, it would be more clear if the text in 181.5.12 referred to the PATH_UP state.

SuggestedRemedy

Change "coordinate the transition to DATA mode." to "coordinate the transition to the PATH_UP state (see Figure 178B-8)."

Proposed Response Response Status

Cl 182 SC 182.5.12 P487 L41 # 196

Huber, Thomas

Nokia

Comment Type T Comment Status X

While it is clear what "DATA mode" is intended to mean here in the context of ILT, that term has specific meaning for 1000BASE-T PHYs that differs from what is intended here (see 1.4.278) Annex 178B.5 indicates that in the context of ILT, "data mode" means the variable tx_mode has the value 'data', which is associated with being in the PATH_UP state per figure 178B-8. As such, it would be more clear if the text in 182.5.12 referred to the PATH_UP state.

SuggestedRemedy

Change "coordinate the transition to DATA mode." to "coordinate the transition to the PATH_UP state (see Figure 178B-8)."

Proposed Response Response Status

Cl 182 SC 182.8.3 P494 L52 # 197

Huber, Thomas

Nokia

Comment Type T Comment Status X

DRn-2 MDIs use pairs of fibers.

SuggestedRemedy

Change "...besides the option to connect to a single fiber MDI, ..." to "...besides the option to connect to a single fiber-pair MDI, ..."

Proposed Response Response Status

Cl 183 SC 183.5.12 P510 L33 # 198

Huber, Thomas

Nokia

Comment Type T Comment Status X

While it is clear what "DATA mode" is intended to mean here in the context of ILT, that term has specific meaning for 1000BASE-T PHYs that differs from what is intended here (see 1.4.278) Annex 178B.5 indicates that in the context of ILT, "data mode" means the variable tx_mode has the value 'data', which is associated with being in the PATH_UP state per figure 178B-8. As such, it would be more clear if the text in 183.5.12 referred to the PATH_UP state.

SuggestedRemedy

Change "coordinate the transition to DATA mode." to "coordinate the transition to the PATH_UP state (see Figure 178B-8)."

Proposed Response Response Status

CI 184 SC 184.2 P533 L4 # 199

Huber, Thomas

Nokia

Comment Type T Comment Status X

It is misleading to present the reordering and deskew functions as optional. The lanes are required to be in the two flow groups (0-15 and 16-31) and deskewed to a 2-symbol boundary. In an implementation that happens to have the inner FEC immediately next to the PCS, this may not require any effort, because the PCS will have created the lanes in order and there won't be any skew to remove, but that doesn't make the process optional from a standardization perspective. There are always design optimizations that can be made that we don't spell out as optional functions.

SuggestedRemedy

Replace "If necessary, the lanes are reordered and deskewed" with "The lanes are reordered and deskewed."

Proposed Response Response Status O

CI 184 SC 184.2 P533 L8 # 200

Huber, Thomas

Nokia

Comment Type E Comment Status X

Missing a hyphen in the compound adjective 'BCH(126, 110) encoded'

SuggestedRemedy

Change to "...interleaving the BCH(126,110)-encoded flows..."

Proposed Response Response Status O

CI 184 SC 184.2 P533 L18 # 201

Huber, Thomas

Nokia

Comment Type E Comment Status X

Awkward grammar : "Convolutional interleaving and permutation are undone to restore the original lanes order".

SuggestedRemedy

Reword as: "Convolutional interleaving and permutation are undone to restore the original order of the lanes".

Proposed Response Response Status O

CI 184 SC 184.4.1 P534 L5 # 202

Huber, Thomas

Nokia

Comment Type T Comment Status X

It is required that the lanes be in the two flow groups and deskewed to a 2-symbol boundary. If the PCS and Inner FEC happen to be adjacent, a designer may be able to omit these functions, but that doesn't make them optional from a standardization perspective

SuggestedRemedy

Change "The alignment lock and deskew functions, when implemented, shall be..." to "The alignment lock and deskew functions shall be ..."

Proposed Response Response Status O

CI 184 SC 184.4.3 P535 L2 # 203

Huber, Thomas

Nokia

Comment Type T Comment Status X

Figure 184-3 could be more clear. The labels "RS-FEC in" and "RS-FEC out" are really the values of the index $i \pmod{4}$. The permutation isn't doing anything with the symbols in flows 16-31 in columns 0 and 1; they stay where they are. It's the symbols in columns 2 and 3 that are changing to create symbol quartets with one symbol from each RS FEC encoder.

SuggestedRemedy

Replace the "RS-FEC in" and "RS-FEC out" labels with "Symbol index $i \pmod{4}$ ". Change the left side of the figure to have one box around columns 2 and 3, rows 16-31, and a different style of box around columns 2 and 3, rows 0-15. Change the right hand side of the figure to show that the top and bottom boxes in columns 2 and 3 from the left hand side have changed positions.

Proposed Response Response Status O

CI 184 SC 184.4.5 P537 L7 # 204

Huber, Thomas

Nokia

Comment Type E Comment Status X

$m(x)$ should have the m in italics

SuggestedRemedy

Italicize the m

Proposed Response Response Status O

Cl 184 SC 184.4.7 P537 L50 # 205
 Huber, Thomas Nokia
 Comment Type E Comment Status X
 Up until this point, the index q has been used for the 32 flows within the inner FEC. It is confusing to use q here as the index for the 4 output flows of the BCH interleaver.
 SuggestedRemedy
 Choose a different index for the 4 flows of inter[]
 Proposed Response Response Status O

Cl 186 SC 186 P579 L1 # 208
 Huber, Thomas Nokia
 Comment Type T Comment Status X
 This clause is missing information on loopbacks
 SuggestedRemedy
 Add a subclause for loopbacks that is aligned to what is in OIF 800ZR
 Proposed Response Response Status O

Cl 184 SC 184.4.7 P537 L51 # 206
 Huber, Thomas Nokia
 Comment Type E Comment Status X
 The index l should be avoided if at all possible, as it can be confused for the number 1.
 SuggestedRemedy
 Pick a different letter to use for this index.
 Proposed Response Response Status O

Cl 186 SC 186.2.1 P582 L4 # 209
 Huber, Thomas Nokia
 Comment Type E Comment Status X
 In the second sentence, clarify "800GBASE-ER1 FEC" is referring to the sublayer rather than the ER1 FEC code.
 SuggestedRemedy
 Change "800GBASE-ER1 FEC" to "800GBASE-ER1 FEC sublayer". This should be applied throughout the subclause.
 Proposed Response Response Status O

Cl 184 SC 184.11.4.1 P554 L18 # 207
 Huber, Thomas Nokia
 Comment Type T Comment Status X
 The signal presented to the permutation function must have the properties that the lane grouping and deskew functions provide, so the functions are mandatory (even if some implementations may not need to perform these functions, they are not optional).
 SuggestedRemedy
 Change the status of these items to M
 Proposed Response Response Status O

Cl 186 SC 186.2.1 P582 L19 # 210
 Huber, Thomas Nokia
 Comment Type E Comment Status X
 The "8 lanes" should not be called lanes since they are not an interface between two sublayers.
 SuggestedRemedy
 Change 8 lanes to "8 ER1 FEC flows" throughout the paragraph and in the last paragraph of this subclause This change also needs to be made in 186.2.3.2, 186.2.3.3, Figure 186-7, and perhaps other places
 Proposed Response Response Status O

CI 186 SC 186.2.1 P582 L23 # 211
 Huber, Thomas Nokia
 Comment Type T Comment Status X
 The interface between the FEC and PMA sublayers is FEC codewords, not symbols.
 SuggestedRemedy
 Delete "as a stream of symbols" from the end of the last sentence of the 3rd-to-last paragraph.
 Proposed Response Response Status O

CI 186 SC 186.2.1 P582 L30 # 212
 Huber, Thomas Nokia
 Comment Type T Comment Status X
 The interface between the FEC and PMA sublayers is FEC codewords, not digitized DP16QAM symbols.
 SuggestedRemedy
 Change the second clause of the second sentence from: "... the 800GBASE-ER1 FEC synchronization process accepts a stream of m-bit digitized DP-16QAM symbols via the PMA:IS_UNITDATA.indication primitive and forms a stream of ER1 FEC codewords" to "... the 800GBASE-ER1 FEC synchronization process accepts a stream of FEC codewords in the form of m-bit digitized bitstreams representing the four components of DP-16QAM symbols."
 Proposed Response Response Status O

CI 186 SC 186.2.2 P582 L47 # 213
 Huber, Thomas Nokia
 Comment Type T Comment Status X
 The text here says the UNITDATA parameter is a symbol, whereas 186.3.2 says it is FEC codewords
 SuggestedRemedy
 Since the PMA includes the Gray coding and symbol mapping processes, it makes more sense to describe the service interface to the PMA as FEC codewords. Change tx_symbol and rx_symbol to tx_codeword and rx_codeword, respectively.
 Proposed Response Response Status O

CI 186 SC 186.2.3.3 P584 L42 # 214
 Huber, Thomas Nokia
 Comment Type E Comment Status X
 The description of the purpose of the pad could be more clear. The idea is that the 5 pad bits create a payload area that is an integer number of 257b blocks.
 SuggestedRemedy
 Change "This aligns the encoded MAC frames to 257-bit boundaries." to "This creates an integer number of 257-bit positions within the payload area of the 800GBASE-ER1 tributary frame."
 Proposed Response Response Status O

CI 186 SC 186.2.3.4.1 P586 L28 # 215
 Huber, Thomas Nokia
 Comment Type E Comment Status X
 The AM field is defined in G.709.1, but the values used in it are in G.709.6 (as indicated in the normative text of this clause).
 SuggestedRemedy
 Change the note to say "Recommendation ITU_T G.709.1, Recommendation ITU-T G.709.6, and OIF-800ZR-01.0"
 Proposed Response Response Status O

CI 186 SC 186.2.3.4.1 P586 L34 # 216
 Huber, Thomas Nokia
 Comment Type E Comment Status X
 The EOH field is defined in G.709.1 rather than G.709.6
 SuggestedRemedy
 Change G.709.6 to G.709.1.
 Proposed Response Response Status O

CI 186 SC 186.2.3.5.5 P588 L14 # 217
 Huber, Thomas Nokia
 Comment Type TR Comment Status X
 The non-zero values of MAP are bytes 6 and 7 of the first row, not 6 and 8
 SuggestedRemedy
 Change "byte 8" to "byte 7"
 Proposed Response Response Status O

CI 186 SC 186.2.4.6.7 P596 L40 # 218
 Huber, Thomas Nokia
 Comment Type T Comment Status X
 While the GID, IID, and MAP fields are fixed values when connected to an 800GBASE-ER1 transmitter, they could have different values if connected to an ITU-T FlexO-8e-DO interface. As such, the receiver probably should verify that they contain the fixed values they are supposed to contain and not demap the signal if they don't.
 SuggestedRemedy
 Add text to 186.2.4.7 to indicate that the client is not demapped if the GID/IID/MAP overhead doesn't have the values that are expected. The SIGNAL_OK parameter should also depend on having a stable and correct value for these fields (as well as the payload type and multiplex structure fields).
 Proposed Response Response Status O

CI 186 SC 186.3.2 P599 L40 # 219
 Huber, Thomas Nokia
 Comment Type E Comment Status X
 The clause describing the service interface has a large number of additional subheadings (one for each primitive, and within those, a 'semantics', 'when generated', and 'effect of receipt' subclause) compared to the FEC subclause, and compared to other service interface descriptions in this amendment
 SuggestedRemedy
 Revise the clause to remove all the subheadings, most of which have only one or two sentences in them. Align the overall structure with what is in 186.2.2.
 Proposed Response Response Status O

CI 178B SC 178B.2 P786 L18 # 220
 Huber, Thomas Nokia
 Comment Type T Comment Status X
 The overview of ILT is confusing. ILT has two aspects - there is per-ISL training, and there is the end-to-end path startup behavior. These need to be more clearly separated in the overview text. The "continuous exchange of fixed-length training frames" is not entirely accurate - that may be what happens during the training phase, but is certainly not what happens once the training is completed.

SuggestedRemedy
 Rewrite the paragraph as follows:
 ILT describes a set of processes that serve two purposes: facilitating timing recovery and optimizing performance on individual ISLs, and coordination of ISLs along a path to enable a smooth path start-up. The individual link training is performed via the exchange of fixed-length training frames between peer interfaces of an ISL that enable the transmitter to optimize the performance of the ISL. Path start-up is performed via the exchange of status indications across the set of ISLs that exist between the path endpoints.
 Proposed Response Response Status O

CI 178B SC 178B.3 P786 L31 # 221
 Huber, Thomas Nokia
 Comment Type E Comment Status X
 The definition of AUI component in Annex 178B uses the terms 'AUI upper component' and 'AUI bottom component', while related text in 45.2.1.269 uses 'upper AUI component' and 'lower AUI component'. The terms should be consistent between the two.
 SuggestedRemedy
 Upper and lower works better than upper and bottom. Change the definition in 178B.3 to use 'upper AUI component' and 'lower AUI component'.
 Proposed Response Response Status O

Cl 178B SC 178B.3 P786 L34 # 222

Huber, Thomas

Nokia

Comment Type E Comment Status X

The definition of ISL is somewhat awkward. The two PMDs are not really 'adjacent sublayers' in the same sense that a pair of PMAs within a PHY implementation are. Also, the definition should be consistent as to whether the sublayers are or are not part of the ISL. As written, it suggests that the ISL is either the AUI (not including the PMAs) or a pair of PMDs plus the medium.

SuggestedRemedy

Change the text to read:

The xAUI-n between a pair of adjacent PMA sublayers, or the MDI between a pair of PMD sublayers.

Proposed Response Response Status O

Cl 178B SC 178B.4 P786 L52 # 223

Huber, Thomas

Nokia

Comment Type T Comment Status X

The second paragraph is confusing. The text begins with "Devices in a path may include one or two physically instantiated interfaces, specifically AUI or PMD components." However, an end-to-end path between two PCS could include as many as 5 ISLs: two AUIs in each Physical Layer implementation, plus the MDI between the PMDs.

SuggestedRemedy

If this paragraph was not present, the information in the rest of the clause is still clear.

Delete the paragraph.

Proposed Response Response Status O

Cl 178B SC 178B.4 P787 L5 # 224

Huber, Thomas

Nokia

Comment Type T Comment Status X

While it's true that there are "one or more per-lane functions", this language is misleading. For an n lane interface there are exactly n per-lane functions.

SuggestedRemedy

Change "one or more per-lane functions" to "one per-lane function for each physical lane"

Proposed Response Response Status O

Cl 178B SC 178B.5 P787 L37 # 225

Huber, Thomas

Nokia

Comment Type E Comment Status X

The organization of subclauses 178B.5 through 178B.13 is suboptimal. The path start-up protocol depends on the per-ILS training protocol, so it would be better to introduce that first, and to have all the various pieces of that in one subclause rather than spread across 8 subclauses. Further, 178B.5.1 seems to be about the individual ISL training rather than the path startup process. and 178B.5.2 and 178B.5.3 are examples of individual ISL training

SuggestedRemedy

Rearrange the material as follows [comments relative to current clauses in square brackets and are not intended to be included in the text of the document]:

- 178B.5 ISL training [new heading]
- 178B.5.1 Interface behavior [current 178B.5.1]
- 178B.5.1.1 Training retimers [current 178B.5.2]
- 178B.5.1.2 Training xMII Extenders [current 178B.5,3]
- 178B.5.2 Training frame structure [current 178B.6]
- 178B.5.3 Control field structure [current 178B.7]
- 178B.5.4 Status field structure [current 178B.8]
- 178B.5.5 Training frame lock [current 178B.9]
- 178B.5.6 Polarity detection and correction [current 178B.10]
- 178B.5.7 Equalization control [current 178B.11]
- 178B.5.8 Training pattern setting [current 178B.12]
- 178B.5.9 Handshake timing [current 178B.13]
- 178B.6 Path start-up protocol [current 178B.5, without the subclauses included above]
- 178B.7 State diagrams [current 178B.14]
- 178B.8 Management variables [current 178B.15]
- 178B.9 PICS [current 178B.16]

Proposed Response Response Status O

Cl 178B SC 178B.5 P787 L43 # 226

Huber, Thomas

Nokia

Comment Type T Comment Status X

The bullet list that attempts to explain how path start-up works is not succeeding. It is not clear if "ready to send" is related to the local_rts and remote_rts indications or if it is something different. It seems like it must be something different, since the third bullet says you can only send local_rts or remote_rts across an ISL that is ready to send. The last two bullets seem to introduce a notion of "device" that is undefined. The concept of an ISL includes a physical instantiation of an AUI or a medium, so the intended meaning of 'device' is reasonably clear (i.e., the endpoint of an ISL), but it would be better to avoid using 'devices' in the description and focus on ISLs and their endpoints.

SuggestedRemedy

The intended behavior is not really clear, so it's hard to provide a specific remedy. It think the intention is that local_rts originates at the A end PCS and traverses all sublayers and ISLs until it reaches the Z end PCS. Upon receiving local_rts, the Z end PCS signals remote_rts to the A end PCS. (and of course vice versa for Z-->A). So local_rts makes its way down the stack in one system, across the medium, and up the stack in the peer system. In order for local_rts (or remote_rts) to go across an ISL, that ISL must be in a 'ready to send' condition that has nothing to do with the 'local_rts' or 'remote_rts' variables, but instead depends on ILT (for ISLs that support ILT) or some other mechanism (for those that don't support ILT) to determine if the ISL is 'ready to send'. If that is correct, write text accordingly to explain this, and modify the terminology or provide better definitions so that it's clear that "ISL ready to send" is not the same thing as local_rts or remote_rts. If the intended behavior is something else, rewrite the text to be more clear about what is intended.

Proposed Response Response Status O

Cl 178B SC 178B.5.1 P788 L9 # 227

Huber, Thomas

Nokia

Comment Type E Comment Status X

"Interface" is vague. I think this clause is about lanes in an ISL.

SuggestedRemedy

Replace "interface" with something more specific and clear. "ISL endpoint" and "ISL lane" could be used as appropriate throughout the clause.

Proposed Response Response Status O

Cl 178B SC 178B.5.1 P788 L15 # 228

Huber, Thomas

Nokia

Comment Type T Comment Status X

This clause appears to be about the process for training each lane of an ISL, so it's not clear why local_rts or remote_rts belong here (since they are about the end-to-end path - although the state diagrams clause suggests that each ISL maybe has its own local_rts and remote_rts - but that would mean that local_rts and remote_rts are not signals that propagate from PCS to PCS). While the intended meaning of 'device' is clear, it would be better to describe the protocol in terms of ISLs and the endpoints of ISLs.

SuggestedRemedy

Clarify what condition it is that causes the propagation_timer to be started... presumably it's not related to local_rts and remote_rts (or if it is, the definitions of local_rts and remote_rts need to be modified to make it clear that they apply to each lane of each ISL, not just to PCS-to-PCS communication).

Proposed Response Response Status O

Cl 178B SC 178B.6.2 P791 L7 # 229

Huber, Thomas

Nokia

Comment Type E Comment Status X

While it is probably not likely that any reader of this annex would get confused, "E1" is of course the name of the European PDH frame structure, so it might be better to avoid using that name. Further, the last sentence "Each interface using ILT shall identify which format is relevant for it" reads too much like a requirement that would show up in a PICS, but that is clearly not what is intended here (the intent being that electrical PHYs use the E format and optical PHYs use the O format).

SuggestedRemedy

The formats E1 and O1 are really about electrical or optical 200G/lane signaling. Maybe it would be better to refer to them that way (i.e., replace "E1" with "electrical 200G/lane" and "O1" with "optical 200G/lane". With that change, the last sentence could be deleted. If the change is made, it should be applied throughout the annex, and potentially in other clauses in the document that may refer to the frame names..

Proposed Response Response Status O

CI 178B SC 178B.7 P795 L4 # 230

Huber, Thomas

Nokia

Comment Type E Comment Status X

It would be better to combine tables 178B-2 and 178B-3 into a single table, with one column for the electrical interfaces and one for the optical interfaces. That would make it easier for the reader to see that the formats are the same, except that on optical links some of the fields are not used. The same applies to tables 178B-4 and 178B-5 in clause 178B.8

SuggestedRemedy

Change the table title to 'Control field structure for 200G/lane interfaces'
 Change the heading of the 3rd column to "Electrical interfaces". Add a fourth column titled "Optical interfaces, and populate it with the information that is in Table 178B-3.
 Delete Table 178B-3
 Make corresponding changes in clause 178B.8 for tables 178B-4 and 178B-5.

Proposed Response Response Status

CI 178B SC 178B.14.2.1 P804 L18 # 231

Huber, Thomas

Nokia

Comment Type T Comment Status X

It is not clear why the ability to enable/disable ILT (via the mr_training_enable variable) is provided. In what circumstance would it be necessary or desirable for ILT to be turned off for any interface that can support it? Providing this ability complicates the feature (there are multiple places where the value of a variable depends on whether mr_training_enable is true or false) and creates the possibility of misconfiguration between two systems, or between a host and a module, complicating the process of bringing up end-to-end paths.

SuggestedRemedy

Reconsider the ability to disable ILT via management configuration.

Proposed Response Response Status

CI 116 SC 116.1.4 P148 L1 # 232

Huber, Thomas

Nokia

Comment Type T Comment Status X

ILT is mandatory for 200G/lane PHYs and AUIs. 178B appears in the tables in the 200G/lane PMD clauses as Required. As such, it should appear in the tables in the introduction as well.

SuggestedRemedy

Update Table 116-3 to show that 178B is conditionally required (based on whether 200G AUIs are used), 116-3aa so show that 178B is mandatory, 116-3a o show it as conditional, 116-3b to show it as mandatory, 116-4 to show it as conditional, 116-4a to show it as mandatory, 116-5 to show it as conditional, and 116-5a to show it as mandatory. There may be older 200G and 400G PMD clauses that also need to be updated to indicate the optional use of the 200G/lane AUIs and conditional use of ILT

Proposed Response Response Status

CI 169 SC 169.1.4 P187 L1 # 233

Huber, Thomas

Nokia

Comment Type T Comment Status X

ILT is mandatory for 200G/lane PHYs and AUIs. 178B appears in the tables in the 200G/lane PMD clauses as Required. As such, it should appear in the tables in the introduction as well.

SuggestedRemedy

Update table 169-2 to show 178B as mandatory for the KR4 and CR4 PHYs and conditional for the KR8/CR8. Update table 169-3 to show 178B as mandatory for xR4 (including FR4-500) and conditional for xR8. Update table 169-3a to include 178B as conditional for all PHYs. It may be necessary to also update the PMD clauses that were updated in 802.3df (for the 800GBASE-xR8 PHYs) to show the new AUIs as optional and ILT as conditional

Proposed Response Response Status

CI 174 SC 174.1.4 P248 L1 # 234
 Huber, Thomas Nokia
 Comment Type T Comment Status X
 ILT is mandatory for 200G/lane PHYs and AUIs. 178B appears in the tables in the PMD clauses as Required. As such, it should appear in the tables in the introduction as well.
 SuggestedRemedy
 Update tables 174-2 and 174-3 to include 178B as conditional for all PMDs
 Proposed Response Response Status O

CI 178A SC 178A P785 L19 # 235
 Mellitz, Richard Samtec
 Comment Type TR Comment Status X
 Re-normalization of s-parameter is not defined in the document
 SuggestedRemedy
 Add new section 178A.2
 The conversion of S s-parameter with reference Z_0 to S' s-parameter with reference Z_1 is computed as follows:

$$S' = A^{(-1)} * (I - S * \rho)^{(-1)} * (S - \rho) * A$$
 where:

$$\rho = (Z_1 - Z_0) / (Z_1 + Z_0)$$

$$A = (Z_1 + Z_0) / \sqrt{Z_1 * Z_0}$$
 S is the original s-parameter matrix with Z_0 as the original diagonal impedance matrix where each diagonal entry is the impedance of that port.
 S' is the new s-parameter matrix with Z_1 as the new diagonal impedance matrix where each diagonal entry is the impedance of that port
 Proposed Response Response Status O

CI 178 SC 178.19 P372 L7 # 236
 Mellitz, Richard Samtec
 Comment Type TR Comment Status X
 Adjust COM voltage to 46.25 ohms measurement reference.
 SuggestedRemedy
 Change
 A_vto 0.415
 A_feto 0.415
 A_netto 0.608
 Proposed Response Response Status O

CI 179 SC 179.11.7.1 P416 L27 # 237
 Mellitz, Richard Samtec
 Comment Type TR Comment Status X
 Adjust COM voltage to 46.25 ohms measurement reference.
 SuggestedRemedy
 Change
 A_vto 0.415
 A_feto 0.415
 A_netto 0.609
 Proposed Response Response Status O

CI 176C SC 176C.7.1 P733 L10 # 238
 Mellitz, Richard Samtec
 Comment Type TR Comment Status X
 Adjust COM voltage to 46.25 ohms measurement reference.
 SuggestedRemedy
 Change
 A_vto 0.415
 A_feto 0.415
 A_netto 0.610
 Proposed Response Response Status O

CI 176D SC 176D.7.2 P750 L23 # 239
 Mellitz, Richard Samtec
 Comment Type **TR** Comment Status **X**
 Adjust COM voltage to 46.25 ohms measurement reference.
 SuggestedRemedy
 Change
 A_vto 0.415
 A_feto 0.415
 A_netto 0.611
 Proposed Response Response Status **O**

CI 172 SC 172 P236 L0 # 240
 Cox, Ian Broadcom
 Comment Type **E** Comment Status **X**
 The header on pages 236-243 reads P802.3df and not dj.
 SuggestedRemedy
 Change the header from 802.3df to 802.3dj
 Proposed Response Response Status **O**

CI 177 SC 177.1 P327 L11 # 241
 Gorshe, Steve Microchip Technology
 Comment Type **E** Comment Status **X**
 The term "SIL" appears in this figure. It is defined in some figures as meaning "Signal Indication Logic" but not in this figure and others.
 SuggestedRemedy
 Since SIL is used in multiple figures without consistent definition, I recommend adding SIL to the abbreviation list in clause 1.5
 Proposed Response Response Status **O**

CI 186 SC 186.2.3.5.10 P590 L14 # 242
 Gorshe, Steve Microchip Technology
 Comment Type **TR** Comment Status **X**
 Why are there 4 Stuff blocks at the beginning of the row 1 payload area in Figure 186-7? The GMP word size (granularity) in each 800GBASE-ER1 frame is one 257-bit block. As shown in Table 186-1, the first block of each 800GBASE-ER1 frame will be a GMP stuff word. Since each of the 8 lanes are mapped into their own 800GBASE-ER1 frame, and GMP mapping is performed per lane, there should be a single stuff block in the first row of Figure 186-7.
 SuggestedRemedy
 If this comment is correct, Figure 186-7 should be modified to begin the payload area with a single stuff block. If the four stuff blocks are correct, an explanation should be added to explain why.
 Proposed Response Response Status **O**

CI 178A SC 178A P777 L26 # 243
 Shakiba, Hossein Huawei Technologies Canada
 Comment Type **TR** Comment Status **X**
 Add quantization noise.
 SuggestedRemedy
 Add a new section "178A.1.7.6 Quantization noise". Please refer to slides 3-5 of the accompanying document for the proposed sub-section content and text.
 Proposed Response Response Status **O**

CI 178A SC 178A.1.7 P774 L50 # 244
 Shakiba, Hossein Huawei Technologies Canada
 Comment Type **TR** Comment Status **X**
 Following first comment, Figure 178A-7 should show addition of the quantization noise after the sampler.
 SuggestedRemedy
 Add quantization noise to the figure. Please refer to slide 6 of the accompanying document for the proposed change.
 Proposed Response Response Status **O**

CI 178A SC 178A.1.7 P775 L2 # 245
 Shakiba, Hossein Huawei Technologies Canada
 Comment Type **TR** Comment Status **X**
 Following first comment, Table 178A-9 should include quantization noise parameters.
SuggestedRemedy
 Add two quantization noise parameters to the table. Please refer to slide 7 of the accompanying document for the proposed change.
 Proposed Response Response Status **O**

CI 178A SC 178A.1.7 P775 L15 # 248
 Shakiba, Hossein Huawei Technologies Canada
 Comment Type **TR** Comment Status **X**
 Following first comment, "sampler" should be replaced with "quantizer".
SuggestedRemedy
 Change "sampler" to "quantizer". Please refer to slide 9 of the accompanying document for the proposed change.
 Proposed Response Response Status **O**

CI 178A SC 178A.1.7 P775 L19 # 246
 Shakiba, Hossein Huawei Technologies Canada
 Comment Type **TR** Comment Status **X**
 Following first comment, Equation (178A-14) should include quantization noise PSD.
SuggestedRemedy
 Add quantization noise PSD to the equation and its description to the descriptions. Please refer to slide 8 of the accompanying document for the proposed change.
 Proposed Response Response Status **O**

CI 178A SC 178A.1.8.1 P777 L43 # 249
 Shakiba, Hossein Huawei Technologies Canada
 Comment Type **TR** Comment Status **X**
 Following first comment, "sampler" should be replaced with "quantizer".
SuggestedRemedy
 Change "sampler" to "quantizer". Please refer to slide 9 of the accompanying document for the proposed change.
 Proposed Response Response Status **O**

CI 178A SC 178A.1.7 P774 L32 # 247
 Shakiba, Hossein Huawei Technologies Canada
 Comment Type **TR** Comment Status **X**
 Following first comment, "sampler" should be replaced with "quantizer".
SuggestedRemedy
 Change "sampler" to "quantizer". Please refer to slide 9 of the accompanying document for the proposed change.
 Proposed Response Response Status **O**

CI 178A SC 178A.1.8.1 P778 L18 # 250
 Shakiba, Hossein Huawei Technologies Canada
 Comment Type **TR** Comment Status **X**
 Following first comment, quantization noise should be added before sampler output is applied to the feed-forward filter in Figure 178A-9.
SuggestedRemedy
 Add quantization noise to the figure. Please refer to slide 10 of the accompanying document for the proposed change.
 Proposed Response Response Status **O**

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

CI 178A SC 178A.1.9.3 P782 L17 # 251
 Shakiba, Hossein Huawei Technologies Canada
 Comment Type **TR** Comment Status **X**
 Following first comment, more text should be added to describe the procedure for deriving the probability density function of the quantization noise.
SuggestedRemedy
 Add the suggested text in slides 11-12 of the accompanying document starting from line 17.
 Proposed Response Response Status **O**

CI 178A SC 178A.1.9.3 P782 L21 # 252
 Shakiba, Hossein Huawei Technologies Canada
 Comment Type **TR** Comment Status **X**
 Following first comment, Equation (178A-36) should include quantization noise PSD.
SuggestedRemedy
 Add quantization noise PSD to the equation. Please refer to slide 13 of the accompanying document for the proposed change.
 Proposed Response Response Status **O**

CI 178A SC 178A.1.10 P783 L19 # 253
 Shakiba, Hossein Huawei Technologies Canada
 Comment Type **TR** Comment Status **X**
 Following first comment, quantization noise should be added before sampler output is applied to the feed-forward filter in Figure 178A-10.
SuggestedRemedy
 Add quantization noise to the figure. Please refer to slide 14 of the accompanying document for the proposed change.
 Proposed Response Response Status **O**

CI 178 SC 178.10.1 P372 L43 # 254
 Shakiba, Hossein Huawei Technologies Canada
 Comment Type **TR** Comment Status **X**
 Following first comment, an updated value for One-sided noise spectral density in Table 178-13 is needed.
SuggestedRemedy
 Change One-sided noise spectral density parameter value in the table (line 43). Please refer to slide 15 of the accompanying document for the proposed change.
 Also, see shakiba_3dj_elec_01_250626.pdf.
 Proposed Response Response Status **O**

CI 178 SC 178.10.1 P372 L1 # 255
 Shakiba, Hossein Huawei Technologies Canada
 Comment Type **TR** Comment Status **X**
 Following first comment, quantization noise parameters should be added to Table 178-13.
SuggestedRemedy
 Add two quantization noise parameters with suggested values to the table. Please refer to slide 15 of the accompanying document for the proposed change.
 Also, see shakiba_3dj_elec_01_250626.pdf.
 Proposed Response Response Status **O**

CI 179 SC 179.11.7.1 P418 L18 # 256
 Shakiba, Hossein Huawei Technologies Canada
 Comment Type **TR** Comment Status **X**
 Following first comment, an updated value for One-sided noise spectral density in Table 179-18 is needed.
SuggestedRemedy
 Change One-sided noise spectral density parameter value in the table (page 418, line 18). Please refer to slide 16 of the accompanying document for the proposed change.
 Also, see shakiba_3dj_elec_01_250626.pdf.
 Proposed Response Response Status **O**

Cl 179 SC 179.11.7.1 P417 L21 # 257

Shakiba, Hossein Huawei Technologies Canada

Comment Type TR Comment Status X

Following first comment, quantization noise parameters should be added to Table 179-18.

SuggestedRemedy

Add two quantization noise parameters with suggested values to the table. Please refer to slide 16 of the accompanying document for the proposed change.

Also, see shakiba_3dj_elec_01_250626.pdf.

Proposed Response Response Status O

Cl 176C SC 176C.7.1 P733 L46 # 258

Shakiba, Hossein Huawei Technologies Canada

Comment Type TR Comment Status X

Following first comment, an updated value for One-sided noise spectral density in Table 176C-8 is needed.

SuggestedRemedy

Change One-sided noise spectral density parameter value in the table (line 46). Please refer to slide 17 of the accompanying document for the proposed change.

Also, see shakiba_3dj_elec_01_250626.pdf.

Proposed Response Response Status O

Cl 176C SC 176C.7.1 P733 L4 # 259

Shakiba, Hossein Huawei Technologies Canada

Comment Type TR Comment Status X

Following first comment, quantization noise parameters should be added to Table 176C-8.

SuggestedRemedy

Add two quantization noise parameters with suggested values to the table. Please refer to slide 17 of the accompanying document for the proposed change.

Also, see shakiba_3dj_elec_01_250626.pdf.

Proposed Response Response Status O

Cl 176D SC 176D.7.1 P751 L23 # 260

Shakiba, Hossein Huawei Technologies Canada

Comment Type TR Comment Status X

Following first comment, an updated value for One-sided noise spectral density in Table 176D-7 is needed.

SuggestedRemedy

Change One-sided noise spectral density in Table 176D-7 (page 751, line 23) value. Please refer to slide 18 of the accompanying document for the proposed change.

Also, see shakiba_3dj_elec_01_250626.pdf.

Proposed Response Response Status O

Cl 176D SC 176D.7.1 P750 L17 # 261

Shakiba, Hossein Huawei Technologies Canada

Comment Type TR Comment Status X

Following first comment, quantization noise parameters should be added to Table 176D-7.

SuggestedRemedy

Add two quantization noise parameters with suggested values to the table. Please refer to slide 18 of the accompanying document for the proposed change.

Also, see shakiba_3dj_elec_01_250626.pdf.

Proposed Response Response Status O

Cl 178A SC 178A.1.10.1 P784 L36 # 262

Shakiba, Hossein Huawei Technologies Canada

Comment Type TR Comment Status X

Proper handling of negative MLSE delta_COM in the COM code was presented in COM ad hoc and approved (shakiba_3dj_COM_02_250408.pdf).
Pointed out by Adee during the discussions, I took the action to look at the implication of this on the draft. This comment is to add a statement to this section to instruct the reader how a possible negative delta_COM should be handled.

SuggestedRemedy

Add a new paragraph at the end of this section with the following content:
"Due to the addition of this additional receiver noise when calculating the advantage of the MLSD-based receiver, there may be occasional cases where the DFE-based receiver performs better. In these cases, the MLSD function should be disabled. This can be done by ignoring the last term in Equation (178A-38) and setting it to zero and setting COM to COM_DFE. This process should also be applied if for any other reason, such as approximations in math and calculations, similar cases are encountered."

Proposed Response Response Status O

Cl 176B SC 176B P699 L12 # 263

Ofelt, David Juniper Networks

Comment Type TR Comment Status X

We have changed the ppm tolerance of the 200Gb/s SERDES to be 50ppm in all cases. This leads to interoperability issues when plugging an older PMD (generated with 25Gb/s or 50Gb/s SERDES) into a new 200Gb/s SERDES-based receiver or when a new 802.3dj PMD is plugged into an older box using 25Gb/s or 50Gb/s SERDES due to the fact one end of those links generates data at 100ppm and the receive side can only handle 50ppm. The solution is to insert an XS to do rate matching. At the moment, I believe this interop issue is not called out anywhere in the draft. I'd like to add in something in the draft to bring the reader's attention to the fact that this issue exists. Adding the required XS also will cause PTP accuracy to suffer. Note that this was not an issue in the 100Gb/s SERDES because they were specified to tolerate 100pm at the receiver, so there were no multi-generational interop issues. This is also not a problem when 100Gb/s source and 200Gb/s sourced PMDs are connected because the 100Gb/s SERDES are specified to have transmitters that are 50ppm.

SuggestedRemedy

Unhelpfully, I don't have fully worked out edit, but will be happy to work with the editorial team in finding a solution. One approach would be to add two examples in clause 176B showing the stack with an included XS for an existing 100ppm-based PMD plugged into a new 200Gb/s-based host and a new 200Gb/s sourced PMD plugged into an older system. We should also include a comment that PTP performance will be impacted due to the requirement for that XS to add or delete idles to match the rates. Another approach would be to add a comment to all the places that 50ppm receiver tolerance is specified, but there are a lot of those and the way 176B is structured seems to lend itself well to documenting this issue.

Proposed Response Response Status O

Cl 186 SC 186.2.3.8 P591 L52 # 264

Wang, Xuebo Huawei

Comment Type E Comment Status X

"OBFG84" should be changed to "OFBG84" as OFBG is the abbreviation of OFEC block group in ITU-T G709.6.

SuggestedRemedy

Change "OBFG84" to "OFBG84".

Proposed Response Response Status O

Cl 186 SC 186.2.4.1 P594 L9 # 265

Wang, Xuebo

Huawei

Comment Type T Comment Status X

The number 344064 should be 172032. Each DP-16QAM symbol represents 8 bits, then 1376256 bits should correspond to 172032 DP-16QAM symbols.

SuggestedRemedy

Change "344064" to "172032".

Proposed Response

Response Status O

Cl 176B SC 176B.4 P702 L40 # 266

Wang, Xuebo

Huawei

Comment Type T Comment Status X

The current content of PMA instantiations seems to include interfaces with all possible data rates per lane. However, for 200 Gb/s and 400 Gb/s physical layer implementations in Annex 176B.4 and Annex 176B.5, some cases are missing. For example, some interfaces with 25 Gbps per lane and 50 Gbps per lane are not included for now. For a complete presentation, it is suggested to add those missing cases.

SuggestedRemedy

1. On Page 702, Line 42: change the title "8:1 and 8:2 PMA instantiations for 200GBASE-R PHYs" to "8:4, 8:2 and 8:1 PMA instantiations for 200GBASE-R PHYs" to include PMD with four 50 Gb/s physical lanes.
2. On Page 703, Line 11: change "n = 2 or 4" to "n = 2, 4 or 8" to include 200GAUI-8 interface.
3. On Page 704, Line 21 and 22: change "{n,p}" to "p". This change is consistent with the style used in Table 176B-1 and avoids the trouble of listing all possible values of n.
4. On Page 704, Line 35, change "120E (C2M)" to "120D (C2C)". This should be a typo.
5. On Page 704, Line 44, change "n = 2 or 4" to "n = 2, 4 or 8" to include 200GAUI-8 interface.
6. On Page 705, Line 11, change "120E (C2M)" to "120D (C2C)". This should be a typo.
7. On Page 705, Line 17, change "n = 2 or 4" to "n = 2, 4 or 8" to include 200GAUI-8 interface.
8. On Page 705, Line 23 and 24: change "{n,p}" to "p". This change is consistent with the style used in Table 176B-1 and avoids the trouble of listing all possible values of n.
9. On Page 707, Line 30, change the title "16:8, 16:4, and 16:2 PMA instantiations for 400GBASE-R PHYs" to "16:16, 16:8, 16:4, and 16:2 PMA instantiations for 400GBASE-R PHYs" to include 400GBASE-SR16 PMD.
10. On Page 707, Line 36, change "p is 2, 4, or 8" to "p is 2, 4, 8, or 16".
11. On Page 708, Line 4, change "16:{4,8,16}:{4,8}, 16:4:4" to "16:{4,8,16}:{4,8,16}".
12. Change "{4,8}" in table titles to "{4,8,16}" in Line 21 on Page 708, Line 4 and Line 28 on Page 709, Line 4 and Line 30 on Page 710.
13. On Page 708, Line 8, change "n=4" to "n=4, 8, or 16" to include 400GAUI-8 and 400GAUI-16 interfaces.
14. On Page 708, Line 14, change "p=4" to "p=4, 8, or 16" to include PMDs with 8 and 16 physical lanes.
15. On Page 708, Line 34, change "p=4: or 8" to "p=4, 8, or 16" to include PMD with 16 physical lanes.
16. In Line 49 on Page 709 and Line 53 on Page 710, change "p=4 or 8" to "p=4, 8, or 16" to include PMD with 16 physical lanes.
17. On Page 710, Line 15 and 16, change "{m, n}" to "m" since n is not used.
18. On Page 710, Line 17, change "n=4 or 8" to "n=4, 8, or 16" to include 400GAUI-16 interface.
19. On Page 710, Line 20, add "n=16: 120C (C2C)" to include 400GAUI-16 C2C.
20. On Page 710, Line 23, change "{n,p}=4 or 8" to "{n,p}=4, 8, or 16".

A contribution covering all the remedies will be provided.

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Proposed Response Response Status

Cl 186 SC 186.3.3.2 P602 L51 # 267

Wang, Xuebo Huawei

Comment Type E Comment Status X

"mfas<0:21>" should be changed to "faw<0:21>", as it is shortened from multi-frame alignment word per CL186.3.3.5.

SuggestedRemedy

Change "mfas<0:21>" to "faw<0:21>".

Proposed Response Response Status

Cl 186 SC 186.3.3.2 P603 L9 # 268

Wang, Xuebo Huawei

Comment Type T Comment Status X

"S<7023:7075>" should be changed to "S<7013:7075>". Each 800GBASE-ER1 PMA frame contains 114 rows of 64 symbols per Line 46 on Page 602 in CL186.3.3.2. S<7013:7075> consists of the 63 payload symbols of row 113 led by the pilot symbol P113.

SuggestedRemedy

Change "S<7023:7075>" to "S<7013:7075>".

Proposed Response Response Status

Cl 178B SC 178B.14.3.5 P810 L13 # 269

Wang, Xuebo Huawei

Comment Type T Comment Status X

There is no time out for exiting the state SEND_TRAINING. If either local_tf_lock or remote_tf_lock is false for a long time, the whole state diagram will be trapped in the state SEND_TRAINING for long. A maximum time duration for this state should be set.

SuggestedRemedy

A contribution to address this will be provided.

Proposed Response Response Status

Cl 176B SC 176B.2 P700 L8 # 270

Wang, Xuebo Huawei

Comment Type E Comment Status X

"of" is missing between "the number" and "upper".

SuggestedRemedy

Add "of" between "the number" and "upper".

Proposed Response Response Status

Cl 176B SC 176B.2 P701 L40 # 271

Wang, Xuebo Huawei

Comment Type E Comment Status X

Typo: "my" should be changed to "may".

SuggestedRemedy

Change "my" to "may".

Proposed Response Response Status

Cl 176B SC 176B.3 P702 L22 # 272

Wang, Xuebo Huawei

Comment Type T Comment Status X

"4:32 BM-PMA" should be changed to "4:32 SM-PMA", as the PMA above it is an SM-PMA.

SuggestedRemedy

Change "4:32 BM-PMA" to "4:32 SM-PMA".

Proposed Response Response Status

Cl 176B SC 176B.4.2 P706 L3 # 273

Wang, Xuebo Huawei

Comment Type T Comment Status X

"Figure 176B-2" should be changed to "Figure 176B-3", as the Extender is shown in Figure 176B-3 instead of 176B-2. The same issue happens in Line 3 on Page 711.

SuggestedRemedy

Change "Figure 176B-2" to "Figure 176B-3" in Line 3 on Page 706 and Line 3 on Page 711.

Proposed Response Response Status

Cl 176B SC 176B.6.1 P713 L28 # 274
 Wang, Xuebo Huawei
 Comment Type T Comment Status X
 The note should describe how an n:p PMA is formed instead of an m:n PMA
 SuggestedRemedy
 Change the sentence "The combination of m:32 PMA and 32:n PMA forms an m:n PMA" to "The combination of n:32 PMA and 32:p PMA forms an n:p PMA".
 Proposed Response Response Status O

Cl 176B SC 176B.7.2 P718 L24 # 277
 Wang, Xuebo Huawei
 Comment Type E Comment Status X
 "n=16" and "n=8" should be changed to "m=16" and "m=8", as the corresponding row is of 1.6TAUI-m.
 SuggestedRemedy
 Change "n=16" to "m=16" in Line 24 on Page 718;
 Change "n=8" to "m=8" in Line 25 on Page 718.
 Proposed Response Response Status O

Cl 176B SC 176B.6.2 P715 L44 # 275
 Wang, Xuebo Huawei
 Comment Type T Comment Status X
 The symbol-multiplexed interfaces and bit-multiplexed interfaces are denoted by "S" and "B", respectively, per CL176B.6.2. However, "S" and "B" are missing in the titles of Table 176B-25. The same issue happens in the titles of 176B-26 and 176B-27 in Line 4 and 24 on Page 716. The missing also does not fit with the title style of other tables in Annex 176B.
 SuggestedRemedy
 Change the title of Table 176B-25 "800 Gb/s 32:4:32 and 32:8:32 PMA instantiations" to "800 Gb/s 32:4:32 and 32:8:32 (S or B) PMA instantiations";
 Change the title of Table 176B-26 "800 Gb/s 32:8:8:32 and 32:4:4:32 (n = m) PMA instantiations" to "800 Gb/s 32:8:8:32 and 32:4:4:32 (n = m, BB or SS) PMA instantiations";
 Change the title of Table 176B-27 "800 Gb/s PMA 32:4:8:32 and 32:8:4:32 (n≠m) instantiations" to "800 Gb/s 32:4:8:32 and 32:8:4:32 (n≠m, SB or BS) PMA instantiations".
 Proposed Response Response Status O

Cl 176B SC 176B.4.2 P706 L1 # 278
 Wang, Xuebo Huawei
 Comment Type E Comment Status X
 The title should not include "200GBASE-R PHYs" as the sub-clause only talks about Extender. The same issue happens in Line 1 on Page 711 of CL176B.5.2 and Line 27 on Page 715 of CL176B.6.2.
 SuggestedRemedy
 Delete "200GBASE-R PHYs" in Line 1 on Page 706;
 Delete "400GBASE-R PHYs" in Line 1 on Page 711;
 Delete "800GBASE-R PHYs" in Line 27 on Page 715.
 Proposed Response Response Status O

Cl 176B SC 176B.7.1 P717 L2 # 276
 Wang, Xuebo Huawei
 Comment Type E Comment Status X
 "or 8" is redundant.
 SuggestedRemedy
 Delete "or 8" in Line 2 on Page 717.
 Proposed Response Response Status O

Cl 176B SC 176B.6.2 P715 L39 # 279
 Wang, Xuebo Huawei
 Comment Type T Comment Status X
 PMD does not exist in Extender. The example should be like: an instantiation with a one S 800GAUI-n and one B 800GAUI-n is denoted "SB" or "BS".
 SuggestedRemedy
 Change "one B PMD" to "one B 800GAUI-n".
 Proposed Response Response Status O

CI 176B SC 176B.5.1 P710 L10 # 280

Wang, Xuebo

Huawei

Comment Type E Comment Status X

A colon is missing between m=2 and 176. The same happens in Line 16, 19, 24, 36, 42, 45, and 51 on Page 710.

SuggestedRemedy

Add a colon between 2 and 176 in Line 10, 16, 19, 24, 36, 42, 45, and 51 on Page 710.

Proposed Response

Response Status O

CI 177 SC 177.5.2 P337 L19 # 281

Ren, Hao

Huawei

Comment Type TR Comment Status X

The definition of the candidate location and the synchronization location is not clear.

The candidate location is the inner FEC codeword boundary of a valid set of codewords. The candidate location is regarded as the synchronization location when the candidate location is confirmed valid for a second window of 128b-bit blocks.

SuggestedRemedy

Change:

The synchronization process searches for a valid set of codewords in a window of 128-bit blocks, confirms the candidate location is valid for a second window of 128b-bit blocks and then monitors that the synchronization location continues to be valid during operation.

to:

[A]: The synchronization process searches for a valid set of codewords in a window of 128-bit blocks. The boundary of these codewords is marked as candidate location, which is confirmed as the synchronization location if it is valid for a second window of 128b-bit blocks. The synchronization process continuously validates the synchronization location during operation.

[B]: The synchronization process searches for a valid set of codewords in a window of 128-bit blocks, marking the boundary of these codewords as candidate location, confirms the candidate location as synchronization location by validating for a second window of 128b-bit blocks, and then monitors that the synchronization location continues to be valid during operation.

Proposed Response

Response Status O

CI 177 SC 177.5.5 P339 L5 # 282

Ren, Hao

Huawei

Comment Type TR Comment Status X

The number of Inner_FEC_codeword_error_bin_k counters can be decreased. k = 0 should be ignored, because this counter value can be calculated from other counters. Also in 802.3ck, k=0 is not set for RS-FEC error bin counter as in 161.6.17.

SuggestedRemedy

Change:

A set of four 32-bit counters where counter k counts once for each codeword received with exactly k bits corrected (flipped) when fas_lock is true (k = 0 to 3).

to:

A set of three 32-bit counters where counter k counts once for each codeword received with exactly k bits corrected (flipped) when fas_lock is true (k = 1 to 3).

Proposed Response

Response Status O

CI 184 SC 184.5.7 P543 L42 # 283

Ren, Hao

Huawei

Comment Type TR Comment Status X

The number of Inner_FEC_codeword_error_bin_k counters can be decreased. k = 0 should be ignored, because this counter value can be calculated from other counters. Also in 802.3ck, k=0 is not set for RS-FEC error bin counter as in 161.6.17.

SuggestedRemedy

Change:

A set of k+1 32-bit counters where k = 0 to 4.

to:

A set of k 32-bit counters where k = 1 to 4.

Proposed Response

Response Status O

CI **FM** SC **FM** P12 L54 # 284

Maguire, Valerie Copperopolis; aff'l w/ CME Consulting and Cisco

Comment Type **E** Comment Status **X**

Missing information on the P802.3da amendment

SuggestedRemedy

Insert,
 "IEEE Std 802.3da™-20xx
 Amendment 1X—This amendment to IEEE Std 802.3-2022 specifies additions and appropriate modifications to enhance the 10 Mb/s shared-medium (multidrop) mode of the 10BASE-T1S Physical Layer in a new, multidrop-only physical layer specification (including reconciliation sublayers, management parameters, Ethernet support for time synchronization protocols, and optional power delivery to support multiple Powered Devices on the 10 Mb/s mixing segment)."

Proposed Response Response Status **O**

CI **180** SC **180.8.1** P443 L44 # 285

Maguire, Valerie Copperopolis; aff'l w/ CME Consulting and Cisco

Comment Type **TR** Comment Status **X**

The cabled optical fiber attenuation characteristics in Table 180-11, Table 181-9, Table 182-11, and Table 183-10 and associated intro text need a careful look... The current revision of the TIA Optical Fiber Cabling and Components Standard is ANSI/TIA-568.3-E. The document specifies B-652.D or B-657 as acceptable fiber for Outside Plant cables and specifies the maximum cabled attenuation as 0.4 dB/km at 1310nm, 1383nm, and 1550nm. While it's true that ANSI/TIA-568.3-E specifies the maximum cabled attenuation as 0.5 dB/km at 1310nm and 1550nm, this is not aligned with B-652.D or B-657 (OS2) as mentioned in the intro paragraph to each table. A dash is missing between "TIA" and "568" in the ANSI/TIA-568.3-C reference. Unecessary commas between 'or' statements. I think what the draft is trying to do is accomodate legacy installed OSP cabling, but calling out 'newer, higher performing cables with exceptions' as the specification is a confusing way to do this.

SuggestedRemedy

Option A, in Table 180-11, Table 181-9, Table 182-11, and Table 183-10 and their corresponding intro text:
 Replace "The optical fiber cable requirements are satisfied by cables containing ITU-T type G.652.D (low water peak, dispersion unshifted), or type G.657.A1, or type G.657.A2 (bend insensitive) fibers, or the requirements in Table 18x-yy where they differ." with "The optical fiber cable requirements are satisfied by cables meeting the characteristics in Table 18x-yy. The use of optical fiber cables containing ITU-T type G.652.D (low water peak, dispersion unshifted), type G.657.A1, or type G.657.A2 (bend insensitive) fibers is recommended."
 Replace "ANSI/TIA 568-C.3" with "ANSI/TIA-568-C.3"

Option B, in Table 180-11, Table 181-9, Table 182-11, and Table 183-10 and their corresponding intro text:
 Replace "The optical fiber cable requirements are satisfied by cables containing ITU-T type G.652.D (low water peak, dispersion unshifted), or type G.657.A1, or type G.657.A2 (bend insensitive) fibers, or the requirements in Table 18x-yy where they differ." with "The optical fiber cable requirements are satisfied by cables meeting the characteristics in Table 18x-yy. Optical fiber cables containing ITU-T type G.652.D (low water peak, dispersion unshifted), type G.657.A1, or type G.657.A2 (bend insensitive) fibers are examples of cables that exceed these requirements."
 Replace "ANSI/TIA 568-C.3" with "ANSI/TIA-568-C.3"

Option C, in Table 180-11, Table 181-9, Table 182-11, and Table 183-10 and their corresponding intro text:
 Replace "0.5" with "0.4"
 Replace "...ITU-T type G.652.D (low water peak, dispersion unshifted), or type G.657.A1, or type G.657.A2 (bend insensitive) fibers, or the requirements in Table 18x-yy where they differ." with "...ITU-T type G.652.D (low water peak, dispersion unshifted), type G.657.A1, type G.657.A2 (bend insensitive), or other fibers meeting the requirements in Table 18x-yy."
 Replace "ANSI/TIA 568-C.3" with "ANSI/TIA-568-E.3"

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Proposed Response Response Status

Cl 183 SC 183.8.2 P518 L26 # 286

Johnson, John Broadcom

Comment Type TR Comment Status X

CL 183.8.2 should be rewritten to mirror the subclause structure and text in CL 180.8.2, with editorial license, including tables of maximum channel insertion loss versus the number of discrete reflections, as discussed in consensus presentation johnson_3dj_01_2505.

SuggestedRemedy

Make the following changes to CL 183.8.2:

1. Re-write CL 183.8.2 using the structure and text in CL 180.8.2, with editorial license.
2. Delete old Table 183-11, maximum value of each discrete reflectance.
3. Insert new Table 183-xx, Maximum channel insertion loss versus number of discrete reflectances for 800GBASE-FR4, with the values given in johnson_3dj_01_2507, slide 17.
4. Insert new Table 183-yy, Maximum channel insertion loss versus number of discrete reflectances for 800GBASE-LR4, with the values given in johnson_3dj_01_2507, slide 18.

Supporting editorial instructions are provided in johnson_3dj_01_2507

Proposed Response Response Status

Cl 183 SC 183.8 P517 L24 # 287

Johnson, John Broadcom

Comment Type TR Comment Status X

Channel insertion loss (max) in Table 183-9 should point to new Tables 183-xx for FR4 and 183-yy for LR4.

SuggestedRemedy

In Table 183-9,

1. Replace Channel insertion loss(max) value 4 dB with "See Table 183-xx", and 6.3 dB with "See Table 183-yy".
2. Add text in CL 183.8 similar to text in CL 180.8: "The maximum value of channel insertion loss is dependent on the number and maximum value of the discrete reflectances within the channel as given in Table 183-xx for 800GBASE-FR4 and Table 183-yy for 800GBASE-LR4. Discrete reflectances below -55 dB may be ignored when determining the supported channel insertion loss." with editorial license.

Supporting editorial instructions are provided in johnson_3dj_01_2507

Proposed Response Response Status

Cl 183 SC 183.7.3 P515 L32 # 288

Johnson, John Broadcom

Comment Type TR Comment Status X

The footnotes in Table 183-8 must be updated to refer to the revised structure of CL 183.8.2.

SuggestedRemedy

In Table 183-8, make the following changes:

Replace footnotes following the form of Table 180-9, with changes appropriate to CL 183, as given in johnson_3dj_01_2507, slide 16.

Supporting editorial instructions are provided in johnson_3dj_01_2507

Proposed Response Response Status

Cl 179A SC 179A.5 P820 L39 # 289

Heck, Howard TE Connectivity

Comment Type TR Comment Status X

MCB loss specified in the lower left of Figure 179A-1 is not directly measurable as it is currently specified. Indirect measurement methods do not provide the necessary accuracy. The version of the figure in D1.4 was measureable and reverting back to it will resolve the problem. Equation 179B-2 requires modification to make it accurately represent the MCB insertion loss measured with the 2Xthru method

SuggestedRemedy

Change Figure 179A-1 back to the version that was in D1.4 in which the MCB loss was specified as 2.7dB to the MCB via. Change Equation 179B-2 to $IL_{catref} = -0.0067 * f^{1.5} + 0.0309 * f - 0.2523 * \sqrt{f} + 0.0868$. Change the ldd_catf curve in Figure 179B-1 to match the updated equation. A supporting contribution is planned for presentation at the June 26 electrical ad hoc meeting.

Proposed Response Response Status

Cl 178B SC 178B.5 P787 L37 # 290

Brown, Matt Alphawave Semi

Comment Type TR Comment Status X

The term inter-sublayer link training (or ILT) by name defines a protocol over an inter-sublayer link (or ISL). Each ISL is one of several possible physical links between a pair of MAC sublayers. It is possible only a subset of the ISLs supports ILT. Annex 178B also defines a path start-up protocol which uses the outcome of ILT on each of the physical links, where supported, to determine when the path between a pair of PCs or between a pair of extender suppliers is ready, allowing for some ISLs that do not support ILT. However, the combination of these two layers of functionality are references only as ILT. This is confusing!

SuggestedRemedy

Within Annex 178B, clearly differentiate these two processes (inter-sublayer link training and path-start-up protocol) as being separate from each other, rather than ILT being a combination of these two. ILT would refer to the process with operates on a specific ISL and with PSP the process that links the states of all ISL on a path. Throughout the draft specify and references these two functions separately. A contribution will be provide to explore this further.

Proposed Response Response Status O

Cl 178B SC 178B.5.1 P788 L30 # 291

Brown, Matt Alphawave Semi

Comment Type TR Comment Status X

There seems to be some confusion around whether ISL is required or optional. Clause 178 through 183 there is rather definitive text specification that indeed ISL is mandatory to implement, but with the ability to enable and disable. Text in 178B.5.1 allows for a case where training is not available with clarification "(disabled or not defined for the interface type)", the latter portion meaning that there is no normative text in the clause or annex. However, it may be helpful to circumvent any confusing and add some clear text at the begin of Annex 178B stating that the requirement for ILT for each interface is defined by the Clause or Annex the specifies the interface and perhaps even adding table list interfaces for which it is mandatory.

SuggestedRemedy

Add the following sentence or similar to the first paragraph in 178B.4: "The mandatory or optional implementation of the ILT function is specified in the clause or annex that defines the interface."

Proposed Response Response Status O

Cl 174A SC 174A P677 L21 # 292

Brown, Matt Alphawave Semi

Comment Type TR Comment Status X

Diagrams showing the various paths or domains described in 174A.3 through 174A.7 would be very helpful to the reader of the annex.

SuggestedRemedy

Add a diagrams illustrating the paths described in 174A.3 through 174A.7.

Proposed Response Response Status O

Cl 00 SC 0 P0 L0 # 293

Brown, Matt Alphawave Semi

Comment Type T Comment Status X

The PICS subclause in many clauses and annexes is incomplete.

SuggestedRemedy

Update PICS subclause in all clauses and annexes as necessary.

Proposed Response Response Status O

Cl 177A SC 177A P765 L21 # 294

Brown, Matt Alphawave Semi

Comment Type TR Comment Status X

The referenced test vectors do not include scrambling of pad bits as specified in 177.4.7.2 as the requirement scrambling was added in a later draft.

SuggestedRemedy

Provide a new test vector set which includes scrambling of the pad bits.

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

CI 45 SC 45.2.1.264 P112 L5 # 295
Brown, Matt Alphawave Semi
Comment Type E Comment Status X
Use of possessive grammar is inconsistent with similar phrases used through this draft and is unnecessary here.
SuggestedRemedy
Change "Lane 0's" to "Lane 0"
Change "Lane 1's" to "Lane 1"
Proposed Response Response Status O

CI 73 SC 73.4.2 P130 L15 # 296
Brown, Matt Alphawave Semi
Comment Type E Comment Status X
Use of possessive grammar is inconsistent with similar phrases used through this draft and is unnecessary here.
SuggestedRemedy
Change "link partner's" to "link partner"
Also on page 131 line 51
Proposed Response Response Status O

CI 169 SC 169.2.10 P190 L42 # 297
Brown, Matt Alphawave Semi
Comment Type T Comment Status X
ILT is supported not just in the PHYs, but also in the xMII extenders and not limited to the PHY types listed here.
SuggestedRemedy
Change to:
A physical layer implementation supports ILT if any of the following are implemented:
800GBASE-KR4, 800GBASE-CR4, 800GBASE-DR4, 800GBASE-FR4-500, 800GBASE-DR4-2, 800GBASE-FR4, 800GBASE-LR4, 800GAUI-4 C2C, 800GAUI-4 C2M.
Update 116.2.9 and 174.2.12 similarly.
Implement with editorial license.
Proposed Response Response Status O

CI 175 SC 175.2.4.6 P265 L28 # 298
Brown, Matt Alphawave Semi
Comment Type E Comment Status X
Use of possessive grammar is inconsistent with similar phrases used through this draft and is unnecessary here.
SuggestedRemedy
Change "PCS lane's" to "PCS lane"
Proposed Response Response Status O

CI 176 SC 176.4.3 P273 L46 # 299
Brown, Matt Alphawave Semi
Comment Type E Comment Status X
The would "may" is to be used for the context "is allowed to".
SuggestedRemedy
Change "is allowed to" to "may".
Implement same in 179.9.5.2.
Proposed Response Response Status O

CI 178 SC 178.7 P359 L23 # 300
Brown, Matt Alphawave Semi
Comment Type T Comment Status X
There are no "FEC lanes". This is likely a carry-over from 802.3ck for 100GBASE-KR1 which indeed does have FEC lanes.
SuggestedRemedy
Change "PCS or FEC" to "PCS".
Proposed Response Response Status O

Cl 178 SC 178.8.1 P360 L38 # 301

Brown, Matt Alphawave Semi

Comment Type E Comment Status X

Use of possessive grammar is inconsistent with similar phrases used through this draft and is unnecessary here.

SuggestedRemedy

Change "transmitter's" to "transmitter"
 Change "receiver's" to "receiver"
 Implement similar in Figure 179-2, Table 179-10, Figure 176C-2, Table 176C-4, Table 176D-4, Table 176D-5,
 On page 723 line 26 change "component's" to "component".
 On page 756 line 1 change "transmitter's measured parameters" to "measured transmitter parameters"

Proposed Response Response Status O

Cl 178 SC 178.8.1 P360 L33 # 302

Brown, Matt Alphawave Semi

Comment Type ER Comment Status X

Figure 178-2. The interface at TP0 is helpfully labelled as "package-to-board interface". A similar label would be helpful at TP0d.

SuggestedRemedy

Add a label at TP0d "die-to-package interface".
 Apply similar change to Figure 176C-2.

Proposed Response Response Status O

Cl 178 SC 178.8.1 P360 L23 # 303

Brown, Matt Alphawave Semi

Comment Type TR Comment Status X

The PMD ends and the medium begins at the MDI. According to 178.11 the MDI is at TP0 and TP5, not at TP0d and TP5d. Further, in most cases "channel" spans from TP0 to TP5; though there are some cases that reference the TP0d to TP5d channel, e.g., "Maximum insertion loss from Tp0d to Tp5d, ILdd, at 53.125 GHz (recommended)" in Table 178-11.

SuggestedRemedy

In Figure 178-2, make the following changes:
 Show the PMD ending and "channel" beginning at TP0 and TP5.
 Add a label at TP0 and TP5 "MDI".
 Apply similar changes to Figure 176C-2.

Proposed Response Response Status O

Cl 178 SC 178.8.1 P360 L32 # 304

Brown, Matt Alphawave Semi

Comment Type ER Comment Status X

The die is labelled "device", whereas the "device" is the combination of die and package.

SuggestedRemedy

Change label pointing to the die on the left side of the Figure 178-2 to "Die".

Proposed Response Response Status O

Cl 178 SC 178.8.9 P361 L25 # 305

Brown, Matt Alphawave Semi

Comment Type TR Comment Status X

Regarding "control the transmitter on each lane of the MDI". It's really controlling the PMD transmitter not the MDI and to be clear it is controlling the PMD transmitter only in response to requests from the link peer interface.

SuggestedRemedy

Change "control the transmitter output on each lane of the MDI" to "control the PMD transmitter output on each lane based on requests from the peer interface".
 Implement similarly in 179.8.9, 176C.3, and 176D.3.

Proposed Response Response Status O

Cl 178 SC 178.9.2.1 P363 L6 # 306

Brown, Matt Alphawave Semi

Comment Type TR Comment Status X

Figure 178-3. It is ambiguous where the test fixture begins. The intent is that the text fixture begins at TP0. Also, it would be good to properly describe the TP0d interface. This figure nor the text definitely define the start and end points of the test fixture.

SuggestedRemedy

In Figure 178-3 do the following:
 Add test point TP0 at the "package-to-board interface".
 Draw a dashed line at this TP0 interface.
 Adjust the test fixture line/arrow to end at this TP0 interface.
 Add a label at the TP0d interface "die-to-package interface".
 In 178.9.2.1 add the following sentence...
 "The transmitter test fixture is between TP0 and TP0v."
 Make similar updates for the receiver test fixture in 178.9.3.1 and Figure 178-4.

Proposed Response Response Status O

Cl 178 SC 178.9.2.1.2 P363 L25 # 307

Brown, Matt Alphawave Semi

Comment Type T Comment Status X

It appears that to measure ERL properly the test fixture would have to be terminated at TP0 with an appropriate impedance or reflections from the device under test would have to be gated out.

SuggestedRemedy

Provide appropriate guidance for measuring the ERL at TP0v.

Proposed Response Response Status O

Cl 178 SC 178.9.2.2 P364 L3 # 308

Brown, Matt Alphawave Semi

Comment Type T Comment Status X

As is done for other parameters, it would be helpful to follow "difference ERL" with variable name "dERL".

SuggestedRemedy

Change "difference ERL" to "difference ERL dERL" where dERL is italic.
 Make a similar change in other subclause throughout that specify dERL.

Proposed Response Response Status O

Cl 178 SC 178.9.2.2 P364 L4 # 309

Brown, Matt Alphawave Semi

Comment Type T Comment Status X

Likely, Table 178-7 should be Table 178-8.

SuggestedRemedy

Change cross-reference from "Table 178-7" to "Table 178-8".

Proposed Response Response Status O

Cl 178 SC 178.9.3.2 P366 L23 # 310

Brown, Matt Alphawave Semi

Comment Type T Comment Status X

178.9.3.3 should be compliant over the range as well.

SuggestedRemedy

Change "178.9.3.4 and 178.9.3.5" to "178.9.3.3 through 178.9.3.5"

Proposed Response Response Status O

Cl 178 SC 178.9.3.3 P366 L32 # 311

Brown, Matt Alphawave Semi

Comment Type T Comment Status X

The more formal word "may" should be used instead of "is allowed to". Per style guide: "The word may is used to indicate a course of action permissible within the limits of the standard (may equals is permitted to)."

SuggestedRemedy

Change "is allowed to" to "may".
 Implement also on page 727 line 13, page 755 line 16.

Proposed Response Response Status O

Cl 178 SC 178.9.3.4.1 P366 L50 # 312

Brown, Matt Alphawave Semi

Comment Type T Comment Status X

So crosstalk is noise, so in this sentence what is "noise", also crosstalk and noise are not distortions per se, but rather perturbations. Is noise referring to alien noise or intrinsic noise? Distortion implies a changing of the launched signal such as insertion loss, bandwidth, and non-linearity, which I don't think are intended here.

SuggestedRemedy

Change "The channel noise source emulates crosstalk, noise, and any other non-equalizable signal distortions that may be introduced by a transmitter or channel."

To "The channel noise source emulates crosstalk, alien and intrinsic noise, and any other non-equalizable signal perturbations that may be introduced by a transmitter or channel."

Proposed Response Response Status O

Cl 178 SC 178.9.3.4.2 P367 L17 # 313

Brown, Matt Alphawave Semi

Comment Type ER Comment Status X

It is not clear which text below this table are exceptions vs addition material. Usually, we use a dashed list to annotate the exceptions.

SuggestedRemedy

Identify the relevant exceptions within a dashed list.

Proposed Response Response Status O

Cl 178 SC 178.9.3.4.2 P367 L21 # 314

Brown, Matt Alphawave Semi

Comment Type E Comment Status X

This is not an ordered list so should be formatted as dashed list.

SuggestedRemedy

Reformat as dashed list.

Proposed Response Response Status O

Cl 178 SC 178.9.3.4.2 P367 L35 # 315

Brown, Matt Alphawave Semi

Comment Type E Comment Status X

This is not an ordered list so should be formatted as dashed list. Further, it is not permitted to use the same list values (e.g., a), b), c)), for two separate lists within the same subclause.

SuggestedRemedy

Reformat as dashed list.

Proposed Response Response Status O

Cl 178 SC 178.9.3.4.3 P368 L21 # 316

Brown, Matt Alphawave Semi

Comment Type T Comment Status X

Per style guide this should be lettered list, not numbered list.

SuggestedRemedy

Reformat as lettered list.

Proposed Response Response Status O

Cl 178 SC 178.9.3.4.3 P368 L44 # 317

Brown, Matt Alphawave Semi

Comment Type E Comment Status X

The noise is RMS so not defined by amplitude. Also, "higher noise" here is compound adjective so should be hyphenated.

SuggestedRemedy

Change "higher amplitude" to "higher voltage" or "higher noise" or similar. If the current wording is desired, then add a hyphen "higher-amplitude".

Proposed Response Response Status O

CI 178 SC 178.9.3.5 P369 L7 # 318

Brown, Matt Alphawave Semi

Comment Type TR Comment Status X

This phrase is hard to parse: "and both JRMS and J4u03 are measured with the jitter frequency and amplitude set according to Case F from Table 179-12." I think it means that J_RMS and J4u_03 are measured after the sinusoidal jitter with frequency and amplitude for Table 179-12 is applied. Also, I think this can be broken into a pair of subbullets for clarity.

SuggestedRemedy

Change to:
 -- For the COM parameter calibration described in 93C.2 item 7):
 -- J4u is substituted by J4u03
 -- JRMS and J4u03 are measured with applied sinusoidal jitter with frequency and amplitude set according to Case F from Table 179-12

Proposed Response Response Status O

CI 178 SC 178.10 P370 L26 # 319

Brown, Matt Alphawave Semi

Comment Type T Comment Status X

The bounds of the "channel" are never defined. And, in fact, the specifications are for two different channels: one is MDI to MDI (or TP0 to TP1) and the other is die to die (or TP0d to TP5d). The former is prevalent, and latter only for the 40 dB insertion loss limit in 178.10.2 and AC-coupling in 178.10.6.

SuggestedRemedy

In the opening paragraph in 178.10 and the following sentence or similar. "Unless otherwise indicated, the channel is bounded TP0 and TP5."
 In Table 178-11 change "Maximum AC-coupling 3 dB corner frequency" to "Maximum AC-coupling 3 dB corner frequency between TP0d and TP5d"
 In 178.10.1, Change "The Channel Operating Margin (COM)" to "The Channel Operating Margin (COM) for the channel between TP0 and TP5"
 In 178.10.2, change "The recommended maximum channel insertion loss, ILDD," to "The recommended maximum insertion loss, ILdd, for the channel between TP0d and TP5d"
 Apply similar changes in 176C.7 to clarify the boundaries of the channels for each parameter.

Proposed Response Response Status O

CI 180 SC 180.9.5 P448 L25 # 320

Brown, Matt Alphawave Semi

Comment Type E Comment Status X

Table 180-15 footnote a is out of sync with the table. Coefficients are labelled as being normalized, thus saying they are relative to c(0) is redundant. However, it is not stated what normalized means. The table already associates "main tap" with c(0) on row 4.

SuggestedRemedy

Change footnote a to: "The normalized tap coefficients are relative to c(0)."
 Implement also in Table 181-13, Table 182-15, and Table 183-14.

Proposed Response Response Status O

CI 180 SC 180.9.5 P448 L27 # 321

Brown, Matt Alphawave Semi

Comment Type T Comment Status X

Regarding Table 180-15 footnote b... The table specifies an non-normalized range for c(0) and normalized values for the other coefficients. It is not immediately clear whether to sum the normalized or non-normalized coefficients.

SuggestedRemedy

Change footnote b to: "Equalizer gain is the sum of the non-normalized coefficients." or similar.
 Implement also in Table 181-13, Table 182-15, and Table 183-14.

Proposed Response Response Status O

CI 180 SC 180.9.6 P449 L14 # 322

Brown, Matt Alphawave Semi

Comment Type E Comment Status X

Use of possessive grammar is inconsistent with similar phrases used through this draft and is unnecessary here.

SuggestedRemedy

Change "transmitter's" to "transmitter"
 Also page 472 line 38, page 499 line 16, page 523 line 46.

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

CI 176C SC 176C.7.1 P731 L18 # 323

Brown, Matt Alphawave Semi

Comment Type TR Comment Status X

In Table 176C-6 (C2C channel characteristics), the "Maximum AC-coupling 3 dB corner frequency" is specified as 50 kHz, whereas the corner for KR (Table 178-11), CR (179.11), and C2M (176D.6.4) is 100 kHz.

SuggestedRemedy

Change "50 kHz" to "100 kHz".

Proposed Response Response Status O

CI 176D SC 176D.3 P741 L19 # 324

Brown, Matt Alphawave Semi

Comment Type TR Comment Status X

The requirement that the C2M interface includes ILT is buried within a paragraphs. Also, the sentence is prefixed with the word "Specifically," as though ILT was related to the service interface defined in the previous sentence. C2M interface is defined as being equivalent functionally to a CR interface. The ILT is a rather major function and deserves specification in the same way as done for CR (see 179.8.9) and KR (see 178.8.9). It may also be time to subdivide the C2M functional specifications into subclauses. The same applies for C2C in Annex 176C.

SuggestedRemedy

Create a new subclause similar 178.8.9 and 179.8.9 in Annex 176C.3.
Consider organizing the functional specification into subclauses.

Proposed Response Response Status O

CI 178B SC 178B.11.4 P802 L25 # 325

Brown, Matt Alphawave Semi

Comment Type T Comment Status X

Use of possessive grammar is inconsistent with similar phrases used through this draft and is unnecessary here.

SuggestedRemedy

Change "transmitter's" to "transmitter", three instances. Also, page 808 line 17, 4 instances. Also on page 804 line 44, change "interface's" to "other interface"

Proposed Response Response Status O

CI 186 SC 186.2.4.4 P594 L16 # 326

Brown, Matt Alphawave Semi

Comment Type TR Comment Status X

For the 800GBASE-ER1/ER1-20 PMD the error ratio specifications are defined in 187.2 as being a CRC error ratio. In order to measure this a set of counters are required.

SuggestedRemedy

Define a set of two counters as follows:
a count of all CRC32 blocks processed
a count of all CRC32 blocks in which error are detected
Add the new counters to the list of status registers in 187.11 and define the registers in Clause 45.

Proposed Response Response Status O

CI 169 SC 169.5 P201 L36 # 327

Brown, Matt Alphawave Semi

Comment Type E Comment Status X

In Table 169-6, footnotes a and b are identical.

SuggestedRemedy

Merge footnote a and b into a single footnote.

Proposed Response Response Status O

CI 179B SC 179B.2.1 P823 L39 # 328

Brown, Matt Alphawave Semi

Comment Type E Comment Status X

Variable subscripts should be normal font rather than italic font unless the subscript represents another variable, e.g. an index, f_i where i is an index variable.

SuggestedRemedy

Change variable subscripts to normal font where appropriate through Annex 179B.

Proposed Response Response Status O

Cl 183 SC 183.7.1 P512 L29 # 329

Landry, Gary Texas Instruments

Comment Type E Comment Status X

min OMA limits for higher TECQ/TDECQ values are referenced to an equation outside the table (Eq 183-1).

SuggestedRemedy

To increase readability and maintain parallel structure to other clauses (e.g., 180, 181, and 182), bring external equation into the table

Proposed Response Response Status O

Cl 183 SC 183.7.1 P512 L31 # 330

Landry, Gary Texas Instruments

Comment Type E Comment Status X

min OMA limits for higher TECQ/TDECQ values are referenced to an equation outside the table (Eq 183-2).

SuggestedRemedy

To increase readability and maintain parallel structure to other clauses (e.g., 180, 181, and 182), bring external equation into the table

Proposed Response Response Status O

Cl 119 SC 119.2.4.1.2 P174 L17 # 331

Zimmerman, George ADI,APLgp,Cisco,Marvell,OnSemi,Sony

Comment Type ER Comment Status X

The description here for the stateless decoder - presumably meant to add clarity to the state diagram - leads the reader on a wandering trip through several places in IEEE Std 802.3 and adds more confusion than clarity. It is not a requirement, because the state diagram is a requirement, so it should be written for clarity, if at all. Note it took a long time to wind through this description - much longer than it was worth.

119.2.4.1.2 leads to 119.2.6.2.2 seemingly for a very short description of tx_raw, which could have been stated directly. Then it sends you to Table 172-1 for the mapping itself (which is still in 802.3df, not 802.3-2022), which has little content except to point to the function "ENCODE" in 172.2.6.2.3, which itself points to 119.2.6.2.3, which then says "the ENCODE function shall encode the block as specified in 119.2.3.", which is 9 subsections describing the 64B/65B encoding, and itself mostly points to 82.2.3.x (various subsections). When you're done, it is difficult to see exactly where the stateless encoding/decoding map ends up. If the stateless description is to provide clarity, it is lost on me. It appears to be largely the mapping in 82.2.3, which could be pointed to directly, and any changes described directly.

SuggestedRemedy

Change the text of 119.2.4.1.2 to read:
 The stateless encoder generates 66-bit blocks based only on the current and preceding 200GMII/400GMII transfers. Each 200GMII/400GMII transfer is mapped into a 72-bit vector tx_raw<71:0>, by placing TXC<0> through TXC<7> in tx_raw<0> through tx_raw<7>, respectively, and TXD<0> through TXD<63> in tx_raw<8> through tx_raw<71>, respectively. The encoder uses the constants LBLOCK_T and EBLOCK_T and the variables reset, tx_raw, and tx_coded defined in 119.2.6.2.1. When reset is one, the encoder outputs the value of LBLOCK_T, and when an invalid block type is specified (see Table 172-1) it outputs EBLOCK_T. Otherwise the encoding follows 119.2.3, which uses the control codes and mappings specified in Table 82-1.

Similarly change text of 119.2.8.2 as above for the decoder.

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl **FM** SC **FM** P1 L33 # 332
 Zimmerman, George ADI,APLgp,Cisco,Marvell,OnSemi,Sony
 Comment Type **E** Comment Status **X**
 Likely that this draft will need to consider amendments 802.3da and 802.3dk, both of which are ahead of it in the process. Commenter's review of 802.3dk in working group ballot has noted some overlaps with this amendment.
SuggestedRemedy
 Add 802.3da and 802.3dk to the list of amendments considered. Editors are encouraged to review the draft for consistency with 802.3dk especially.
 Proposed Response Response Status **O**

Cl **FM** SC **FM** P13 L1 # 333
 Zimmerman, George ADI,APLgp,Cisco,Marvell,OnSemi,Sony
 Comment Type **E** Comment Status **X**
 Likely that 802.3da and 802.3dk will publish before this amendment their abstracts should be included.
SuggestedRemedy
 Consult with 802.3 leadership on likely amendment order, insert abstracts for 802.3da and 802.3dk from the latest drafts of those.
 Proposed Response Response Status **O**

Cl **186A** SC **186A** P868 L17 # 334
 Zimmerman, George ADI,APLgp,Cisco,Marvell,OnSemi,Sony
 Comment Type **T** Comment Status **X**
 As the editor's note indicates Annex 186A doesn't have content at this time. Arguably it is informative and therefore not for technical completeness, but also, it does not appear to be referenced elsewhere in the draft, making it difficult to tell whether the material should be considered relevant to completeness.
SuggestedRemedy
 Either include test vectors at initial WG ballot and provide some link in the normative text explaining where and how it is informative, or delete Annex 186A.
 Proposed Response Response Status **O**

Cl **185A** SC **185A.1** P859 L16 # 335
 Zimmerman, George ADI,APLgp,Cisco,Marvell,OnSemi,Sony
 Comment Type **T** Comment Status **X**
 The annex only contains a single methodology (ETCC), and it really doesn't define the parameter - it specifies the method of calculation.
SuggestedRemedy
 Replace text of 185A.1 text with: "This annex defines the method for measuring and computing the Extended transmitter constellation closure (ETCC). The ETCC is a
 Proposed Response Response Status **O**

Cl **187** SC **187.8.6** P643 L44 # 336
 Zimmerman, George ADI,APLgp,Cisco,Marvell,OnSemi,Sony
 Comment Type **E** Comment Status **X**
 This section says, "The method and ETCC calculation are defined in 187.9." - but when I look at 187.9, I only find that it is computed using the test setup and calculation defined in Annex 185A. (and parameter values for the front end in Tables 187-12 and 187-13) - none of this is defines the method and calculation - it just points the reader on to another section - better point to 185A and the tables directly rather than a wild goose chase with an in between reference that just points ahead.
SuggestedRemedy
 Change "The method and ETCC calculation are defined in 187.9." to "The method and ETCC calculation are defined in 185A, using the parameters in the Tables 187-12 and 187-13."
 Proposed Response Response Status **O**

Cl **185A** SC **185A.2.5.2** P865 L39 # 337
 Zimmerman, George ADI,APLgp,Cisco,Marvell,OnSemi,Sony
 Comment Type **T** Comment Status **X**
 The required signal to noise ratio (in general) is not what is in equation 185A-2. Equation 185A-2 is the Required signal to noise ratio in the presence of virtual ASE. (RSNR_ase) not just RSNR.
SuggestedRemedy
 change "required signal to noise ratio (RSNR)" to "required signal to noise ratio in the presence of virtual ASE (RSNR_ase)" at line 39
 Proposed Response Response Status **O**

Cl 185A SC 185A.2.5.2 P865 L46 # 338
 Zimmerman, George ADI,APLgp,Cisco,Marvell,OnSemi,Sony
 Comment Type E Comment Status X
 DeltaRSNR_trx doesn't relate to "RSNR" in equation 185A-3, it relates to RSNR_ASE.
 SuggestedRemedy
 Change RSNR to RSNR_ase at line 46
 Proposed Response Response Status O

Cl 119 SC 119.2.4.1 P174 L27 # 339
 Zimmerman, George ADI,APLgp,Cisco,Marvell,OnSemi,Sony
 Comment Type TR Comment Status X

NOTE - this comment also applies to the same statement in 192.2.5.8 (for the decoder). It seems that the existing text, which correctly describes the behavior being in the state diagram has been replaced by improper text which imputes that the state diagram BEHAVIOR specified in 802.3 is an IMPLEMENTATION. "using the state-diagram encoder" and "using the alternative stateless encoder"- would specify an implementation, not a behavior. IEEE Std 802.3 specifies behaviors. Any implementation (including magic) that produces the same behavior is acceptable. I note this is a descriptive statement, not a shall. If you fix the language, you don't need all that "alternative stateless encoder" stuff, which I presume produces the same output. (see next comment on that). I can understand that it may be useful to also describe the behavior as a stateless encoding, but that behavior is without a requirement tying to it. The "shall" - the requirement that this describes, appears to be in 119.2.6.3 (in the base standard, not modified), where it says "The PCS shall perform the functions of alignment marker lock, PCS synchronization, Transmit, and Receive as specified in the respective state diagrams." (Figures 119-14 and 119-15 are the Transmit and Receive state diagrams respectively). The original text simply needs to be augmented with a pointer to the stateless description. Also, if you do this, the alternative stateless encoder/decoder just becomes a description of the state diagram and there is no scope issue I can see that would limit the phy types. The notion that the two are considered implementations is reflected in the PICS.

Note that the suggested remedy is written assuming the two specifications produce the same result. If they don't then there is an interoperability issue and the option and differences in the output of "stateless decoder" and the state diagram need to be described and fully specified.

Also note that the same defect exists, uncaught in IEEE Std 802.3df. When this is properly addressed here, it will need to be addressed there in maintenance.

SuggestedRemedy

119.2.4.1
 Reverse the strikeout of P174 L27 through 30.
 Replace lines 31 through 50 ("The transmit PCS..." through the editor's note) with:
 "The same encoding is described as a stateless encoder in 119.2.4.1.1." (note this is now 119.2.4.1.2 but will be 119.2.4.1.1 after these edits)
 Delete 119.2.4.1.1 heading and contents
 Change title of 119.2.4.1.2 (now 119.2.4.1.1) to Stateless encoder description

119.2.5.8
 KEEP strikeout of P175 L36.
 Move P176 L13&14 (body text of 119.2.5.8.1) to P175 L37,
 Delete header 119.2.5.8.1.
 Replace P175 L37 ("The receive PCS...") through P176 L6 (end of editor's note) with:
 "The same decoding is described as a stateless decoder in 119.2.5.8.1" (note this is now 119.2.5.8.2 but after these edits will be xx.1)"

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Change title of 119.2.5.8.2 (now 119.2.5.8.1) to Stateless decoder description.

119.7.4.1 (Page 180) Delete option "*SE" Uses stateless encoder row
 Change TF2 to "Transmit 64B/65B complies with Figure 119-14", change subclause reference to 119.2.6.3, change Status to M
 Delete TF3 row.
 119.7.4.2 (page 181) Delete option "*SD" Uses stateless decoder row
 Change row RF7 Feature to Complies with Figure 119-14, subclause reference to 119.2.6.3, change status to M
 Delete RF8 row

Proposed Response Response Status

Cl 175 SC 175.6 P280 L17 # 340

de Koos, Andras Microchip Technology

Comment Type E Comment Status X

phrasing is awkward: "... path delays are reported as if ..., and the PCS_timesync_multilane_ability variable is asserted.
 Does this mean that path data delays are reported as if the PCS_timesync_multilane_ability variable is asserted?
 The text says "report as if A, and B" when it should say "when B is true, report as if A".

SuggestedRemedy

Rephrase as the sentence as:
 When the PCS_timesync_multilane_ability variable is asserted, the transmit and receive path data delays are reported as if the DDMP (data delay measurement point) is at the start of the set of four interleaved RS-FEC codewords (see 90.7)

Proposed Response Response Status

Cl 169 SC 169.4 P196 L12 # 341

de Koos, Andras Microchip Technology

Comment Type T Comment Status X

The main reason for specifying the max delay constraints is to accommodate PAUSE reach - given the delays in the near-end and far-end physical layers, and given the buffer depth on the near-end, there is a maximum length of medium that can be supported while guaranteeing no buffer overflow when using link PAUSE.
 What are the max delays through the near-end and far-end physical layers? It is not at all clear.

Would the near-end buffer device be designed with some awareness of the near-end physical layer's composition? Maybe, maybe not.

There is never any awareness of the far-end physical layer's composition. Crucially, the far end may or may not have an MII extender, which adds 2*800ns due to the extra PCSs (plus the delays through the extra PMA layers).

As written, the standard is not very helpful in figuring out the maximum possible delay through the entirety of the physical layer given the range of possible physical layer stacks. To be fair, this deficiency has existed since MII-Extenders were introduced for 200G and 400G PHYs. Before MII extenders, the range of physical layer stacks were quite limited, so the delay error-bars due to an extra AUI+PMA, for example, were small.

Same comment can apply to 200Gb/s, 400Gb/s and 1.6Tb/s clauses.

SuggestedRemedy

Consider adding the values that an implementor needs, i.e. the worst-case delay (i.e. over ALL possible physical layer stacks) through the entire physical layer, per PMD type.

Proposed Response Response Status

Cl 180 SC 180.7.3 P441 L46 # 342

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

MPI/DGP penalty of 0.1 dB would be too small for 200GBASE-DR1/400GBASE-DR2/800GBASE-DR4/1.6TBASE-DR8

SuggestedRemedy

The BS/CD MPI penalty were evaluated with ER of 5 dB which is too high for 200G Si MZM. Analysis need to be based on SER of 5.6E-4, with half the loss at mid-span, and ER=3.5, see https://www.ieee802.org/3/dj/public/25_05/ghiasi_3dj_01b_2505.pdf and https://www.ieee802.org/3/dj/public/25_05/johnson_3dj_01a_2505.pdf
 Given that Table 180-12 with 8 discrete reflectance -55 dB and -45 dB and zero discrete reflectacen of -45 dB and -35 dB has 0.15 dB of MPI penalty with addition of ~0.18 dB, or with ~ 0.3 dB total penalty.
 Require following adjsutments:
 Table 180-9 power budget increases from 6.5 dB to 6.7 dB
 Table 180-7 average launch power increases from -3.3 dBm to -3.1 dBm, OMA(min) increases by +0.2 dB
 Table 180-8 average receive power increases from -6.3 dBm to -6.1 dBm
 See ghiasi_3dj_02_2507

Proposed Response Response Status

Cl 180 SC 180.9.5 P448 L18 # 343

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

Contribution https://www.ieee802.org/3/dj/public/25_05/chayeb_3dj_01_2505.pdf showed that for some weired FFE setting still one may have compliant TDECQ but BER can degrade with this 100G DSP likley due to timing recovery

SuggestedRemedy

Contribution https://www.ieee802.org/3/dj/public/24_07/ghiasi_3dj_02a_2407.pdf with data from several suppliers was used to set the limits for TDECQ. Limiting the taps can result in many good modules and we are not sure given that we have link training if this type of problem still exist for weired transmitter FFE settigns. Any limit on TDECQ FFE taps must not result in failing good moduels, looking at the data in Chayeb the following tap adjsutments will have minimum impact on module yield and will address the case of weired transmitter FFE casuing receive BER floor:
 Change C(1) from 0.2 to 0.1 and add following restriction Max C(1)-C(-1) taps=0.4
 Other improvements are is to use Block TDECQ and functional hardware receiver
 see https://www.ieee802.org/3/dj/public/25_05/ghiasi_3dj_03a_2505.pdf
 see ghiasi_3dj_03_2507

Proposed Response Response Status

Cl 181 SC 181.7.3 P465 L35 # 344

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

MPI/DGP penalty of 0.5 dB would be too small for 800GBASE-FR4-500

SuggestedRemedy

The BS/CD MPI penalty were evaluated with ER of 5 dB which is too high for 200G Si MZM. Analysis need to be based on SER of 5.6E-4, with half the loss at mid-span, and ER=3.5, see https://www.ieee802.org/3/dj/public/25_05/ghiasi_3dj_01b_2505.pdf and https://www.ieee802.org/3/dj/public/25_05/johnson_3dj_01a_2505.pdf
 Given that double link has 4 discrete reflectance -55 dB and -45 dB and 4 discrete reflectacen of -45 dB and -35 dB has 0.5 dB of MPI penalty with addition of ~0.18 dB, or with ~ 0.7 dB total penalty.
 Require following adjsutments:
 Table 180-9 power budget increases from 7.4 dB to 7.6 dB
 Table 181-5 average launch power increases from -2.2 dBm to -2 dBm, OMA(min) increases by +0.2 dB
 Table 181-6 average receive power increases from -5.7 dBm to -5.5 dBm
 See ghiasi_3dj_02_2507

Proposed Response Response Status

Cl 181 SC 181.9.5 P471 L35 # 345

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

Contribution https://www.ieee802.org/3/dj/public/25_05/chayeb_3dj_01_2505.pdf showed that for some weired FFE setting still one may have compliant TDECQ but BER can degrade with this 100G DSP likley due to timing recovery

SuggestedRemedy

Contribution https://www.ieee802.org/3/dj/public/24_07/ghiasi_3dj_02a_2407.pdf with data from several suppliers was used to set the limits for TDECQ. Limiting the taps can result in many good modules and we are not sure given that we have link training if this type of problem still exist for weired transmitter FFE settigns. Any limit on TDECQ FFE taps must not result in failing good moduels, looking at the data in Chayeb the following tap adjsutments will have minimum impact on module yield and will address the case of weired transmitter FFE casuing receive BER floor:
 Change C(1) from 0.2 to 0.1 and add following restriction Max C(1)-C(-1) taps=0.4
 Other improvements are is to use Block TDECQ and functional hardware receiver
 see https://www.ieee802.org/3/dj/public/25_05/ghiasi_3dj_03a_2505.pdf
 see ghiasi_3dj_03_2507

Proposed Response Response Status

IE P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

CI 182 SC 182.7.3 P491 L33 # 346

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

MPI/DGP penalty of 0.4 dB would be excessive for 200GBASE-DR1-2/400GBASE-DR2-2/800GBASE-DR4-2/1.6TBASE-DR8-2

SuggestedRemedy

The BS/CD MPI penalty were evaluated with ER of 5 dB which is too high for 200G Si MZM. Analysis need to be based on SER of 9.6E-3, with half the loss at mid-span, and ER=3.5, see https://www.ieee802.org/3/dj/public/25_05/ghiasi_3dj_01b_2505.pdf and https://www.ieee802.org/3/dj/public/25_05/johnson_3dj_01a_2505.pdf
Given that double link with 8 discrete reflectance -55 dB and -45 dB MPI penalty is 0.09 dB of MPI penalty with addition of ~0.18 dB, or with ~ 0.3 dB total penalty instead of current 0.5 dB.

Require following adjustments:

Table 182-9 power budget decreases from 7.8 dB to 7.6 dB

Table 182-7 average launch power increases from -3.3 dBm to -3.1 dBm, OMA(min) increases by +0.2 dB

Table 182-8 average receive power increases from -7.3 dBm to -7.1 dBm, Stressed sensitivity becomes -1.9 dBm, and receive sensitivity also improves by +0.3 dB

See ghiasi_3dj_02_2507

Proposed Response Response Status O

CI 182 SC 182.9.5 P498 L18 # 347

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

Contribution https://www.ieee802.org/3/dj/public/25_05/chayeb_3dj_01_2505.pdf showed that for some weired FFE setting still one may have compliant TDECQ but BER can degrade with this 100G DSP likley due to timing recovery

SuggestedRemedy

Contribution https://www.ieee802.org/3/dj/public/24_07/ghiasi_3dj_02a_2407.pdf with data from several suppliers was used to set the limits for TDECQ. Limiting the taps can result in many good modules and we are not sure given that we have link training if this type of problem still exist for weired transmitter FFE settings. Any limit on TDECQ FFE taps must not result in failing good modules, looking at the data in Chayeb the following tap adjustments will have minimum impact on module yield and will address the case of weired transmitter FFE casuing receive BER floor:

Change C(1) from 0.2 to 0.1 and add following restriction Max C(1)-C(-1) taps=0.4

Other improvements are is to use Block TDECQ and functional hardware receiver

see https://www.ieee802.org/3/dj/public/25_05/ghiasi_3dj_03a_2505.pdf

see ghiasi_3dj_03_2507

Proposed Response Response Status O

CI 178 SC 178.9.3.7 P369 L13 # 348

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

In 802.3ck the limit for RLcd was 50 GHz, going up to 50 GHz is not adequate

SuggestedRemedy

Suggest to increase to 67 GHz

Proposed Response Response Status O

CI 183 SC 183.9.5 P522 L18 # 349

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

Contribution https://www.ieee802.org/3/dj/public/25_05/chayeb_3dj_01_2505.pdf showed that for some weired FFE setting still one may have compliant TDECQ but BER can degrade with this 100G DSP likley due to timing recovery

SuggestedRemedy

Contribution https://www.ieee802.org/3/dj/public/24_07/ghiasi_3dj_02a_2407.pdf with data from several suppliers was used to set the limits for TDECQ. Limiting the taps can result in many good modules and we are not sure given that we have link training if this type of problem still exist for weired transmitter FFE settings. Any limit on TDECQ FFE taps must not result in failing good modules, looking at the data in Chayeb the following tap adjustments will have minimum impact on module yield and will address the case of weired transmitter FFE casuing receive BER floor:

Change C(1) from 0.2 to 0.1 and add following restriction Max C(1)-C(-1) taps=0.4

Other improvements are is to use Block TDECQ and functional hardware receiver

see https://www.ieee802.org/3/dj/public/25_05/ghiasi_3dj_03a_2505.pdf

see ghiasi_3dj_03_2507

Proposed Response Response Status O

CI 176D SC 176D.7.2 P748 L51 # 350

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

The partial channel is only needed for cable assembly CR and not for C2M which has the complete S-Parameters

SuggestedRemedy

Partial channel not need for C2M COM and should be removed

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 178 SC 178.9.2.7 P365 L12 # 351

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

The reference package A and B SDNR are known specific value

SuggestedRemedy

I believe these are the value in https://www.ieee802.org/3/dj/public/24_11/healey_3dj_01_2411.pdf page 5 at least for package A, for service to community reference SNDR should be provided

Proposed Response Response Status O

Cl 176D SC 176D.6.3 P745 L38 # 352

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

We currently have no effective output compliance test method for C2M or input calibration of stressor. We replaced VEC with with JRMS, EOJ, and J4U back in Sept 2024 and it has been more than 9 months without any proof that using jitter alone is sufficient for receive compliance.

SuggestedRemedy

TDECQ/EECQ already captures the jitter as shown in ghiasi_3dj_01a_2409 but also captures amplitude penalty and the effect of PM to AM conversion in the same way as receiver will observe the penalty. In COM we use reference equalizer to determine compliance, in 802.3ck we used VEC/VEO with a reference equalizer and in OIF Linear and RTL we use EECQ with reference equalizer for compliance. We have not proven that discrete jitter measurements without a reference equalizer is sufficient for C2M compliance. Task force need to investigate either show that current methodology works otherwise replace it with CKmethod or OIF EECQ before going to SA ballot.

Proposed Response Response Status O

Cl 176D SC 176D.6.4 P746 L38 # 353

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

We currently have no effective output compliance test method for C2M or input calibration of stressor. We replaced VEC with with JRMS, EOJ, and J4U back in Sept 2024 and it has been more than 9 months without any proof that using jitter alone is sufficient for receive compliance.

SuggestedRemedy

TDECQ/EECQ already captures the jitter as shown in ghiasi_3dj_01a_2409 but also captures amplitude penalty and the effect of PM to AM conversion in the same way as receiver will observe the penalty. In COM we use reference equalizer to determine compliance, in 802.3ck we used VEC/VEO with a reference equalizer and in OIF Linear and RTL we use EECQ with reference equalizer for compliance. We have not proven that discrete jitter measurements without a reference equalizer is sufficient for C2M compliance. Task force need to investigate either show that current methodology works otherwise replace it with CKmethod or OIF EECQ before going to SA ballot.

Proposed Response Response Status O

Cl 176D SC 176D.6.5 P747 L12 # 354

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type T Comment Status X

In 802.3ck VCM(LF) was 32 mV which is more than 2x larger than limit in the DJ draft at TP4 with only 15 mV

SuggestedRemedy

Given that Module/TP4 would be the target source of VCM(LF), recommend increasing to 20 mV

Proposed Response Response Status O

CI 176D SC 176D.8.7 P754 L20 # 355

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

The dSNDR procedure for host is not clear as some of the paragraph are for determination of reference SNDR but the last paragraph is for actual measurement of DUT SNDR.

SuggestedRemedy

Here are suggestions:

- Please separate the measurement of reference channel SNDR from measurement of DUT SNDR
- After definition of reference SNDR "calculate reference SNDR"
- In the 2nd part clearly identify this procedure is for measurement of DUT SNDR add to sentence "...of 6 ps is used for measurement of DUT SNDR"
- Then last step is dSNDR=DUT SNDR - Ref SNDR

Proposed Response Response Status O

CI 176D SC 176D.8.7 P754 L34 # 356

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

The dSNDR procedure for module is not clear as some of the paragraph are for determination of reference SNDR but the last paragraph is for actual measurement of DUT SNDR.

SuggestedRemedy

Here are suggestions:

- Please separate the measurement of reference channel SNDR from measurement of DUT SNDR
- After definition of reference SNDR "calculate reference SNDR"
- In the 2nd part clearly identify this procedure is for measurement of DUT SNDR
- Then last step is dSNDR=DUT SNDR - Ref SNDR

Proposed Response Response Status O

CI 176D SC 176D.8.7 P754 L34 # 357

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

The dSNDR procedure for DUT measurement is missing

SuggestedRemedy

The module inputs at TP1 on each lane are driven by asynchronous signals created by PRBS31Q or PCS data, with transmit equalization (see 176D.8.6) set to preset 1, and calibrated at the generator output with target maximum steady-state voltage as specified in Table 176D-3 and transition time of 6 ps is used for measurement of DUT SNDR.

Proposed Response Response Status O

CI 176D SC 176D.8.1 P751 L50 # 358

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

Differential and common-mode signals are not defined in 93.8.1.3, just the figure is used for level definition.

SuggestedRemedy

Replace with, Differential and common-mode signal levels definition is given by 93.8.1.3.

Proposed Response Response Status O

CI 176D SC 176D.8.1 P752 L13 # 359

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

The VCM(LF, FB) is measured at probability of 1E-5, in DJ it is tighten to P=1E-7

SuggestedRemedy

Common mode is bigger issue at 200G compared to 100G, with tighten probability may result in failures. Change P to 1E-5 two places

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 176D SC 176D.8.2 P752 L50 # 360
 Ghiasi, Ali Ghiasi Qunatum/Marvell
 Comment Type TR Comment Status X
 Not clear why Nbx is zero
 SuggestedRemedy
 Suggest to make Nbx=14 which number of fixed FFE taps
 Proposed Response Response Status O

Cl 179 SC 179.9.4.8 P403 L35 # 363
 Ghiasi, Ali Ghiasi Qunatum/Marvell
 Comment Type TR Comment Status X
 802.3ck common mode return loss frequency was up to 50 GHz
 SuggestedRemedy
 We should at least extend the RLcc to 67 GHz.
 Proposed Response Response Status O

Cl 176D SC 176D.8.2 P752 L29 # 361
 Ghiasi, Ali Ghiasi Qunatum/Marvell
 Comment Type TR Comment Status X
 Line 30 says that "Tfx equal to twice the test fixture delay", statement is not clear.
 SuggestedRemedy
 Tfx for measurement of Host Input/Output is twice the HCB delay.
 Tfx for measurement of Module Input/Output is twice the MCB delay.
 Suggest to move Tfx into the table and make the above as footnotes in the table.
 We shouldn't state in IEEE standard "Tfx is provided by the test fixture provider", what about if fixture supplier doesn't!
 Proposed Response Response Status O

Cl 179 SC 179.9.4.9 P404 L35 # 364
 Ghiasi, Ali Ghiasi Qunatum/Marvell
 Comment Type TR Comment Status X
 802.3ck common mode to differential return loss frequency was up to 50 GHz
 SuggestedRemedy
 We should at least extend the RLdc to 67 GHz.
 Proposed Response Response Status O

Cl 176C SC 176C.6.3 P724 L22 # 362
 Ghiasi, Ali Ghiasi Qunatum/Marvell
 Comment Type TR Comment Status X
 J4U03 has two values, package A and package B, not clear what determines actual DUT package as Class A or Class B. Is it total loss? What happens if one has Class B package with short trace, is that class A?
 SuggestedRemedy
 Please provide how to determine DUT package is Class A or B.
 Also add reference to table 176C-7
 Proposed Response Response Status O

Cl 176C SC 176C.6.4.4 P727 L33 # 365
 Ghiasi, Ali Ghiasi Qunatum/Marvell
 Comment Type TR Comment Status X
 The more critical return loss is common mode to differential, but for some reason in clause 176C instead RLcd is defined
 SuggestedRemedy
 Change RLcd to RLdc (common mode to differential)
 Proposed Response Response Status O

Cl 176C SC 176C.6.4.4 P727 L33 # 366
 Ghiasi, Ali Ghiasi Qunatum/Marvell
 Comment Type TR Comment Status X
 802.3ck common mode to differential return loss frequency was up to 50 GHz
 SuggestedRemedy
 We should at least extend the RLdc to 67 GHz.
 Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 178 SC 178.9.2.3 P364 L28 # 367
 Ghiasi, Ali Ghiasi Qunatum/Marvell
 Comment Type **TR** Comment Status **X**
 802.3ck common mode return loss frequency was up to 50 GHz
 SuggestedRemedy
 We should at least extend the RLcc to 67 GHz.
 Proposed Response Response Status **O**

Cl 179 SC 179.9.4.7 P403 L19 # 371
 Ghiasi, Ali Ghiasi Qunatum/Marvell
 Comment Type **TR** Comment Status **X**
 Not clear why Nbx is zero
 SuggestedRemedy
 Suggest to make Nbx=15 which number of fixed FFE taps
 Proposed Response Response Status **O**

Cl 179 SC 179.9.5.6 P410 L44 # 368
 Ghiasi, Ali Ghiasi Qunatum/Marvell
 Comment Type **TR** Comment Status **X**
 The more critical return loss is common mode to differential, but for some reason in clause 179 instead RLcd is defined
 SuggestedRemedy
 Change RLcd to RLdc (common mode to differential)
 Proposed Response Response Status **O**

Cl 179 SC 179.11.7.1 P417 L8 # 372
 Ghiasi, Ali Ghiasi Qunatum/Marvell
 Comment Type **TR** Comment Status **X**
 The only place that host classes are defined is in Table 179A-1
 SuggestedRemedy
 Need reference to table 179A-1 or Host classes should be added to the glossary
 Proposed Response Response Status **O**

Cl 179 SC 179.9.5.6 P410 L47 # 369
 Ghiasi, Ali Ghiasi Qunatum/Marvell
 Comment Type **TR** Comment Status **X**
 802.3ck common mode to differential return loss frequency was up to 50 GHz
 SuggestedRemedy
 We should at least extend the RLdc to 67 GHz.
 Proposed Response Response Status **O**

Cl 179 SC 179.11.7.1 P417 L8 # 373
 Ghiasi, Ali Ghiasi Qunatum/Marvell
 Comment Type **TR** Comment Status **X**
 Table 179-17 provide partial channel for different host classes, it would be helpful to also include the losses for the 3 partial channels
 SuggestedRemedy
 Host Partial HL Class loss = 1.72 dB
 Host partial NL Class loss = 9.4 dB
 Host partial HH Class loss = 14.35 dB
 If one adds the MCB loss of 3.2 dB to the above value then that would give host channel see below and similar to Table 179A-1
 Host HL Class loss = 4.9 dB
 Host NL Class loss = 9.4 dB
 Host HH Class loss = 14.35 dB
 The above losses are the not max or min losses, some explanation why value in table 179-17 are chosen would be helpful.
 For the HH case if we go with Zp=140 mm will result in loss of 18.3 dB when MCB is included which inline to max loss in table 179A-1.
 Proposed Response Response Status **O**

Cl 179 SC 179.9.4 P394 L46 # 370
 Ghiasi, Ali Ghiasi Qunatum/Marvell
 Comment Type **TR** Comment Status **X**
 Reference to host classes missing
 SuggestedRemedy
 Please reference table 179A-1
 Proposed Response Response Status **O**

Cl 178B SC 178B.2 P786 L18 # 374

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

3 major functions are included in the ILT: Electrical LT, Optical LT, and inter-sublayer link signal or RTS. Designating evertng as ILT is rather confusing throughout the draft.

SuggestedRemedy

I suggest the following definition:
 All electrical link training called "ELT"
 All optical link training called "OLT"
 Inter-sublayer signaling RTS called "ILT" or could be called "ILM" (inter-sublayer link messaging)

Proposed Response Response Status O

Cl 178B SC 178B.4 P787 L30 # 375

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

Figure 178B-1 is trying to convey two different messages and combining the two function as shown is confusing

SuggestedRemedy

Some suggested improvements
 Call them figure 1A and 1B
 Figure 1A is for AUI so it needs two ILT functions in the box (left and right)
 Figure 1B better to show as following:
 -Receive function connected to Transmit Function left-right (output SLi)
 -Receive function to Transmit Function right-left (input DLi)
 -Duplicate per-lane ILT function one for Egress and one for Ingress

Proposed Response Response Status O

Cl 178B SC 178B.5.3 P789 L24 # 376

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

Figure can improve for better representation

SuggestedRemedy

Suggest the followng:
 - CDR ouput add mux (Training/mission modes)
 - Connect Training frame decode to training frame encode
 - You can also create a new block called "Training State Machine" then connect training decode and encode to it.

Proposed Response Response Status O

Cl 178B SC 178B.7 P796 L5 # 377

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type TR Comment Status X

https://www.ieee802.org/3/dj/public/24_05/ghiasi_3dj_01a_2405.pdf looked at number of options for OLT such as Presets, FFE adjustment, OMA control, chirp, inner-outer eye adjustments, but at the time the Task Force decided to just enable the basic OLT with pre-coder control. A vendor selected Preset can provide set of Presets optimized for example shorter/longer reachs, lower OMA more linear or higher OMA less linear, higher peaking or less peaking

SuggestedRemedy

The enhancement to OLT issomehting that Task Force should consider specially that MMF will require enabling Presets. Just like E1 O1 should have 6 Presets, with default Preset 1 only meeting TDECQ, Presets 2-6 may have +1 dB TDECQ penalty. Clasue 183 800GBASE-LR4 and possibly 800GBASE-FR4 are good candiate to have several presets to better mitigate dispersion penalties
 See ghiasi_3dj_01_2507

Proposed Response Response Status O

Cl 178 SC 178.10.1 P371 L12 # 378
 Ghiasi, Ali Ghiasi Qunatum/Marvell
 Comment Type ER Comment Status X
 All symbols such as Cd(1) or Ls(1) the "(1)" seems like is superscript
 SuggestedRemedy
 Please make it inline
 Proposed Response Response Status O

Cl 178 SC 178.10.1 P372 L33 # 379
 Ghiasi, Ali Ghiasi Qunatum/Marvell
 Comment Type ER Comment Status X
 Symbols fp1 and fp2 seem connected
 SuggestedRemedy
 May need to adjsut or inceased spacing
 Proposed Response Response Status O

Cl 179 SC 179.10.1 P415 L45 # 380
 Ghiasi, Ali Ghiasi Qunatum/Marvell
 Comment Type ER Comment Status X
 All symbols such as Cd(1) or Ls(1) the "(1)" seems like is superscript
 SuggestedRemedy
 Please make it inline
 Proposed Response Response Status O

Cl 180 SC 180.9.5 P447 L21 # 381
 Ghiasi, Ali Ghiasi Qunatum/Marvell
 Comment Type TR Comment Status X
 Current TDECQ reference equalizer is only 15 tap FFE where most implemetnation of DSPs are 20-30 taps FFE with DFE and optional MLSE. Many have raised that real receivers perform much better than reference equalizer which is a good thing, but this also leaves all the margin for RX DSP.
 SuggestedRemedy
 A reasonblae next step is to supplement the current TDECQ equalizer based on 15T FFE with 1T DFE. The Scope can already support 1TDFE. The reference equalizer is a 15-tap feed-forward equalizer (FFE) and 1-tap decision-feedback equalizer (DFE), where T is the symbol period, with equalizer coefficient constraints as shown in Table 180-15. In table 180-15 add limits for DFE min=-0.4 max=0 see ghiasi_3dj_04_2507
 Proposed Response Response Status O

Cl 181 SC 181.9.5 P471 L8 # 382
 Ghiasi, Ali Ghiasi Qunatum/Marvell
 Comment Type TR Comment Status X
 Current TDECQ reference equalizer is only 15 tap FFE where most implemetnation of DSPs are 20-30 taps FFE with DFE and optional MLSE. Many have raised that real receivers perform much better than reference equalizer which is a good thing, but this also leaves all the margin for RX DSP.
 SuggestedRemedy
 A reasonblae next step is to supplement the current TDECQ equalizer based on 15T FFE with 1T DFE. The Scope can already support 1TDFE. The reference equalizer is a 15-tap feed-forward equalizer (FFE) and 1-tap decision-feedback equalizer (DFE), where T is the symbol period, with equalizer coefficient constraints as shown in Table 180-15. In table 180-15 add limits for DFE min=-0.4 max=0 see ghiasi_3dj_04_2507
 Proposed Response Response Status O

CI 182 SC 182.9.5 P497 L41 # 383

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type **TR** Comment Status **X**

Current TDECQ reference equalizer is only 15 tap FFE where most implementation of DSPs are 20-30 taps FFE with DFE and optional MLSE. Many have raised that real receivers perform much better than reference equalizer which is a good thing, but this also leaves all the margin for RX DSP.

SuggestedRemedy

A reasonable next step is to supplement the current TDECQ equalizer based on 15T FFE with 1T DFE. The Scope can already support 1TDFE. The reference equalizer is a 15-tap feed-forward equalizer (FFE) and 1-tap decision-feedback equalizer (DFE), where T is the symbol period, with equalizer coefficient constraints as shown in Table 180-15. In table 180-15 add limits for DFE min=-0.4 max=0 see ghiasi_3dj_04_2507

Proposed Response Response Status

CI 183 SC 183.9.5 P522 L10 # 384

Ghiasi, Ali Ghiasi Qunatum/Marvell

Comment Type **TR** Comment Status **X**

Current TDECQ reference equalizer is only 15 tap FFE where most implementation of DSPs are 20-30 taps FFE with DFE and optional MLSE. Many have raised that real receivers perform much better than reference equalizer which is a good thing, but this also leaves all the margin for RX DSP.

SuggestedRemedy

A reasonable next step is to supplement the current TDECQ equalizer based on 15T FFE with 1T DFE. The Scope can already support 1TDFE. The reference equalizer is a 15-tap feed-forward equalizer (FFE) and 1-tap decision-feedback equalizer (DFE), where T is the symbol period, with equalizer coefficient constraints as shown in Table 180-15. In table 180-15 add limits for DFE min=-0.4 max=0 see ghiasi_3dj_04_2507

Proposed Response Response Status

CI 185 SC 185.6.1 P564 L33 # 385

Maniloff, Eric Ciena

Comment Type **TR** Comment Status **X**

The value of 3.4dB ETCC results in an excessively stringent requirement on the receiver. This value needs to be reduced to allow realistic receiver parameters. A supporting contribution will be presented.

SuggestedRemedy

Replace the 3.4dB ETCC Max Value with 2.5 dB

Proposed Response Response Status

CI 185 SC 185.6.1 P564 L27 # 386

Maniloff, Eric Ciena

Comment Type **TR** Comment Status **X**

The average launch power on ETCC should be updated to align with any updates to ETCC Max

SuggestedRemedy

Update the maximum ETCC value in Average Power with a value of 2.5dB

Proposed Response Response Status

CI 185 SC 185.6.2 P565 L30 # 387

Maniloff, Eric Ciena

Comment Type **TR** Comment Status **X**

OIF 800LR allows a maximum Average transmitter power of -4 dB. To allow interoperability, The 800GBASE-LR1 Average receive power tolerance (max) should be set to -4 dBm

SuggestedRemedy

Modify Average receive power tolerance (max) to -4dBm

Proposed Response Response Status

Cl 187 SC 187.6.1 P638 L26 # 388

Maniloff, Eric

Ciena

Comment Type T Comment Status X

The methodology in 800GBASE-ER1 on defining the Average optical power specifications should be aligned with the coupling to ETCC defined in 800GBASE-LR1. A supporting contribution with details of the values for Tx optical power and ETCC max will be provided

SuggestedRemedy

Update the 800GASE-ER1 and 800GBASE-ER1-20 to couple the optical powers to ETCC, to use a methodology aligned with 800GBASE-LR1.

Proposed Response Response Status O

Cl 187 SC 187.6.1 P638 L27 # 389

Maniloff, Eric

Ciena

Comment Type T Comment Status X

The ± 1.8GHz accuracy specification in Table 187-5 is required for DWDM applications, however is note required for single-wavelength applications such as 800GBASE-ER1. This accuracy can be loosened, and depending on other requirements can still be compatible with DWDM lasers. Loosening the optical frequency accuracy spec allows additional technologies to be used for 800GBASE-ER1

SuggestedRemedy

Relax the accuracy spec in 800GBASE-ER1 to ± 20GHz. A supporting contribution will be provided, showing the tradeoffs with different laser implementations.

Proposed Response Response Status O

Cl 187 SC 187.6.1 P638 L24 # 390

Maniloff, Eric

Ciena

Comment Type T Comment Status X

The -7dBm Average launch power (max) specification for 800GBASE-ER1-20 is not required based on Rx maximum power specifications. This value can be increased with no consequences.

SuggestedRemedy

Increase the Average launch power (max) value for 800GBASE-ER1-20 to -5 dBm

Proposed Response Response Status O

Cl 180 SC 180.7.2 P440 L33 # 391

Rodes, Roberto

Coherent

Comment Type TR Comment Status X

The receiver sensitivity specification currently relies on a complex block error ratio calculation. However, the methodology is unclear regarding the required test duration to meet the specification, and it lacks guidance on how to perform a 'statistical projection'. As receiver sensitivity is a primary specification for a PMD receiver, its test and verification procedures should be clear and practical to execute, while ensuring a reasonable level of confidence. Supporting presentation will be provided

SuggestedRemedy

replace note c by: "Measured using the conformance test signal at TP3 (refer to Section 180.8), with an error ratio allocation one decade lower than specified in 174A.12 for PMD-to-PMD." Apply also to clauses 181, 182 and 183

Proposed Response Response Status O

Cl 180 SC 180.9.5 P448 L23 # 392

Rodes, Roberto

Coherent

Comment Type T Comment Status X

In chayeb_3dj_01_2505, 100G module data showed that transmitters with intentionally excessive group delay can cause issues at the receiver, despite still passing the TDECQ test. Introducing a limit on the maximum absolute difference between the first postcursor and the first precursor would significantly increase the TDECQ penalty for such poorly tuned transmitters, preventing their use and reducing the burden on receivers.

SuggestedRemedy

add footnote c: "The absolute difference between c(-1) and c(1) shall be less than 0.3.". Apply also to clauses 181, 182 and 183

Proposed Response Response Status O

Cl 180 SC 180.9.5 P447 L21 # 393

Rodes, Roberto Coherent

Comment Type T Comment Status X

The current reference receiver assumption used in TDECQ measurements prevents a large number of transmitters—despite demonstrating excellent real-world receiver performance—from passing the TDECQ test. The reference receiver is significantly less capable than actual implemented receivers. It is proposed to add a 1-tap DFE with a limited maximum value to better reflect practical receiver performance. Supporting presentation will be provided

Suggested Remedy

replace with: "The reference equalizer is a 15-tap, T-spaced, feed-forward equalizer (FFE) combined with a 1-tap decision feedback equalizer (DFE), where T is the symbol period, with equalizer coefficient constraints as shown in Table 180–15...". In Table 180-15 add limit for 1-tap DFE with max value 0.3. Apply also to clauses 181, 182 and 183

Proposed Response Response Status

Cl 180 SC 180.7.2 P440 L4 # 394

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type TR Comment Status X

In Table 180-8, footnote c for stressed receiver sensitivity. The requirement of measured for the block error ratio specified in 180.2 is impractical to implement. Reason is the same as the comment to 180.2.

This comment applies to all applicable optical PMD Clauses, i.e. CL180~183, CL185

Suggested Remedy

instead of pointing to block error ratio. Point to the error allocation clause of 180.2.

Change footnote c in Table 180-6 to:

" Measured with conformance test signal at TP3 (see 181.0.13) for the error ratio allocation specified in 180.2. "

This comment applies to all applicable optical PMD Clauses, i.e. CL180~183, CL185. Change the respective CL18x.

Proposed Response Response Status

Cl 180 SC 180.2 P432 L33 # 395

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type TR Comment Status X

The error ratio allocation provides reference to 174A.5, which defines the PHY to PHY link. The clause itself is focused on optical PMD. Table 174A-1 provide detailed error allocation of the components in the PHY link, and specifically addresses the optical PHYs as this clause. It provides the full picture of error allocation. We should reference it more clearly.

This comment applies to all IMDD optical PMDs. i.e. CL180~183, CL185.

Suggested Remedy

change to "A complete PHY is expected to meet the frame loss ratio specifications in 174A.5, with each component in the PHY meeting the error ratio allocations specified in Table 174A-1. "

This comment applies to all applicable optical PMDs. i.e. CL180~183, CL185.

Proposed Response Response Status

CI 180 SC 180.2 P432 L33 # 396

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type TR Comment Status X

The receiver sensitivity and stressed receiver sensitivity, as the two most important optical parameter are defined as the input OMA at which the receiver hits the threshold of an error ratio metric. They will be tested for each module to be shipped, which currently has a volume in the million ports/year level now. That means the time spent on testing the receiver sensitivity is a huge factor in cost, both in terms of CAPEX and OPEX of the module vendor, system vendor and the end user.

While block error ratio maybe theoretically perfect, it is almost impossible to implement practically or cost effectively, reasons as following:

The expected measurement time of getting direct measurement result for each of the test_block_error_bin_i is impractical in both DVT and volume testing. An estimated of 10 days to observe 1 event in bin 15 in the cases of the upper limit Hmax. For practical products, performance are expected to be better than Hmax, making it even longer to observe. And to have statistical confidence, one would even require to observe over 10 times of the event to make it representative, or the data set to "be sufficiently large to reliably verify".

My previous contribution with 100G/L data and Michael He's 200G/L data have shown that a time span of several mins would be required to get reasonable result. Comparing what is being used today (a few seconds), that is ~10 times the length.

The data also showed that statistical projection can be very subjective approach, sometimes even impossible. This eliminates the block error histogram and the block error ratio (which is calculated using the histogram) being objective metric for link performance, especially when it comes to quantitative comparison. Whether or not a DUT passes the requirement can be dependent on an engineer's experience and judgement. This is not a economical feasible parameter to be used in mass volume production in modern industry, which typically employs automatic testing and validation.

This comment applies to all applicable optical PMDs. i.e. CL180~183, CL185.

SuggestedRemedy

Provide the information of BER threshold under random error assumption as previous generations of ethernet optical PMDs. Point out that for links that are prone to burst error, further evaluation of the PHY/link/PMD can be done based on the block error ratio method. Similar statement on leaving margin for not-so-random links has been use before. Leave it to the implementer and user of this standard to decide which method to use in their design, DVT and volume production stage,.

This comment applies to all applicable optical PMDs. i.e. CL180~183, CL185.

A contribution will be provided with detailed suggested remedy.

Proposed Response Response Status O

CI 178B SC 178B P786 L10 # 397

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type TR Comment Status X

ILT should be supported for coherent optical PMDs, at the minimum 800GBASE-LR1 spec. 800GBASE-LR1 and 800GBASE-LR4 modules can be used in the same switch/router, and potentially interchangeable in pairs in deploying network equipment depending on the fiber link condition. By allowing ILT in 800GBASE-LR1, the host equipment does not need to differentiate the optical port, and use one routine of link up process. This brings benefits to opex and firmware development.

This comment also requires updates to sub clause 160.2.10 in page190.

SuggestedRemedy

Extend ILT capability to LR1, at the minimum by supporting transmission of RTS. RTS condition of the ISL path between two LR1 PMDs could be derived from the states of the LR1 inner FEC, where dsp frame locking and aligning are already performed. A contribution will be provided.

Proposed Response Response Status O

CI 185 SC 185.6.1 P564 L50 # 398

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type TR Comment Status X

The Tx laser frequency slew rate is required to be measured at the stages of pre-acquisition and post acquisition and satisfy the value defined in Table 185-5, however there is no definition of the term of acquisition in the draft. Though "acquisition" is a widely used term for coherent experts, it appears out of context in this draft. It may be able to relate to some of the Inner FEC behaviour or PMA behaviour, but it could use some explanation.

SuggestedRemedy

add definition of acquisition in the text where Tx laser frequency slew rate is defined. Looking for help from Coherent experts here.

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

CI 187 SC 187.6.2 P639 L35 # 399

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type TR Comment Status X

In the system of coherent optical specification, two parameters are introduced, the Rx Sensitivity and the Rx AOP tolerance_min. when checking across LR1, ER1-20, and ER1 spec, it is noticed that the relation of the two parameters of ER1 was not consistent with the other two coherent PMDs. for both LR1 and ER1-20, Rx AOP min - Tx AOP min = IL and Rx Sens. - Tx AOP min = Power budget. While for ER1, Rx AOP min - Tx AOP min = Power Budget and Rx Sens. - Tx AOP min = Power budget +1, essentially offset by 1dB, same as ER1 penalty allocation.

SuggestedRemedy

either shift Tx AOP down by 1dB or raise the Rx Sens. & Rx AOP tolerance_min up by 1dB

Proposed Response Response Status O

CI 185 SC 185.3.1.3.2 P560 L1 # 400

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type TR Comment Status X

the SIGNAL_OK of 800GABSE-LR1 is tied to Global_PMD_signal_detect, which is decided based on the optical power at the receiver. This doesn't guarantee a valid, decodable signal, as suggested by the note below the paragraph. With this definition, the parameter SIGNAL_OK doesn't bear sufficient information to help bring up the link. While the IMDD optical PMDs, by leveraging ILT, SIGNAL_OK can indicate the received signal meets the minimum requirement of communication, making it a meaningful parameter. There is no reason not to do the same in the case of LR1.

SuggestedRemedy

change the signal_ok definition, tie it to the state of LR1 Inner FEC, or ILT state if allowed. This comment is related to the comment regarding ILT in coherent PMDs. A contribution will be provided

Proposed Response Response Status O

CI 174A SC 174A.8 P679 L25 # 401

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type TR Comment Status X

two methods were proposed for block error evaluation. Either by examining the block error histogram being below the Hmax histogram mask, or checking block error ratio being smaller than $1.45e-11$. however, when using the Hmax to calculate its corresponding block error ratio, I arrived at $1.55e-11$, which is not passing the block error ratio requirement.

SuggestedRemedy

I am strongly confused by this now. no suggested remedy at this time. I will reach out to Adam for help.

Proposed Response Response Status O

CI 174A SC 174A.8 P679 L24 # 402

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type ER Comment Status X

This clause discusses the error ratio tests for 200Gb/s per lane ISLs, whereas this sentence says "A method for constraining the error ratio of a PHY based on error masks using PMA measurements". The test method for PHY is to be discussed in the later subclause of 174A.10

SuggestedRemedy

change the word "PHY" to "ISL" in the mentioned sentence.

Proposed Response Response Status O

CI 174A SC 174A.8.1 P679 L38 # 403

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type ER Comment Status X

There is only one sub-clause under 174A.8, which is 174A.8.1, no need to have this level in the hierarchy.

SuggestedRemedy

remove the hierarchy of 174A.8.1, make its sub-clauses 174A.8.x

Proposed Response Response Status O

CI 174A SC 174A.8.1.2 P681 L31 # 404

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type TR Comment Status X

The total number of test blocks being measured and analyzed is required as: " The value of test_block_total_count_i should be sufficiently large to reliably verify that the expected block error ratio is met, either by direct measurement or statistical projection. The projection should provide an accurate prediction of the value of Hm(i)(k) that would be observed over longer-term testing or at least provide an upper bound on the value."

A statistical projection is an estimate of future events with level of confidence. It can not be accurate.

Reconsider the statement on "accurate prediction ".

H_m(k) is a statistical possibility which is observed over a window of measurement in a very long window if not infinite. It is unclear how to decide whether the measured data and the projection based on the data could represent the value of long-term observation or the upper bound on the value.

SuggestedRemedy

Reconsider the state ment of the statistical projection.

Proposed Response Response Status O

CI 174A SC 174A.8.1.7 P683 L7 # 405

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type TR Comment Status X

In this section, the block error ratio method for a single lane is described. The block error counters are measured independently for each lane. In the determination of lane l, step d) says "For p times, iteratively assign the result of hconv(He(k) , Hm(k)) (see 174A.8.1.4) to He(k)". It is unclear what does the p times mean in this step.

To measure p times the lengths of blocks? and use the collected as 1 dataset?

To repeat the same measurement on the same lengths of blocks for p times? Should the histogram be averaged over the p times of measurement?

SuggestedRemedy

please clarify.

Proposed Response Response Status O

CI 174A SC 174A.10.1.3 P685 L18 # 406

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type TR Comment Status X

The total number of FEC codewords being measured and analyzed is required as: " The value of FEC_cw_counter should be sufficiently large to reliably verify that the expected block error ratio is met, either by direct measurement or statistical projection. The projection should provide an accurate prediction of the value of Hm(k) that would be observed over longer-term testing or at least provide an upper bound on the value."

A statistical projection is an estimate of future events with level of confidence. It can not be accurate.

H_m(k) is a statistical possibility which is observed over a window of measurement in a very long window if not infinite. It is unclear how to decide whether the measured data and the projection based on the data could represent the value of long-term observation or the upper bound on the value.

SuggestedRemedy

Reconsider the state ment of the statistical projection.

Proposed Response Response Status O

CI 174A SC 174A.10.1.3 P685 L40 # 407

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type ER Comment Status X

typo of the word then in the sentence

SuggestedRemedy

change "the" to "then"

Proposed Response Response Status O

CI 174A SC 174A.10.1.3 P685 L45 # 408

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type ER Comment Status X

missing a word "to"

SuggestedRemedy

change to " expected to be less"

Proposed Response Response Status O

CI 174A SC 174A.12 P686 L22 # 409

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type TR Comment Status X

Table 174A-1, FLR was changed from 6.2e-11 to 6e-11. The reasoning seems to be the 0.2e-11 was allocated to the xMII extenders and PCS to FEC links illustrated in Table 174A-3. However, in reality, no such case as cascading two sets of two-part AUI link would exist. The title of Table 174A-1 "optical PHYs with no FEC sublayer or with an inner FEC sublayer" also indicating that Table 174A-3 does not apply. Essentially, Table 174A-1 doesn't apply to 800GBASE-ER1 and 800GBASE-ER1-20 with xMII extenders, but is using the allocation for such cases.

The change may not affect the performance of a Ethernet device much, but may cause some confusion of the readers.

SuggestedRemedy

Change back to 6.2e-11 for Table 174A-1. Add another error allocation table for the case of ER coherent PMDs

Proposed Response Response Status

CI 176D SC 176D.8.11 P755 L21 # 410

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type TR Comment Status X

beginning of this section, the amplitude tolerance is said to be defined as the maximum steady state voltage. In this note, it says the steady-state voltage is defined with preset 1. In the same time, the receiver is not required to tolerate preset 1 unless it specifically requests it.

It is very confusing which voltage is used and how it is defined.

SuggestedRemedy

Please clarify.

Proposed Response Response Status

CI 176D SC 176D.8.11 P755 L12 # 411

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type TR Comment Status X

The determination of a receiver can tolerate a given voltage as its amplitude tolerance, is based on the receiver satisfies the error allocation requirements in 176D.2 when operating in Data mode.

In 176D.2, the error allocation is to meet the block error ratio of 1.45e-11 measured using the method described in 174A.8, where one can examine the histogram and compare it to a mask or calculate the block error ratio based on the histogram.

The histogram consists of 17 bins, with bin 0 to bin 15 should be measured or projected with value, to calculated bin 16p.

The expected measurement time of getting direct measurement result for each of the test_block_error_bin_i is impractical in both DVT and volume testing. An estimated of 10 days to observe 1 event in bin 15 in the cases of the upper limit Hmax. For practical products, performance are expected to be better than Hmax, making it even longer to observe.

My previous contribution with 100G/L data and Michael He's 200G/L data have shown that statistical projection can be very subjective approach, sometimes even impossible. This eliminates the block error histogram and the block error ratio (which is calculated using the histogram) being objective metric for link performance, especially when it comes to quantitative comparison. Whether or not a DUT passes the requirement can be dependent on an engineer's experience and judgement.

Judgement of amplitude tolerance of the module input and host input based on block error ratio is not economical feasible.

SuggestedRemedy

Consider the approach of using BER, and use block error method as recommendation / informative test to complement verification of the system.

Proposed Response Response Status

Cl 176D SC 176D.6.4 P746 L24 # 412

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type **TR** Comment Status **X**

The current value Rpeak of module output in AUI-C2M is set too high, which can not be met by the reference COM model as shown by the COM simulation result in P9 of mellitz_3dj_03_2505.

SuggestedRemedy

change Rpeak to 0.456 as a starting point. A contribution will be provided.

Proposed Response Response Status **O**

Cl 176D SC 176D.7.1 P748 L37 # 413

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type **TR** Comment Status **X**

In the reference insertion loss budget of AUI-C2M, the connector loss was not specified. However, in CL179A.4 for CR channel parameter, a 2.45dB of mated connector insertion loss was assumed. Since the CR can be implemented as DAC, which has been using the same mated connector and packaging formfactor as many of the IMDD pluggable modules, the same connector loss could be used in the reference channel model of AUI-C2M for a clear illustration.

SuggestedRemedy

indicate a connector loss of 2.45dB in the drawing of Figure 176D-6, add appropriate description to the text.

Proposed Response Response Status **O**

Cl 176D SC 176D.6.4 P746 L34 # 414

Mi, Guangcan Huawei Technologies Co., Ltd

Comment Type **TR** Comment Status **X**

As Ali's contribution ghiasi_3dj_02b_2505, dSNDR is a complicated parameter. Rich's contribution further proposed to set a set of SNDR_ref values.

For module vendors, both SNDR and dSNDR are newly introduced, and dependent on the IL at the host side. It is not practical for the module vendors to test for all the IL variations.

SuggestedRemedy

The AUI C2M methodology affects both the SERDES/equipment and the optical module community. The newly introduced parameters need to be open for consideration from both sides, and find consensus in simplifying the measurements.

Proposed Response Response Status **O**

Cl 178B SC 178B.14.3.1 P808 L25 # 415

Ran, Adee Cisco Systems

Comment Type **TR** Comment Status **X**

In order to bring up a link that includes multiple ISLs, the functionality of ILT as specified by Figure 178B-7 and Figure 178B-8 is required across ISLs.

In PMDs that don't have a training protocol, and in PMDs that have it but training is disabled, the "quiet" and "local pattern" modes are the method of communicating the RTS to the peer.

However, the specification for the transmitted local pattern is incomplete - it only says "transmits a pattern from a valid pattern generator".

A local pattern for ILT should be specified in every PMD clause and AUI annex. This comment addresses the general requirements; additional comments are submitted for the PMD clauses (including 185 and 187 that currently do not have ILT as a requirement at all):

- For AUIs, the local pattern is PRBS31Q, which may be generated by the PMA to which the AUI component is attached and fed into the AUI component.
- For PMDs in clauses 178-182 (directly below an SM-PMA with no inner FEC), the local pattern is PRBS31Q, which may be generated by the SM-PMA and fed into the PMD service interface.
- For PMDs in clauses 183 and 185 (below a clause 177 or clause 184 Inner FEC, respectively), the local pattern is PRBS31 encoded by the Inner FEC, which may be generated by the Inner FEC and fed into the PMD service interface.
- For the PMD in clause 187, the local pattern is the output of the test pattern generator defined in 186.2.3.12.

SuggestedRemedy

Add text in the definition of tx_mode (178B.14.3.1) stating that the pattern used as local_pattern is specified in each clause or annex that uses the ILT function.

Proposed Response Response Status **O**

Cl 178 SC 178.8.9 P361 L13 # 416

Ran, Adeo Cisco Systems

Comment Type TR Comment Status X

In order to bring up a link that includes multiple ISLs, the functionality of ILT as specified by Annex 178B (specifically Figure 178B-7 and Figure 178B-8) is required across ISLs.

In PMDs that have a training protocol but it's disabled, the "quiet" and "local pattern" modes are the method of communicating the RTS to the peer. However, the local pattern is currently not defined.

Applies to the multiple ILT function subclauses of the PMD functional specifications in clauses 178 through 182 (which have an SM-PMA above the PMD)

SuggestedRemedy

Specify that PRBS31Q (which may be generated by the PMA, see 176.7.4.2) is the pattern used when mr_training_enable is false and tx_mode has the value local_pattern (see 178B.14.3.1).

Proposed Response Response Status O

Cl 183 SC 183.5.12 P510 L33 # 417

Ran, Adeo Cisco Systems

Comment Type TR Comment Status X

In order to bring up a link that includes multiple ISLs, the functionality of ILT as specified by Annex 178B (specifically Figure 178B-7 and Figure 178B-8) is required across ISLs.

In PMDs that have a training protocol but it's disabled, the "quiet" and "local pattern" modes are the method of communicating the RTS to the peer. However, the local pattern is currently not defined.

SuggestedRemedy

Specify that PRBS31 encoded by Inner FEC as defined in 177.6.1.1 (which may be generated by the inner FEC sublayer) is the pattern used when mr_training_enable is false and tx_mode has the value local_pattern (see 178B.14.3.1).

Proposed Response Response Status O

Cl 185 SC 185.1 P556 L40 # 418

Ran, Adeo Cisco Systems

Comment Type TR Comment Status X

In order to bring up a link that includes multiple ISLs, the functionality of ILT as specified by Annex 178B (specifically Figure 178B-7 and Figure 178B-8) is required across ISLs. This is true regardless of the PMD type, and even if the PMD does not use a training protocol, such as 800GBASE-LR1.

In PMDs that don't have a training protocol, the "quiet" and "local pattern" modes are the method of communicating the RTS to the peer. However, the local pattern is currently not defined.

SuggestedRemedy

Add 178B-ILT, Required as row in Table 185-1 (as in other PMD clauses)..

Add a subclause under 185 defining the ILT functionality; it is as specified in Annex 178B, with mr_training_enable always set to false (since 800GBASE-LR1 doesn't have a training protocol). Specify that Inner FEC encoded PRBS31 test pattern defined in 184.6.1 (which may be generated by the inner FEC sublayer) is the pattern used when tx_mode has the value local_pattern (see 178B.14.3.1).

Proposed Response Response Status O

Cl 187 SC 187.1 P630 L44 # 419

Ran, Adeo Cisco Systems

Comment Type TR Comment Status X

In order to bring up a link that includes multiple ISLs, the functionality of ILT as specified by Annex 178B (specifically Figure 178B-7 and Figure 178B-8) is required across ISLs. This is true regardless of the PMD type, and even if the PMD does not use a training protocol, such as 800GBASE-ER1 and 800GBASE-ER1-20.

In PMDs that don't have a training protocol, the "quiet" and "local pattern" modes are the method of communicating the RTS to the peer. However, the local pattern is currently not defined.

SuggestedRemedy

Add 178B-ILT, Required as row in Table 187-1 (as in other PMD clauses)..

Add a subclause under 187 defining the ILT functionality; it is as specified in Annex 178B, with mr_training_enable always set to false (since 800GBASE-ER1/ER1-20 don't have a training protocol). Specify that the 800GBASE-ER1 FEC encoded PRBS31 test pattern defined in 186.2.3.12 (which may be generated by the 800GBASE-ER1 FEC sublayer) is the pattern used when tx_mode has the value local_pattern (see 178B.14.3.1).

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 178B SC 178B.14.3.3 P809 L14 # 420

Ran, Adee Cisco Systems

Comment Type T Comment Status X

A presented in https://www.ieee802.org/3/dj/public/25_05/ran_3dj_02a_2505.pdf, there is a potential benefit in having a timer to the ILT training control state diagram, to inform management when the adaptation exceeds the expected time.

SuggestedRemedy

Implement the changes to clause 175 per slide 11 of ran_3dj_02a_2505, with editorial license.

Proposed Response Response Status O

Cl 178B SC 178B.5.3 P789 L44 # 421

Ran, Adee Cisco Systems

Comment Type TR Comment Status X

The text about training xMII extenders does not address the communication of the status variables isl_ready and remote_rts between interfaces (PMD to AUI and vice versa) when there is a PHY XS and PCS between them.

Ideally, this communication should be the same as the one defined in 178B.14.2.1 using adjacent_signal_ok, but the case of an extender is not covered by NOTE that describes what "adjacent" is.

Since this behavior is specific to PHYs attached to extenders, it should be specified in this subclause, preferably with a diagram.

SuggestedRemedy

Add a NOTE in 178B.5.3 stating that, for the purpose of adjacent_signal_ok, the adjacent interface of a PMD in a PHY attached to an xMII extender is the service interface of the PHY XS; and the adjacent interface of the AUI component above the PHY XS is the service interface of the PMD.

Add a figure to illustrate the communication of adjacent_signal_ok between the PMD and the AUI (across the PCS and PHY XS, and possibly other sublayers).

Proposed Response Response Status O

Cl 178B SC 178B.15 P813 L1 # 422

Ran, Adee Cisco Systems

Comment Type T Comment Status X

"If the MDIO Interface is not implemented, an alternate mechanism to access management variables shall be provided"

Specifically for AUI-C2M, the most prevalent management interface is expected to be CMIS rather than MDIO. We expect CMIS to provide access to these management variables. CMIS should be referenced, at least informatively.

SuggestedRemedy

Append the following sentence: "For example, for modules using AUI-C2M, the Content Management Interoperability Services (CMIS) interface may be used as an alternate mechanism". Add a footnote with a reference to the CMIS specification (undated, since the current version does not address ILT yet).

Proposed Response Response Status O

Cl 174 SC 174.2.1 P248 L48 # 423

Ran, Adee Cisco Systems

Comment Type TR Comment Status X

"MII" is defined in 1.4.393 with reference to Clause 22, which is 100 Mb/s. It is irrelevant for this project. Saying that "The MII is not intended to be physically instantiated" does not match this definition.

"MII" has been used in other clauses in a way that contradicts the definition. This is wrong, and should not be carried on.

The text can say that 1.6T Ethernet uses a specific interface between the RS and the PCS, the 1.6TMII. Or simply use 1.6TMII everywhere instead of MII.

SuggestedRemedy

Change "MII" to "1.6TMII", and change the expanded acronym accordingly, across this clause, with editorial license.

Proposed Response Response Status O

Cl 178B SC 178B P786 L12 # 424

Ran, Adeo Cisco Systems

Comment Type T Comment Status X

There should be a distinction between "ILT", which is a protocol on a single ISL, and the end-to-end (RS-to-RS) path bring-up procedure. The latter is an ability that is enabled by the former, but is system-level result, while ILT is a local mechanism.

Additional terminology may be helpful, e.g. "Physical layer startup procedure".

SuggestedRemedy

Add a definition of "Physical layer startup procedure" and update the text in multiple places to distinguish it from "ILT" used over a single ISL. Implement with editorial license.

Proposed Response Response Status O

Cl 180 SC 180.7.1 P438 L51 # 425

Ran, Adeo Cisco Systems

Comment Type TR Comment Status X

Transmitter jitter specifications are required for optical PMDs. Clock jitter, especially at low frequencies, are not captured adequately by existing specifications, and should be limited by specifications to avoid correlated errors in receivers that would degrade link performance.

A presentation with more details is planned, but the suggested remedy contains a summary of the suggested changes.

SuggestedRemedy

In Table 180-7, add an "Output jitter" row with parameters, values, and units as in Table 176D-3 (module output specifications at TP4).

In Table 180-14, add an "Output jitter" row with pattern 4 or 6, and reference to 180.9.14 (new subclause).

Add a new subclause 180.9.14 for Output jitter. The content is to be taken from 176D.8.9, with additional exceptions:
 - transmit equalizer is fixed
 - when the PHY includes an xAUI-n, the clock source for the test pattern is derived from the clock recovered from the xAUI-n input signal.

Implement with editorial license.

Proposed Response Response Status O

Cl 181 SC 181.7.1 P462 L39 # 426

Ran, Adeo Cisco Systems

Comment Type TR Comment Status X

Transmitter jitter specifications are required for optical PMDs. Clock jitter, especially at low frequencies, are not captured adequately by existing specifications, and should be limited by specifications to avoid correlated errors in receivers that would degrade link performance.

A presentation with more details is planned, but the suggested remedy contains a summary of the suggested changes.

SuggestedRemedy

Refer to my similar comment against 180.7.1, implement the corresponding changes in Clause 181, with editorial license.

Proposed Response Response Status O

Cl 182 SC 182.7.1 P489 L25 # 427

Ran, Adeo Cisco Systems

Comment Type TR Comment Status X

Transmitter jitter specifications are required for optical PMDs. Clock jitter, especially at low frequencies, are not captured adequately by existing specifications, and should be limited by specifications to avoid correlated errors in receivers that would degrade link performance.

A presentation with more details is planned, but the suggested remedy contains a summary of the suggested changes.

SuggestedRemedy

Refer to my similar comment against 180.7.1, implement the corresponding changes in Clause 182, with editorial license.

Proposed Response Response Status O

Cl 183 SC 183.7.1 P512 L50 # 428

Ran, Adeo Cisco Systems

Comment Type TR Comment Status X

Transmitter jitter specifications are required for optical PMDs. Clock jitter, especially at low frequencies, are not captured adequately by existing specifications, and should be limited by specifications to avoid correlated errors in receivers that would degrade link performance.

A presentation with more details is planned, but the suggested remedy contains a summary of the suggested changes.

SuggestedRemedy

Refer to my similar comment against 180.7.1, implement the corresponding changes in Clause 183, with editorial license.

Proposed Response Response Status

Cl 181 SC 181.7.1 P462 L19 # 429

Ran, Adeo Cisco Systems

Comment Type T Comment Status X

Table 181-5 has a sub-row of OMA_{outer} (min): "for TDECQ<0.9 dB"

Shouldn't it be "for max(TECQ, TDECQ)<0.9 dB", as in the similar rows in Table 180-7, Table 182-7, and Table 183-6?

SuggestedRemedy

Change to "for max(TECQ, TDECQ)<0.9 dB".

Proposed Response Response Status

Cl 180 SC 180.9.5 P448 L17 # 430

Ran, Adeo Cisco Systems

Comment Type TR Comment Status X

The reference equalizer currently allows a very large magnitude for the precursor (i = -1) and postcursor (i = 1) coefficients of the reference receiver. This assumes real receivers will be able to apply similar equalization.

Reference receiver coefficient data was provided in the following contributions:

- https://www.ieee802.org/3/dj/public/24_05/welch_3dj_01_2405.pdf - where most data points have pre/post coefficients within the range -0.3 to +0.1.
- https://www.ieee802.org/3/dj/public/24_09/welch_3dj_01_2409.pdf - where new data sets are included with pre/post cursors that reach approximately -0.4.

The reference receiver limits were set with margin relative to all provided data sets, such that they are all acceptable, and allowing transmitters that require even stronger equalization. However, there was no evidence or indication in either presentation that these transmitters enable good receiver performance.

Contributed data in https://www.ieee802.org/3/dj/public/25_05/chayeb_3dj_01_2505.pdf shows that reference receiver coefficients that have large magnitudes, and especially large difference between pre/post coefficients (indicating phase distortion), create severe degradation in real receivers. It is known fact that DSP receiver implementations have limited equalization capability (especially for precursor) and that strong equalization degrades the performance (e.g. due to limited ADC range). It is not expected to be much better in future designs.

Requiring such strong equalization settings indicates poor transmitter waveform shaping and would likely create unexpectedly bad link performance. Even if real transmitters will not have such impairments, a signal with such bad waveform shaping might be used for stressed receiver testing; this should not be allowed.

See

https://www.ieee802.org/3/dj/public/adhoc/electrical/25_0605/ran_3dj_elec_01b_250605.pdf, slides 12-18; the suggested remedy has been updated since that presentation.

SuggestedRemedy

In Table 180-15, change the Minimum value for i=-1 from -0.5 to -0.3, and for i=1 from -0.6 to -0.3.

Change the Maximum value for i=1 from 0.2 to 0.1.

Alternatively, specify that the difference between coefficients -1 and +1 of the reference receiver does not exceed +/-0.3.

Apply the same changes in Table 181-13, Table 182-15, and Table 183-14.

Proposed Response Response Status

Cl 119 SC 119.2.4.1 P174 L33 # 431

Ran, Adeo Cisco Systems

Comment Type T Comment Status X

Limiting the stateless encoder/decoder to only new PHYs is not required for interoperability, since they are interoperable with the previously defined state-diagram functions.

Additionally, the additional wording makes interpreting the standard more cumbersome.

The stateless encoder and decoder are likely to be required in the already-defined PHYs for support of Ethernet metadata (expected new project) so at some point these non-inclusive lists will go away. Why not do it now.

SuggestedRemedy

Delete the list of PHYs in 119.2.4.1 and in 119.2.5.8, to enable the stateless functions to be used in all PHYs that use the Clause 119 PCSs. Implement with editorial license.

Proposed Response Response Status O

Cl 175 SC 175.2.5.3 P273 L40 # 433

Ran, Adeo Cisco Systems

Comment Type TR Comment Status X

As shown in https://www.ieee802.org/3/dj/public/25_05/ran_3dj_03a_2505.pdf, there is a potential for corrupted data reaching the PCS client after uncorrectable codeword is processed, due to scrambler error multiplication that occurs separately in flow 0 and flow 1.

For the 1.6TBASE-R PCS, this can be addressed by adding a requirement that the Reed-Solomon decoder applies error extension, as described on slides 23 and 25 of ran_3dj_03a_2505.

SuggestedRemedy

Add an exception that if an uncorrectable codeword is detected in any of the two flows, the 257b block following the uncorrectable codeword is replaced (after the descrambler) by a block corresponding to 16 error characters. Implement with editorial license.

Proposed Response Response Status O

Cl 172 SC 172.2.5.2 P242 L18 # 432

Ran, Adeo Cisco Systems

Comment Type TR Comment Status X

As shown in https://www.ieee802.org/3/dj/public/25_05/ran_3dj_03a_2505.pdf, there is a potential for corrupted data reaching the PCS client after uncorrectable codeword is processed, due to error multiplication due to scrambler error multiplication that occurs separately in flow 0 and flow 1.

For the 800GBASE-R PCS, this can be addressed by adding a requirement that the Reed-Solomon decoder applies error extension, as described on slides 23 and 24 of ran_3dj_03a_2505.

Since this PCS is already defined, this comment may raise questions of scope. It is provided to facilitate discussion of the technical change separately from the scope of the project. If necessary, a maintenance request will be submitted in the future.

SuggestedRemedy

Bring 172.2.5.3 from 802.3df-2024 into this amendment, and add an exception to the list, that if an uncorrectable codeword is detected in any of the two flows, the 257b block following the uncorrectable codeword is replaced, after processing by the descrambler of that flow, by a block corresponding to 4 EBLOCK_R blocks (or 16 error characters). Implement with editorial license.

Proposed Response Response Status O

IEEE P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 1 SC 1.3 P53 L49 # 434

Ran, Adee Cisco Systems

Comment Type T Comment Status X

Several items in the normative references list include a specific Draft number. Some of these drafts are no longer available, and in some cases the version number does not match the date indicated (which suggests that a newer draft was intended).

For SFF documents, only the most recent draft (typically with version number x.y.z) is available; older drafts are removed.

Per the IEEE SA style manual (12.3.1 item c): "Draft standards: Unpublished drafts may be used as normative references as long as they are: (-) Dated (-) Readily available (-) Retrieval; A copy of ALL drafts shall be submitted to IEEE SA to be placed on file as an archive."

Thus, if we keep a dated draft, it should be archived in IEEE SA.

This comment pertains to the following references:

"SFF-8665, Rev 1.9.4, April 1, 2022" (QSFP+) - 1.9.4 is a draft that is no longer available. The current draft is 1.9.8. The published version, 1.9, is from 2015, apparently too old.

"SFF-TA-1011 Rev 1.1, April 19, 2024" (SFF cross reference) - revision number does not match the date; Rev 1.1 is from 2019-10-01 and is apparently too old to be referenced by this project. The current draft is 1.1.6.

"SFF-TA-1027, Rev 1.0, April 16, 2024" - (QSFP2 connector, cage, & module) - revision number does not match the date; Rev 1.0 is from 2023-05-30 and does not include QSFP224 as required for this project. The current draft is 1.0.6.

"QSFP-DD/QSFP-DD800/QSFP-DD1600 Hardware Specification for QSFP Double Density 8x Pluggable Transceivers, Rev 7.1, June 25, 2024.7" - this is indeed the current version, but it is a not a draft; there is no reason to refer to a specific version rather than the latest one.

"SFF-TA-1031, Rev 1.0, June 11, 2023, SFP2 Cage, Connector, & Module Specification" - this is indeed the current version (which does not include SFF224, subject of another comment) but it is not a draft; there is no reason to refer to a specific version rather than the latest one.

Since these are normative references that apply to multiple projects, including future ones, they should refer to documents that are available to readers in the future. Thus, we should use undated references where possible. Per the style manual (12.3.2), standards may be dated or undated; but drafts "shall be numbered and dated".

An editor's note may be used to indicate the current draft and as a reminder that "drafts shall be submitted to IEEE SA".

SuggestedRemedy

For each of the indicated references that is a draft, add an editor's note (to be removed before publication) indicating the revision number and date as of D2.1, and a reminder to update to the latest draft revision and date and provide a copy for the archive prior to publication.

Make similar changes as appropriate in the text that refers to these form factors in Annex 179C.

Proposed Response Response Status O

Cl 1 SC 1.3 P53 L53 # 435

Ran, Adee Cisco Systems

Comment Type TR Comment Status X

Footnote 6 refers to OSFP1600, but OSFP is a normative reference not just for OSFP1600 but also for the original OSFP, which is used in the base standard (e.g. clause 136).

Similarly, Footnote 7 refers to QSFP-DD1600, but QSFP-DD is a normative reference for the base standard.

SuggestedRemedy

Delete "1600" in both footnotes.

Proposed Response Response Status O

Cl 1 SC 1.3 P53 L54 # 436

Ran, Adee Cisco Systems

Comment Type TR Comment Status X

QSFP-DD MSA specification is not the reference for SFP-DD224 (which does not exist yet) and QSFP224 (which is an SFF specification).

SuggestedRemedy

Delete "SFP-DD224, QSFP224, and"

Proposed Response Response Status O

Cl 179C SC 179C.1 P833 L25 # 437

Ran, Adeo Cisco Systems

Comment Type TR Comment Status X

There are currently no specifications, neither final or draft, of SFP224 and SFP-DD224 that can be referred to.

The amendment cannot be finalized with references to undefined specifications.

We should at least decide on a deadline for availability of these specifications. If they are not available by the deadline, they will need to be removed.

SuggestedRemedy

Add editor's note at the beginning of Annex 179C stating that SFP224 and SFP-DD224 specifications are not available yet, and that all references to these connector types will be removed if specifications are not available by the first SA ballot recirculation (i.e. they will not appear in D3.1).

These notes should replace the notes in 179C.2.1 and 179C.2.2.

Add similar notes in 179.11.7.2.2 and 179.12 where these connectors are mentioned too.

Proposed Response Response Status O

Cl 179C SC 179C.2.3 P841 L40 # 438

Ran, Adeo Cisco Systems

Comment Type T Comment Status X

The Editor's note is obsolete - the recent version of SFF-TA-1027 (1.0.6, <https://members.snia.org/document/dl/36947>) does include QSFP224.

SuggestedRemedy

Delete the note.

Proposed Response Response Status O

Cl 73 SC 73.4.1 P129 L31 # 439

Ran, Adeo Cisco Systems

Comment Type T Comment Status X

"but will not transmit an ability it does not possess"

"will" is not suitable - it is a requirement, not a statement of fact.

"advertise" is typically used for abilities, and is preferable over "send" here.

SuggestedRemedy

Change to "but it shall not advertise an ability it does not possess".

Proposed Response Response Status O

Cl 73 SC 73.6.2.5 P133 L50 # 440

Ran, Adeo Cisco Systems

Comment Type T Comment Status X

"FEC capability (F4, F2, F3, F0, F1) is encoded in bits D43:D47" three of these bits encode requests, rather than capabilities.

SuggestedRemedy

Change to "FEC capability and request bits (F4, F2, F3, F0, F1) are encoded in bits D43:D47"

Proposed Response Response Status O

Cl 119 SC 119.6 P178 L19 # 441

Ran, Adeo Cisco Systems

Comment Type TR Comment Status X

The timeout for link_fail_inhibit_timer, minimum 60 seconds, creates an unacceptably long minimum time to retry AN.

A proposal to enable faster restart of AN was presented in https://www.ieee802.org/3/dj/public/25_05/ran_3dj_02a_2505.pdf.

The changes proposed to clause 119 appear on slides 5-6 of ran_3dj_02a_2505.

SuggestedRemedy

Implement the changes to clause 119 per slides 5-6 of ran_3dj_02a_2505, with editorial license.

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 172 SC 172.6 P242 L35 # 442

Ran, Adeo Cisco Systems

Comment Type TR Comment Status X

The timeout for link_fail_inhibit_timer, minimum 60 seconds, creates an unacceptably long minimum time to retry AN.

A proposal to enable faster restart of AN was presented in https://www.ieee802.org/3/dj/public/25_05/ran_3dj_02a_2505.pdf.

The changes proposed to clause 172 appear on slides 5-6 of ran_3dj_02a_2505.

SuggestedRemedy

Implement the changes to clause 172 per slides 5-6 of ran_3dj_02a_2505, with editorial license.

Proposed Response Response Status

Cl 175 SC 175.7 P280 L30 # 443

Ran, Adeo Cisco Systems

Comment Type TR Comment Status X

The timeout for link_fail_inhibit_timer, minimum 60 seconds, creates an unacceptably long minimum time to retry AN.

A proposal to enable faster restart of AN was presented in https://www.ieee802.org/3/dj/public/25_05/ran_3dj_02a_2505.pdf.

The changes proposed to clause 175 appear on slides 5-6 of ran_3dj_02a_2505.

SuggestedRemedy

Implement the changes to clause 175 per slides 5-6 of ran_3dj_02a_2505, with editorial license.

Proposed Response Response Status

Cl 73 SC 73.10.2 P142 L13 # 444

Ran, Adeo Cisco Systems

Comment Type TR Comment Status X

The timeout for link_fail_inhibit_timer, minimum 60 seconds, creates an unacceptably long minimum time to retry AN.

A proposal to enable faster restart of AN was presented in https://www.ieee802.org/3/dj/public/25_05/ran_3dj_02a_2505.pdf.

The changes proposed to clause 73 appear on slide 7 of ran_3dj_02a_2505.

SuggestedRemedy

Bring in subclause 73.9.1.1 from the base standard and implement the changes to clause 73 per slide 7 of ran_3dj_02a_2505, with editorial license.
(Affected subclauses: 73.9.1.1 and 73.10.2, Table 73-7)

Proposed Response Response Status

Cl 45 SC 45.2.3.2 P117 L43 # 445

Ran, Adeo Cisco Systems

Comment Type TR Comment Status X

The timeout for link_fail_inhibit_timer, minimum 60 seconds, creates an unacceptably long minimum time to retry AN.

A proposal to enable faster restart of AN was presented in https://www.ieee802.org/3/dj/public/25_05/ran_3dj_02a_2505.pdf.

The changes proposed to clause 45 appear on slide 7 of ran_3dj_02a_2505.

SuggestedRemedy

Implement the changes to clause 45 per slide 7 of ran_3dj_02a_2505, with editorial license.

Proposed Response Response Status

CI 179 SC 179.9.4 P394 L13 # 446

Ran, Adee Cisco Systems

Comment Type TR Comment Status X

For CR host output, DC common-mode voltage is specified only as a maximum value (1 V). For all other interfaces, it is specified as a range (0.2 to 1 V). See Table 178-6, Table 176C-2, Table 176D-2, and Table 176D-4.

Having no minimum limit would allow extremely low CM voltage to be driven by the host, which could cause large in-rush current through the cable's AC coupling into the link partner's receiver. This should be avoided.

The specifications for CR hosts should be aligned with those of C2M hosts.

SuggestedRemedy

Change the DC common-mode voltage specification to a range, 0.2 to 1 V.

Proposed Response Response Status O

CI 176D SC 176D.6.4 P745 L47 # 447

Ran, Adee Cisco Systems

Comment Type T Comment Status X

AC coupling in modules using capacitors is becoming a challenge to signal integrity at 200G per lane. At the same time, modules are build using DSPs which use advanced CMOS processes just like the host ASICs.

It is common to have on-die AC coupling in the receiver, which works well assuming the common mode is limited to the same range on both sides. if both sides have this feature, it is possible to avoid external AC coupling in modules (both Tx and Rx), but it is currently an explicit requirement.

We should consider removing this requirement.

This would require:

- Adding DC common mode range specifications for module output and input. These can be consistent with the host's respective specifications..
- Adding DC common mode tolerance specifications for host input and output. These can be consistent with the module's respective specifications.
- Changing text and figures to remove the AC coupling requirements.

SuggestedRemedy

Add common mode range and tolerance specifications and update the text and figures as listed in the comment, with editorial license.

Proposed Response Response Status O

CI 178B SC 178B.14.2.1 P803 L47 # 448

Ran, Adee Cisco Systems

Comment Type T Comment Status X

The second case in the NOTE says: "For ILT in an AUI component above a PMA, the adjacent service interface is the interface below the AUI component". That is the PMA's service interface. It may be easier to understand if it is stated. Also, a figure illustrating the two cases would be helpful.

SuggestedRemedy

Change "the adjacent service interface is the interface below the AUI component" to "the adjacent service interface is the PMA service interface (below the AUI component)". Add a figure, with editorial license.

Proposed Response Response Status O

CI 176 SC 176.7.1.2 P316 L24 # 449

He, Xiang Huawei

Comment Type TR Comment Status X

If ILT is disabled by management, how would precoding request signals get carried over to the transmitter side? I understand this is the language we used to define the precoding config before ILT was introduced. Combining this with 178B, when bring up a link while disabling the ILT, a Rx without precoding may not be able to start the link with a Tx with precoding turned on?

SuggestedRemedy

For PMDs that require to implement precoding on the transmit side, when ILT is disabled, a default mode should be defined to have precoding disabled, either in 176 or 178B.

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 178B SC 178B.6.2 P791 L7 # 450

He, Xiang Huawei

Comment Type TR Comment Status X

The definition of E1 and O1 is unclear.
 "Two formats are defined for the control and status fields, E1 and O1." So E1 and O1 are two "formats" for the control and status fields. (This is the origin of E1 and O1 in the document). After this point in 178B, they were used as "E1 interfaces" and "O1 interfaces" all over the places - like in 178B.7. There are also 5 references using "Type E1 interface" and "Type O1 interface" in PMD clauses, like in 183.5.12.
 We should do a better definition for these terms in Clause 178B, and use clear references in other clauses.

SuggestedRemedy

First change: Clearly define two types of interfaces, "Type E1 interface" and "Type O1 interface", and stick to these terms all across 178B and the document.

Second change: Change the reference from "178B" to the subclause where they were defined, like "178B.6.2".

Proposed Response Response Status O

Cl 186 SC 186.2.4.4 P594 L51 # 451

He, Xiang Huawei

Comment Type TR Comment Status X

A new subclause defining FEC degrade behavior for ER1 and ER1-20 should be added. FEC degrade is intended to warn the degradation before a failure, not until oFEC is unable to correct all errors and caught by CRC32.

SuggestedRemedy

Reuse the methodology in OIF 800ZR IA, 4.7.3 and 4.7.4. Define at least one BER level lower than the FEC threshold as the degrade threshold.

Proposed Response Response Status O

Cl 186 SC 186.2.4.4 P595 L11 # 452

He, Xiang Huawei

Comment Type TR Comment Status X

"counts the number of bit errors detected by CRC32 check" is incorrect. CRC32 can only detect errors.

SuggestedRemedy

Change the degrade detection method to align with OIF 800ZR IA.

Proposed Response Response Status O

Cl 177A SC 177A P765 L1 # 453

He, Xiang Huawei

Comment Type TR Comment Status X

The test vectors have not been updated since scrambler was added to the padding bits. Annex 177A should be updated to reflect the change.

SuggestedRemedy

A presentation with zipped files will be provided.

Proposed Response Response Status O

Cl 175 SC 175.2.4.6 P265 L17 # 454

He, Xiang Huawei

Comment Type TR Comment Status X

The term "free running" is not defined clearly in the standard. One interpretation is that it is "continuously-running" whenever there is a clock (two adjacent pads are not continuous); another interpretation based on the context is that if we extract all the pads and concatenate them you will get a "continuously-running" PRBS9 sequence; and finally there is also an interpretation of the word "free" to be each PRBS9 segment could have its own random seed.

I understand this language was used in previous standards, and the pad is discarded on receive side, but there are testers out there testing these pad and warning bit slips if the don't match how the testers were designed. Explaining this to end users is very difficult especially to the non-English speaking regions. It would be a nice thing to define this clearly or define in a way that showing we really don't care.

SuggestedRemedy

Change "The initial value of the PRBS9 pattern generators may be any pattern other than all zeros." to "The initial value of the PRBS9 pattern generators in each pad may be any pattern other than all zeros."

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 73 SC 73.5.1 P131 L9 # 455
 He, Xiang Huawei
 Comment Type **TR** Comment Status **X**
 Max transmit differential peak-to-peak output voltage for DME should be the same for all rates for compatibility reasons.
 SuggestedRemedy
 Remove case 2.
 Proposed Response Response Status **O**

Cl 116 SC 116.5 P167 L32 # 456
 Slavick, Jeff Broadcom
 Comment Type **ER** Comment Status **X**
 Footnote D is new but not underlined. The new references in the Notes sections are appropriately underlined.
 SuggestedRemedy
 Underline footnote d and its references in Table 116-8
 Proposed Response Response Status **O**

Cl 116 SC 116.5 P167 L32 # 457
 Slavick, Jeff Broadcom
 Comment Type **E** Comment Status **X**
 The laundry list of PMA types that do odd lane skew is more clear if it's a comma separated list instead of using multiple "or" options.
 SuggestedRemedy
 Change "by the 200GBASE-R 1:8 or 8:1 PMA or 400GBASE-R 2:16 or 16:2 PMA if the PHY includes any of these PMA types."
 To: "by the 200GBASE-R 1:8 PMA, 200GBASE-R 8:1 PMA, 400GBASE-R 2:16 PMA and 400GBASE-R 16:2 PMA if the PHY includes any of these PMA types."
 Proposed Response Response Status **O**

Cl 178B SC 178B.4 P786 L52 # 458
 Slavick, Jeff Broadcom
 Comment Type **TR** Comment Status **X**
 The second paragraph of 178B.4 talks about "devices" that have one or two physically instantiated interfaces. The use of "former" and "latter" is referring to one and two? Or PMD and AUI?
 What about devices with no physically instantiated interfaces, it still uses ILT on the medium.
 SuggestedRemedy

Change the 2nd paragraph from:
 Devices in a path may include one or two physically instantiated interfaces, specifically PMD or AUI components. An example of the former is a PMA adjacent to a PCS or to a PHY XS with a single AUI-C2M (Annex 176D) or AUI C2C (Annex 176C) interface (the interface with the PCS or PHY XS is never physically instantiated). An example of the latter is a retimer with an AUI C2C (Annex 176C) interface on one side and an AUI-C2M (Annex 176D) on the other side.
 To:
 Devices in a path may include zero, one or two physically instantiated interfaces between the MAC and the PMD. Figure 176B-1 depicts a device with zero physically instantiated interfaces. The left two stacks in Figure 176B-2 depict a device with a single xAUI interface, either a AUI-C2M (Annex 176D) or AUI-C2C (Annex 176C). The right 3 stacks in Figure 176B-2 depicts a device with two xAUI interfaces.
 Proposed Response Response Status **O**

Cl 178B SC 178B.14.2.1 P804 L32 # 459
 Slavick, Jeff Broadcom
 Comment Type **TR** Comment Status **X**
 Training status can not be both a AUI component variable and a per-lane training variable. Local_rts is an equivalent status to it and is mapped to a MDIO register bit.
 SuggestedRemedy
 Move the definition of training_status to 178B14.3.1
 Remove the enumeration of "READY" from its definition.
 Delete training_status <= READY from Figyre 178B-7
 Proposed Response Response Status **O**

Cl 178B SC 178B.14.3.4 P809 L4 # 460
 Slavick, Jeff Broadcom
 Comment Type TR Comment Status X
 The duration of the quiet_timer breaks the time allotted during AN to begin sending negotiated rate data stream per 73.4.3.
 SuggestedRemedy
 Presentation of options to be supplied.
 Proposed Response Response Status O

Cl 178B SC 178B.11.2 P783 L47 # 461
 Slavick, Jeff Broadcom
 Comment Type TR Comment Status X
 No pointer to the CHECK_REQ function is provided.
 SuggestedRemedy
 Add the following sentence to the last paragraph of 178B.11.2: "The function CHECK_REQ is defined in 178B.14.3.1."
 Proposed Response Response Status O

Cl 176C SC 176C.5.3.1 P706 L35 # 462
 Slavick, Jeff Broadcom
 Comment Type TR Comment Status X
 There is ILT has a Type E1 not type E.
 SuggestedRemedy
 Change Type E to Type E1.
 Proposed Response Response Status O

Cl 176D SC 176D.8.6 P735 L51 # 463
 Slavick, Jeff Broadcom
 Comment Type TR Comment Status X
 There is no reference to the number TAPs the C2M Tx FIR supplies (no reference to 179.4.1). In 179 there are separate sub-clauses for the FIR and ILT but it's combined in the Annexes. Can we align the C2M and C2C description to refer to 179 with exceptions for the reduced ranges and start up conditions.
 SuggestedRemedy

Replace the text of 176D.8.6 with the following:
 The transmit equalizer is identical to that specified in 179.4.1 and utilizes the inter-sublayer link training (ILT) function for Type E1 interface as defined in 179.8.9 with the following exceptions:
 * Table 179D-9 is used instead of Table 179-8 for coefficient initialization values
 * Host output step size and coefficient limits are specified in Table 179D-2
 * Module output step size coefficient limits are specified in Table 179D-3
 Replace the text of 176C.5.3.1 with the following:
 The transmit equalizer is identical to that specified in 179.4.1 and utilizes the inter-sublayer link training (ILT) function for Type E1 interface as defined in 179.8.9 with the following exceptions:
 * Table 179D-9 is used instead of Table 179-8 for coefficient initialization values
 * Output step size and coefficient limits are specified in Table 179C-2
 Proposed Response Response Status O

Cl 179 SC 179.8.9 P379 L13 # 464
 Slavick, Jeff Broadcom
 Comment Type TR Comment Status X
 Move Table 179-8 and here. It's relevant only to the ILT function.
 SuggestedRemedy
 Move Table 179-8 to the end of 179.8.9 and delete 179.9.4.1.3
 Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

CI **178B** SC **178B.5** P**788** L**3** # **465**
Slavick, Jeff Broadcom
Comment Type **TR** Comment Status **X**
The otherwise is not necessary as the heading says you use one or the other.
SuggestedRemedy
Remove the "otherwise".
Proposed Response Response Status **O**

CI **FM** SC **FM** P**13** L**0** # **468**
Slavick, Jeff Broadcom
Comment Type **ER** Comment Status **X**
In the Introduction, the description of 802.3dj does not list out the annexes.
SuggestedRemedy
Change <annexes> to be Annex 174A through 186A
Proposed Response Response Status **O**

CI **178B** SC **178B.5.1** P**788** L**21** # **466**
Slavick, Jeff Broadcom
Comment Type **TR** Comment Status **X**
Having an unspecified time limit for rx_ready assertion (from entry to TRAIN_LOCAL) makes for unpredictable link up behaviors. A time limit from the point at which TRAIN_LOCAL is entered to entry to TRAIN_REMOTE will improve predictability of operation which will facilitate predictable device behaviors.
SuggestedRemedy
Presentation for a solution to be provided.
Proposed Response Response Status **O**

CI **1** SC **1.1.3.2** P**52** L**21** # **469**
Slavick, Jeff Broadcom
Comment Type **E** Comment Status **X**
Do we need to actually list the number of widths? It's a laundry list just introduce it as a list.
SuggestedRemedy
Change "Four widths" to "The following widths" on pg52 line 21 and line 40
Change "Two widths" to "The following widths" on pg53 line 6
Change "four widths" to "the following widths" on pg55 line 31
Change "four widths" to "the following widths" on pg56 line 19
Change "two widths" to "the following widths" on pg57 line 43
Proposed Response Response Status **O**

CI **178B** SC **178B.10** P**799** L**44** # **467**
Slavick, Jeff Broadcom
Comment Type **TR** Comment Status **X**
The fact that polarity_invert persists after training completes should be the last part of this sub-clause.
SuggestedRemedy
Move the 2nd paragraph in 178B.10 to be after the NOTE.
Proposed Response Response Status **O**

CI **30** SC **30.3.2.1.2** P**61** L**16** # **470**
Slavick, Jeff Broadcom
Comment Type **TR** Comment Status **X**
Clause 186 is not a PCS anymore. So it's just a 800GBASE-R PHY now.
SuggestedRemedy
Remove the text associated with 800GBASE-ER1 from 30.3.2.1.2 and 30.3.2.1.3
Proposed Response Response Status **O**

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 69 SC 69.1.2 P128 L50 # 471
 Slavick, Jeff Broadcom
 Comment Type TR Comment Status X
 Changes to 69.1.2 are missing.
 SuggestedRemedy
 Amend Figure 69-5 from 802.3df to add on 1.6T the same stack as 800G.
 Proposed Response Response Status O

Cl 69 SC 69.2.1 P128 L50 # 472
 Slavick, Jeff Broadcom
 Comment Type TR Comment Status X
 Changes to 69.2.1 are missing.
 SuggestedRemedy
 Amend 69.2.1 to add in the Clause 170 RS and 1.6TMII to the list of MIIs. This clause was amended in 802.3.df.
 Proposed Response Response Status O

Cl 69 SC 69.2.3 P128 L50 # 473
 Slavick, Jeff Broadcom
 Comment Type TR Comment Status X
 Changes to 69.2.3 are missing.
 SuggestedRemedy

Need new paragraph talking about the new PHYs. Add this paragraph after the one 11th paragraph that was amended by 802.3df.
 "Backplane Ethernet also specifies 200GBASE-KR1, 400GBASE-KR2, 800GBASE-KR4, and 1.6TBASE-KR8. The 200GBASE-KR1 embodiment employs the PCS defined in Clause 119, the PMA defined in Clause 176, and the PMD defined in Clause 178, and specifies 200 Gb/s operation using 4-level PAM over one differential paths in each direction. The 400GBASE-KR2 embodiment employs the PCS defined in Clause 119, the PMA defined in Clause 176, and the PMD defined in Clause 178, and specifies 400 Gb/s operation using 4-level PAM over two differential paths in each direction. The 800GBASE-KR4 embodiment employs the PCS defined in Clause 172, the PMA defined in Clause 176, and the PMD defined in Clause 178, and specifies 800 Gb/s operation using 4-level PAM over four differential paths in each direction. The 1.6TBASE-KR8 embodiment employs the PCS defined in Clause 175, the PMA defined in Clause 176, and the PMD defined in Clause 178, and specifies 1.6 Tb/s operation using 4-level PAM over eight differential paths in each direction."

Proposed Response Response Status O

Cl 69 SC 69.2.3 P128 L50 # 474
 Slavick, Jeff Broadcom
 Comment Type TR Comment Status X
 Changes to 69.2.3 are missing.
 SuggestedRemedy
 Add reference to Table 174-3 to the last paragraph of 69.2.3 as amended by 802.3df.
 Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

CI 69 SC 69.4 P128 L50 # 475

Slavick, Jeff Broadcom

Comment Type TR Comment Status X

The delay constrain references are missing.

SuggestedRemedy

Add the following 69.3 in the appropriate locations:

For 200GBASE-KR1, normative delay specifications may be found in 117.1.4, 119.5, 176.8, and 178.6, and also referenced in 80.4.

For 400GBASE-KR2, normative delay specifications may be found in 117.1.4, 119.5, 176.8, and 178.6, and also referenced in 80.4.

For 800GBASE-KR4, normative delay specifications may be found in 170.1.4, 172.5, 176.8, and 178.6, and also referenced in 169.4.

For 1.6TBASE-KR4, normative delay specifications may be found in 170.1.4, 175.5, 176.8, and 178.6, and also referenced in 174.4.

Proposed Response Response Status O

CI 69 SC 69.5 P128 L50 # 476

Slavick, Jeff Broadcom

Comment Type TR Comment Status X

Add dj clauses to the list of clauses the PICS cover. It appears we insert only the "FEC" and "PMD" Clauses in this list.

SuggestedRemedy

Insert in the list of Clauses in the first paragraph of 69.5 as amended by 802.3df: "Clause 175, Clause 178,"

Proposed Response Response Status O

CI 73 SC 73.6.2.4 P134 L1 # 477

Slavick, Jeff Broadcom

Comment Type E Comment Status X

The table is showing up on the next page which is fine, but the next section begins first and table inserts itself in the middle of list.

SuggestedRemedy

Can you force the table to occur before the next sub-section?

Proposed Response Response Status O

CI 178 SC 178.9.2.4 P364 L35 # 478

Healey, Adam Broadcom, Inc.

Comment Type T Comment Status X

"The reference value [...] is calculated based on the receiver package class to which the device adheres." Since this subclause is about transmitter difference steady-state voltage, it seems that the calculation should be based on the transmitter package class.

SuggestedRemedy

Change "receiver" to "transmitter".

Proposed Response Response Status O

CI 178 SC 178.10.1 P371 L1 # 479

Healey, Adam Broadcom, Inc.

Comment Type E Comment Status X

"The maximum likelihood sequence detection (MLSD) defined in 178A.1.10 is to be used for the calculation of COM." Now that Table 178-12 includes a parameter that indicate whether or not maximum likelihood sequence detection is included, this statement has become redundant.

SuggestedRemedy

Remove this sentence. Also remove similar sentences in 179.11.7, 176C.7.1, and 176D.7.2.

Proposed Response Response Status O

Cl 178 SC 178.10.1 P370 L50 # 480

Healey, Adam Broadcom, Inc.

Comment Type T Comment Status X

The introductory paragraph states that COM is calculated twice, ones with the Test 1 package transmission line length parameters and once with the Test 2 package transmission line length parameters. However, there are also Class A and Class B package models and this introductory paragraph does not mention this. It would be useful to include reminders/guidance on how Class A and Class B models are to be selected.

SuggestedRemedy

Add text stating that COM is calculated with the parameters for the transmitter and receiver package classes that the channel under test is intended to support. Add similar text in 176C.7.1.

Proposed Response Response Status O

Cl 179 SC 179.9.4.5.3 P400 L30 # 481

Healey, Adam Broadcom, Inc.

Comment Type T Comment Status X

It has been demonstrated that the reference SNDR is a weak function of the test fixture s-parameters. This suggests that the SNDR test can be greatly simplified by specifying a fixed set of reference values that are a function of the preset. The reference values should be derived from the equivalent SNDR produced by the COM transmitter model under similar conditions.

SuggestedRemedy

Replace the dSNDR procedure with a comparison of the measured SNDR to a limit that is a function of the preset. Set the limits to the SNDR^(ref) values on slide 5 of <https://www.ieee802.org/3/dj/public/24_11/healey_3dj_01_2411.pdf> for presets 1 to 5. Set the limit to 31 dB for preset 6. Add a note that the limits are consistent with parameter values in the corresponding COM table. If desired, the subclause defining reference SNDR can be retained as documentation of the procedure used to define the limits.

Proposed Response Response Status O

Cl 176C SC 176C.7 P731 L13 # 482

Healey, Adam Broadcom, Inc.

Comment Type T Comment Status X

There is potential confusion about what channel insertion loss covers. While 176C.3 defines the "channel" to be from TP0d to TP5d, the input to the COM calculation is the portion between TP0 and TP5 and the input to the ERL calculation is a measurement at TP0 or TP5.

SuggestedRemedy

To eliminate the possibility of any confusion, state the channel insertion loss recommendation is for TP0d to TP5d (similar to what is done in Table 178-11).

Proposed Response Response Status O

Cl 179C SC 179C.2.1 P839 L45 # 483

D'Ambrosia, John Futurewei, U.S. Subsidiary of Huawei

Comment Type TR Comment Status X

Editor's Note states the following:
 The reference for SFP224 does not currently include 200G per lane specifications but it's expected to include before publication of this standard.
 It is not clear that the referenced SFP224 specification will include 200G per lane specifications.
 The current state of development in SFF-1031 or SFP-DD is unclear.
 The IEEE P802.3dj standard could not be approved in this state.
 Similar comment for 179C.2.2, 179C.2.3

SuggestedRemedy

Two options are offered, as the state of development in noted organizations is unclear.
 1. If development is underway in noted organizations, modify the note to indicate that if the specification is not received for consideration by the Task Force by Jan 2026, the note will be removed and the MDI will be noted in a non-specific manner.
 2. Remove any references to the SFF specification and make the section generic.

Proposed Response Response Status O

CI 178B SC 178B P786 L6 # 484

D'Ambrosia, John Futurewei, U.S. Subsidiary of Huawei

Comment Type TR Comment Status X

ISL is a major new capability, and needs to be clearer than currently specified. For example, the title indicates "Inter-sublayer link training for electrical and optical interfaces". However, it is the understanding of the commentator that this clause covers link training for the interfaces as well as the total path. Additionally, as this is a new capability, it is not clear that there won't be differences for link training between AUIs and PMDs.

SuggestedRemedy

Separate Annex 178B into 3 Annexes - one for the total path, one for the AUIs, and one for PMDs. Clauses with tables pointing to Annex 178B would need to be updated to point to the correct clause

Proposed Response Response Status O

CI 178B SC 178B.7.1 P796 L26 # 485

Kimber, Mark Semtech

Comment Type TR Comment Status X

Potentially confusing as this only applies to E1 cases but refers to configurations specified in the AUI and PMD clauses. There is a comment in the O1 table stating it should be ignored on receipt. It would be better to also state in this text that it refers only to E1.

SuggestedRemedy

Change
The initial condition request bits are used to select one of the up to six predefined transmitter equalizer configurations (presets) specified in the AUI annexes or PMD clauses.
To
Only applies for E1 interfaces. The initial condition request bits are used to select one of the up to six predefined transmitter equalizer configurations (presets) specified in the AUI annexes or PMD clauses.

Proposed Response Response Status O

CI 178B SC 178B.7.5 P796 L50 # 486

Kimber, Mark Semtech

Comment Type TR Comment Status X

Potentially confusing as this only applies to E1 cases. There is a comment in the O1 table stating it should be ignored on receipt. It would be better to also state in this text that it refers only to E1.

SuggestedRemedy

Change
The coefficient select bits are used to identify the coefficient that is the target of a coefficient request.
To
Only applies for E1 interfaces. The coefficient select bits are used to identify the coefficient that is the target of a coefficient request....

Proposed Response Response Status O

CI 178B SC 178B.7.6 P797 L1 # 487

Kimber, Mark Semtech

Comment Type TR Comment Status X

SuggestedRemedy

Change
The coefficient request bits are used to change the value of the coefficient specified by the coefficient select bits.
To
Only applies to E1 interfaces. The coefficient request bits are used to change the value of the coefficient specified by the coefficient select bits.

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 180 SC 180.7.1 P438 L44 # 488
 Kimber, Mark Semtech
 Comment Type TR Comment Status X
 Over equalizing transmitters can cause BER floor issues as shown in kimber_3dj_01a_2505. Keeping Ceq > 1 (0dB) helps to prevent Tx peaking.
 SuggestedRemedy
 Add additional specification line after TECQ specification.
 Noise Enhancement Factor, Ceq (min) 1
 Proposed Response Response Status O

Cl 183 SC 183.7.1 P512 L37 # 491
 Kimber, Mark Semtech
 Comment Type TR Comment Status X
 Over equalizing transmitters can cause BER floor issues as shown in kimber_3dj_01a_2505. Keeping Ceq > 1 (0dB) helps to prevent Tx peaking.
 SuggestedRemedy
 Add additional specification line after TECQ specification.
 Noise Enhancement Factor, Ceq (min) 1
 Proposed Response Response Status O

Cl 181 SC 181.7.1 P462 L26 # 489
 Kimber, Mark Semtech
 Comment Type TR Comment Status X
 Over equalizing transmitters can cause BER floor issues as shown in kimber_3dj_01a_2505. Keeping Ceq > 1 (0dB) helps to prevent Tx peaking.
 SuggestedRemedy
 Add additional specification line after TECQ specification.
 Noise Enhancement Factor, Ceq (min) 1
 Proposed Response Response Status O

Cl 176D SC 176D.6.3 P745 L21 # 492
 Dudek, Mike Marvell
 Comment Type TR Comment Status X
 The differential-mode to common mode input return loss module specification in combination with the common-mode to differential-mode return loss specification for the host output are inadequate, allowing for an interfering signal that is only 16dB below the wanted signal at frequencies above 35GHz. (The specifications are probably adequate for the original purpose in CR because there is a minimum loss of 16dB at Nyquist between these points). These specifications are also weaker than the specifications for 100G chip to module in 802.3ck
 SuggestedRemedy
 Replace the references to equations 179-20 in tables 176D-2 and 176D-3 and equation 179-27 in tables 176D-4 and 176D-5 with references to new equations. The equations should be 25-22(f/106.25) from 0.05 to 53.12 GHz and 19-10(f/106.25) from 53.12 to 67 GHz which are the same equations as used for 100G C2M scaled in frequency. In addition to this change in order to measure this the common-mode to differential-mode return loss for the mated compliance boards need to be improved. Change equation 179B-8 and Figure 179B-5 to 30-26(f/106.25) from 0.05 to 53.12 GHz and 22-10(f/106.25) from 53.12 to 67 GHz
 Proposed Response Response Status O

Cl 182 SC 182.7.1 P487 L9 # 490
 Kimber, Mark Semtech
 Comment Type TR Comment Status X
 Over equalizing transmitters can cause BER floor issues as shown in kimber_3dj_01a_2505. Keeping Ceq > 1 (0dB) helps to prevent Tx peaking.
 SuggestedRemedy
 Add additional specification line after TECQ specification.
 Noise Enhancement Factor, Ceq (min) 1
 Proposed Response Response Status O

SuggestedRemedy
 Replace the references to equations 179-20 in tables 176D-2 and 176D-3 and equation 179-27 in tables 176D-4 and 176D-5 with references to new equations. The equations should be 25-22(f/106.25) from 0.05 to 53.12 GHz and 19-10(f/106.25) from 53.12 to 67 GHz which are the same equations as used for 100G C2M scaled in frequency. In addition to this change in order to measure this the common-mode to differential-mode return loss for the mated compliance boards need to be improved. Change equation 179B-8 and Figure 179B-5 to 30-26(f/106.25) from 0.05 to 53.12 GHz and 22-10(f/106.25) from 53.12 to 67 GHz
 Proposed Response Response Status O

CI 176C SC 176C.6.3 P723 L46 # 493

Dudek, Mike Marvell

Comment Type TR Comment Status X

The common-mode to differential-mode output return loss specifications is missing for C2C

SuggestedRemedy

Add this specification to Table 176C-2 using the same values as in equation 176C-1. As this link does not have a minimum loss consider as an alternative using the values proposed in a separate comment for C2M for both this new specification and the differential-mode to common-mode input return loss specification in equation 176C-1

Proposed Response Response Status O

CI 178 SC 178.9.2 P362 L24 # 494

Dudek, Mike Marvell

Comment Type TR Comment Status X

There is no specification for common-mode to differential-mode output return loss for KR, which would allow 100% of the common mode return energy from the channel and the far end receiver to be reflected as interfering differential mode energy which would severely degrade performance.

SuggestedRemedy

Add this specification to Table 178-6 using the same values as in equation 178-4. (Note that there is no minimum loss for the channel so common-mode reflections from the far end receiver as well as from the channel can create the interference).

Proposed Response Response Status O

CI 178 SC 178.9.2 P362 L36 # 495

Dudek, Mike Marvell

Comment Type TR Comment Status X

The signal-to-residual-intersymbol-interference ratio is an additional effective transmitter noise source which is not included in the COM analysis beyond what is created with the reference package.

SuggestedRemedy

Change the specification to a difference signal-to-residual-intersymbol-interference with a value of 0 dB where the reference is the value of signal-to-residual-intersymbol-interference for the package claimed. Make the same change for C2C, C2M and CR where the reference is the COM module appropriate to the specification. (Or better complete the calculations and put in the value that matches).

Proposed Response Response Status O

CI 178 SC 178.9.3.5 P369 L4 # 496

Dudek, Mike Marvell

Comment Type TR Comment Status X

Not stressing the jitter tolerance signal with noise in addition to the jitter under-stresses receivers.

SuggestedRemedy

Delete the exception "No broadband noise is added". Change the following exception from "The test channel COM, calculated per the method in 178.9.3.4.2, is at least 3 dB." to "The test channel COM with the jitter included, calculated per the method in 178.9.3.4.2, is 3 dB." Make the similar change for C2C on page 730.

Proposed Response Response Status O

CI 179 SC 179.9.5.4.2 P410 L3 # 497

Dudek, Mike Marvell

Comment Type TR Comment Status X

Not stressing the jitter tolerance signal with noise in addition to the jitter under-stresses receivers.

SuggestedRemedy

Change "The jitter tolerance test procedure is similar to that of 179.9.5.3, with the exception that no noise is injected (i.e., step g in 179.9.5.3.3 is not performed). Instead, jitter with the specified frequency and amplitude is applied to the pattern generator and the jitter amplitude is adjusted to obtain the peak-to-peak jitter specified for that frequency in Table 179-12 at the Tx test reference (see Figure 110-3a). The test channel COM, calculated per 179.9.5.3.3 with the jitter-stressed transmitter output, shall not be lower than the value in Table 179-11."

to "The jitter tolerance test procedure is similar to that of 179.9.5.3, with the exception that jitter with the specified frequency and amplitude is applied to the pattern generator and the jitter amplitude is adjusted to obtain the peak-to-peak jitter specified for that frequency in Table 179-12 at the Tx test reference (see Figure 110-3a). The test channel COM, calculated per 179.9.5.3.3 with the jitter-stressed transmitter output and the broadband noise added, shall be equal to the value in Table 179-11."

Make the equivalent change for C2M in section 176D.8.13.2 on page 759

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 178B SC 178B.2 P786 L19 # 498
 Dudek, Mike Marvell
 Comment Type E Comment Status X
 The english isn't good.
 SuggestedRemedy
 Change "in a ISL or multi-ISL paths" to "in a ISL path or multi-ISL paths"
 Proposed Response Response Status O

Cl 178B SC 178B.14.3 P806 L1 # 499
 Dudek, Mike Marvell
 Comment Type E Comment Status X
 The Path ready descriptions apply to both E1 and O1 interfaces. It would read better if these paragraphs were placed before the paragraph that describes the different behaviour.
 SuggestedRemedy
 Move the first paragraph to after the 3rd paragraph.
 Proposed Response Response Status O

Cl 178B SC 178B.14.3.1 P807 L44 # 500
 Dudek, Mike Marvell
 Comment Type E Comment Status X
 "Correspondent" is strange. "Corresponding" is better, as used in the base document in multiple places e.g. 73.7.6 first paragraph
 SuggestedRemedy
 Change "correspondent" to "corresponding" here and on line 48.
 Proposed Response Response Status O

Cl 179 SC 179.9.5.3.3 P407 L11 # 501
 Dudek, Mike Marvell
 Comment Type T Comment Status X
 The host channel as defined in 179A.4 includes the package and connector. Listing the host channel and package separately could lead to double counting. Partial host channel model is what this is called in Table 179-16.
 SuggestedRemedy
 Change "using the receiver host channel, package, and device termination models" to "using the receiver partial host channel, package, and device termination models. Also in C2M on page 757 line 34.
 Proposed Response Response Status O

Cl 179A SC 179A.4 P818 L40 # 502
 Dudek, Mike Marvell
 Comment Type T Comment Status X
 It is not helpful saying that the assumed mated connector insertion loss is 2.45dB. Host vendors can trade connector losses for cable/pcb/package losses.
 SuggestedRemedy
 Delete the last sentence. "The recommended maximum differential insertion loss (TP0d-to-TP2) or (TP3-to-TP5d) are consistent with the host channels and an assumed mated connector insertion loss of 2.45 dB." If this is not done then change "are" to "is" as loss is singular.
 Proposed Response Response Status O

Cl 176C SC 176C.7 P731 L17 # 503
 Dudek, Mike Marvell
 Comment Type TR Comment Status X
 There is no specification for differential-mode to common-mode conversion for the C2C channel, which would allow a very large amount of common mode to be input to the Rx.
 SuggestedRemedy
 Add a specification to the channel specification for differential-mode to common-mode conversion with the same equation as used for KR (equation 178-6) or as used for CR cable (equation 179-28)
 Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

CI 176C SC 176C.6.3 P723 L39 # 504

Dudek, Mike Marvell

Comment Type T Comment Status X

The max value of Low Frequency AC common mode noise is 30mV for KR but 32mV for C2C with a tighter Block Error ratio requirement. There isn't a reasonable justification for this difference.

SuggestedRemedy

Change the C2C value to 30mV in table 176C-2.

Proposed Response Response Status O

CI 176D SC 176D.6.6 P747 L36 # 505

Dudek, Mike Marvell

Comment Type TR Comment Status X

The input specifications are best measured at the input to the compliance board as is specified in 176D.6.1 page 744 line 23 and as is done for the host in section 176D.6.5 not at TP1a. (Note however that 176D.8.10 specifically calls out AC common mode voltage tolerance at TP1a).

SuggestedRemedy

Change from "specifications at TP1a" to "Specifications at TP1"

Proposed Response Response Status O

CI 176D SC 176D.6.3 P745 L16 # 506

Dudek, Mike Marvell

Comment Type TR Comment Status X

The module AC common-mode input tolerance is 80mV max full band and 32mV for the low frequency. The allowed host output AC common-mode full band is however 85mV max (and 30mV max for the low frequency). The host output value should not be higher than the module input tolerance full band, and there isn't a reason why the module should tolerate more than the host outputs at low frequency.

SuggestedRemedy

Change the full band AC common-mode output voltage for the host from 85mV to 80mV. Consider also changing the low frequency from 30mV to 32mV to match the module tolerance.

Proposed Response Response Status O

CI 176D SC 176D.6.5 P747 L13 # 507

Dudek, Mike Marvell

Comment Type T Comment Status X

The Host AC common-mode input tolerance is 80mV max full band . The allowed module output AC common-mode full band is however only 60mV max . There isn't a reason why the host should tolerate more than the module outputs.

SuggestedRemedy

Change the host AC common-mode input tolerance full band from 80mV to 60mV

Proposed Response Response Status O

CI 180 SC 180.9.5 P448 L23 # 508

Dudek, Mike Marvell

Comment Type TR Comment Status X

It is shown in https://grouper.ieee.org/groups/802/3/dj/public/25_05/chayeb_3dj_01_2505.pdf (at 100G) that despite a passing TDECQ value, with non optimum Tx settings that require the reference receiver to have a large difference in value between the 1st precursor tap and the 1st postcursor tap, a receiver has excessive BER and post-FEC errors. It is not expected that well tuned transmitters will have this large difference in the reference equalizer tap values.

SuggestedRemedy

Add an extra requirement to table 180.15 that $Abs(C(-1)-C(+1)) < 0.3$. Also to tables 181-13, 182-15 and 183-14

Proposed Response Response Status O

CI 179A SC 179A.5 P819 L8 # 509

Dudek, Mike Marvell

Comment Type T Comment Status X

Figure 179A-3 does not show the maximum insertion loss of the cable assembly assembly and maximum insertion loss of the cable. There is no illustration of this as there are multiple combinations possible and the maximum values of all the items listed is not simultaneously allowed.

SuggestedRemedy

Change "and is illustrated in Figure 179A-3" to "and is illustrated for the HN to HN channel in Figure 179A-2"

Proposed Response Response Status O

CI 179A SC 179A.7 P822 L13 # 510
 Dudek, Mike Marvell
 Comment Type T Comment Status X
 Figure 179A-3 does not show that Device package models are included in the TP0d and TP5d channels and there are no such things as TP0d and TP5d channels which are test point.
 SuggestedRemedy
 Either delete the sentence "Device package models are included in the TP0d and TP5d channel (Figure 179A-3);" or replace it with "Device package models are included in the TP0d to TP5d channel (Figure 179-2)."
 Proposed Response Response Status O

CI 179B SC 179B.2 P823 L29 # 511
 Dudek, Mike Marvell
 Comment Type T Comment Status X
 The TP2 and TP3 test points are not well illustrated in Figure 179-2 as it does not really show
 SuggestedRemedy
 Add "and figure 179A-1" after Figure 179-2
 Proposed Response Response Status O

CI 179B SC 179B.2.1 P823 L34 # 512
 Dudek, Mike Marvell
 Comment Type TR Comment Status X
 The point at which the loss is defined needs to be better defined not left ambiguous.
 SuggestedRemedy
 Insert the sentence "The printed circuit board insertion loss is defined as the loss between the reference plane of the RF test connector and the end of the gold fingers on the HCB" between the 1st and 2nd sentences. An alternative (less desirable in my opinion) sentence would be "The printed circuit board insertion loss is defined as the loss between the reference plane of the RF test connector and the nominal contact location on the gold finger".
 Proposed Response Response Status O

CI 179B SC 179B.2.1 P823 L34 # 513
 Dudek, Mike Marvell
 Comment Type TR Comment Status X
 The loss needs to be better defined to be less ambiguous.
 SuggestedRemedy
 Insert the sentence "The cable assembly tested fixture loss is equal to the loss of the mated test fixture minus the loss of the specific TP2 or TP3 test fixture printed circuit board loss used when measuring the mated text fixture loss." between the 1st and 2nd sentences.
 Proposed Response Response Status O

CI 179B SC 179B.1 P823 L22 # 514
 Dudek, Mike Marvell
 Comment Type TR Comment Status X
 The reference impedances for measuring the test fixtures is not listed except for the ERL (where it is 92.5 Ohm differential)
 SuggestedRemedy
 Add the sentence (or a reference impedance subsection) stating "The reference impedance for differential specifications is 92.5 ohms and the reference impedance for common-mode specifications is 25 Ohms unless specified otherwise. Consider using 92.5 Ohm instead of 100 Ohm for the differential measurements
 Proposed Response Response Status O

CI 179B SC 179B.4.2 P826 L34 # 515
 Dudek, Mike Marvell
 Comment Type T Comment Status X
 It has been stated that making test fixtures that are 92.5 Ohm differential impedance throughout their length is not feasible and sections of the fixtures near the RF connectors need to be 100 Ohm which degrades this ERL measurement resulting in a need for a more relaxed specification. However it is important that the mating interface to the DUT is close to the 92.5 Ohm value.
 SuggestedRemedy
 Consider adding an additional Mated test fixture ERL specification with a tighter value but with the length of the reflection signal reduced and the Time gated propagation delay set to a non-zero value. It may be necessary to have different settings for the different directions of the measurement.
 Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 179B SC 179B.4.3 P826 L44 # 516

Dudek, Mike Marvell

Comment Type TR Comment Status X

There isn't a specification for the differential-mode to common mode insertion loss but theoretically it will be similar to the common mode to differential insertion loss. The specification in section 179B.4.3 is very weak and an MCB that only just passes this specification would cause a module to fail the 60mV full band AC common-mode specification in Table 176D-3 even if the module itself has no AC common mode output noise.

SuggestedRemedy

Change Equation 179B-6 (and figure 179B-3) to $30 \cdot (21/28) \cdot f$ from 0.01 to 40GHz and 15 from 40GHz to 67GHz which is the scaled equation from clause 162B.4.3

Proposed Response Response Status O

Cl 179B SC 179B.4.6 P829 L26 # 517

Dudek, Mike Marvell

Comment Type E Comment Status X

Incomplete sentence (no verb)

SuggestedRemedy

Change "voltage determined" to "voltage is determined"

Proposed Response Response Status O

Cl 179B SC 179B.4.6 P830 L14 # 518

Dudek, Mike Marvell

Comment Type E Comment Status X

missing letter

SuggestedRemedy

change "th" to "the"

Proposed Response Response Status O

Cl 179C SC 179C.1 P834 L4 # 519

Dudek, Mike Marvell

Comment Type T Comment Status X

For inter-operability the PMDs on both ends and the cable pins have to match.

SuggestedRemedy

Change "should be used" to "shall be used"

Proposed Response Response Status O

Cl 180A SC 180A P850 L9 # 520

Dudek, Mike Marvell

Comment Type E Comment Status X

The title of the Annex seems over broad as there are many optical PHYs that it is not relevant to (compare the title of Annex 179C where all the relevant PHYs are listed)

SuggestedRemedy

Change "optical PHYs" to "Clause 180 and Clause 181 optical PHYs"

Proposed Response Response Status O

Cl 180 SC 180.6 P437 L35 # 521

Dudek, Mike Marvell

Comment Type T Comment Status X

The positioning and ordering of the lanes at the MDI is not specified in 180.9.

SuggestedRemedy

Change the reference from 180.9 to 180A.4

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 181 SC 181.8.3 P468 L45 # 522

Dudek, Mike Marvell

Comment Type E Comment Status X

It would be good to provide a reference to Annex 180A in this section.

SuggestedRemedy

Add a paragraph similar to that in the equivalent section of clause 180. "Annex 180A specifies the details of the MDIs for 200GBASE-DR1-2, 400GBASE-DR2, 800GBASE-DR4-2, and 1.6TBASE-DR8-2."

Proposed Response Response Status O

Cl 180A SC 180A.4.1 P852 L17 # 523

Dudek, Mike Marvell

Comment Type T Comment Status X

For inter-operability the PMDs on both ends and the fiber cable plant have to match.

SuggestedRemedy

Change "should be used" to "shall be used". Also on page 853 line 47

Proposed Response Response Status O

Cl 181 SC 181.8.3 P468 L46 # 524

Dudek, Mike Marvell

Comment Type E Comment Status X

Lines 47 to 54 on page 444 in clause 180 provide details of the MDI that also apply to the clause 181 MDI's. Specifying which connectors should be used.

SuggestedRemedy

Either add this information in clause 181.8.3 or move that information into Annex 180A.3

Proposed Response Response Status O

Cl 185A SC 185A.2.5.2 P866 L7 # 525

Dudek, Mike Marvell

Comment Type E Comment Status X

Unnecessary duplication of "waveforms"

SuggestedRemedy

Delete "as waveforms"

Proposed Response Response Status O

Cl 179 SC 179.9.4.2 P398 L30 # 526

Dudek, Mike Marvell

Comment Type T Comment Status X

The method used to determine transmitter linearity (reference to 120D.3.1.2) uses the measured waveform. It is unlikely to work with all the different initial conditions, or with high loss hosts, due to the amount of ISI that is likely to be present.

SuggestedRemedy

Add after 120D.3.1.2 "except that the fitted waveform as defined in 120D.3.1.3 is used in place of the measured waveform"

Proposed Response Response Status O

Cl 179 SC 179.9.4.6 P401 L36 # 527

Dudek, Mike Marvell

Comment Type E Comment Status X

Poor wording. Obviously the transmitter output of the lane under test shouldn't be disabled but it would be better to be more precise.

SuggestedRemedy

Change "transmitter output is" to transmitter outputs of the lanes not under test are"

Proposed Response Response Status O

Cl 174 SC 174.1.4 P248 L32 # 528
 Dudek, Mike Marvell
 Comment Type T Comment Status X
 Clause 73 auto-negotiation is missing from the electrical Phys in table 174-3. (Compare table 169-2 and tables 116-3 and 116-3a.
 SuggestedRemedy
 Add it.
 Proposed Response Response Status O

Cl 179 SC 179.11.2 P412 L29 # 529
 Dudek, Mike Marvell
 Comment Type T Comment Status X
 For CA-A the maximum loss is 19dB with a minimum loss of 16dB allowing only a 3dB range for guardbanding for measurement accuracy and manufacturing tolerance.
 SuggestedRemedy
 Consider changing the cable minimum loss (for all cable types) to 15dB with a consequent reduction in the Test 1 test channel insertion losses and Cable assembly insertion losses in Table 179-11 from 15.5 Min and 16.5 max to 14.5 min and 15.5 max. Also modifying Table 179A-3 replacing 16 with 15 for ILddCA,min and 13 with 12 for ILddch,min. and Figure 179A-3 (including the footnotes from 13dB to 12dB for the minimum channel loss from TP0d to TP5d and 15 instead of 16 in the first equation footnote and 3.1 instead of 4.1 in the second equation footnote.
 Proposed Response Response Status O

Cl 180 SC 180.9.1 P445 L31 # 530
 Dudek, Mike Marvell
 Comment Type TR Comment Status X
 PRBS31Q with pre-coding should be listed as a possible test pattern. Also it would be better to reference the description of the 200G per lane PRBS31Q test pattern in 176.7.4.2 rather than the older reference in
 SuggestedRemedy
 Add PRBS31Q with precoding as an additional test pattern (8) in table 180-13. In table 180-14 add this pattern as an option wherever patter 3 is used. The reference for the test pattern definition should be 176.7.4.2. Change the test pattern generator generator for PRBS31Q from 120.5.11.2.2 to 176.7.4.2. Make equivalent changes to Clause 181.
 Proposed Response Response Status O

Cl 180 SC 180.9.12 P450 L38 # 531
 Dudek, Mike Marvell
 Comment Type TR Comment Status X
 Whether the precoding is used for Receiver sensitivity and stressed receiver sensitivity should be explicitly stated.
 SuggestedRemedy
 On line 38 inset the sentence . "A precoded pattern shall be used if the receiver requests precoding during ILT." between ". Table 180-14" and "The" Also after Table 180-14 on line 2 of page 451. Make equivalent changes to Clause 181.
 Proposed Response Response Status O

Cl 176C SC 176C.6.4.5.3 P729 L48 # 532
 Dudek, Mike Marvell
 Comment Type TR Comment Status X
 The C2C receiver should be able to determine whether pre-coding is used.
 SuggestedRemedy
 Change "test transmitter equalizer using the ILT function" to "test transmitter equalizer and precoder using the ILT function" Also for KR on page 368 line 22
 Proposed Response Response Status O

Cl 176D SC 176D.8.12.4 P758 L35 # 533
 Dudek, Mike Marvell
 Comment Type TR Comment Status X
 The C2M receiver should be able to determine whether pre-coding is used.
 SuggestedRemedy
 Change "PRBS31Q pattern" to "PRBS31Q pattern with the precoder enabled or disabled as the receiver would select using the ILT protocol"
 Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

CI 179 SC 179.9.5.3 P406 L26 # 534

Dudek, Mike Marvell

Comment Type TR Comment Status X

It should be explicit that the test pattern for Interference tolerance for CR can be precoded.

SuggestedRemedy

Add a footnote to PRBS31Q in table 179-11. Footnote to say "With precoding enabled or disabled as the receiver would select using the start-up protocol described in 179.8.9."

Proposed Response Response Status O

CI 176C SC 176C.6.4.2 P727 L9 # 535

Dudek, Mike Marvell

Comment Type TR Comment Status X

There isn't a minimum loss specified for the C2C channel. Inserting the the minimum channel loss from the KR interference tolerance test isn't appropriate.

SuggestedRemedy

Consider whether using the same minimum loss used for the interference tolerance test is appropriate. If so add to 176C.7.2. The recommended minimum channel insertion loss is 13dB.

On page 727 line 9 replace "using a channel with the minimum insertion loss specified in 178.9.3.4" with "using an amplitude tolerance test channel" Add a sentence to the end of the paragraph. The loss of the amplitude tolerance test channel including the package loss of the compliant transmitter used in the test is equal to the Test 1 loss in table 176C-5

If not then replace "using a channel with the minimum insertion loss specified in 178.9.3.4" with "using a minimal loss channel"

Proposed Response Response Status O

CI 176C SC 176C.7 P731 L13 # 536

Dudek, Mike Marvell

Comment Type T Comment Status X

It isn't clear what the channel includes. (including where the lldd is measured from).

SuggestedRemedy

Change the description in table to "Maximum insertion loss from Tp0d to Tp5d, lLdd, at 53.125 GHz (recommended)" (as used for KR).

Proposed Response Response Status O

CI 178 SC 178.9.3.3 P366 L9 # 537

Dudek, Mike Marvell

Comment Type T Comment Status X

There isn't a minimum loss specified for the KR channel. Specifying this as the minimum channel loss from the KR interference tolerance test may not be appropriate. It is also not very clear what loss is being referred to.

SuggestedRemedy

Consider whether using the same minimum loss used for the interference tolerance test is appropriate. If so add to 178.10.2. "The recommended minimum channel insertion loss is 18dB."

On page 727 line 9 replace "using a channel with the minimum insertion loss specified in 178.9.3.4" with "using an amplitude tolerance test channel" Add a sentence to the end of the paragraph. The loss of the amplitude tolerance test channel including the package loss of the compliant transmitter used in the test is equal to the Test 1 loss in table 178-10

If not then replace "using a channel with the minimum insertion loss specified in 178.9.3.4" with "using a minimal loss channel"

Proposed Response Response Status O

CI 73 SC 73.4.3 P130 L27 # 538

Levin, Itamar Altera corp.

Comment Type TR Comment Status X

20msec are allocated for the signals at the MDI to conform to all of the PHY specifications when the PHY is connected to the MDI through the "Transmit Switch function". The clause is not clear about the event that starts this time period.

SuggestedRemedy

State in line 27 "When a PHY is connected to the MDI through the Transmit Switch function, the signals at the MDI shall conform to all of the PHY specifications within 20 ms of the AN-GOOD_CHECK state entry.

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 120F SC 120F.1 P662 L1 # 539

Levin, Itamar Altera corp.

Comment Type TR Comment Status X

In light of the approved channel reach for C2C it may not be sufficient to content with optional TXEQ. There are different TX tuning mechanisms in C2C and C2M and also in the functional specifications (see 176C.3) which may cause confusion.

SuggestedRemedy

Align this sub-clause with annex 176C.3 functional specification

Proposed Response Response Status O

Cl 176C SC 176C.7.1 P734 L9 # 540

Levin, Itamar Altera corp.

Comment Type T Comment Status X

The table says the highest allowed tap index is 56 while footnote (b) says the latest post-cursor position for a floating tap is 50. Given that the number of floating taps per group is 4, there is a discrepancy between the comment and highest allowed tap index

SuggestedRemedy

either fix the comment and highest index to be 54 or add clarifying text in the comment explaining the apparent discrepancy.

Proposed Response Response Status O

Cl 176D SC 176D.8.6 P753 L36 # 541

Levin, Itamar Altera corp.

Comment Type TR Comment Status X

There is no preset that has a different than 0 precursor c(1). Also - the initialize and preset 6 are exactly the same.

SuggestedRemedy

Consider a preset with c(1) <> 0. this may help with CDR locking on some channels. Also consider to remove preset 6 or add a comment in this clause explaining why it was added

Proposed Response Response Status O

Cl 176D SC 176D.8.7 P754 L36 # 542

Levin, Itamar Altera corp.

Comment Type T Comment Status X

no reference / example test-fixture like in the previous annex 163B, that meets the requirements for TP0

SuggestedRemedy

can we add an example test-fixture annex for 200G similar to 163B with the COM values to serve as a reference for dVf, dSNR, etc'?

Proposed Response Response Status O

Cl 178 SC 178.10.6 P375 L50 # 543

Levin, Itamar Altera corp.

Comment Type TR Comment Status X

100Khz 3dB cutoff frequency requires AC blocking capacitors of at least XXX nF. This poses two issues: 1. it is hard to find a high quality capacitor that would behave well across the entire channel frequency band (low parasitics), 2. for on package or on die placement of the decoupling cap - the parasitics involved with such a capacitor degrade serdes performance

This corner frequency trades off these factors for better baseline wander mitigation, however - the impact on baseline wander from a 2x or even 3x corner frequency would not be severe and may be a good sacrifice for the benefits of a smaller cap.

SuggestedRemedy

increase corner freq. to at least 250Khz.

Proposed Response Response Status O

Cl 179B SC 179B.4.6 P830 L14 # 544

Schreiner, Stephan Rosenberger Hochfrequenztechnik GmbH & Co. KG

Comment Type E Comment Status X

missing "e" at the end of "the"

SuggestedRemedy

change "th" to "the"

Proposed Response Response Status O

Cl 1 SC 1.5 P58 L28 # 545
 Schreiner, Stephan Rosenberger Hochfrequenztechnik GmbH & Co. KG
 Comment Type T Comment Status X
 RLdc and RLcd are mentioned in the abbreviations. However ILdc and ILcd are not mentioned. TCL / LCL and TCTL / LCTL would be also a typical name for the conversion parameters
 SuggestedRemedy
 Add ILdc and ILcd into the abbreviations or change "RLdc, RLcd, ILdc, and ILcd" into "TCL, LCL, TCTL, and LCTL" within the document
 Proposed Response Response Status O

Cl 169 SC 169.2.10 P190 L52 # 546
 Maki, Jeffery Juniper Networks
 Comment Type TR Comment Status X
 800GBASE-LR1, 800GBASE-ER1-20, and 800GBASE-ER1 are missing in the list. There is no reason to exclude coherent PHY types from using ILT. They will benefit from optical receiver adaption and thus ability to receive Ready To Send signaling for the bring up of the entire link (PHY) as is the case for IMDD PHY types.
 SuggestedRemedy
 Add 800GBASE-LR1, 800GBASE-ER1-20, and 800GBASE-ER1 (See additional comments that correct missing mandatory ILT support for these PHY types.)
 Proposed Response Response Status O

Cl 185 SC 185.1 P556 L40 # 547
 Maki, Jeffery Juniper Networks
 Comment Type TR Comment Status X
 Associated clause 178B—ILT is missing as Required for 800GBASE-LR1.
 SuggestedRemedy
 Add Associated clause 178B—ILT as Required for 800GBASE-LR1.
 Proposed Response Response Status O

Cl 185 SC 185.5 P560 L27 # 548
 Maki, Jeffery Juniper Networks
 Comment Type TR Comment Status X
 "Inter-sublayer link training (ILT) function" is missing in "185.5 PMD functional specifications."
 SuggestedRemedy
 Add to "185.5 PMD functional specifications" a sub-subclause with appropriate numbering entitled "Inter-sublayer link training (ILT) function" with text "A PMD shall provide the ILT function for a Type O1 interface, specified in Annex 178B. When the variable mr_training_enable is true, the ILT function is used to request changes to the peer transmitter state (modulation, training pattern, and precoder state), indicate the receiver state, and coordinate the transition to DATA mode."
 Proposed Response Response Status O

Cl 185 SC 185.5.1 P561 L7 # 549
 Maki, Jeffery Juniper Networks
 Comment Type TR Comment Status X
 SIGNAL_OK --> ILT and ILT --> SIGNAL_OK missing from Figure 185-3.
 SuggestedRemedy
 Add SIGNAL_OK --> ILT and ILT --> SIGNAL_OK to Figure 185-3. Add text in paragraph above stating, "The ILT function indicated in Figure 185–3 is defined in Annex 178B."
 Proposed Response Response Status O

Cl 187 SC 187.1 P630 L39 # 550
 Maki, Jeffery Juniper Networks
 Comment Type TR Comment Status X
 Associated clause 178B—ILT is missing as Required for 800GBASE-ER1-20 and 800GBASE-ER1.
 SuggestedRemedy
 Add Associated clause 178B—ILT as Required for 800GBASE-ER1-20 and 800GBASE-ER1.
 Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 187 SC 187.5 P634 L27 # 551

Maki, Jeffery Juniper Networks

Comment Type TR Comment Status X

"Inter-sublayer link training (ILT) function" is missing in "187.5 PMD functional specifications."

SuggestedRemedy

Add to "187.5 PMD functional specifications" a sub-subclause with appropriate numbering entitled "Inter-sublayer link training (ILT) function" with text "A PMD shall provide the ILT function for a Type O1 interface, specified in Annex 178B. When the variable mr_training_enable is true, the ILT function is used to request changes to the peer transmitter state (modulation, training pattern, and precoder state), indicate the receiver state, and coordinate the transition to DATA mode."

Proposed Response Response Status O

Cl 187 SC 187.5.1 P635 L7 # 552

Maki, Jeffery Juniper Networks

Comment Type TR Comment Status X

SIGNAL_OK --> ILT and ILT --> SIGNAL_OK missing from Figure 187-3.

SuggestedRemedy

Add SIGNAL_OK --> ILT and ILT --> SIGNAL_OK to Figure 187-3. Add text in paragraph above stating, "The ILT function indicated in Figure 187-3 is defined in Annex 178B."

Proposed Response Response Status O

Cl 178B SC 178B.2 P786 L20 # 553

Maki, Jeffery Juniper Networks

Comment Type TR Comment Status X

The description "ILT supports these functions through the continuous exchange of fixed-length training frames between peer interfaces in an ISL" indicates training frames are continuously exchanged. The presumed purpose to be continuous would be for the AUI components to update their equalization coefficients yet there is no description of returning to training such as with recovered clock while continuing to carry real traffic nor is there status indicators that updated training is occurring.

SuggestedRemedy

Add to "Table 178B-2—Control field structure for E1 interfaces" indicator that updated training is occurring using traffic and recovered clock.

Proposed Response Response Status O

Cl 45 SC 45.2.1.168c P96 L46 # 554

Nicholl, Shawn AMD

Comment Type ER Comment Status X

In the first row of Table 45-133c the Bit(s) column contains 1.1476.15:9 text.

SuggestedRemedy

Propose 1.1477.15:9 in the first row of Table 45-133c in the Bit(s) column.

Proposed Response Response Status O

Cl 45 SC 45.2.1.168d P97 L13 # 555

Nicholl, Shawn AMD

Comment Type ER Comment Status X

Currently, in the 1.1478.13 row, the Description column contains some incorrect text that is carried over from another table.

1 = PCS lane synchronization is complete. This bit indicates that all_locked_mux is true and deskewed
0 = local_rx_ready or remote_rx_ready is false on any lane of the interface

SuggestedRemedy

Propose the following text:

1 = PCS lane synchronization is complete. This bit indicates that all_locked_mux is true and deskew is complete.
0 = PCS lane synchronization is not complete.

Proposed Response Response Status O

Cl 45 SC 45.2.1.216 P101 L33 # 556

Nicholl, Shawn AMD

Comment Type E Comment Status X

Missing a space in Table 45-180, row 1.2200.4 description column.

Current text: "1 =IFEC decoder"

SuggestedRemedy

Proposed text: "1 = IFEC decoder"

Proposed Response Response Status O

Cl 45 SC 45.2.1.216 P101 L24 # 557

Nicholl, Shawn

AMD

Comment Type ER Comment Status X

Missing a note that this Table 45-180 was amended in 802.3ck-2022.

Missing a new section after the table that describes the new field that is added to the table in P802.3dj.

Suggested Remedy

Proposed text: "Change Table 45-180 (as amended by IEEE Std 802.3ck-2022) as follows:"

Also propose to add new section:

Insert 45.2.1.216aa before 45.2.1.216.a as follows:

45.2.1.216.aa IFEC degraded SER enable (1.2200.4)

Bit 1.2200.4 enables the IFEC decoder to indicate the presence of a degraded SER when the ability is supported. When set to a one, this variable enables degraded SER detection. When set to a zero, degraded SER detection is disabled. Writes to this bit are ignored and reads return a zero if the IFEC does not have the ability to signal the presence of a degraded SER.

Proposed Response

Response Status

Cl 45 SC 45.2.1.217.6a P103 L3 # 558

Nicholl, Shawn

AMD

Comment Type TR Comment Status X

802.3-2022 Clause 152 defines the Inverse RS-FEC sublayer for 100GBASE-R, 100GBASE-P, and 100GBASE-Z PHYs. Sub-Clause "152.6 Inverse RS-FEC MDIO function mapping" contains many references to IFEC. "Table 152-2 -- MDIO/Inverse RS-FEC status variable mapping" contains references to 1.2201 register.

P802.3dj Sub-Clause "186.7 Management variables" also contains references to IFEC. "Table 186-8 -- 800GBASE-ER1 FEC status variables and MDIO mapping" contains references to 1.2201 register.

Since there are (at least) two IFEC receivers (i.e. one that is described in Clause 152 and one that is describe in Clause 186), it would help the reader to enhance the description found in "45.2.1.217.6a IFEC received local degraded (1.2201.5)" to clarify that this field pertains only to the Clause 186 IFEC. Same comment for "45.2.1.217.6b IFEC received remote degraded (1.2201.4)".

Suggested Remedy

Proposed text (for 45.2.1.217.6a): "Bit 1.2201.5 is set to one when the 800GBASE-ER1 IFEC receiver detects the value ... consecutive 800GBASE-ER1 FEC frames. Bit 1.2201.5 is set to zero ..."

Note that in the above text, besides adding "800GBASE-ER1", it is also necessary to correct the typo 1.2201.4 (current text) to 1.2201.5 (proposed text).

Proposed text (for 45.2.1.217.6b): "Bit 1.2201.4 is set to one when the 800GBASE-ER1 IFEC receiver detects the value ... consecutive 800GBASE-ER1 FEC frames. Bit 1.2201.4 is set to zero ..."

Proposed Response

Response Status

Cl 45 SC 45.2.1.222 P104 L8 # 559

Nicholl, Shawn

AMD

Comment Type ER Comment Status X

With the inclusion of lanes up to lane 31, the legacy text no longer reads smoothly in the P802.3dj draft.

Current text: "FEC lane 1, lower 16 bits are shown in register 1.2212; FEC lane 1, upper 16 bits are shown in register 1.2213; FEC lane 2, lower 16 bits are shown in register 1.2214; through register 1.2217 for FEC lane 3, upper 16 bits; and so on."

SuggestedRemedy

Current text: "FEC lane 1, lower 16 bits are shown in register 1.2212; FEC lane 1, upper 16 bits are shown in register 1.2213; FEC lane 2, lower 16 bits are shown in register 1.2214; FEC lane 2, upper 16 bits are shown in register 1.2215; etc."

Proposed Response Response Status O

Cl 45 SC 45.2.1.258 P109 L22 # 560

Nicholl, Shawn

AMD

Comment Type ER Comment Status X

Sub-Clause "177.5.5 Inner FEC decode" defines Inner_FEC_corrected_cw_counter, Inner_FEC_uncorrected_cw_counter, Inner_FEC_total_bits_counter, and Inner_FEC_corrected_bits_counter. "Table 177-8 -- Inner FEC status variables and MDIO mapping" also uses these terms.

Currently, the description column of "Table 45-212h -- Inner FEC corrected codewords counter bit definitions" contains FEC_corrected_cw_counter. And the Name column contains "FEC corrected codewords". It is inconsistent with Sub-Clause 177 as it is missing the word "Inner" in both columns.

The same issue exists in "Table 45-212j -- Inner FEC uncorrected codewords counter bit definitions", "Table 45-212j -- Inner FEC total bits register bit definitions", and "Table 45-212k -- Inner FEC corrected bits register bit definitions".

SuggestedRemedy

Propose updating the description column of "Table 45-212h -- Inner FEC corrected codewords counter bit definitions" to Inner_FEC_corrected_cw_counter and the Name column to "Inner FEC corrected codewords".

Propose similar updates in "Table 45-212i -- Inner FEC uncorrected codewords counter bit definitions", "Table 45-212j -- Inner FEC total bits register bit definitions", and "Table 45-212k -- Inner FEC corrected bits register bit definitions".

Proposed Response Response Status O

Cl 45 SC 45.2.1.262 P111 L12 # 561

Nicholl, Shawn

AMD

Comment Type T Comment Status X

Several previous sublayers contains FEC_corrected_cw_counter, FEC_uncorrected_cw_counter, FEC_cw_counter, FEC_codeword_error_bin_i (1 <= i <= 15).

802.3df-2024 172.3.5 FEC_cw_counter defines a 48-bit counter that counts once for each FEC codeword received ... is mapped to registers defined in 45.2.3.48a (3.300 to 3.302).

802.3df-2024 172.3.6 FEC_codeword_error_bin_i defines FEC_codeword_error_bin_i, where i=1 to 15, ... mapped to registers defined in 45.2.3.48b (3.340 to 3.369).

802.3ck-2022 161.6.21 FEC_cw_counter defines a 48-bit counter that counts once for each FEC codeword received ... is mapped to the registers defined in 45.2.1.120a (1.207 to 1.209).

802.3ck-2022 161.6.17 FEC_codeword_error_bin_i defines FEC_codeword_error_bin_i, where i=1 to 15, ... mapped to the registers defined in 45.2.1.131a (1.340 to 1.369).

P802.3dj draft contains "Table 45-212l -- Inner FEC codeword error bin register definitions" which includes inner_FEC_codeword_error_bin_0 (i.e. codewords with no bit errors). At the same time, there is no FEC_cw_counter that count once for each Inner FEC codeword received.

It would be better to be consistent with the definition of FEC statistics found in other 802.3 Clauses

SuggestedRemedy

Propose adding a new 48-bit register FEC_cw_counter that counts once for each Inner FEC codeword received.

Propose deleting the inner_FEC_codeword_error_bin_0 register, since it becomes redundant if FEC_cw_counter is defined.

Proposed Response Response Status O

IEEE P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 45 SC 45.2.1.262 P111 L12 # 562

Nicholl, Shawn

AMD

Comment Type ER Comment Status X

Currently, the description column of "Table 45-212I -- Inner FEC codeword error bin register definitions" contains inner_FEC_codeword_error_bin_0 through inner_FEC_codeword_error_bin_4, while "Table 177-8 -- Inner FEC status variables and MDIO mapping" contains Inner_FEC_codeword_error_bin_k. In other words, the first letter is capitalized in one case, but not in the other case.

SuggestedRemedy

Propose updating the description column of "Table 45-212I -- Inner FEC codeword error bin register definitions" to contain Inner_FEC_codeword_error_bin_0 through Inner_FEC_codeword_error_bin_4 to enhance searchability of the document.

Proposed Response Response Status O

Cl 169 SC 169.3.2 P191 L17 # 563

Nicholl, Shawn

AMD

Comment Type TR Comment Status X

Current text: "... between the Inner FEC or Segmented FEC, and the PMA, PCS ..."

This is the first (and only) mention of "Segmented FEC" in P802.3dj document.

SuggestedRemedy

Proposed text: "... between the Inner FEC or 800GBASE-ER1 FEC and the PMA, PCS ..."

Proposed Response Response Status O

Cl 169 SC 169.3.2 P193 L38 # 564

Nicholl, Shawn

AMD

Comment Type T Comment Status X

There is no figure showing 800GBASE-R inter-sublayer service interfaces including 800GBASE-ER1 FEC.

SuggestedRemedy

After "Figure 169-2a-800GBASE-R inter-sublayer service interfaces including 800GBASE-R Inner FEC" add a new figure "800GBASE-R inter-sublayer service interfaces including 800GBASE-ER1 FEC".

Proposed Response Response Status O

Cl 169 SC 169.5 P199 L1 # 565

Nicholl, Shawn

AMD

Comment Type ER Comment Status X

Text above "Figure 169-5 -- 800GBASE-R Skew points for a PHY with two 800GAUI-n" contains a typo.

Current text: "Replace Figure 169-4 with the following figure:"

SuggestedRemedy

Proposed text: "Replace Figure 169-5 with the following figure:"

Proposed Response Response Status O

Cl 171 SC 171.1 P211 L24 # 566

Nicholl, Shawn

AMD

Comment Type E Comment Status X

In the legend for Figure 171-1 -- "800GXS and 1.6TXS relationship to the ISO/IEC Open System Interconnection (OSI) reference model and the IEEE 802.3 Ethernet model" several lines are wrapping onto a second line. It decreases readability.

Currently "1.6TAUI-n = 1.6 Tb/s n-LANE ATTACHMENT UNIT INTERFACE" is wrapping. Currently "800GAUI-n = 800 Gb/s n-LANE ATTACHMENT UNIT INTERFACE" is wrapping.

SuggestedRemedy

Propose the following text:

Option1) Propose modifying the legend to move the second column (i.e. DTE, MAC, MDI, etc.) further to the right. That should allow space to avoid the text wrap. See "Figure 171-3a -- Example 1.6TBASE-R PMA layering with 1.6TXS" for an example of this solution.

Option2) Propose using the term AUI in the legend of the figure. The term AUI is already defined in Sub-Clause 1.4.198 "Attachment Unit Interface (AUI)" of 802.3-2022. In other words, for Figure 171-1, propose the legend say "1.6TAUI-n = 1.6 Tb/s n-LANE AUI" and "800GAUI-n = 800 Gb/s n-LANE ATTACHMENT UNIT INTERFACE". Optionally (if deemed necessary by the editors), add a new entry (above DTE) "AUI = ATTACHMENT UNIT INTERFACE" to the legend.

Proposed Response Response Status O

Cl 176 SC 176.8 P318 L7 # 567
 Nicholl, Shawn AMD
 Comment Type **TR** Comment Status **X**
 The entries in "Table 176-7 -- Delay constraints" also pertain to 200GBASE-R, 400GBASE-R, and 1.6TBASE-R. They don't just pertain to 800GBASE-R.
 Current text: "... the definitions for bit times and pause_quanta can be found in 169.4."
SuggestedRemedy
 Proposed text: "... the definitions for bit times and pause_quanta can be found in 116.4, 169.4, and 174.4"
 Proposed Response Response Status **O**

Cl 177 SC 177.5.5 P338 L31 # 568
 Nicholl, Shawn AMD
 Comment Type **E** Comment Status **X**
 Current text: "The decoder is expected to correct all codewords with one bit error. It may also be able to correct ..."
 The current sentence, although containing no language that indicates a mandatory requirement, might be interpreted by readers as a requirement.
 It is preferred to clarify the language as improved soft-decision decoder performance (gain) may be obtained by an implementation that is not bound by a rule to correct all codewords with one bit error
SuggestedRemedy
 Referring to 802.3-2022 Sub-Clause "1.1.6 Word usage", perhaps the word "should" provides sufficient clarity.
 Proposed text: "The decoder should correct all codewords with one bit error. It may also be able to correct ..."
 Proposed Response Response Status **O**

Cl 177 SC 177.5.5 P339 L6 # 569
 Nicholl, Shawn AMD
 Comment Type **TR** Comment Status **X**
 Current text: "... when fas_lock is true (k = 0 to 3). For example, if an Inner FEC codeword has exactly two bits corrected, then Inner_FEC_codeword_error_bin_2 is incremented. Error bin 3 increments when three or more bits are corrected in an Inner FEC codeword."
 The text in Sub-Clause "177.5.5 Inner FEC decode" is inconsistent with "Table 45-212I -- Inner FEC codeword error bin register definitions". The MDIO register contains bin_0 through bin_4.
SuggestedRemedy
 Proposed text: "... when fas_lock is true (k = 0 to 4). For example, if an Inner FEC codeword has exactly two bits corrected, then Inner_FEC_codeword_error_bin_2 is incremented. Error bin 4 increments when four or more bits are corrected in an Inner FEC codeword."
 Proposed Response Response Status **O**

Cl 177 SC 177.10 P346 L47 # 570
 Nicholl, Shawn AMD
 Comment Type **TR** Comment Status **X**
 Some values are missing in the "MDIO register/bin number" column of the "Inner_FEC_codeword_error_bin_k (Inner FEC lane 0)" row of "Table 177-8-Inner FEC status variables and MDIO mapping".
 Same issue is observed for rows "Inner_FEC_codeword_error_bin_k (Inner FEC lane 1)" through "Inner_FEC_codeword_error_bin_k (Inner FEC lane 7)".
SuggestedRemedy
 In the "MDIO register/bin number" column of the "Inner_FEC_codeword_error_bin_k (Inner FEC lane 0)" row of "Table 177-8-Inner FEC status variables and MDIO mapping" add 1.2332 and 1.2333.
 In each of rows "Inner_FEC_codeword_error_bin_k (Inner FEC lane 1)" through "Inner_FEC_codeword_error_bin_k (Inner FEC lane 7)" also add the MDIO registers that correspond to bin_4.
 Proposed Response Response Status **O**

Cl 177 SC 177.10 P346 L47 # 571

Nicholl, Shawn

AMD

Comment Type E Comment Status X

In the "Status variable" column of the "Inner_FEC_codeword_error_bin_k (Inner FEC lane 0)" row of "Table 177-8 -- Inner FEC status variables and MDIO mapping", it is not obvious what is meant by 'k'.

Same issue is observed for rows "Inner_FEC_codeword_error_bin_k (Inner FEC lane 1)" through "Inner_FEC_codeword_error_bin_k (Inner FEC lane 7)".

SuggestedRemedy

Propose that in the "Status variable" column of the "Inner_FEC_codeword_error_bin_k (Inner FEC lane 0)" row of "Table 177-8-Inner FEC status variables and MDIO mapping" add text "(k = 0 to 4)".

Propose that in each of rows "Inner_FEC_codeword_error_bin_k (Inner FEC lane 1)" through "Inner_FEC_codeword_error_bin_k (Inner FEC lane 7)" also add the text "(k = 0 to 4)".

Proposed Response Response Status O

Cl 184 SC 184.10 P551 L47 # 572

Nicholl, Shawn

AMD

Comment Type E Comment Status X

In the "MDIO register/bit number" column of the Inner_FEC_codeword_error_bin_0 row of "Table 184-5 -- Inner FEC status variables and MDIO mapping", the MDIO bit indices are unnecessarily mentioned.

There are only 16 bits in an MDIO register, thus "15:0" is implied and does not need to be mentioned. Also, other rows (eg. test_block_error_bin_0_16p) of the same table don't include the "15:0". Also, Table 177-8 excludes the "15:0" for the exact same MDIO registers.

SuggestedRemedy

Propose "MDIO register/bit number" column of the Inner_FEC_codeword_error_bin_0 row of "Table 184-5 -- Inner FEC status variables and MDIO mapping", contain "1.2424," and "1.2425" on two lines.

Same comment for Inner_FEC_codeword_error_bin_1 through Inner_FEC_codeword_error_bin_4.

Proposed Response Response Status O

Cl 120F SC 120F.1 P663 L38 # 573

Nicholl, Shawn

AMD

Comment Type E Comment Status X

The legend for "Figure 120F-1 -- Example 100GAUI-1, 200GAUI-2, 400GAUI-4, 800GAUI-8, and 1.6TAUI-16 C2C relationship to the ISO/IEC Open System Interconnection (OSI) reference model and the IEEE 802.3 Ethernet model" is quite noisy (cluttered).

Readability could be enhanced with a more concise approach.

SuggestedRemedy

In the left-hand column of the legend, propose replacing "ATTACHMENT UNIT INTERFACE" with "AUI", replacing "MEDIA INDEPENDENT INTERFACE" with "MII", and replacing "PHYSICAL MEDIUM ATTACHMENT" with "PMA".

In the right-hand column of the legend propose adding "AUI = ATTACHMENT UNIT INTERFACE", adding "MII = MEDIA INDEPENDENT INTERFACE", adding "PMA = PHYSICAL MEDIUM ATTACHMENT".

There are other Figures throughout P802.3dj (especially in the Annexes) whose legend could be improved in a similar manner.

Proposed Response Response Status O

Cl 174A SC 174A.8.1.3 P681 L19 # 574

Nicholl, Shawn

AMD

Comment Type **TR** Comment Status **X**

Current text: "... defined as follows:

- Hm (i)(k) where k < 16 is the probability of k test symbol errors in a test block for lane i.
- Hm (i)(16) is the probability of more than 15 test symbol errors in a test block for lane i."

SuggestedRemedy

Propose deleting the duplicate text ("is the is the") and align the text with 174A.8.1.2 and 174A.8.1.4 Sub-Clauses.

Propose the following text:

Option1 (most preferred by commenter): Introduce the term "ratio".

Proposed text: "... defined as follows:

- Hm (i)(k) where k < 16 is the ratio (to total number of test blocks analyzed) of k test symbol errors in a test block for lane i.
- Hm (i)(16) is the ratio (to total number of test blocks analyzed) of 16 or more test symbol errors in a test block for lane i."

Option2 (less preferred by commenter): Retain the term "probability".

Proposed text: "... defined as follows:

- Hm (i)(k) where k < 16 is the probability of k test symbol errors in a test block for lane i.
- Hm (i)(16) is the probability of 16 or more test symbol errors in a test block for lane i."

Proposed Response Response Status

Cl 174A SC 174A.8.1.4 P681 L50 # 575

Nicholl, Shawn

AMD

Comment Type **TR** Comment Status **X**

Current text: "... are 17-bin error histograms representing a count of the number of test blocks with k test symbol errors for k < 16 and a count of the number of test blocks with 16 or more test symbol errors for k = 16."

Reading this text, it sounds like these histograms are simply error counts, while an earlier section defined them as a ratio between error counts and total count.

SuggestedRemedy

Propose the following text:

Option1 (most preferred by commenter): Introduce the term "ratio".

Proposed text: "... are 17-bin error histograms representing the ratio (to total number of test blocks analyzed) of test blocks with k test symbol errors for k < 16 and the ratio (to total number of test blocks analyzed) of test blocks with 16 or more test symbol errors for k = 16.

Option2 (less preferred by commenter): Retain the term "probability".

Proposed text is: "... are 17-bin error histograms representing the probability of k test symbol errors in a test block for k < 16 and the probability of 16 or more test symbol errors in a test block for k = 16.

Proposed Response Response Status

Cl 174A SC 174A.8.1.5 P682 L17 # 576

Nicholl, Shawn

AMD

Comment Type **ER** Comment Status **X**

Current text: "For each lane i, measure the error histogram Hm(k) (see 174A.8.1.3) and assign Hm(k) to Hm (i)(k)." However, 174A.8.1.3 does not define Hm(k) -- rather it defines Hm(i)(k).

SuggestedRemedy

Propose to make the text more concise.

Proposed text: "For each lane i, measure the error histogram Hm(i)(k) (see 174A.8.1.3)."

Proposed Response Response Status

Cl 174A SC 174A.8.1.6 P682 L37 # 577
 Nicholl, Shawn AMD
 Comment Type ER Comment Status X
 Current text: "For each lane i, measure the error histogram Hm(k) (see 174A.8.1.3) and assign Hm(k) to Hm(i)(k)." However, 174A.8.1.3 does not define Hm(k) -- rather it defines Hm(i)(k).
 SuggestedRemedy
 Propose to make the text more concise.
 Proposed text: "For each lane i, measure the error histogram Hm(i)(k) (see 174A.8.1.3)."
 Proposed Response Response Status O

Cl 1 SC 1.4.92i P54 L46 # 580
 Nicholl, Shawn AMD
 Comment Type ER Comment Status X
 Current text: "... using the physical coding sublayer defined in Clause 175 for 1.6 Tb/s operation. (See IEEE Std 802.3, Clause 174.)"
 Propose pointing to the correct Clause number.
 SuggestedRemedy
 Proposed text: "... using the physical coding sublayer defined in Clause 175 for 1.6 Tb/s operation. (See IEEE Std 802.3, Clause 175.)"
 Proposed Response Response Status O

Cl 174A SC 174A.8.1.7 P683 L2 # 578
 Nicholl, Shawn AMD
 Comment Type ER Comment Status X
 Current text: "a) For each lane i, measure the error histogram Hm(k) (see 174A.8.1.3)."
 However, 174A.8.1.3 does not define Hm(k) -- rather it defines Hm(i)(k).
 Current text: "d) ... hconv(He(k) , Hm(k)) (see ...)"
 SuggestedRemedy
 Propose to make the text more concise.
 Proposed text: "a) For each lane i, measure the error histogram Hm(i)(k) (see 174A.8.1.3)."
 Proposed text: "d) ... hconv(He(k) , Hm(i)(k)) (see ...)"
 Proposed Response Response Status O

Cl 1 SC 1.4.92g P54 L40 # 581
 Nicholl, Shawn AMD
 Comment Type ER Comment Status X
 Currently, the definitions of 1.6TBASE-DR8-2, 200GBASE-DR1-2, 400GBASE-DR2-2, 800GBASE-DR4-2 incorrectly point to Clause 181. They should point to Clause 182.
 SuggestedRemedy
 1.4.92g 1.6TBASE-DR8-2: IEEE 802.3 Physical Layer ... least 2 km. (See IEEE Std 802.3, Clause 182.)
 1.4.104a 200GBASE-DR1-2: IEEE 802.3 Physical Layer ... least 2 km. (See IEEE Std 802.3, Clause 182.)
 1.4.134c 400GBASE-DR2-2: IEEE 802.3 Physical Layer ... least 2 km. (See IEEE Std 802.3, Clause 182.)
 1.4.184ca 800GBASE-DR4-2: IEEE 802.3 Physical Layer ... least 2 km. (See IEEE Std 802.3, Clause 182.)
 Proposed Response Response Status O

Cl 174A SC 174A.9 P683 L18 # 579
 Nicholl, Shawn AMD
 Comment Type ER Comment Status X
 In the "174A.9 Error ratio tests for 800GBASE-LR1 ISLs", the text current says "... between a pair of 200GBASE-LR1 Inner FEC sublayers ...".
 SuggestedRemedy
 Propose to replace with "... between a pair of 800GBASE-LR1 Inner FEC sublayers ...".
 Proposed Response Response Status O

Cl 45 SC 45.2.1.60c.1 P82 L21 # 582

Nicholl, Shawn

AMD

Comment Type ER Comment Status X

Currently, 45.2.1.60c.1 contains the information for 1.74.0 register while 45.2.1.60c.2 contains the information for 1.74.1 register.

The MDIO register definitions sections are typically ordered from bit <n> to bit 0.

SuggestedRemedy

Propose the following text:

45.2.1.60c.1 should contain the information for 1.74.1 register. 45.2.1.60c.2 should contain the information for 1.74.0 register.

In other words, it should read as follows:

45.2.1.60c.1 800GBASE-ER1 ability (1.74.1)

When read as a one, bit 1.74.1 indicates ... as a 800GBASE-ER1 PMA/PMD type. When read as a zero, bit 1.74.1 indicates ... as a 800GBASE-ER1 PMA/PMD type.

45.2.1.60c.2 800GBASE-ER1-20 ability (1.74.0)

When read as a one, bit 1.74.0 indicates ... as a 800GBASE-ER1-20 PMA/PMD type. When read as a zero, bit 1.74.0 ... as a 800GBASE-ER1-20 PMA/PMD type.

Proposed Response Response Status O

Cl 177 SC 177.1.1.3 P326 L6 # 583

Nowell, Mark

Cisco

Comment Type E Comment Status X

Unlike Clause 184.1.3 which summarizes the functions of that clauses inner FEC, Clause 177.1.3 doesn't include the basic detail that it is a BCH(128,120) encoding/decoding.

For readability and consistency these two subclauses should provide similar information to the reader.

SuggestedRemedy

In clause 177.1.3, include the description that that the inner FEC encoding for Clause 177 is BCH(128,120)

Proposed Response Response Status O

Cl 119 SC 119.2.4.1 P174 L32 # 584

Nicholl, Gary

Cisco Systems

Comment Type T Comment Status X

Since the new stateless encoder is optional and fully backwards compatible / interoperable with the legacy state-diagram encoder there is no need to restrict it's use to the new PHY types being defined in 802.3dj. The stateless encoder should be allowed to be used for all 200GBASE-R and 400GBASE-R PHY types.

Same comment for the stateless decoder in 119.2.5.8.

SuggestedRemedy

Update the description in 119.2.4.1 and 119.2.5.8 to allow the stateless encoder and stateless decoder , respectively, to be used for all 200GBASE-R and 400GBASE-R PHY types.

Proposed Response Response Status O

Cl 174A SC 174A.6 P678 L28 # 585

Nicholl, Gary Cisco Systems

Comment Type TR Comment Status X

FLR allocation for 800GBASE-ER1/ER1-20.

During the March plenary the consensus was to adopt option# 2 of https://www.ieee802.org/3/dj/public/25_03/brown_3dj_04a_2503.pdf, for the FLR allocation for 800GBASE-ER1/ER1-20.

Also, see the final response to comment #16 in https://www.ieee802.org/3/dj/comments/D1p4/8023dj_D1p4_comments_final_clause.pdf.

An implication of this decision is that 800GBASE-ER1/ER1-20 PHYs are different from other 802.3dj PHYs, in that you are only allowed to have AUIs in the PHY or Extender, but not both (see slide 18 of brown_3dj_04a_2503). For other 802.3dj PHYs you are allowed to have AUIs in both the PHY and the Extender.

This means it is possible to have a host design that contains two AUIs (one in an Extender and one in the PHY) that would not support an 800GBASE-ER1/ER1-20 PHY, but would support all other 802.3dj PHYs.

I don't think that an 800GBASE-ER1/ER1-20 PHY should be treated as a special case.

I propose changing the FLR allocation for the 800GBASE-ER1/ER1-20 PHY to be consistent with all other 802.3dj PHYs, such that there are no restriction on which hosts an 800GBASE-ER1/ER1-20 PHY can be deployed in.

This is essentially option #3 in brown_3dj_04a_2503, where the FLR of a 800GBASE-ER1/ER1-20 PHY, with or without an AUI, is defined as 6 x 10⁻¹¹ (consistent with all other 802.3dj PHYs). This in turn means reducing the FLR for the ER1-to-ER1 FEC link from 6 x 10⁻¹¹ to 5.8 x 10⁻¹¹.

SuggestedRemedy

Change the FLR allocation for 800GBASE-ER1/ER1-20 to implement option #3 in https://www.ieee802.org/3/dj/public/25_03/brown_3dj_04a_2503.pdf.

Make the necessary changes in clauses 187 and 174A.

A supporting presentation will be provided.

Proposed Response Response Status

Cl 174A SC 174A.8.1.2 P681 L3 # 586

Shrikhande, Kapil Marvell

Comment Type T Comment Status X

Stating "5 consecutive PAM4 symbols" is clear, but then the sentence goes on to say "or, equivalently, 10 consecutive bits" which could be confusing since 10 consecutive bits could come from 6 PAM4 symbols. I believe we want it to be 5 consecutive PAM4 symbols.

SuggestedRemedy

Change the sentence to be "Test symbols are defined as non-overlapping groups of 5 consecutive PAM4 symbols", period. I.e. remove the last part "or, equivalently, 10 consecutive bits".

Proposed Response Response Status

Cl 178B SC 178B.5.1 P788 L21 # 587

Shrikhande, Kapil Marvell

Comment Type T Comment Status X

"rx_ready" is not defined before this term is used. rx_ready is used on lines 21 and 23. Presumably rx_ready is receiver ready, which is defined later in clause in 178B.8.1 ?

SuggestedRemedy

Define rx_ready and / or clarify that this variable is same as receiver ready defined in 178B.8.1

Proposed Response Response Status

Cl 175 SC 175.1.3 P261 L5 # 588

Shrikhande, Kapil Marvell

Comment Type T Comment Status X

Will be better to state that transcoding is from four 66b blocks to 257 bit blocks. This follows the previous bullet which states that encoding is from eight 1.6TMI data octets to 66-bit blocks.

SuggestedRemedy

Change the second bullet to "Transcoding from (to) four 66-bit blocks to (from) 257-bit blocks (256B/257B)".

Proposed Response Response Status

IE P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 175 SC 175.5 P280 L4 # 589

Shrikhande, Kapil

Marvell

Comment Type T Comment Status X

The 1.6TbE PCS and XS delay constraint value chosen in 802.3dj (400ns) is half of that specified for 800GE (800ns). There isn't a strong justification for cutting the delay constraint in half for 1.6TbE (compared to 800GE) : both 1.6TE and 800GE use the same FEC, and functional blocks within the PCS are the same. While there is a small reduction in FEC codeword accumulation latency since 1.6TbE uses 4x400G FEC while 800GE uses 4x200G FEC, this reduction is only ~ 12.5ns. Additionally, the delay constraint for 800GE PCS is the same as 400GE and 200GE PCS (~800ns). To enable a broad base of designs, across end-hosts as well as modules, recommend changing the 1.6TbE PCS/XS delay constraint value to match 800GE/400GE/200GE.

SuggestedRemedy

Change the delay constraint for 1.6TbE PCS (and XS) to be the same as 800GE (800ns or 2500 pause quanta).

Proposed Response Response Status O

Cl 174A SC 174A.3 P677 L35 # 590

Shrikhande, Kapil

Marvell

Comment Type T Comment Status X

In the subclause title "Error ratio allocation for an Ethernet network path", the term "network path" is a bit vague. Network path may mean a multi-hop network path (e.g. End Host to Switch to End host). Should search for a more descriptive term to use instead of "network path". Since the error allocation is from the PLS service interface of one RS to the PLS service interface of the other RS, suggest using "RS-to-RS" ? or MAC-to-MAC ? This is similar to PHY-to-PHY, PCS-to-FEC, etc. terminology used in other sections of this annex.

SuggestedRemedy

Replace "network path" in the subclause title with "RS-to-RS".

Proposed Response Response Status O

Cl 174A SC 174A.5 P678 L17 # 591

Shrikhande, Kapil

Marvell

Comment Type E Comment Status X

Cross reference to 174A.6 is missing.

SuggestedRemedy

Add cross reference

Proposed Response Response Status O

Cl 180 SC 180.7.1 P438 L40 # 592

He, Michael

TeraHop

Comment Type T Comment Status X

Tx OMAouter (min) equals $-1.2 + \max(\text{TECQ}, \text{TDECQ})$ for $0.9 \text{ dB} < \max(\text{TECQ}, \text{TDECQ}) < 3.4 \text{ dB}$. It means that Tx OMAouter shall increase to compensate TECQ/TDECQ induced penalty. However, the testing data show 1dB TECQ/TDECQ degradation will only cause <1dB Rx sensitivity penalty, which means the TECQ/TDECQ penalty is overestimated.

SuggestedRemedy

The TDECQ test methodology needs to be optimized to make it more closely to reflect the real TECQ/TDECQ induced penalty. The expected 1dB TECQ/TDECQ degradation vs it's induced penalty would be at least 0.75dB or above. Some new approaches, e.g. adding 1-tap DFE for the ref. equalizer, or narrowing histogram spacing of the eye diagram (referring to rodes_3dj_01_2411) may help. May submit one contribution with collected data to support feasibility.

Proposed Response Response Status O

Cl 180 SC 180.7.2 P440 L33 # 593

He, Michael

TeraHop

Comment Type T Comment Status X

The footnote for receiver sensitivity show that it shall be measured with conformance test signal at TP3 (see 180.8) for the block error ratio specified in 180.2. However, accurately measuring with block error ratio method may need too long time. We need to find a proper way to shorten the testing time to make it acceptable either for compliance or for mass production.

SuggestedRemedy

Is it possible to just accumulate a limited codewords for FEC-bin and prediction via extrapolating the FEC-bin curve. Will submit a contribution to discuss the feasibility.

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 179A SC 179A.5 P819 L38 # 594
 Kocsis, Sam Amphenol
 Comment Type TR Comment Status X
 The MTF illustration in Figure 179A-1 allocates an informative reference of the MCB that is hard to validate.
 SuggestedRemedy
 Move the allocation marker to cover TP1-MCB Via, and align the allocation with the equations in 179B.3
 Proposed Response Response Status O

Cl 179 SC 179.9.4.7 P403 L2 # 597
 Kocsis, Sam Amphenol
 Comment Type TR Comment Status X
 The ERL of a transmitter at TP2 is defined without a reference impedance. The implied reference impedance is inferred from 179.9.3, 100-ohm. The use of a 100-ohm reference impedance for ERL is not consistent throughout D2P0.
 SuggestedRemedy
 Add definition of a 92.5-ohm reference impedance for the ERL computation, consistent with Annex179B.
 Proposed Response Response Status O

Cl 178 SC 178.9.2.1.2 P363 L24 # 595
 Kocsis, Sam Amphenol
 Comment Type TR Comment Status X
 The ERL for a test fixture at TP0v is defined without a reference impedance. The implied reference impedance is inferred from 178.9.1, 100-ohm. The use of a 100-ohm reference impedance for ERL is not consistent throughout D2P0.
 SuggestedRemedy
 Add definition of a 92.5-ohm reference impedance for the ERL computation, consistent with Annex179B.
 Proposed Response Response Status O

Cl 179 SC 179.9.5.5 P410 L29 # 598
 Kocsis, Sam Amphenol
 Comment Type TR Comment Status X
 The ERL of a receiver at TP3 is defined without a reference impedance. The implied reference impedance is inferred from 179.9.3, 100-ohm. The use of a 100-ohm reference impedance for ERL is not consistent throughout D2P0.
 SuggestedRemedy
 Add definition of a 92.5-ohm reference impedance for the ERL computation, consistent with Annex179B.
 Proposed Response Response Status O

Cl 178 SC 178.10.3 P373 L33 # 596
 Kocsis, Sam Amphenol
 Comment Type TR Comment Status X
 The ERL for a channel at TP0 and TP5 is defined without a reference impedance. The implied reference impedance is inferred from 178.9.1, 100-ohm. The use of a 100-ohm reference impedance for ERL is not consistent throughout D2P0.
 SuggestedRemedy
 Add definition of a 92.5-ohm reference impedance for the ERL computation, consistent with Annex179B.
 Proposed Response Response Status O

Cl 179 SC 179.11.3 P413 L6 # 599
 Kocsis, Sam Amphenol
 Comment Type TR Comment Status X
 The ERL of a cable assembly at TP1 and TP4 is defined without a reference impedance. The implied reference impedance is inferred from 179.11.1, 100-ohm. The use of a 100-ohm reference impedance for ERL is not consistent throughout D2P0.
 SuggestedRemedy
 Add definition of a 92.5-ohm reference impedance for the ERL computation, consistent with Annex179B.
 Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 179B SC 179B.2.1 P823 L34 # 600
 Kocsis, Sam Amphenol
 Comment Type TR Comment Status X
 Text says "TP2 or TP3 test fixture printed circuit board board (PCB) insertion loss values" implies only PCB material is used in the HCB fixture reference. This is not always the case
 SuggestedRemedy
 Remove "printed circuit board (PCB)". Test fixture can be implemented against the reference in many ways. There are (3) instances in this section that would be corrected.
 Proposed Response Response Status O

Cl 179B SC 179B.4.2 P826 L10 # 603
 Kocsis, Sam Amphenol
 Comment Type TR Comment Status X
 There is no documented procedure for adjusting the reference reference impedance for an ERL computation, though one exists in the COM code.
 SuggestedRemedy
 Add details to this Annex to document the procedure and provide a reference for other places where an ERL computation requires a reference impedance other than 100-ohm.
 Proposed Response Response Status O

Cl 179B SC 179B.3.1 P824 L33 # 601
 Kocsis, Sam Amphenol
 Comment Type TR Comment Status X
 Text says "cable assembly test fixture PCB, test point, ocnnector and any associated vias" has proven to be difficult to validate. Since the effects of the differences between an actual test fixture and the reference insertion loss are to be accounted for, the reference definition should be more tangible.
 SuggestedRemedy
 Replace "cable assembly test fixture PCB, test point, ocnnector and any associated vias" with "cable assembly test fixture, from the RF connector refrence plane to the MDI transition". Update Equation 179B-1 appropriately, and remove "PCB" from the other (2) instance in this section.
 Proposed Response Response Status O

Cl 179B SC 179B.4.1 P826 L1 # 604
 Kocsis, Sam Amphenol
 Comment Type TR Comment Status X
 The rise time used in the FOM_ILD calculation is inconsisnt with the rise time used on ICN calculations
 SuggestedRemedy
 Converge to a single rise time setting for mated test fixture calculations and adjust criteria pass/fail limits appropriately.
 Proposed Response Response Status O

Cl 179B SC 179B P823 L39 # 602
 Kocsis, Sam Amphenol
 Comment Type ER Comment Status X
 Flip the order of polynomial from decreasing to increasing to align formatting with older clauses.
 SuggestedRemedy
 Impacted equations: 179B-1, -2, -3, -4, -5
 Proposed Response Response Status O

Cl 179B SC 179B.4.6 P829 L39 # 605
 Kocsis, Sam Amphenol
 Comment Type TR Comment Status X
 The aggressor amplitudes in the ICN calculations are not consistent with the expected worst-case maximum transmitter amplitudes.
 SuggestedRemedy
 Adjust the amplitudes match the transmitter swing and scale the criteria pass/fail limits appropriately.
 Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 176C SC 176C.6.3.5 P726 L18 # 606
 Palkert, Thomas Samtec, Macom
 Comment Type **TR** Comment Status **X**
 The C2C specification should use 92.5 ohm impedance for transmitter and receiver ERL
 SuggestedRemedy
 add line in Table 176C-3 to specify 92.5 ohm impedance
 Proposed Response Response Status

Cl 178A SC 178A.1.3 P768 L20 # 610
 Palkert, Thomas Samtec, Macom
 Comment Type **TR** Comment Status **X**
 All impedance values should be 92.5 ohms
 SuggestedRemedy
 Channel can be measured with 100 ohms but should be converted to 92.5 ohms
 Proposed Response Response Status

Cl 176C SC 176C.7.3 P734 L43 # 607
 Palkert, Thomas Samtec, Macom
 Comment Type **TR** Comment Status **X**
 The C2C specification should use 92.5 ohm impedance for channel ERL
 SuggestedRemedy
 add line in Table 176C-9 to specify 92.5 ohm impedance
 Proposed Response Response Status

Cl 178 SC 178.9.1 P361 L43 # 611
 Palkert, Thomas Samtec, Macom
 Comment Type **TR** Comment Status **X**
 All impedance values should be 92.5 ohms
 SuggestedRemedy
 Change reference impedance to 92.5 ohms
 Proposed Response Response Status

Cl 176D SC 176D.8.2 P752 L44 # 608
 Palkert, Thomas Samtec, Macom
 Comment Type **TR** Comment Status **X**
 The C2M specification should use 92.5 ohm impedance for TP1a ERL
 SuggestedRemedy
 add line in Table 176D-8 to specify 92.5 ohm impedance
 Proposed Response Response Status

Cl 179 SC 179.9.3 P393 L40 # 612
 Palkert, Thomas Samtec, Macom
 Comment Type **TR** Comment Status **X**
 All impedance values should be 92.5 ohms
 SuggestedRemedy
 Change reference impedance to 92.5 ohms
 Proposed Response Response Status

Cl 176D SC 176D.7.2 P749 L34 # 609
 Palkert, Thomas Samtec, Macom
 Comment Type **TR** Comment Status **X**
 All impedance values should be 92.5 ohms
 SuggestedRemedy
 Change COM Impedance to 92.5 ohms
 Proposed Response Response Status

Cl 179 SC 179.11.1 P412 L47 # 613
 Palkert, Thomas Samtec, Macom
 Comment Type **TR** Comment Status **X**
 All impedance values should be 92.5 ohms
 SuggestedRemedy
 Change reference impedance to 92.5 ohms
 Proposed Response Response Status

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 176C SC 176C.6.2 P723 L17 # 614
Palkert, Thomas Samtec, Macom
Comment Type **TR** Comment Status **X**
All impedance values should be 92.5 ohms
SuggestedRemedy
Change reference impedance to 92.5 ohms
Proposed Response Response Status

Cl 178 SC 178.10 P370 L34 # 618
Palkert, Thomas Samtec, Macom
Comment Type **TR** Comment Status **X**
The KR specification should use 92.5 ohm impedance for KR channel impedance
SuggestedRemedy
add line in Table 178-11 to specify 92.5 ohm impedance
Proposed Response Response Status

Cl 00 SC 0 P373 L43 # 615
Palkert, Thomas Samtec, Macom
Comment Type **TR** Comment Status **X**
The KR specification should use 92.5 ohm impedance for all ERL measurements
SuggestedRemedy
add line in Table 178-14 to specify 92.5 ohm impedance
Proposed Response Response Status

Cl 179 SC 179.9.4 P394 L18 # 619
Palkert, Thomas Samtec, Macom
Comment Type **TR** Comment Status **X**
Improve ERL specification
SuggestedRemedy
Presentation to be provided
Proposed Response Response Status

Cl 178 SC 178.9.1.2 P363 L32 # 616
Palkert, Thomas Samtec, Macom
Comment Type **TR** Comment Status **X**
The KR specification should use 92.5 ohm impedance for TP0v test fixture
SuggestedRemedy
add line in Table 178-7 to specify 92.5 ohm impedance
Proposed Response Response Status

Cl 179 SC 179.9.4.7 P403 L13 # 620
Palkert, Thomas Samtec, Macom
Comment Type **TR** Comment Status **X**
The CR specification should use 92.5 ohm impedance for transmitter and Receiver ERL
SuggestedRemedy
add line in Table 179-9 to specify 92.5 ohm impedance
Proposed Response Response Status

Cl 178 SC 178.9.2.2 P364 L15 # 617
Palkert, Thomas Samtec, Macom
Comment Type **TR** Comment Status **X**
The KR specification should use 92.5 ohm impedance for KR transmit ERL
SuggestedRemedy
add line in Table 178-8 to specify 92.5 ohm impedance
Proposed Response Response Status

Cl 179 SC 179.11 P412 L23 # 621
Palkert, Thomas Samtec, Macom
Comment Type **TR** Comment Status **X**
The CR specification should use 92.5 ohm impedance for cable assembly
SuggestedRemedy
add line in Table 179-13 to specify 92.5 ohm impedance
Proposed Response Response Status

CI 179 SC 179.11.3 P413 L19 # 622
 Palkert, Thomas Samtec, Macom
 Comment Type **TR** Comment Status **X**
 The CR specification should use 92.5 ohm impedance for cable assembly ERL
SuggestedRemedy
 add line in Table 179-14 to specify 92.5 ohm impedance
 Proposed Response Response Status **O**

CI 179 SC 179.9.5.3 P406 L26 # 623
 Palkert, Thomas Samtec, Macom
 Comment Type **TR** Comment Status **X**
 The CR specification should use 92.5 ohm impedance for interference tolerance parameters
SuggestedRemedy
 add line in Table 179-11 to specify 92.5 ohm impedance
 Proposed Response Response Status **O**

CI 179B SC 179B.4.2 P826 L19 # 624
 Palkert, Thomas Samtec, Macom
 Comment Type **TR** Comment Status **X**
 The CR specification should use 92.5 ohm impedance for MTF ERL
SuggestedRemedy
 add line in Table 179B-1 to specify 92.5 ohm impedance
 Proposed Response Response Status **O**

CI 185A SC 185A.2.3 P862 L30 # 625
 Kota, Kishore Marvell Semiconductor
 Comment Type **TR** Comment Status **X**
 The offline digital signal processing described in this section and Fig 185A-4. is missing a post-equalizer after the "carrier phase recovery" block which is required to allow relaxation of the IQ Quadrature skew (max)" spec to 0.75ps in Table 185-5. The relaxed skew specification is required to allow design of lower complexity 800GBASE-LR1 modules. Without this block the ETCC calculation will result in a large penalty if the skew gets close to the max allowed value.

SuggestedRemedy
 Add post-equalizer stage to the digital signal processing. Presentation to be provided.
 Proposed Response Response Status **O**

CI 178B SC 178B.14.3.5 P810 L7 # 626
 Law, David HPE
 Comment Type **TR** Comment Status **X**
 The variable training_status is used by the 'Training control state diagram' in subclause 178B.14.3.5 'State diagram figures' but is not defined in the associated subclause 178B.14.3.1 'Variables'.

In addition, it appears that the training_status is a per-interface variable based on the definition found in 178B.14.2.1 'Variables', yet it appears to be driven by both the per-interface 'RTS update state diagram' (Figure 178B-7) and the per-lane 'Training control state diagram' (Figure 178B-8). I'm not sure how this would operate.

As an example, if the Training control state diagram on one lane in an interface enters the FAIL state, it would set training_status for the interface to FAIL. If, however, the Training control state diagram on another lane in the same interface enters the PATH_UP state immediately afterwards, training_status for the interface would then be set to OK. This doesn't seem to be correct.

SuggestedRemedy
 Provide a definition for the training_status variable used in Figure 178B-8 'Training control state diagram' in its associated subclause 178B.14.3.1 'Variables'. In addition, clarify the operation of training_status regarding it being driven by both the per-interface 'RTS update state diagram' (Figure 178B-7) and the per-lane 'Training control state diagram'.
 Proposed Response Response Status **O**

CI 178B SC 178B.14.3.5 P810 L2 # 627

Law, David

HPE

Comment Type T Comment Status X

The variables mr_restart and reset are used in Figure 178B-8 'Training control state diagram', Figure 178B-9 'Training frame lock state diagram', and Figure 178B-10 'Coefficient update state diagram', but are not defined in the associated subclause 178B.14.3.1 'Variables'.

SuggestedRemedy

Add the following two entries in alphabetical order to subclause 178B.14.3.1:

mr_restart
See 178B.14.2.1.

Reset
See 178B.14.2.1.

Proposed Response Response Status O

CI 178B SC 178B.14.3.5 P810 L10 # 628

Law, David

HPE

Comment Type T Comment Status X

The variables mr_training_enable, local_rts and remote_rts are used in Figure 178B-8 'Training control state diagram' but are not defined in the associated subclause 178B.14.3.1 'Variables'.

SuggestedRemedy

Add the following entry in alphabetical order to subclause 178B.14.3.1:

local_rts
See 178B.14.2.1.

mr_training_enable
See 178B.14.2.1.

remote_rts
See 178B.14.2.1.

Proposed Response Response Status O

CI 178B SC 178B.14.3.5 P810 L45 # 629

Law, David

HPE

Comment Type E Comment Status X

Subclause 178B.14.1 'State diagram conventions' says that 'The notation used in the state diagrams follows the conventions of 21.5.'. Table 21-1 'State diagram operators' defines the [not equal sign] character as 'Not equals'.

SuggestedRemedy

Change the text 'max_recovery_events !=0' to read 'max_recovery_events [not equal sign] 0'.

Proposed Response Response Status O

CI 178B SC 178B.14.3.5 P810 L46 # 630

Law, David

HPE

Comment Type E Comment Status X

Subclause 178B.14.1 'State diagram conventions' says that 'The notation used in the state diagrams follows the conventions of 21.5.'. Table 21-1 'State diagram operators' defines the use of the [greater than or equal sign] character as 'Greater than or equal to'.

SuggestedRemedy

Change the text 'recovery_event_count >= max_recovery_events' to read 'recovery_event_count [greater than or equal sign] max_recovery_events'.

Proposed Response Response Status O

CI 178B SC 178B.14.3.1 P808 L2 # 631

Law, David

HPE

Comment Type E Comment Status X

Typo.

SuggestedRemedy

Change '... variable that is set to TRUE when ...' to read '... variable that is set to true when ...'.

Proposed Response Response Status O

Cl 178B SC 178B.14.3.1 P807 L36 # 632

Law, David

HPE

Comment Type T Comment Status X

The variables remote_mc_mode and remote_tp_mode are defined in subclause 178B.14.3.1 'Variables' but are not used in any of the respective state diagrams, Figure 178B-8 'Training control state diagram', Figure 178B-9 'Training frame lock state diagram', or Figure 178B-10 'Coefficient update state diagram'.

SuggestedRemedy

Remove the definitions of remote_mc_mode and remote_tp_mode from subclause 178B.14.3.1 'Variables'.

Proposed Response Response Status O

Cl 178B SC 178B.14.2.4 P805 L1 # 633

Law, David

HPE

Comment Type E Comment Status X

Change the title of subclause 178B.14.2.4 'State diagram figures' to read 'State diagram figure' since there is only one state diagram figure in this subclause, Figure 178B-7 'RTS update state diagram'.

SuggestedRemedy

See comment.

Proposed Response Response Status O

Cl 178B SC 178B.6.2 P791 L7 # 634

Law, David

HPE

Comment Type T Comment Status X

Subclause 178B.6.2 'Control and status fields' says that 'Two formats are defined for the control and status fields, E1 and O1.'. Everywhere else in the draft, however, it seems that E1 and O1 are defined as types of interfaces. For example, subclause 178B.7 'Control field structure' says, 'The structure of the control field for E1 interfaces shall be as shown in Table 178B-2 and for O1 interfaces as shown in Table 178B-3.'.

SuggestedRemedy

Suggest that the text 'Two formats are defined for the control and status fields, E1 and O1.' is changed to read 'The type E1 interface and a type O1 interface use different formats for the control and status fields (see 178B.7)'.

Proposed Response Response Status O

Cl 178B SC 178B.15 P813 L50 # 635

Law, David

HPE

Comment Type E Comment Status X

Suggest that the text 'Bit reference is provided for lane 0, bits for lanes 1 to 3 ...' is split into two sentences.

SuggestedRemedy

Change 'Bit reference is provided for lane 0, bits for lanes 1 to 3 ...' to read 'Bit reference is provided for lane 0. Bits for lanes 1 to 3 ...'

Proposed Response Response Status O

Cl 186 SC 186.4.2.1 P610 L35 # 636

Law, David

HPE

Comment Type T Comment Status X

I believe that the FAW field lock state diagram requests a FAW_SLIP, not a SLIP (see the FAW_SLIP state in Figure 186-16 '800GBASE-ER1 PMA FAW field lock state diagram'.

SuggestedRemedy

Suggest that '... the SLIP requested by the FAW field lock state ...' should be changed to read '... the FAW_SLIP requested by the FAW field lock state ...'.

Proposed Response Response Status O

Cl 184 SC 184.7.2.2 P547 L2 # 637

Law, David

HPE

Comment Type T Comment Status X

I believe that the e DSP frame lock state diagram requests a SYM_SLIP, not a SLIP (see the SYM_SLIP state in Figure 184-9—DSP 'lock state diagram'.

SuggestedRemedy

Suggest that '... the SLIP requested by the DSP frame lock state ...' should be changed to read '... the SYM_SLIP requested by the DSP frame lock state ...'.

Proposed Response Response Status O

Cl 178 SC 178.2 P357 L5 # 638

Li, Mike Altera (An Intel company)

Comment Type T Comment Status X

Refer to figure 174A-5,
 1.) BERadded is the BER contribution outside of the measured sublayer link.
 2.) Measured sublayer link is PCS-to-PCS including PMD and FEC. Both TX-FEC and RX-FEC must be included in the PHY-based measurement. To use FEC decoder, the incoming signal must be encoded (compared with the incoming signal does not need to be encoded to use PMA-based block error measurement).
 3.) May the measured link have xMII extender outside this sublayer link (its BER budget is not 8e-6 according to CL-174A.4).
 4.) with Table 174A-2, table 174A-3, xMII extender (if used) is not part of CER < 1.45e-11 spec.
 5.) Considering all of these, the BERsddd value for CL-178.2 should not be simple 8e-6. Instead, it should be 8e-6 * Number_of_C2C_SubLayerLink outside of the measured sublayer link between the two ends MACs.

SuggestedRemedy

change the BERsddd value from 8e-6 to 8e-6 * Number_of_C2C_SubLayerLink outside of the measured sublayer link between the two ends MACs.

Proposed Response Response Status O

Cl 179 SC 179.2 P387 L46 # 639

Li, Mike Altera (An Intel company)

Comment Type T Comment Status X

Refer to figure 174A-5,
 1.) BERadded is the BER contribution outside of the measured sublayer link.
 2.) Measured sublayer link is PCS-to-PCS including PMD and FEC. Both TX-FEC and RX-FEC must be included in the PHY-based measurement. To use FEC decoder, the incoming signal must be encoded (compared with the incoming signal does not need to be encoded to use PMA-based block error measurement).
 3.) May the measured link have xMII extender outside this sublayer link (its BER budget is not 8e-6 according to CL-174A.4).
 4.) with Table 174A-2, table 174A-3, xMII extender (if used) is not part of CER < 1.45e-11 spec.
 5.) Considering all of these, the BERsddd value for CL-179.2 should not be simple 8e-6. Instead, it should be 8e-6 * Number_of_C2C_SubLayerLink outside of the measured sublayer link between the two ends MACs.

SuggestedRemedy

change the BERsddd value from 8e-6 to 8e-6 * Number_of_C2C_SubLayerLink outside of the measured sublayer link between the two ends MACs.

Proposed Response Response Status O

Cl 178 SC 178.8.1 P360 L15 # 640

Swenson, Norman Nokia, Point2

Comment Type ER Comment Status X

The test points in the figure are not the test points at which the OMD is specified. The PMD is specified at TP0v, which is not shown in the figure. The first sentence starting with "The test points" implies that these are the only test points.

SuggestedRemedy

Change the title of the section from "Specified Test Points" to "Referenced Test Points". Delete the word "The" at the beginning of the first sentence. Add a sentence after the first sentence that reads: "The PMD is specified at test points TP0v and TP5v (see 178.9.2.1 and 178.9.3.1)."

Proposed Response Response Status O

Cl 178 SC 178.9.2 P361 L48 # 641

Swenson, Norman Nokia, Point2

Comment Type ER Comment Status X

The sentence states that specifications must be met at TP0v, but TP0v has not yet been defined.

SuggestedRemedy

Change the sentence to "The transmitter on each lane shall meet the specifications at TP0v (see 178.9.2.1) given ..."

Proposed Response Response Status O

Cl 178 SC 178.9.2.1 P362 L49 # 642

Swenson, Norman Nokia, Point2

Comment Type ER Comment Status X

"measurements of the transmitter are made at the output of a test fixture (TP0v) as shown in Figure 178-3 and described in Annex 163A" reads like the test fixture is described in Annex163A, which it is not.

SuggestedRemedy

Change to "the transmitter is measured using the methodology described in Annex 163A at the output of a test fixture (TP0v) as shown in Figure 178-3."

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 178 SC 178.9.2.1 P362 L49 # 643
Swenson, Norman Nokia, Point2
Comment Type **TR** Comment Status **X**
Annex 163A describes methods for measuring transmitter characteristics applicable to 802.3ck. Are these same methods applicable here? Annex 163A refers to use of Clause 93A. Is that still applicable here, or should Clause 178A be used instead?
SuggestedRemedy
Please clarify.
Proposed Response Response Status **O**

Cl 178 SC 178.9.2.1 P362 L49 # 644
Swenson, Norman Nokia, Point2
Comment Type **ER** Comment Status **X**
"An example test fixture is described in Annex 163B." Annex 163B does not describe an example test fixture. A description of an example test fixture would be a drawing of a physical test fixture, or perhaps a description of a possible implementation of an example fixture. Annex 163B gives example electrical characteristics for a test fixture for which reference values can be calculated. (I am not certain my interpretation is correct and would like clarification.)
SuggestedRemedy
Change to " Annex 163B gives example electrical characteristics of a test fixture for which reference values can be calculated."
Proposed Response Response Status **O**

Cl 179 SC 179.5 P388 L41 # 645
Swenson, Norman Nokia, Point2
Comment Type **ER** Comment Status **X**
The term "pervasive management" does not have a plain and ordinary meaning, nor is it defined anywhere in the document.
SuggestedRemedy
Either drop the word "pervasive" or provide a definition of "pervasive management".
Proposed Response Response Status **O**

Cl 179 SC 179.8.1 P390 L26 # 646
Swenson, Norman Nokia, Point2
Comment Type **TR** Comment Status **X**
TP1 is described as the cable assembly input. I believe it is not the cable assembly input, but rather the input to the cable assembly test fixture that feeds the cable assembly input.
SuggestedRemedy
Change the description of TP1 to "The input of the cable assembly test fixture that feeds the cable assembly input."
Proposed Response Response Status **O**

Cl 179 SC 179.8.1 P390 L28 # 647
Swenson, Norman Nokia, Point2
Comment Type **TR** Comment Status **X**
TP2 is described as the host output. I believe it is not the host output, but rather the output of the TP2 or TP3 test fixture that is fed by host output.
SuggestedRemedy
Change the description of TP2 to "The output of the TP2 or TP3 test fixture that is fed by the host output."
Proposed Response Response Status **O**

Cl 179 SC 179.8.1 P390 L30 # 648
Swenson, Norman Nokia, Point2
Comment Type **TR** Comment Status **X**
TP3 is described as the host input. I believe it is not the host input, but rather the input to the TP2 or TP3 test fixture that feeds the host input.
SuggestedRemedy
Change the description of TP3 to "The input of the TP2 or TP3 test fixture that feeds the host input."
Proposed Response Response Status **O**

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 179 SC 179.8.1 P390 L32 # 649
 Swenson, Norman Nokia, Point2
 Comment Type **TR** Comment Status **X**
 TP4 is described as the cable assembly output. I believe it is not the cable assembly output, but rather the output of the cable assembly test fixture that is fed by the cable assembly output.
 SuggestedRemedy
 Change the description of TP4 to "The output of the cable assembly test fixture that is fed by the cable assembly output."
 Proposed Response Response Status

Cl 179 SC 179.8.1 P390 L37 # 650
 Swenson, Norman Nokia, Point2
 Comment Type **ER** Comment Status **X**
 "The channel between TP0d to TP5d" is grammatically incorrect. It should be "between TP0d and TP5d", or it should be "from TP0d to TP5d".
 SuggestedRemedy
 Change to "between TP0d and TP5d"
 Proposed Response Response Status

Cl 179 SC 179.9.4.1.1 P395 L47 # 651
 Swenson, Norman Nokia, Point2
 Comment Type **ER** Comment Status **X**
 "For each configuration of the transmit equalizer" is not well defined, as no list of required configurations has been mentioned.
 SuggestedRemedy
 Clarify
 Proposed Response Response Status

Cl 179 SC 179.9.4.1.1 P396 L1 # 652
 Swenson, Norman Nokia, Point2
 Comment Type **ER** Comment Status **X**
 "Compute the linear fit pulse response" using what setting for the equalizer? This is not clear.
 SuggestedRemedy
 Clarify
 Proposed Response Response Status

Cl 179 SC 179.11.3 P413 L6 # 653
 Swenson, Norman Nokia, Point2
 Comment Type **TR** Comment Status **X**
 93A.5 does not specify how to terminate the far end of the cable when measuring ERL.
 SuggestedRemedy
 Specify a source impedance and a termination impedance for the ERL measurement.
 Proposed Response Response Status

Cl 176D SC 176D.7.1 P748 L25 # 654
 Swenson, Norman Nokia, Point2
 Comment Type **ER** Comment Status **X**
 Figure 176D-6 includes a connector, which is actually a mated connector, though that is not clear.
 SuggestedRemedy
 Draw a vertical line down the center of the rectangle labeled connector to indicate that both parts of the mated connector are included in the 28.2dB Host channel loss. Compare with figures 176D-4 and 176D-5. Change "Connector" to "Mated Connector" in the figure so it is clear that the loss of the mated connector is included on the Host channel loss.
 Proposed Response Response Status

CI 176D SC 176D.7.2 P748 L45 # 655
 Swenson, Norman Nokia, Point2
 Comment Type ER Comment Status X
 "COM calculation, as defined in 178A.1, is also used for calibration of noise in the interference tolerance test (see 176D.8.12)." What is the meaning of "also", that is, in addition to what? It is not clear, as no other purpose was mentioned here.
 SuggestedRemedy
 Clarify (This may be the purpose of the note on p. 749, line 9. If that is the case, I believe the text of the note belongs in the main text as a sentence leading into the sentence in question.)
 Proposed Response Response Status O

CI 179A SC 179A.4 P818 L37 # 656
 Swenson, Norman Nokia, Point2
 Comment Type TR Comment Status X
 I believe the host channel loss is to include the mated host/cable connector. But the text says "host connector", which is ambiguous.
 SuggestedRemedy
 Change "host connector" to "mated host/cable connector".
 Proposed Response Response Status O

CI 179A SC 179A.4 P818 L53 # 657
 Swenson, Norman Nokia, Point2
 Comment Type TR Comment Status X
 The Range(dB) for Host-High (HH) should be 4.45 to 18.95.
 SuggestedRemedy
 Change 18.5 to 18.95
 Proposed Response Response Status O

CI 179A SC 179A.5 P821 L4 # 658
 Swenson, Norman Nokia, Point2
 Comment Type TR Comment Status X
 What is the extra rectangle labeled Paddle/Wire Termination shown in Fig. 179A-2 that is not shown in the mated test fixtures in Fig 179A-1? It is not explained in the text.
 SuggestedRemedy
 Clarify
 Proposed Response Response Status O

CI 179B SC 179B.2.1 P824 L12 # 659
 Swenson, Norman Nokia, Point2
 Comment Type ER Comment Status X
 Curve label is inconsistent with the text.
 SuggestedRemedy
 Change ILdd_{catf} to ILdd_{catref}
 Proposed Response Response Status O

CI 179B SC 179B.3.1 P824 L32 # 660
 Swenson, Norman Nokia, Point2
 Comment Type TR Comment Status X
 It is unclear how "The effects of differences between the insertion loss of an actual test fixture and the reference insertion loss" are to be determined, given that the specification in 179B.4 is for the mated test fixture and not the Cable Assembly Test Fixture by itself.
 SuggestedRemedy
 Explain how the differences are to be determined.
 Proposed Response Response Status O

Cl 186 SC 186.4.3 P618 L17 # 661

Law, David

HPE

Comment Type T Comment Status X

Since Figure 186–18 is the '800GBASE-ER1 FEC FAM field lock state diagram', it seems that:

- [1] The condition from the GET_BLOCK state to the FIND_1ST state should be test_fam.
- [2] The condition from the INVALID_FAM state to the 5_BAD state should be fam_bad_count = 5.
- [3] The condition from the COMP_2ND state to the 2_GOOD state should be fam_match.

SuggestedRemedy

Change:

- [1] The GET_BLOCK state to the FIND_1ST state transition condition from test_amp to test_fam.
- [2] The INVALID_FAM state to the 5_BAD state transition condition from amp_bad_count = 5 to fam_bad_count = 5.
- [3] The COMP_2ND state to the 2_GOOD state transition condition from amp_match to fam_match.

Proposed Response Response Status O

Cl 186 SC 186.4.3 P619 L9 # 662

Law, David

HPE

Comment Type T Comment Status X

The Figure 186–19 800GBASE-ER1 FEC multi-frame alignment state diagram uses the variable fec_mfas_restart, but only fec_mfas_restart_lock is defined in the associated subclause 186.4.2.1 'Variables'.

SuggestedRemedy

Either change the three instances of fec_mfas_restart to read fec_mfas_restart_lock in Figure 186–19, or change fec_mfas_restart_lock to read fec_mfas_restart in subclause 186.4.2.1.

Proposed Response Response Status O

Cl 186 SC 186.4.3 P620 L4 # 663

Law, David

HPE

Comment Type E Comment Status X

Subclause 186.4.1 'State diagram conventions' says 'The notation used in the state diagrams follows the conventions of 21.5.'. Table 21–1 'State diagram operators' in subclause 21.5 defines the use of the [equal sign] character as 'Equals (a test of equality)'.

SuggestedRemedy

Change the five instances of the text '... == ...' in Figure 186–20 to read '... = ...'.

Proposed Response Response Status O

Cl 186 SC 186.4.3 P620 L39 # 664

Law, David

HPE

Comment Type E Comment Status X

Subclause 186.4.1 'State diagram conventions' says 'The notation used in the state diagrams follows the conventions of 21.5.'. Table 21–1 'State diagram operators' in subclause 21.5 defines the use of the [greater than or equal sign] character as 'Greater than or equal to'.

SuggestedRemedy

Change the text 'zero_aml_cnt >= 5' to read 'zero_aml_cnt [greater than or equal sign] 5' in Figure 186–20 '800GBASE-ER1 FEC Alignment marker location state diagram'.

Proposed Response Response Status O

Cl 186 SC 186.4.3 P620 L23 # 665

Law, David

HPE

Comment Type E Comment Status X

Subclause 186.4.1 'State diagram conventions' says 'The notation used in the state diagrams follows the conventions of 21.5.'. Table 21–1 'State diagram operators' in subclause 21.5 defines the use of the [left arrow] character as the 'Assignment operator'.

SuggestedRemedy

Change the five instances of the use of the characters '<=' as the assignment operator in the states in Figure 186–20 '800GBASE-ER1 FEC Alignment marker location state diagram' to use the [left arrow] character.

Proposed Response Response Status O

CI 179 SC 179.9.4.1.3 P397 L 22 # 666

Ran, Adeo Cisco Systems

Comment Type TR Comment Status X

As noted in comment #263 against D1.4, the different initialize value for CR vs. AUI-C2M creates an unnecessary burden for implementations. Firmware will need to have different modes, and training/adaptation algorithms will need to account for the different starting point. This will likely create confusion and interoperability issues that overshadow any potential benefit.

In https://www.ieee802.org/3/dj/public/25_03/ran_3dj_03_2503.pdf it was proposed to use preset 6 as the "initialize" setting for CR. This was referred to as "Change A" (slide 3).

There was consensus to apply this change, as recorded in straw polls #TF-7 and #TF-8 (see minutes_3dj_2503_approved, page 17).

Note that KR was not mentioned in "Change A" but it is assumed that the initialize value would be the same in KR and CR. Thus the intent is that this change would apply to KR as well.

Suggested Remedy

Implement change A as shown on slide 3 in ran_3dj_03_2503, with editorial license.

Proposed Response Response Status

CI 179 SC 179.9.5.2 P406 L 10 # 667

Ran, Adeo Cisco Systems

Comment Type TR Comment Status X

As noted in comment #263 against D1.4, the amplitude tolerance required by a receiver (at its input, TP3) is not a swing identical to the output of the transmitter. This is due to both channel attenuation and initial Tx equalization (which is addressed by another comment). This is despite the fact that the tolerance is defined using the output of the transmitter (but this value is at TP2).

The comment suggested adding an informative NOTE to highlight this non-trivial fact for readers. Similar comments exist in Amplitude tolerance subclauses of AUIs, both C2C and C2M.

In https://www.ieee802.org/3/dj/public/25_03/ran_3dj_03_2503.pdf it was referred to as "Change B" (slide 3).

There was consensus to apply this change, as recorded in straw polls #TF-7 and #TF-8 (see minutes_3dj_2503_approved, page 17).

Similar notes should be used for all instances of amplitude tolerance.

Suggested Remedy

Implement change B as shown on slide 3 in ran_3dj_03_2503, with editorial license.

Proposed Response Response Status

Cl 179 SC 179.9.4 P394 L 22 # 668

Ran, Adee Cisco Systems

Comment Type TR Comment Status X

As noted in comment #263 against D1.4, limiting the transmitter steady-state voltage v_f to 0.5 volt would reduce the effective channel reach that devices can operate on. In previous generations the v_f limit was 0.6 V (1.2 Vpp), and in current 802.3ck compliant systems, values at the upper half of this range (output swings above 1 Vpp) are commonly used to extend the reach and operate over longer cables and/or improve error statistics.

The comment suggested changing the transmitter specifications (v_f and peak-to-peak) and the corresponding receiver amplitude tolerance, but without changing the corresponding COM parameter (A_{ne}). In https://www.ieee802.org/3/dj/public/25_03/ran_3dj_03_2503.pdf it was referred to as "Change C" (apply for CR) and "Change D" (also for KR) (slide 3).

There was a preference to apply change D, as recorded in straw polls #TF-7 and #TF-8 (see minutes_3dj_2503_approved, page 17).

The following options are suggested for CR and KR (no change in C2C and C2M):

1. Change Tx maximum v_f to 0.6 V as proposed. Apply in Tx and Rx specifications (no change in COM A_{ne}).
2. Change as in option 1 and additionally change A_{ne} accordingly (increase by 20%).
3. Add a footnote in the transmitter specifications tables (179.9.4 and 178.9.2) to allow "engineered links" to operate above the specified v_f ; as a model, use the second paragraph of 178.10.6 (operating without AC-coupling in the channel).
4. Add an optional "high swing" mode. In a device that supports high swing mode, it is disabled by default. When it is enabled the transmitter v_f range is 0.5 to 0.6. Enabling this mode is under the responsibility of the system integrator.

SuggestedRemedy

Implement any of the four options listed in the comment. As a starting point, option A is suggested.

Proposed Response Response Status

Cl 175 SC 175.2.5.3 P273 L 41 # 669

Opsasnick, Eugene Broadcom

Comment Type TR Comment Status X

In ran_3dj_03a_2505.pdf, it was shown that the 64B/66B stateless decoder defined in 175.2.5.9, by reference to 172.2.5.9.2, may allow a corrupted 66-bit block to pass through to the MAC with a small probability. This can occur due to the error propagation of the de-scrambler from an uncorrectable FEC codeword into the first block the the following good FEC codeword. The 64B/66B stateless decoder does mark every block following an ERROR block as an ERROR which was originally intended to cover the de-scrambler error propagation, but it does not work as intended due to the merging of data streams from the two parallel RX flows prior to the 64B/66B decoding.

SuggestedRemedy

The Reed-Solomon FEC decoder within each RX flow of the 1.6TbE PCS, by reference to 119.2.5.3, causes every 66-block within two interleaved RS-FEC codewords to be set to an error block when one or both of the codewords is found to be uncorrectable. This should be extended to the four 66-bits blocks that make up the first 257-bit block of the following codeword to account for the errors possibly being propagated by the de-scrambler that follows within each flow.

In addition, the 64B/66B stateless decoder in 175.2.5.9 can and should be simplified to not set each 66-block after an error block to also be set to an error block since this does not work as intended and the correct marking can be done more easily in the RE-FEC decoder within each RX flow.

The RS decoder in 200GbE, 400GbE and 800GbE PCS clauses 119.2.5.3 and 172.2.5.3 should also be updated to extend the marking of error blocks to the four 66-bits blocks that make up the first 257-bit block that follows an uncorrectable FEC codeword for all PHYs that can use the stateless 64B/66B decoder.

Proposed Response Response Status

Cl 175 SC 175.2.4.1 P264 L24 # 670

Opsasnick, Eugene Broadcom

Comment Type T Comment Status X

The 64B/66B TX encoder function in 175.2.4.1 is allowed to use the stateless encoder defined in 172.3.4.1.2 or the state-diagram based encoder defined in Figure 119-14. This stateless encoder does some, but not all, of block sequence checking that is performed by the state-diagram based encoder. However, a 1.6TbE PCS is always co-located with an ethernet MAC above it which by definition only sends valid block sequences to the PCS. Therefore, the stateless 64B/66B encoder can be simplified to just encode the current 64B block and does not need to also look at the previous incoming block to validate the sequence of blocks sent by the MAC TX function.

SuggestedRemedy

Change the stateless 64B/66B encoder from the current definition in Table 172-1 to something like:

"When reset is asserted, tx_coded is set to LBLOCK_T, otherwise tx_coded = ENCODE(tx_raw) where LBLOCK_T is defined in 175.2.6.2.1 and the ENCODE function is defined in 175.2.6.2.3." or a much simplified table closer in form to Table 172-1.

Implement with editorial license.

Proposed Response Response Status O

Cl 116 SC 116.3.2 P156 L14 # 671

Dawe, Piers Nvidia

Comment Type T Comment Status X

Now that we are used to these generic primitives, the IS_ is redundant

SuggestedRemedy

Remove it, so that we have e.g. PMA:UNITDATA_i.request. This may need a maintenance request.

Proposed Response Response Status O

Cl 116 SC 116.3.2 P157 L6 # 672

Dawe, Piers Nvidia

Comment Type E Comment Status X

Primitives for other instances, of inter-sublayer interfaces, are

SuggestedRemedy

Too many commas

Proposed Response Response Status O

Cl 116 SC 116.3.3.3.1 P161 L16 # 673

Dawe, Piers Nvidia

Comment Type TR Comment Status X

communication *with* ... lower sublayer

SuggestedRemedy

I think this means from, not with. Needs clarification.

Proposed Response Response Status O

Cl 116 SC 116.5 P168 L9 # 674

Dawe, Piers Nvidia

Comment Type E Comment Status X

106.25 GBd PMD lane
In footnotes: at PMD lane signaling rate

SuggestedRemedy

106.25 GBd lane ... at lane signaling rate (3 times, presumably not for 113.4375 GBd). Also in Table 169-6.

Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 119 SC 119.2.1 P174 L9 # 675
 Dawe, Piers Nvidia
 Comment Type E Comment Status X
 data-units
 SuggestedRemedy
 data units
 Proposed Response Response Status O

Cl 169 SC 169.1.3 P186 L10 # 678
 Dawe, Piers Nvidia
 Comment Type E Comment Status X
 800 Gb/s PHY using - they all are, it's in the text that introduces the table, and its title. This table is too long and wordy; it uses sentence construction rather than columns. At least make a start.
 SuggestedRemedy
 Change "800 Gb/s PHY using" to "Uses"
 Proposed Response Response Status O

Cl 119 SC 119.2.4.1 P174 L32 # 676
 Dawe, Piers Nvidia
 Comment Type E Comment Status X
 alternative stateless encoder - there is only one kind of stateless encoder, per speed, I hope, and it's called "stateless encoder"
 SuggestedRemedy
 Delete "alternative, here and in 119.2.5.8"
 Proposed Response Response Status O

Cl 169 SC 169.2.4a P189 L47 # 679
 Dawe, Piers Nvidia
 Comment Type E Comment Status X
 The 800 Gb/s Attachment Unit Interface (800GAUI-n) ... *The* 800GAUI-n is defined for chip-to-chip (C2C) and chip-to-module (C2M) implementations.
 The 800GAUI-n C2C *is* specified in Annex 120F and Annex 176C.
 The 800GAUI-n C2M *is* specified in Annex 120G and Annex 176D.
 SuggestedRemedy
 An 800 Gb/s Attachment Unit Interface (800GAUI-n) ... 800GAUI-n is defined for chip-to-chip (C2C) and chip-to-module (C2M) implementations.
 Two types of 800GAUI-n C2C are specified, in Annex 120F and Annex 176C.
 Two types of 800GAUI-n C2M are
 Proposed Response Response Status O

Cl 120 SC 120.1.4 P184 L11 # 677
 Dawe, Piers Nvidia
 Comment Type TR Comment Status X
 Confusion between output and transmit side (possibly also in items 5 and 6)
 SuggestedRemedy
 Change " the signaling rate range for a ... PMA output" to " the signaling rate range in the transmit direction for a ... PMA"
 Proposed Response Response Status O

Cl 169 SC 169.2.4b P190 L3 # 680
 Dawe, Piers Nvidia
 Comment Type E Comment Status X
 In the title: FEC sublayer -> plural, or spell them out
 SuggestedRemedy
 800GBASE-R Inner FEC, 800GBASE-LR1 Inner FEC and 800GBASE-ER1 FEC sublayers
 Proposed Response Response Status O

Cl 169 SC 169.2.10 P190 L35 # 681
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 ILT jargon again.
 SuggestedRemedy
 See an earlier comment
 Proposed Response Response Status

Cl 170 SC 170.4.3 P207 L7 # 684
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 There should be major options for MAC rate, as in 81.5.2.3 and 171.9.3
 SuggestedRemedy
 Split this item into two
 Proposed Response Response Status

Cl 169 SC 169.3.2 P191 L17 # 682
 Dawe, Piers Nvidia
 Comment Type **E** Comment Status **X**
 missing commas: the PHY 800GXS above isn't called the PMA service interface
 SuggestedRemedy
 Insert comma
 Proposed Response Response Status

Cl 171 SC 171.1a P212 L14 # 685
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 An 800GMII/1.6TMII Extender is expected to meet the frame loss ratio specifications in 174A.4": is partly out of scope
 SuggestedRemedy
 A 800GMII Extender using SM-PMAs or a 1.6TMII Extender is expected to meet the frame loss ratio specifications in 174A.4
 Proposed Response Response Status

Cl 170 SC 170.1 P202 L12 # 683
 Dawe, Piers Nvidia
 Comment Type **T** Comment Status **X**
 This clause defines the characteristics of the Reconciliation Sublayer (RS) ... *The* RS, characteristics
 SuggestedRemedy
 the behavior of the 800 Gb/s Reconciliation Sublayer (RS) for 800 Gb/s and 1.6 Tb/s
 Proposed Response Response Status

Cl 171 SC 171.3.3 P216 L2 # 686
 Dawe, Piers Nvidia
 Comment Type **T** Comment Status **X**
 average data rate on the 800GMII - there are two 800GMII. Similarly in 171.3.3a
 SuggestedRemedy
 the average data rate across the 800GMII in the PHY 800GXS
 Similarly in 171.3.3
 Proposed Response Response Status

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 171 SC 171.3.3a P216 L25 # 687
 Dawe, Piers Nvidia
 Comment Type E Comment Status X
 will is deprecated
 SuggestedRemedy
 Change will be to is - several places
 Proposed Response Response Status O

Cl 173 SC 173.1.1a P244 L35 # 691
 Dawe, Piers Nvidia
 Comment Type T Comment Status X
 any ... in Table 169-2 *and* Table 169-3.
 SuggestedRemedy
 any ... in Table 169-2 *or* Table 169-3.
 Proposed Response Response Status O

Cl 171 SC 171.9.5.1 P231 L47 # 688
 Dawe, Piers Nvidia
 Comment Type TR Comment Status X
 For the PHY XS, this may be a misuse of "Transmit"
 SuggestedRemedy
 Use separate items for PHY XS and DTE XS
 Proposed Response Response Status O

Cl 174 SC 174.2.1 P248 L51 # 692
 Dawe, Piers Nvidia
 Comment Type TR Comment Status X
 physically instantiated
 SuggestedRemedy
 exposed
 Proposed Response Response Status O

Cl 173 SC 173.1.1 P244 L18 # 689
 Dawe, Piers Nvidia
 Comment Type E Comment Status X
 forms
 SuggestedRemedy
 types
 Proposed Response Response Status O

Cl 174 SC 174.2.5 P249 L39 # 693
 Dawe, Piers Nvidia
 Comment Type TR Comment Status X
 instantiations - are like placements in IC design one PMA, one placement, one instantiation. 176B.7 describes combinations of PMAs
 SuggestedRemedy
 Change instantiations to combinations
 Proposed Response Response Status O

Cl 173 SC 173.1.1a P244 L35 # 690
 Dawe, Piers Nvidia
 Comment Type T Comment Status X
 supports
 SuggestedRemedy
 connects to
 Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 175 SC 175.2.4.6.1 P266 L10 # 694

Dawe, Piers Nvidia

Comment Type **TR** Comment Status **X**

This is a specification, not a school lecture. am_x is not an example, we are defining its name here. 179 linear fit has "define", which is better although we don't usually write in the imperative.

SuggestedRemedy

Change
Let am_x<119:0> be the alignment marker for PCS lane x, x=0 to 15, where bit 0 is the first bit transmitted.
to
The alignment marker for PCS lane x, where x=0 to 15, is defined as am_x<119:0>. Bit 0 is the first bit transmitted.
Make similar changes elsewhere.

Proposed Response Response Status **O**

Cl 176 SC 176.1.1 P288 L18 # 695

Dawe, Piers Nvidia

Comment Type **T** Comment Status **X**

Three types of the - delte the, as in 173

SuggestedRemedy

Delete the, as in 173

Proposed Response Response Status **O**

Cl 176 SC 176.4.3.2.1 P305 L28 # 696

Dawe, Piers Nvidia

Comment Type **T** Comment Status **X**

round-robin and round robin

SuggestedRemedy

alternating, in rotation

Proposed Response Response Status **O**

Cl 177 SC 177.4.5 P333 L16 # 697

Dawe, Piers Nvidia

Comment Type **ER** Comment Status **X**

is most naturally defined

SuggestedRemedy

Clean up

Proposed Response Response Status **O**

Cl 177 SC 177.4.5 P333 L18 # 698

Dawe, Piers Nvidia

Comment Type **TR** Comment Status **X**

alpha

SuggestedRemedy

Define

Proposed Response Response Status **O**

Cl 177 SC 177.4.5 P333 L20 # 699

Dawe, Piers Nvidia

Comment Type **TR** Comment Status **X**

x

SuggestedRemedy

Define

Proposed Response Response Status **O**

Cl 177 SC 177.4.5 P333 L24 # 700

Dawe, Piers Nvidia

Comment Type **TR** Comment Status **X**

T

SuggestedRemedy

Define

Proposed Response Response Status **O**

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 177 SC 177.4.5 P333 L25 # 701
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 MSB
 SuggestedRemedy
 Define
 Proposed Response Response Status **O**

Cl 177 SC 177.4.5 P334 L4 # 705
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 generator matrix vs. Generation matrix - confusingly similar names
 SuggestedRemedy
 Rename one
 Proposed Response Response Status **O**

Cl 177 SC 177.4.5 P333 L30 # 702
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 big dot
 SuggestedRemedy
 Define
 Proposed Response Response Status **O**

Cl 178 SC 178.8.9 P361 L31 # 706
 Dawe, Piers Nvidia
 Comment Type **E** Comment Status **X**
 supports the coefficient indexes k_list = {-3, -2 -1, 0, 1} Too much nerdy, too little English.
 SuggestedRemedy
 Use the traditional "functional model is a FFE with these taps" language. Several clauses.
 Proposed Response Response Status **O**

Cl 177 SC 177.4.5 P333 L50 # 703
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 big dot
 SuggestedRemedy
 Define
 Proposed Response Response Status **O**

Cl 178 SC 178.9 P361 L40 # 707
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 characteristics
 SuggestedRemedy
 specifications
 Proposed Response Response Status **O**

Cl 177 SC 177.4.5 P334 L1 # 704
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 ^1
 SuggestedRemedy
 Define
 Proposed Response Response Status **O**

Cl 178 SC 178.9.2 P361 L47 # 708
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 characteristics
 SuggestedRemedy
 specifications
 Proposed Response Response Status **O**

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 178 SC 178.9.2 P361 L53 # 709
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 fourth-order vs. 5th order BT4. And why 60 GHz?
 SuggestedRemedy
 Change to 5th order, 53.125 GHz
 Proposed Response Response Status

Cl 178 SC 178.10.1 P371 L25 # 713
 Dawe, Piers Nvidia
 Comment Type **ER** Comment Status **X**
 Confusion between z and Z
 SuggestedRemedy
 As Z for impedance is very strongly established, use something other than z for length, such as L
 Proposed Response Response Status

Cl 178 SC 178.9.2.4 P364 L34 # 710
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 Nv = 400 ! That's ludicrously rare, 4^400 is 7e240. 100 is enough
 SuggestedRemedy
 Change Nv to 100 wherever it is 400 in this draft
 Proposed Response Response Status

Cl 178 SC 178.10.1 P372 L46 # 714
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 With a new COM, we can break away from old mistakes from the 8B/10B days. OIF did this years ago.
 SuggestedRemedy
 Change "Random jitter" to "Gaussian jitter", and sigma_RJ to sigma_GJ
 Proposed Response Response Status

Cl 178 SC 178.9.3.4.1 P366 L48 # 711
 Dawe, Piers Nvidia
 Comment Type **E** Comment Status **X**
 0.8V
 SuggestedRemedy
 insert space
 Proposed Response Response Status

Cl 178 SC 178.10.1 P372 L46 # 715
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 Unrealistic jitter values
 SuggestedRemedy
 "RJ" should be increased and D-D jitter should be reduced
 Proposed Response Response Status

Cl 178 SC 178.10.1 P371 L15 # 712
 Dawe, Piers Nvidia
 Comment Type **ER** Comment Status **X**
 Indices that look like exponents, should be subscripts
 SuggestedRemedy
 Change C_d^(1) to C_d1 or Cd1, and so on
 Proposed Response Response Status

IEEE P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 178 SC 178.10.3 P373 L51 # 716
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 Tukey window: it's not a flag (status bit) it's a switch (control bit)
 SuggestedRemedy
 Change Tukey window flag to Tukey window
 Proposed Response Response Status

Cl 179 SC 179.11.7 P415 L11 # 720
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 Add 4th host class:
 SuggestedRemedy
 CA-A HL HL, HN, HH or HH2 4
 HN HL, HN, or HH 3
 HH HL or HN 2
 HH2 HL 1
 Proposed Response Response Status

Cl 179 SC 179.1 P383 L22 # 717
 Dawe, Piers Nvidia
 Comment Type **E** Comment Status **X**
 The electrical specifications are separate for each host class - awkward
 SuggestedRemedy
 There are electrical specifications for each host class
 Proposed Response Response Status

Cl 180 SC 180.9.5 P447 L24 # 721
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 4.56×10^{-4} and the related Q t value (see 121.8.5.3) is 3.428
 -> $Q_t = 3.846$, 1 dBe better "SNR" (but doesn't change xECQ by that much). (implied $9e-5$ but that doesn't matter). do this less for SRS and URS. $10 \cdot \log_{10}(3.846/3.428) = 0.5$
 SuggestedRemedy
 Change Q_t to 3.846, 1 dBe better "SNR" (but doesn't change xECQ by that much). (implied $9e-5$ but that doesn't matter). Don't change Q_t for for SRS and URS. FYI $10 \cdot \log_{10}(3.846/3.428) = 0.5$
 Proposed Response Response Status

Cl 179 SC 179.1 P384 L35 # 718
 Dawe, Piers Nvidia
 Comment Type **ER** Comment Status **X**
 Tables 1 and 2, and 3 and 4, can be combined
 SuggestedRemedy
 Combine them into two, as Table 167-2, here and in other clauses
 Proposed Response Response Status

Cl FM SC FM P13 L1 # 722
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 802.3dk is ahead of this project
 SuggestedRemedy
 Insert: IEEE Std 802.3dk-202x
 This amendment includes changes to IEEE Std 802.3-2022 and adds Clause . This amendment adds Physical Layer specifications and management parameters for 100 Gb/s Ethernet optical interfaces for bidirectional operation over a single strand of single-mode fiber.
 Make other changes as appropriate
 Proposed Response Response Status

Cl 179 SC 179.9 P393 L19 # 719
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 PMD electrical characteristics
 SuggestedRemedy
 PMD electrical specifications
 Proposed Response Response Status

IEEE P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

CI 45 SC 45.2.1.26 P111 L49 # 723
 Dawe, Piers Nvidia
 Comment Type E Comment Status X
 PMAL - not defined, and somehow unmemorable. If it were to be kept, it would need to be added to the abbreviations list, but PMA lane / PMAL is used so much less often than PCS lane / PCSL that it's not worth coining an abbreviation for it.
 SuggestedRemedy
 Change PMAL to PMA lane, throughout the draft
 Proposed Response Response Status O

CI 45 SC 45.2.3.1 P116 L37 # 724
 Dawe, Piers Nvidia
 Comment Type ER Comment Status X
 Editor's note (to be removed after first working group ballot): doesn't respect SA balloters
 SuggestedRemedy
 Change to: Editor's note (to be removed after first SA ballot):
 11 times
 Proposed Response Response Status O

CI 45 SC 45.2.1.6 P74 L20 # 725
 Dawe, Piers Nvidia
 Comment Type TR Comment Status X
 as amended by IEEE Std 802.3df-2024
 SuggestedRemedy
 as amended by IEEE Std 802.3df-2024 and IEEE Std 802.3dk-202x
 Show the changes to these bits made by P802.3dj
 Similarly in other tables
 Proposed Response Response Status O

CI 45 SC 45.2.1.6 P74 L41 # 726
 Dawe, Piers Nvidia
 Comment Type ER Comment Status X
 So that the reviewers can confirm that the new material is inserted in the correct place, in the correct style, and without using a bit that's already taken
 SuggestedRemedy
 Please show the sub-rows below and above, each time.
 Proposed Response Response Status O

CI 73 SC 73.8 P140 L6 # 727
 Dawe, Piers Nvidia
 Comment Type E Comment Status X
 Cramped table title
 SuggestedRemedy
 Make its box full width
 Proposed Response Response Status O

CI 116 SC 116.1.4 P148 L6 # 728
 Dawe, Piers Nvidia
 Comment Type E Comment Status X
 2 or 4 -> two or four
 SuggestedRemedy
 Change
 PHY type and clause correlation (200GBASE copper with 2 or 4 lanes)
 to
 PHY type and clauses (200GBASE copper with two or four lanes)
 and similarly for other tables
 Proposed Response Response Status O

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 116 SC 116.1.4 P148 L10 # 729
 Dawe, Piers Nvidia
 Comment Type T Comment Status X
 There must be a BM PMA below any SM PMA
 SuggestedRemedy
 Move 176 and 176C to between 119 and 120. Also in 116-3a 4 and 5.
 Proposed Response Response Status O

Cl 116 SC 116.1.4 P148 L26 # 730
 Dawe, Piers Nvidia
 Comment Type T Comment Status X
 I don't see why the SM PMA is shown as conditional. It might be needed if one wants a 200GAUI-1 C2C, but that's not to do with the PMD.
 SuggestedRemedy
 Change C to O and/or revise the footnote. Also in 116-3a 4 and 5.
 Proposed Response Response Status O

Cl 116 SC 116.2.9 P155 L35 # 731
 Dawe, Piers Nvidia
 Comment Type TR Comment Status X
 If IS stands for inter-sublayer (116.3) and ISL for inter-sublayer link (178B), this would be ISLT. However, the "IS_" in the primitives has outlived its usefulness and should be removed, and optical PHYs do not have what one would recognise as training, even if there is a start-up protocol that uses training frames.
 SuggestedRemedy
 Find a better name for this, such as ISS (inter-sublayer startup), or remove 178B.
 Proposed Response Response Status O

Cl 116 SC 116.2.9 P155 L37 # 732
 Dawe, Piers Nvidia
 Comment Type TR Comment Status X
 Un-introduced, undefined jargon: inter-sublayer link, network path, peer, DATA mode. Also I suspect that "transmitter states, receiver states" misuse "transmitter" "receiver".
 SuggestedRemedy
 Rewrite this, with appropriate references, or remove 178B. Similarly in e.g. 169.2.10, 174.2.12
 Proposed Response Response Status O

Cl 116 SC 116.2.9 P155 L44 # 733
 Dawe, Piers Nvidia
 Comment Type TR Comment Status X
 is supported by - yuk
 SuggestedRemedy
 These PHY types include an ILT sublayer:
 Also in 169.2.10 and 174.2.12.
 Proposed Response Response Status O

Cl 119 SC 179.9.4 P393 L43 # 734
 Dawe, Piers Nvidia
 Comment Type TR Comment Status X
 Transmitter characteristics
 SuggestedRemedy
 Transmitter specifications
 Proposed Response Response Status O

IEEE P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

CI 179 SC 179.9.4 P394 L25 # 735
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 Bad names HL HN HH because H and L are ambiguous: loss or performance or length?
 Which loss?
 SuggestedRemedy
 Change to A B C, with A for best
 Proposed Response Response Status

CI 179 SC 179.9.4.6.1 P402 L1 # 738
 Dawe, Piers Nvidia
 Comment Type **ER** Comment Status **X**
 The standard should be written in English. The three-pronged magnet is pretentious,
 unfamiliar and unnecessary.
 SuggestedRemedy
 Change to: For each transition I in the set A:
 Proposed Response Response Status

CI 179 SC 179.9.4 P394 L37 # 736
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 Difference signal-to-noise-and-distortion ratio, dSNDR is too arcane and not justified for CR
 where the compliance board is properly defined and adjustment for its deviation is allowed
 SuggestedRemedy
 Change to SNDR, or delete and use EECQ
 Proposed Response Response Status

CI 179 SC 179.9.4.6.2 P402 L18 # 739
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 J4u03 can't be measured for CR because of the losses in the host
 SuggestedRemedy
 Delete, combine with other impairments into EECQ
 Proposed Response Response Status

CI 179 SC 179.9.4.5 P399 L1 # 737
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 Difference signal-to-noise-and-distortion ratio, dSNDR too arcane and not justified for CR
 where the compliance board is properly defined and adjustment for its deviation is allowed
 SuggestedRemedy
 Change to SNDR, or delete and use EECQ
 Proposed Response Response Status

CI 179 SC 179.9.4.5.1 P400 L4 # 740
 Dawe, Piers Nvidia
 Comment Type **T** Comment Status **X**
 Downsampling for P_Signal in SNDR seems fussy and unnecessary
 SuggestedRemedy
 Remove it
 Proposed Response Response Status

CI 179 SC 179.9.4.6 P401 L28 # 741
 Dawe, Piers Nvidia
 Comment Type **TR** Comment Status **X**
 Dud jitter method. Turning off aggressor lanes is desperate
 SuggestedRemedy
 Don't attempt to isolate jitter
 Proposed Response Response Status

E P802.3dj D2.0 200 Gb/s, 400 Gb/s, 800 Gb/s, and 1.6 Tb/s Ethernet Initial Working Group ballot comment

Cl 179 SC 179.9.4.6.3 P402 L43 # 742
Dawe, Piers Nvidia
Comment Type **TR** Comment Status **X**
EOJ03 should be included in SNDR or EECQ. It's not clear that we need a separate spec for it
SuggestedRemedy
Ensure that SNDR or EECQ include it (by telling the scope that the pattern is twice as long as it is), and delete
Proposed Response Response Status

Cl 179 SC 179.9.5.3.4 P408 L16 # 745
Dawe, Piers Nvidia
Comment Type **TR** Comment Status **X**
"peak-to-peak differential when measured on an alternating zero-three sequence": this isn't how peak-to-peak voltage is defined these days, and does not appear in 178.9.3.4.1, 176C.6.4.5.1
SuggestedRemedy
Delete "when measured on an alternating zero-three sequence", refer to 176D.8.1.
Proposed Response Response Status

Cl 179 SC 179.9.4.7 P403 L5 # 743
Dawe, Piers Nvidia
Comment Type **TR** Comment Status **X**
mating interface discontinuity - ambiguous and not defined.
SuggestedRemedy
Clarify what this means
Proposed Response Response Status

Cl 179 SC 179.9.5.3 P406 L39 # 744
Dawe, Piers Nvidia
Comment Type **ER** Comment Status **X**
See 179.2 for definition of block error ratio - not. 179.9.5.3.5 says "Block error ratio is defined in 174A.8."
SuggestedRemedy
Change "See 179.2 for definition of block error ratio." to "See 179.2 and 174A.8."
Proposed Response Response Status