Additional possible corrections for 802.1AS

Geoff Garner

June 8, 2011

1. p.66, subclause 10.2.12.2.1. localClockTickInterval should be multiplied by rateRatio, and not divided.
2. p.62, subclause 10.2.10.2.2. localClockTickInterval should be multiplied by gmRateRatio, and not divided,
3. p.75, subclause 10.3.8.1. updateRolesTree should be updtRolesTree.
4. p.82, subclause 10.3.12.1.4, item (d). This should say: "Computes the first three components of the masterPriorityVector for each port." This is in accordance with RSTP in 802.1D-2004, subclause 17.21.25, item (d).
5. p.34, subclause 8.6.2.4, item (b). The value is based on previous draft TDEV and PTPVAR masks (D6.2, where PTPDEV was 3*tau rather than 6.08*tau ns (and TDEV was 2.5*tau ns rather than 5*tau ns). The new value should be 0x436A = 17258 (and old value was already incorrect, because the log to base 2 was truncated before multiplying by 2^8; the procedure for calculating offsetScaledLogVariance from PTPVAR, and an example, is given in 7.6.3.3 of IEEE 1588-2008).