2008/11/24

Document under Review:		Ballo	t Number: No		Comment Date
Comment # 456	Comment submitted by:	Feder, Peretz	Disapprove	Produ	cer 09/16/2007 03:3
Comment Type Technica	al	Starting Page # 180	Starting Line # 46	Fig/Table# Yes	Section
It appears that CoS values from the LINK_PARAM_TYPE of "general" were removed and QOS_LIST (see above comment), defined on page 186 line 26, was added to the list of LINK_PARAM_TYPEs. However, throughput and packet error rate now occur in both types. Additionally, throughput is defined differently; UNSIGNED_INT(2) in LINK_PARAM but UNSIGNED_INT(4) in QOS_LIST.					
Suggested Remedy					
Proposed Resolution	Recommendation:		Recommendation by		
Delete Throughput and Packet Error Rate from QoS list.					
Reason for Recommendation					
Resolution of Group	Decision of Group: A	gree			
Reason for Group's Decision/Resolution					
Group's Notes					
Group's Action Items					
Editor's Notes	Editor's Actions k) done	9			
Editor's Questions and Concerns	5				
Editor's Action Items					