

Protocol Team : Open Issues

1) Speed Signaling

— proposal on web site this week

2) Error handling

— how does a coding error (e.g. invalid 10 bit character is received) get communicated to the Link layer?

3) Timings

— e.g. max delays DS <-> Beta, Beta <-> Beta

4) Interfaces

— to 1394a??

— to PMDs??

Input to Alistair Coles, anc@hplb.hpl.hp.com

Proposed Interfaces

