

---

Cl 11 SC 11.5 P 275 L 24 # i-3  
Romascanu, Dan Avaya Inc.

Comment Type TR Comment Status A

In the MIB module referred in Section 11.5 the MIB module that defines the IEEE8023-IF-CAP-STACK-MIB needs to be replaced with a reference to the IETF Internet-Draft <http://www.ietf.org/id/draft-ietf-opsawg-rfc5066bis-01.txt>. This is in accordance to the decision of the coordination team between the IEEE 802 and the IETF leadership to continue to maintenance of this part of RFC 5066 by the IETF, as documented in Section 7.4 in <http://www.ietf.org/iesg/ieee/20121217/coordination-04.txt>

*SuggestedRemedy*

In the MIB ASCII text replace the IEEE8023-IF-CAP-STACK-MIB module definition with a note that points to the IETF Internet-Draft <http://www.ietf.org/id/draft-ietf-opsawg-rfc5066bis-01.txt>

- Strike out any mention of IEEE8023-IF-CAP-STACK-MIB objects from the rest of the document.

Response Response Status W

ACCEPT.

add a note that points to IETF Internet-Draft <http://www.ietf.org/id/draft-ietf-opsawg-rfc5066bis-01.txt> to Clause 11 text. Add an

editors note that requests that the pointer be updated if/when the draft attains RFC status before publication of 802.3.1.

Also add to the bibliography.