

**INTERNATIONAL ELECTROTECHNICAL COMMISSION****TC65: INDUSTRIAL PROCESS MEASUREMENT, CONTROL AND AUTOMATION****SC65C: INDUSTRIAL NETWORKS**

**DOC TYPE:** Liaison letter  
**TITLE:** Liaison requested from IEC TC65/SC65C/JWG10  
**TO:** IEEE 802.3 on Power over Ethernet performance in industrial environments.  
**SOURCE:** SC65C Secretary, Mr Bernard Dumortier  
**PROJECT:** IEC 61918: Installation of communications networks in industrial premises  
**STATUS:** Request by JWG10 at Nice meeting, France 2009-03-6  
**ACTION:** For information  
**DUE DATE:** N/A  
**REQUEST ACTION:** To IEEE 802.3 for consideration  
To IEC SC65C/JWG10 for information

**Nb. PAGES:** 2 (including cover)

**DISTRIBUTION:**

IEEE 802.3	Chairman	Mr D. Law
IEEE 802.3 at	Chairman	Mr M. McCormack
IEC SC65C	Chairman	Mr A. Capel
ISO/IEC JTC1/SC25/WG3	Secretary	Dr-Ing W. von Pattay
TC65CX	Chairman	Mr R. Schultz
	Secretary	Mr M. Adams



**To:** Mr Mike McCormack Chair of 802.3at [[mike\\_mccormack@ti.com](mailto:mike_mccormack@ti.com)]  
**Copy:** Mr David Law Chair of 802.3 [[david\\_law@3com.com](mailto:david_law@3com.com)]  
**From:** IEC SC65 SC65C JWG10 [*Approved at the 18th meeting Nice, France on 2009-03-06*]  
**Date:** 15 May 2009  
**Subject:** Expected performance of Power over Ethernet when used in industrial applications.

1. At the recent meeting of IEC SC65C JWG10, members reported cases where Ethernet field devices have been damaged by unexpected release of power from PSE source entities.

The causes of these problems are not clear. However it seems that the PSE and remote field device have correctly implemented 802.3.

One possible explanation is that the PSE "probing & classification" procedure gave wrong results because the industrial site had high levels of noise on the line, and the outcome was incorrect release of power and damage to the connected device.

Has IEEE had any similar reports?

Have IEEE members reported any testing or evaluation of expected performance of the PoE "probing & classification" procedure when used in noisy environments?

What are the IEEE recommendations or guidance to avoid damage to vulnerable PD's when used in noisy environments such as MICE  $E_2$  and  $E_3$ ?

2. A related topic raised by members of JWG10 is the bit error rate performance of a normal 802.3 communication channel when the channel is also providing PoE to a switching inductive load such as a solenoid or motor starter that regularly changes state with consequent transients in the power demand.

What are the expected bit error rates for normal Ethernet signals during such transients in PoE demand on the same or adjacent pairs?

What recommendations are proposed to mitigate any anticipated problems?

We look forward to your guidance in these areas.

Russo

*Francesco Russo,*  
Convenor of JWG10  
[[russof76@libero.it](mailto:russof76@libero.it)]