

P802.1AS-Rev/D8.3 Editor's Report

Proposed Comment Resolution for 2nd Recirculation Sponsor Ballot

Geoffrey M. Garner
Huawei (Consultant)

gmgarner@alum.mit.edu

IEEE 802.1 TSN TG
2019.1.11

Ballot Statistics

☐ Thanks to all who reviewed the document and commented

Category	All respondents	
	Total	Percent
Yes (voters)	122	100
No (voters)	0	0
Voting Yes or No	122	100
Abstain Time	4	
Abstain Expertise	2	
Abstain Other	1	
Abstain Total	7	5 (5.426)
Respondents	129	79 (79.6296)
Voting Members	162	
Non-voting commenters	1	
Number of Commenters	1	
Number of Comments	1	
TR	0	
T	0	
ER	0	
E	0	
GR	0	
G	1	

Classification of Comments, and Order of Coverage

- One comment was received, from IEEE Staff
 - The comment type is General (G)
 - “Must be satisfied” is No
 - Discussion points are given in the proposed comment resolution (initially marked “Discuss”)

1588-Rev Citations that need to be Corrected - 1

- ❑ Comment r01-50 against the first sponsor ballot recirculation of 802.1AS-Rev (D8.1), and its response, were:

<i>Cl</i> 7	<i>SC</i> 7.5	<i>P</i> 49	<i>L</i> 37	# r01-50
Weber, Karl		Beckhoff Automation		
<i>Comment Type</i>	GR	<i>Comment Status</i>	A	
The reference to 6.2 in 1588 is wrong				
<i>SuggestedRemedy</i>				
The reference is currently 6.5.2 and should be changed accordingly But as the 1588 Std is not complete it is not possible to do the final commenting on the 159 1588 references and numerous "hidden" references where text is copied from 1588. Thus, the document should be checked after 1588 completion and revised if necessary.				
<i>Response</i>	<i>Response Status</i> C			
ACCEPT IN PRINCIPLE. Change 6.2 to 6.5.2. After IEEE Std 1588 is published, check the references to IEEE Std 1588 (including references to specific clauses/subclauses, figures, and tables), and correct any that are not correct.				

- ❑ In particular, the response to this comment indicates that the references to 1588 will be checked and corrected if necessary
- ❑ P1588-Rev/D1.6 was recommended for approval at the November 6, 2019 RevCom meeting, and was approved at the November 7, 2019 SASB meeting

1588-Rev Citations that need to be Corrected - 2

- Based on the above, the editor has examined all the citations in 802.1AS-Rev/D8.3 for which specific clause, subclause, figure, table, etc. references need to be updated
 - P1588-Rev/D1.6 was used to determine the correct citations, as this is the approved draft
- The list is on the following slides
 - Page, clause/subclause numbers, and line numbers refer to where in P802.1AS-Rev/D8.3 the 1588 citation that must be corrected is
 - Current citation is the current clause, subclause, figure, or table number in 1588 that is in P802.1AS-Rev/D8.3
 - Current citation is what the clause, subclause, figure, or table number in 1588 that is in P802.1AS-Rev/D8.3 should be

1588-Rev Citations that need to be Corrected - 3

Page (in 802.1AS)	Subclause (in 802.1AS)	Line number (in 802.1AS)	Current Citation (in 1588)	Corrected Citation (in 1588)
21	3.34	35	3.1.82	3.1.81
147	10.6.3.3.2	5	Table 50	Table 52
148	10.6.4.3.1	7	14.2	14.3
148	10.6.4.3.2	38	14.2.2.1	14.3.2.1151
151	10.6.4.4.1	28	14.2	14.3
152	10.6.4.5.1	36	14.2	14.3
159	11.1.2. (footnote)	54	3.1.86	3.1.87
161	11.1.3	49	11.4.5.1, 11.5.1, 11.5.2.2	10.3.2 and 10.3.3
197	11.4.4.3.1	44	14.2	14.3
198	11.4.4.3.2	25	14.2.2.1	14.3.2.1

1588-Rev Citations that need to be Corrected - 4

Page (in 802.1AS)	Subclause (in 802.1AS)	Line number (in 802.1AS)	Current Citation (in 1588)	Corrected Citation (in 1588)
384	16.5.2.1.1.1	7	14.2	14.3
384	16.5.2.1.1.2	42	Table 50	Table 52
384	16.5.2.1.1.2	42	14.2.2.1	14.3.2.1
427	F.3	10	16.6	16.14