

P802.3dm D2.1 Asymmetrical Electrical Automotive Ethernet 1st Working Group recirculation ballot comn

<i>Cl</i> 45	<i>SC</i> 45.2.1	<i>P</i> 37	<i>L</i> 18	<i>#</i> 294
Wienckowski, Natalie		IVN Solutions LLC; Ethernovia, Bosch		
<i>Comment Type</i> T	<i>Comment Status</i> X		<i>late</i>	
We changed the name of register 1.18, but don't show the updated name in Table 45-3				
<i>SuggestedRemedy</i>				
Bring in the row for register 1.18 and show the name change as shown in 45.2.1.16.				
<i>Proposed Response</i>	<i>Response Status</i> O			

<i>Cl</i> 45	<i>SC</i> 45.2.1	<i>P</i> 37	<i>L</i> 24	<i>#</i> 295
Wienckowski, Natalie		IVN Solutions LLC; Ethernovia, Bosch		
<i>Comment Type</i> T	<i>Comment Status</i> X		<i>late</i>	
We changed the name of register 1.2100, but don't show the updated name in Table 45-3				
<i>SuggestedRemedy</i>				
Bring in the row for register 1.2100 and show the name change as shown in 45.2.1.214.				
<i>Proposed Response</i>	<i>Response Status</i> O			