

Comment Sequence Number e.g., 1, 2, etc.	Commenter Name:	Clause:	Page:	Line:	Comment Type:	Part of NO vote(Y/N)	Comment:	Suggested Remedy:	NT STATUS X/received D/dispached for consideration	ONSE STATUS O/open W/written C/closed	Notes
1	Allen, James	0	0	0	e		This assumes the formatting problems continue to be addressed before sponsor ballot.		A	O	
312	Gilb, James	0	all		T	Y	A careful review of less than 10% of the document turned up an average of more than 1 error per page of the document. It is as if no one had even scanned the document before it was sent out. A quick scan of the document turns up at least 2 errors per clause. The multitude of errors in the document make a good technical evaluation very difficult. This document is not ready for review, let alone ready for sponsor ballot. It seems as if the document was sent out to make a deadline rather than being published when it was ready for review.	The document needs careful review and editing before it is sent for a working group ballot. After it is corrected for the numerous spelling, formatting and cross-reference errors, it would be ready for a technical evaluation by the working group. It its current form it is not ready for technical evaluation.	A	O	Changed to Editorial
10	Gilb, James	3	7	19, 25	e	N	Extra wording, "(Erratum 1040)"	Delete "(Erratum 1040)"	A	O	
17	Gilb, James	4	11-16	various	e	N	There is not a consistent application of capitalization to the acronym definitions. Some common words are capitalized, e.g. Call Control on 11, line 24, most are not.	Lower case all words except proper names and other acronyms	A	O	
32	Watanabe, F	5.2	18	22	e	n	Figure number is incorrect		A	O	
34	Camp, Micha	6.1	21	18	e	N	Awkward phrase: "have an increasing data capability"	Reword: "have increased data capabilities"	A	O	
35	Bisdikian, Ch	6.3	27	8	e		...and a set interoperable...	...and a set of interoperable...	A	O	
36	Bisdikian, Ch	6.3	27	11	e		...in the specifications. This...	...in the specification. This...	A	O	
182	Bisdikian, Ch	6.3	27	14	E		...protocols as identified in Figure 4. The rest of this subclause...	...protocols as identified in Figure 1. However, for completeness, the rest of this subclause....	A	O	
183	Gilb, James	6.3	27	14	E	N	Figure 4 is referenced, but it should be Figure 5. Also, a new paragraph should be started following the reference.	Change "Figure 4" to "Figure 5" and start a new paragraph with the sentence "The rest of this subclause ..."	A	O	
38	Camp, Micha	7.1	29	50	e	N	Editing tags left in text: "[XREF]"	Remove tags	A	O	
185	Gilb, James	7.1	29	52-54	E	N	The sentence refers to the draft standard as a specification and the regulatory documents as standards	Change "specification" to "standard" and "standard" to "regulatory", check for other occurrences of specification in the draft standard.	A	O	
184	Gilb, James	7.1	29 and following	51	E	Y	Extra text "[XREF]" for section cross-references and "[XREF]<BLUE>" for table cross-references	Delete "[XREF]" and "[XREF]<BLUE>" in all occurrences. Likely this can be done by modifying the cross-reference definition and applying it to the whole document in frame.	A	O	
39	Camp, Micha	7.2	30	48	e	N	Editing tags left in text: "[XREF]"	Remove tags	A	O	
40	Camp, Micha	7.2	30	51	e	N	Editing tags left in text: "[XREF]"	Remove tags	A	O	
41	Camp, Micha	7.2	31	8	e	N	Table 1 - Inconsistent border style	Make bottom border a heavier line weight	A	O	
42	Camp, Micha	7.2	31	16	e	N	Table 2 - Inconsistent border style	Make bottom border a heavier line weight	A	O	

Comment Sequence Number e.g., 1, 2, etc.	Commenter Name:	Clause:	Page:	Line:	Comment Type:	Part of NO vote(Y/N)	Comment:	Suggested Remedy:	NT STATUS X/received D/dispatched for consideration	ONSE STATUS O/open W/written C/closed	Notes
43	Camp, Michael	7.3	31	29	e	N	Editing tags left in text: "[XREF]"	Remove tags	A	O	
44	Camp, Michael	7.3	32	5	e	N	Editing tags left in text: "[XREF]"	Remove tags	A	O	
45	Camp, Michael	7.3	32	12	e	N	Editing tags left in text: "[XREF]"	Remove tags	A	O	
46	Camp, Michael	7.6	39	3	e	N	Editing tags left in text: "[XREF]"	Remove tags	A	O	
188	Gilb, James	8	47ff	various	E	Y	The table format in this clause is not consistent with the rest of the document.	Change the table formats to be consistent with the rest of the standard.	A	O	
190	Gilb, James	8.1	41	49	E	Y	The cross reference to the Physical layer section does not include a clause number or page number	Change cross references throughout this clause to include either the clause number, the page number or preferably both.	A	O	
50	Gilb, James	8.5	59	47-48	e	N	Text in bold format where it should be in normal text format. This formatting occurs at various places in this clause and should be changed wherever it occurs.	Remove bold formatting here and throughout the clause to match the rest of the standard.	A	O	
52	Camp, Michael	8.7	69	50	e	N	Phrase "An exception forms"	Suggested text: "An exception exists when forming"	A	O	
53	Camp, Michael	8.8	70	30	e	N	Cross-references to subclauses 8.1 and 8.2 are incorrect.	Should refer to subclauses 8.8.1 and 8.8.2	A	O	
54	Roberts, Rick	9.1	152	18	e	N	page 152, line 18 ... what does <Blue> mean? Should this be removed?		A	O	
265	Cypher, David	9.2	153	17	t	N	What is H2.1.1?	Clarify or correct what H2.1.1 is.	A	O	Changed to Editorial
266	Cypher, David	9.2	153	19	t	N	What is H2.1.1?	Clarify or correct what H2.1.1 is.	A	O	Changed to Editorial
55	Roberts, Rick	9.4	186	7	e	N	page 186, figure 5 ... text has spelling error (oofset --> offset)		A	O	
57	Roberts, Rick	10	6		e	N	How come clause 10 is given as page 6?		A	O	
58	Roberts, Rick	10	6		e	N	The numbering on clause 10 should be 10.1 ... not 10.0.1		A	O	
59	Roberts, Rick	10	11		e	N	Clause 10, page 11 ... word "Erratum" appears ... in fact this appears all over clause 10		A	O	
377	Marquess, Keith	12.1	243	32			improper page break		A	O	
192	Cypher, David	12.3	250	42	E		If Figure 141 is correct, then where is figure 140. Possible numbering problem or missing figure	No suggestion until question is answered.	A	O	
60	Roberts, Rick	10.0.1			e		In clause 10.0.1, we have a font change under Figure 2		A	O	
61	Roberts, Rick	10.0.1			e		In clause 10.0.1, in the text under Figure 2 is a referral to Figure 3 on page 7. There are two page 7 in this document ... very confusing!		A	O	
193	Cypher, David	10.0.48	58	4	E		Naming does not match that listed in table 30.	Change BD_ADDR_List to BD_ADDR_Lst.	A	O	
194	Cypher, David	10.0.48	58	through	E		Current value indicates 6 octets, however the type is a pointer. Since a pointer is implementation dependent, it should not be indicated how many octets to use.	Value should be N/A since it is a pointer	A	O	
318	Cypher, David	11.2.7.14	143	52	T	N	Current hex coding does not equal 5 seconds.	Change value 0x1FA0 to 0x1F40 to make 5 seconds.	A	O	Assumed Typo fixed submit errata (call KrisF) A -> 4 OR 5 -> 5.06
378	Marquess, Keith	11.2.7.2	129	49 & 50			What is 'policy' regarding "Note:" usage? I would suggest that for clarity that Notes are made footnotes.		A	O	

Comment Sequence Number e.g., 1, 2, etc.	Commenter Name:	Clause:	Page:	Line:	Comment Type:	Part of NO vote(Y/N)	Comment:	Suggested Remedy:	NT STATUS X/received D/dispatched for consideration	ONSE STATUS O/open W/written C/closed	Notes
319	Cypher, David	11.2.7.21	151	14&16	T		The range value 0x0012 does not agree with Range value 0.625 msec.	Either change 0x0012 to 0x0001 or change 0.625 to 11.25.	A	O	Did not fix Assumed Typo (call KrisF) x0012 -> x0001 OR 0.625 -> 11.25
62	Roberts, Rick	12.1.1	246	4	e		Figure 138 in section 12 (Service Access Point) has a spelling error ... Servide --> Service		A	O	
274	Cypher, David	12.2.1	248	47	t	N	There is no item c in figure 139. To what is it referring	Add labels to figure to match text	A	O	Changed to Editorial
64	Gilb, James	1-Annex H	all	page #	e	N	The page numbers appear on the wrong side of the pages (I suspect left and right pages are messed up).	Change master pages and master page usage so that odd page numbers appear on the right hand side of the right hand pages.	A	O	IEEE / SA will be modifying this before Sponsor Ballot
63	Gilb, James	1-Annex H	All Even	page #	e	N	The even page numbers (i.e. the left page master) has a different font than the odd side page numbers.	Change even page number font to match odd page number font. 802.11 appears to be Times Roman (the even page number format) rather than Helvetica (the odd page number format)	A	O	
66	Bisdikian, Ch	6.1.1	21	34	e		For example, a PDA must...	For example, a communications-enabled PDA must....	A	O	
67	Bisdikian, Ch	6.1.1	21	40	e		a park, industrial plants. The...	a park, industrial plants, and so on. The...	A	O	
68	Bisdikian, Ch	6.1.1	21	48	e		his/her possession, in his/her vicinity...	his/her possession, or in his/her vicinity...	A	O	
69	Bisdikian, Ch	6.1.2.2	23	4	e		LAN (Ethrenet), their primary objective...	LAN (Ethrenet), a WLAN's primary objective...	A	O	
197	Bisdikian, Ch	6.2.1	24	27	E		As shown in Figure 3, the...	As shown in Figure 1, the...	A	O	
71	Camp, Michael	6.2.2	25	3	e	N	Phrase "power-cautious"	Reword: "power-conscious"	A	O	
72	Camp, Michael	6.2.2	25	11	e	N	Phrase "ad hoc" should be in italics	Format: "ad hoc" in italics	A	O	
73	Camp, Michael	6.2.2	25	51	e	N	Inverted sentence structure	Reword: "The jitter for voice traffic is kept low by using small transmission slots."	A	O	
74	Camp, Michael	6.2.2	26	7	e	N	Phrase "managing the traffic on the packet"	Reword: "managing the transmission of the packet"	A	O	
70	Bisdikian, Ch	6.2.2	26	3->8	e		Figure 2 shows ... upper layer data.	Figure 2 shows the general format of a single-slot, payload-bearing packet transmitted over-the-air in a Bluetooth WPAN. The packet comprises of an which carries upper layer data. Due to the small size of the packet, large upper-layer packets need to be segmented prior to transmission over the air. Detailed information about this packet format can be found in clause 8.	A	O	
76	Camp, Michael	7.3.1	32	20	e	N	Editing tags left in text: "[XREF]"	Remove tags	A	O	
80	Camp, Michael	7.3.1.2	33	14	e	N	Editing tags left in text: "[XREF]"	Remove tags	A	O	
81	Camp, Michael	7.3.2.2	33	44	e	N	Editing tags left in text: "[XREF]"	Remove tags	A	O	
83	Camp, Michael	7.3.3	33	53	e	N	Editing tags left in text: "[XREF]"	Remove tags	A	O	
84	Camp, Michael	7.3.3	33	54	e	N	Editing tags left in text: "[XREF]"	Remove tags	A	O	
85	Camp, Michael	7.4.2	34	46	e	N	Editing tags left in text: "[XREF]"	Remove tags	A	O	
86	Camp, Michael	7.4.2	34	47	e	N	Editing tags left in text: "[XREF]"	Remove tags	A	O	
87	Camp, Michael	7.4.2	34	48	e	N	Editing tags left in text: "[XREF]"	Remove tags	A	O	
88	Camp, Michael	7.4.3	35	32	e	N	Editing tags left in text: "[XREF]"	Remove tags	A	O	
89	Camp, Michael	7.4.4	35	52	e	N	Formatting: Page break should fall before subclause	Keep Clause header with text that follows.	A	O	

Comment Sequence Number e.g., 1, 2, etc.	Commenter Name:	Clause:	Page:	Line:	Comment Type:	Part of NO vote(Y/N)	Comment:	Suggested Remedy:	NT STATUS X/received D/dispatched for consideration	ONSE STATUS O/open W/written C/closed	Notes
90	Camp, Micha	7.4.4	36	4	e	N	Editing tags left in text: "[XREF]"	Remove tags	A	O	
91	Camp, Micha	7.4.6	36	16	e	N	Editing tags left in text: "[XREF]"	Remove tags	A	O	
92	Camp, Micha	7.4.6	36	17	e	N	Spurious colon at end of sentence	Remove colon	A	O	
93	Camp, Micha	7.4.7	37	2	e	N	Editing tags left in text: "[XREF]"	Remove tags	A	O	
327	Gilb, James	7.4.8	37	28	T	Y	The reference "(see Pseudo_Random Sequence, on page 1084)" is undefined. There is no page 1084 (due to the page numbering problem) and a text search of the PDF reveals no other occurrences of that phrase. A search for pseudo reveals that the proper reference is on page 875, E.2.1.2. Also the PRBS-15 is undefined	Correct the reference for PRBS-9 and add a reference for PRBS-15.	A	O	Changed to Editorial
94	Camp, Micha	7.4.8	37	29	e	N	Unnecessary underline in cross-reference	Remove underline	A	O	
95	Camp, Micha	7.4.8	37	29	e	N	Bad cross-reference, page number 1084 does not exist.	Fix cross-reference	A	O	
96	Camp, Micha	7.5.1.1	37	42	e	N	Text refers to "test report", no internal or external document reference.	Add internal or external document reference.	A	O	
98	Camp, Micha	8.10.6.3	86	39	e	N	Grammar: "It will in fact transmit also"	Change to: "It will also transmit"	A	O	
99	Camp, Micha	8.10.6.3	87	51	e	N	Typo: "page train is independent on the presence"	Change to: "page train is independent of the presence"	A	O	
101	Camp, Micha	8.10.6.4.1	90	33	e	N	Phrase: "can already arrive"	Change to: "can arrive"	A	O	
103	Camp, Micha	8.10.6.4.2	91	37	e	N	First two sentences of paragraph are repeated from the paragraph above.	Delete first two sentences of paragraph starting on line 37.	A	O	
104	Camp, Micha	8.10.7.3	92	25	e	N	Verb tense: "has been assumed that the HV3 packet are used"	Change to: "has been assumed that the HV3 packet is used"	A	O	
105	Camp, Micha	8.10.7.4	94	4	e	N	Verb tense: "a slave on average responses 4 times"	Change to: "A slave, on average, responds four times"	A	O	
331	Cypher, Davi	8.10.7.4	93-94	36-54	T		The new procedures either prohibit entering or leaving Inquiry Response. After RAND slots return to inquiry scan on first inquiry message go to inquiry response and return FHS. At this point device is in inquiry response. Now what triggers the device out of this state?	It now appears that all actions are done in the inquiry scan substate and there is no need for the inquiry response state, so delete it and its related description.	A	O	Submit Bluetooth Errata
278	Cypher, Davi	8.10.9.3	104		t		Introduces step 1 through step 3 and later text step 4, but never clear what are the steps	Clearly mark where each of the steps are.	A	O	tms -- Inspect details of text and make recommendation
106	Roberts, Rick	8.13.2.1	121	2	e		On page 121 of section 8.13.2.1, change the phrase "X-raying" to "Xoring"		A	O	
107	Roberts, Rick	8.14.2.1	126	11	e		Page 126, line 11 needs excess carriage return removed		A	O	

Comment Sequence Number e.g., 1, 2, etc.	Commenter Name:	Clause:	Page:	Line:	Comment Type:	Part of NO vote(Y/N)	Comment:	Suggested Remedy:	NT STATUS X/received D/dispatched for consideration	ONSE STATUS O/open W/written C/closed	Notes
333	Cypher, David	8.3.2	44	50-53	T		What does this statement mean? It is in conflict with the statement in section 8.10.8.5.1 on page 102 line 20.	I have asked this on LB#3 and the response from BSIG is that to remove what is confusing to me would only confuse others. So please someone, any one, tell me what it means.	A	O	Re-submit Bluetooth Errata 1253, which was rejected, text is still unclear. Is the SCO slave <u>always</u> allowed to transmit in it's SCO, slot? We believe that the Slave is always allowed to send it's data in it's reserved slot. However, the current V1.1 text indicates a possible exception for slave transmission in it's reserved slot. To remove this ambiguity, delete "unless a different slave was addressed into the previous master-to-slave slot". or provide the conditions under which the exception will occur. Ref. Bluetooth Core v1.1 Part B Sec 3.2, 2nd Paragraph
109	Camp, Michael	8.4.1	45	52	e	N	Typo: "linkcontroller" should read "link controller"	Add space in text.	A	O	
112	Camp, Michael	8.4.4	50	7	e	N	Awkward phrase: "up to now"	Delete phrase	A	O	
113	Camp, Michael	8.4.4	50	18	e	N	Awkward phrase: "so far"	Delete phrase	A	O	
114	Camp, Michael	8.4.4.1	51	3	e	N	Entire subclause is phrased awkwardly.	Suggested text: "There are five packet types defined which are independent of the underlying physical link type. Additionally, the ID packet type is defined which is used in the paging and inquiry procedures, described later in this document. These packet types are defined as follows.	A	O	
115	Camp, Michael	8.4.4.1.4	51	40	e	N	Phrase: "This clock information is updated before each transmission. The retransmission of the FHS payload is thus somewhat different from the retransmission of ordinary data payloads where the same payload is used for each retransmission."	Suggested Text: "Subsequent transmissions of the FHS packet contain updated clock information. Each transmission always contains the most recent native clock data from the Bluetooth node.	A	O	
116	Camp, Michael	8.4.4.1.4	52	32	e	N	External document reference missing "Bluetooth Assigned Numbers"	Add external document reference.	A	O	
117	Camp, Michael	8.4.4.2	53	54	e	N	Phrase: "Up to now, three pure SCO packets have been defined."	Suggested Text: "In previous clauses, three SCO packet types were defined."	A	O	
118	Camp, Michael	8.4.4.2.4	54	40	e	N	Grammar: "The voice and data fields are treated completely separate."	"The voice and data fields are treated separately."	A	O	
119	Camp, Michael	8.4.5.2	56	30	e	N	Inappropriate pluralization: "2-bytes"	Reword: "2-byte"	A	O	
120	Camp, Michael	8.4.5.2	56	35	e	N	Inappropriate pluralization: "2-bytes"	Reword: "2-byte"	A	O	
121	Camp, Michael	8.4.5.2	57	16	e	N	Text should indicate that codes are binary representations	Use notation of form: "01b", or whatever form is approved in IEEE.	A	O	
122	Camp, Michael	8.4.5.2	57	30	e	N	"LMP_features_res" message needs cross reference.	Refer to subclause 9.3.11 "Supported Features"	A	O	
125	Gilb, James	8.4.5.2	58	25-26	e	N	Text in bold format where it should be in normal text format	Remove bold formatting to match the rest of the clause.	A	O	
127	Camp, Michael	8.5.3.5	65	4	e	N	Graphic: Figure 19 text "roadcast packets"	Should read "Broadcast packets"	A	O	
128	Cypher, David	8.5.3.5	65	5	e		Misspelling of broadcast	Add "B" in front of "roadcast paclets"	A	O	
130	Roberts, Rick	8.5.3.5	65	5	e		Figure 19 has a spelling error on the figure		A	O	
131	Camp, Michael	8.5.4	65	49	e	N	Graphic: Caption for Figure 20 is above graphic, and separated by a page break.	Captions should appear below the associated graphic, and stay on the same page.	A	O	

Comment Sequence Number e.g., 1, 2, etc.	Commenter Name:	Clause:	Page:	Line:	Comment Type:	Part of NO vote(Y/N)	Comment:	Suggested Remedy:	NT STATUS X/received D/dispatched for consideration	ONSE STATUS O/open W/written C/closed	Notes
133	Roberts, Rick	8.5.4	65	50	e		Put the caption for figure 20 and the figure on the same page.		A	O	
134	Roberts, Rick	8.5.4	66	1	e		Figure 20 is an orphan figure		A	O	
132	Camp, Michael	8.5.4	66	11	e	N	80% of page is blank	Move figures 21 and 22 to page 66	A	O	
138	Gilb, James	8.9.3	77	44	e	N	Unnecessary use of bold for the states, it distracts from the description in this and other paragraphs.	Remove the bold formatting of the transceiver states in this clause.	A	O	
139	Camp, Michael	8.9.6	79	28	e	N	Phrase "according the RX/TX timing"	Should read "according to the RX/TX timing"	A	O	
140	Camp, Michael	8.9.6	79	35	e	N	Phrase "message sent secondly in the master-to-slave slot"	Should read "message sent on the second frequency of the preceding master-to-slave slot"	A	O	
141	Camp, Michael	8.9.6	81	2	e	N	The second sentence in the paragraph is not clear.	Suggested wording: "The response sent 625us after the start of the FHS packet acknowledges receipt of the FHS.	A	O	
142	Camp, Michael	8.9.7	81	13	e	N	Phrase "exception is found in the access window"	Change to: "exception is the access window"	A	O	
143	Cypher, David	9.3.18	177	54	e		Wrong section number.	Replace with 7.3	A	O	
235	Cypher, David	9.3.6.3	162	32	E		Section 8.14.2.2.2 Does not contain COF. What section does?	Correct reference number or remove bad reference.	A	O	
336	Cypher, David	9.5.1.1	192	27	T		www.bluetooth.org/assigned-numbers.htm is password protected. How can one use IEEE 802.15.1 without this information?	Remove password protection	A	O	editorial changes will be made to point to IEEE archive specs
282	Cypher, David	A.4.3.10	279	39	t		Text in parentheses indicates able to initiate SCO links, but there are two items initiating SCO (Master A.36/1and Slave A.36/2)	Add A.36/2 to Condition C.2	A	O	fw -- Contact Stan via email
305	Cypher, David	A.5.3.1	282	36 & 43	t	N	The condition C.1 does not make sense to me. Since DH1 is marked as mandatory in Baseband PICS, why is this a condition based on whether DH1 are used or not?	Delete C.1 and replace with O (optional)	A	O	Changed to Editorial
243	Cypher, David	B	all	all	E		All SDLs need to be updated according to the new version of this draft text.	Various	A	O	
244	Gilb, James	C	837ff	N/A	E	Y	The figure and table numbering in section C is incorrect, it runs A.1, B.1, C.1, etc. for both figures and tables	Fix figure and table numbering	A	O	
245	Gilb, James	C	858ff	31	E	N	The cross references in this section are in wrong font and emphasis and do not provide either clause numbers or pages. For example, the cross references in this section are "Baseband Specification" and "Link Manager Protocol"	Change cross references through out this clause to include either the clause number, the page number or preferably both.	A	O	
246	Cypher, David	C.10.2	866	32	E		What are references [2] and [1]?	Add references	A	O	[1] corresponds to clause 8, [2] corresponds to clause 9.
247	Cypher, David	C.4.2.3.3	841	41	E		What is reference [1]?	Add reference	A	O	[1] corresponds to clause 8, [2] corresponds to clause 9.
252	Gilb, James	D	870-871	1	E	Y	The table numbering and figure numbering in the annex are incorrect	Fix the figure and table numbering throughout the annex	A	O	

Comment Sequence Number e.g., 1, 2, etc.	Commenter Name:	Clause:	Page:	Line:	Comment Type:	Part of NO vote(Y/N)	Comment:	Suggested Remedy:	NT STATUS X/received D/dispatched for consideration	ONSE STATUS O/open W/written C/closed	Notes
253	Gilb, James	D.1	868	16ff	F	N	The paging scheme 1 (or l) reference uses the wrong font and emphasis	Change the font and emphasis to match the rest of the paragraph on this line and all other occurrences in the annex.	A	O	
309	Cypher, David	D.2.4	871	53	T	N	The appears to be missing text, since The hopping Has no end	Add missing text	A	O	lan to recover missing text
354	Gilb, James	D.2.4	871	53	T	Y	The subclause ends prematurely, just as it was getting interesting.	Put in the rest of the text or delete the sub-clause	A	O	lan to recover missing text
254	Gilb, James	E	872	42	E	Y	The table numbering and figure numbering in the annex are incorrect. In addition, the table format in this annex (particularly the table title) is not consistent with the rest of the document.	Fix the figure and table numbering throughout the annex. Change the table format to be consistent with the rest of the standard	A	O	
255	Gilb, James	E	872ff	N/A	E	Y	The footer is justified incorrectly and the font and line spacing is not consistent with the rest of the document	Import the master pages from what ever document is being used to contain the correct formatting of the standard.	A	O	
170	Camp, Michael	FM	iii	46	E	N	Acronym: "SIG" not defined	Use full text : Special Interest Group	A	O	
171	Camp, Michael	Footer	All	N/A	E	N	Page numbers on facing page footers are inconsistent. Left hand pages are Helvetica/Arial and right pages are Times fonts	Re-format footers to use consistent fonts in footer	A	O	
258	Bisdikian, Charles	front	iii	26	E	N	As of the publication of this standard.....	As of the publication of this draft standard....	A	O	
259	Bisdikian, Charles	front	iii	27	E	N	Version 0.9	this (and other) version number from the current Bluetooth specifications/documents may have to be updated prior to the final publication of this standard	A	O	
260	Gilb, James	G	889ff	various	E	Y	The figure numbering is incorrect. In addition, the cross references to the figures are incorrect	Fix the figure numbering.	A	O	
261	Gilb, James	G.4.4	903	29	E	N	The reference to figure 4.4 is incorrect and points no-where.	Change to reference what is currently figure 0.13 (and fix the figure numbering)	A	O	
262	Gilb, James	G.7	917	3	E	N	Extra text "<BLUE>" in figure cross reference and in other cross references in the annex	Delete extra text in this and all other figure cross references.	A	O	
174	Gilb, James	Introduction	xiii	54	E	N	The introduction ends on an odd page, should end on an even page	Delete page xiii	A	O	
175	Gilb, James	TOC	x-xii		E	N	The spacing in the TOC between subsections of the annexes is not consistent with the spacing of the subsections of the clauses.	Change the TOC format to fix the spacing of the subsections of the annexes.	A	O	