

IEEE 802.17 Maintenance Request 0004

MR number 0004 Classification Technical Date received 1/24/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 245 Subclause 10.2.4 Figure _____ Table _____

Surname Chathnath Given Name Praveen

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

The variable unreservedRate[ri] used in Fairness clause (Pages 273 [ed: 249] & 269 [ed: 245]) should refer to the ringInfo.unreservedRate[ri]. Currently it refers to myTopoInfo.unreservedRate[ri].

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Correct the variable reference in 10.2.4 (Page 269 [ed: 245]) to ringInfo.unreservedRate[ri].

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

ringInfo.unreservedRate[ri] is the variable which contains information of total unreserved bandwidth in the ringlet. More over myTopoInfo does not have a variable unreservedRate[ri].

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

Should not affect the existing 802.17 equipment.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.