

## IEEE 802.17 Maintenance Request 0018

MR number 0018 Classification Technical Date received 3/13/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 416 Subclause B.2.1.6.1 Figure \_\_\_\_\_ Table \_\_\_\_\_

Surname Lemon Given Name John

**Perceived Problem** [ If more space is needed, please provide an additional file, preferably as plain text. ]

802.3 MAC attributes were mistakenly added to the PacketPHY.

**Proposed Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

Remove the 802.3 preamble and IPG from the PacketPHY.

**Rationale For Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

See attached text.

**Remedy's Effect On Existing Equipment** [ If more space is needed, provide an additional file, preferably as plain text. ]

1G and 10G PHYs are capable of working with without these 10/100 leftovers.

**When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.**