

maint-request-haddock-6-10-1111.txt

IEEE 802.1 REVISION REQUEST 0018

DATE: 9/29/11
NAME: Stephen Haddock
COMPANY/AFFILIATION: Haddock Consulting LLC
E-MAIL: shaddock@stanfordalumni.org

REQUESTED REVISION:
STANDARD: 802.1Q-2011
CLAUSE NUMBER: 6.10
CLAUSE TITLE: Support of the ISS/EISS by Provider Instance Ports

RATIONALE FOR REVISION:

The last sentence of Note 1 contains an incorrect reference. In IEEE Std 802.1ah-2007 this sentence was correct: "Figure 26-2 shows a Provider Instance Port with both Bridge Port Connectivity and CFM shims." In 802.1Q-2011 "Figure 26-2" was erroneously changed to "Figure 6-4".

PROPOSED REVISION TEXT:

Change "Figure 6-4" to "Figure 26-2" in the last sentence of Note 1 in 6.10.

IMPACT ON EXISTING NETWORKS:

None.

Please attach supporting material, if any
Submit to: - Tony Jeffree, Chair IEEE 802.1
and copy: - Paul Congdon, Vice-Chair IEEE 802.1
E-Mail: stds-802-1-maint-req@ieee.org

----- For official 802.1 use -----
REV REQ NUMBER: 0018
DATE RECEIVED: 9/29/11
EDITORIAL
ACCEPTED/DENIED
BALLOT REQ'D YES/NO
Status: R
