

```

+-----+
| IEEE 802.1 REVISION REQUEST 0141 |
+-----+

```

DATE: July 17, 2014  
NAME: John Messenger  
COMPANY/AFFILIATION: ADVA Optical Networking Ltd  
E-MAIL: JMessenger@advaoptical.com

## REQUESTED REVISION:

STANDARD: 802.1Q-2014  
CLAUSE NUMBER: 6.6.1, 6.7.1  
CLAUSE TITLE: ISS, and Support of ISS

## RATIONALE FOR REVISION:

Maintenance item 0125 copied these functions from 802.1Q to 802.1AC, but left them in 802.1Q so that Q-Rev could be completed independently of 802.1AC-Rev. Once 802.1AC-Rev has been published, this needs to be fixed up.

## PROPOSED REVISION TEXT:

Delete 6.6.1 Control primitives and parameters (which is now covered in 11.4 of 802.1AC-Rev), and 6.7.1 Support of the Internal Sublayer Service by IEEE Std 802.3 (CSMA/CD) (which is now covered at the end of 12.1 of 802.1AC-Rev).

Change the references to 6.6.1 to references to 11.4 of 802.1AC-20XX in 6.8.4, 12.26.1, 36.1.2, M.1.

Change any references to 6.7.1 to references to 12.1 of 802.1AC-20XX. Except there aren't any at the time of writing.

```

+-----+
| Please attach supporting material, if any |
| Submit to:- Glenn Parsons, Chair IEEE 802.1 |
| and copy:- John Messenger, Vice-Chair IEEE 802.1 |
| E-Mail: stds-802-1-maint-req@ieee.org |
| |
| +----- For official 802.1 use -----+ |
| | REV REQ NUMBER: 0141 | |
| | DATE RECEIVED: 17 July 2014 | |
| | EDITORIAL/TECHNICAL | |
| | ACCEPTED/DENIED | |
| | BALLOT REQ'D YES/NO | |
| | Status: R | |
| +-----+ |
+-----+

```