

IEEE P802.3cq D3p1 2-Pair PoE Maintenance 1st Sponsor recirculation ballot comments

---

Cl 0 SC 0 P L # r01-1

Gibbons, Patrick

Comment Type E Comment Status D

This draft meets all editorial requirements.

SuggestedRemedy

Proposed Response Response Status W

PROPOSED ACCEPT.

---

Cl 0 SC 0 P0 L0 # r01-2

Hajduczenia, Marek

Charter Communications

Comment Type TR Comment Status X

MR 1322 (see [http://www.ieee802.org/3/maint/requests/maint\\_1322.pdf](http://www.ieee802.org/3/maint/requests/maint_1322.pdf)) still needs to be addressed.

As a result .3cq deprecated 33.5: (NOTE--33.5 has been deprecated. Since May 2019, maintenance changes are no longer being considered for this sub- clause. ).

However, 802.3.2 YANG was written against a version of 802.3 that predates the AT amendment (so pre-2009) and contains pointers to things that no longer exist in the Clause 33 state diagram, specifically ERROR\_DELAY\_OVER and ERROR\_DELAY\_SHORT. Clause 33 incorrectly calls these non-existent states. The MR was merely helping .3cq identify orphaned references and how to fix them, yet the comments submitted against D1.0 of .3cq were rejected.

SuggestedRemedy

Please fix references per MR 1322.

Proposed Response Response Status W

TFTD