

IEEE P802.3dd D3.1 Clause 104 Maintenance 1st Sponsor recirculation ballot comments

Cl **FM** SC **FM** P **3** L **31** # **R1-1**

Grow, Robert RMG Consulting

Comment Type **E** Comment Status **D** Frontmatter

This paragraph of mandatory text is inconsistent with the current front matter as found in P802.3/D3.2. (Not having FrameMaker, I checked P802.3/D3.2 against the 2021 Word frontmatter template and P802.3/D3.2 and confirmed those two are consistent.)

SuggestedRemedy

Use current mandatory front matter.

Proposed Response Response Status **W**

PROPOSED ACCEPT IN PRINCIPLE.

Request the publication editor to update the mandatory text with the current approved text from IEEE-SA at the time of publication.

Cl **FM** SC **FM** P **11** L **39** # **R1-2**

Grow, Robert RMG Consulting

Comment Type **E** Comment Status **D** Frontmatter

The Section description is not consistent with the current front matter as found in P802.3/D3.2.

SuggestedRemedy

Update for consistency with P802.3/D3.2.

Proposed Response Response Status **W**

PROPOSED ACCEPT IN PRINCIPLE.

Request the publication editor to update the text of the introduction with the final approved text for IEEE P802.3dc (IEEE Std 802.3-202x) prior to publication.