```
2
                    REVISION REQUEST
3
   +-----
4
   DATE: 04 October 2024
5
   NAME: Charity Reed
6
   COMPANY/AFFILIATION: UNH-IOL
7
   E-MAIL: creed@iol.unh.edu
8
9
   REQUESTED REVISION:
10
    STANDARD: 802.3-2022
11
    CLAUSE NUMBER: 149.3.9.2.13
12
    CLAUSE TITLE: OAM Reed-Solomon
13
   PROPOSED REVISION TEXT:
14
   Replace
15
16
    "When all 16 symbols of the OAM are embedded in tx RSmessage<9:0> as
17
    described in 149.3.2.2.17 then OAM<15:14><9:0> are dummy symbols and
18
   are ignored at the receiver."
19
20
   with
21
22
   "When all 16 symbols of the OAM are embedded in tx RSmessage<3259:3250>
23
    as described in 149.3.2.2.17 then OAM<15:14><9:0> are dummy symbols and
24
   are ignored at the receiver."
25
26
   RATIONALE FOR REVISION:
27
   The bit reference is incorrect, according to 149.3.2.2.17 the correct
28
   bit reference is tx RSmessage<3259:3250>.
29
30
   IMPACT ON EXISTING NETWORKS:
31
32
33
   +-----
34
   |Please attach supporting material, if any
   |Submit to:- David Law, Chair IEEE 802.3 | and copy:- Adam Healey, Vice-Chair IEEE 802.3
35
36
37
   |At:-
38
               E-Mail: stds-802-3-maint-req@ieee.org
39
40
              +-----+
41
              | REV REO NUMBER: 1465
              | DATE RECEIVED: 04 October 2024
42
              | EDITORIAL/TECHNICAL
43
              ACCEPTED/DENIED
44
              | BALLOT REQ'D YES/NO
45
              | COMMENTS:
46
   +-----
47
48
   | For information about this Revision Request see -
49
   |http://www.ieee802.org/3/maint/requests/revision history.html#REQ1465 |
50
   +-----
51
```